



19-Jan-2022

PCN #: P-22-022024

Subject : Spec 44 and FLDW Wires

Description of Change : TE Connectivity was informed by one of its material supplier on a consolidation in their manufacturing plant for PVDF based Color Concentrates (CC). TE Wire and Cable plants in Tijuana and Redwood City use PVDF CCs as colorant for outer insulation layer in spec 44 and FLDW primary wires. TE has evaluated the PVDF CCs from the supplier's new manufacturing location and no change to Form, Fit and Function of finished parts has been observed.

Reason : Part status change. TE was notified by its material supplier that except for Black PVDF CC, no change has been made in material formulation and recipe for PVDF CCs produced from their new manufacturing site. Due to health and safety policy of vendor's new manufacturing site with respect to handling raw carbon black pigments, this CC has undergone a change of one raw material component. TE evaluated these changes on the key characteristics of the CCs and the finished goods and no impact on the properties and performance of finished parts has been observed. Test reports on the wire characteristics can be provided upon request. In addition to the evaluation conducted by TE, FAIs will be performed on the first manufactured primary wire lot per each gauge for validation.

Key Dates :

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
259658-000	"6-1191899-2", "345/63B-26-90-0"		
900161-000	"2-1196997-1", "EPD44226A-US"		
282621-000	"4-1192120-5", "44A0111-22-903"		
382252-000	"1192859-7", "44A1131-22-0/1/9-9"		
356621K001	"5-1192676-2"		

631661K001	"2-1194998-0"		
759341K001	"9-1195915-5"		
743179K001	"7-1195798-0"		
A84395K001	"1200571-3"		
415400K001	"9-1199146-5"		
116883K001	"5-1190851-0"		
349041K001	"2-1192626-7"		
452541-000	"44A9416-22-9126CS1981", "1193398-3"		
381063-000	"1-1192849-6", "EPD52675A-22-0"		
692547-000	"5-1195436-6", "EPD53083A-X-0"		
E74258-000	"3-1201692-7", "44A0111-10-9-3"		
279195-000	"5-1192066-1", "345M15B-22-28-0CS2041"		
756261K001	"8-1195893-2"		
726959-000	"44A9970-14-9CS2745BAR REL", "8-1195681-0"		
CR3709-000	"44A0221-20-9/9CS3030"		
737555-000	"44AM1122-16-0/9-9", "3-1195758-2"		
CP8890-000	"EPD-RWC-22059"		
463993K001	"3-1193479-4"		
117567K001	"9-1190855-8"		

287808-000	"2-1192183-9", "44A0111-18-966"		
728835-000	"44B9536-12-MST3-9CS1728", "9-1195694-3"		
D44901K001	"6-1200577-9"		
CS2887-000	"44A0311-20-9-F871"		
356795-000	"1197969-6", "EPD70554A-US"		
CY0084-000	"EPD-RWC-19002-L021"		
CS6999-000	"EPD-DND-21508-L099"		
389764-000	"6-1192925-1", "44A1121-26-2/9-3"		
CF3597-000	"44AM1121-26-9/96-9CS2994", "2-1899213-2"		
532133K001	"6-1194178-0"		
382361-000	"1-1192862-3", "44A1131-18-0/2/9-9-MX"		
173517-000	"1-1191262-4", "FB-RWC-12907"		
D55644-000	"8-1200290-5", "FLDWC0311-22-9CS2979"		
948781-000	"44A1331-18-0/2/9-9CS2746", "7-1197340-5"		
518023-000	"1-1199930-6", "EPD91413A"		
004545-000	"7-1190034-4", "EPD51068A-22-0"		

610237K001	"4-1194825-6"		
CJ9798-000	"EPD-CAN-10020-L016CS2979", "8-1899317-6"		
026283K001	"1190204-3"		
CU6274-000			
CP5189-000			
071793K001	"9-1190538-7"		
735497K001	"1-1195744-3"		
828073-000	"8-1196466-8", "EPD-ADD-10009"		
BM8769-000			
380633K001	"3-1192846-3"		
466961K001	"1-1193500-8"		
175423-001	"5-1191275-9", "44A9441-24-MST3-9CS527"		
238487-000	"4-1191753-4", "44A9674-22-9-9CS2746"		
556403K001	"3-1194389-6"		
110173-000	"6-1190804-7", "EPD52622A-X-0"		
336375-000	"8-1192539-7", "44AM3121-22-9/92"		
736999-000	"44A9083-16-9CS2745BAR REL", "5-1195754-2"		
909334-000	"44A0113-24-9CS2979", "3-1199961-5"		

557064-000	"44A0331-20-0/2/9CS2747", "6-1200248-2"		
559207-000	"3-1194414-3", "EPD-ROK-10285"		
282019-049	"3-1192093-3", "44A0111-18-9-MX"		
301018-001	"9-1192279-0", "44AM1111-18-9-9"		
CF4748-000	"44B4124-24-1/9-9CS3217"		
363006-000	"6-1192721-6", "44A1811-20-9-9-US"		
CU7472-000	"44A0111-10-9-L179"		
282260-000	"1192111-4", "44A0311-12-9-US", "44A0311-12-9-US"		
396173-000	"6-1192971-4", "44A0111-22-STRIPE-KIT-112"		
251657-000	"3-1191844-9", "EPD-RWC-10425"		
463913-000	"44A1221-16-9/96-9-5CF/1", "7-1193478-5"		
297275-000	"5-1192251-0", "44AM1111-18-954-9"		
475891-001	"4-1193564-7", "44A7559-24-0/9-94CS448"		
704989K001	"6-1195529-4"		
EG9500-000	"EPD-RWC-24080-L352"		
CS8296-000	"EPD-DND-21459-L016"		

CA7489-000	"44A9749-26-1/9-9CS3185"		
CA7512-000	"44A9749-16-1/9-9CS3185"		
564059K001	"9-1194455-7"		
584047-000	"345M12B-26-12-0CS2041", "4-1194625-7"		
750339-000	"6-1195851-8", "EPD-RWC-13952"		
474636-000	"4-1199869-2", "EPD-ROK-10477"		
368775-000	"7-1192763-0", "EPD-RWC-10302"		
EM6447-000	"EPD-RWC-25127CS3490"		
345433-000	"4-1192600-7", "44A1121-26-9/90-9"		
836211K001	"6-1196527-0"		
622507-000	"4-1194920-9", "EPD-RWC-14756"		
279873-000	"1-1192071-4", "EPD-RWC-14916"		
C69765-000	"5-1201759-2", "44A0111-18-96-2KF"		
119865-000	"1-1190872-9", "44AM1131-18-3/6/9-9"		
501065K001	"4-1193746-2"		
154567-000	"3-1191116-9", "EPD-MPP-10046"		
EL6394-000	"44AM1121-18-0/9-9CS3451"		

003097-000	"6-1190023-7", "EPD52629A-22-0"		
754767K001	"5-1195883-7"		
409455K001	"9-1193087-7"		
306655-000	"1-1192323-6", "EPD51413A-X-0"		
242685-000	"5-1191780-7", "EPD-ADD-10093"		
906255-000	"44A9698-14-F955-0", "1197041-6"		
277156-000	"5-1199827-1", "44A7620-16-9/5-9CS2979"		
CS8529-000	"EPD-DND-21972-L016"		
EM7720-000			
246475-000	"1191808-5", "44AM1131-22-0/1/9-9CS1702"		
375219-000	"1192811-5", "44A9664-18-0/2/9-0"		
737050-000	"44AM1121-22-0/9-97", "5-1199113-9"		
514579K001	"2-1194042-4"		
CN8361-000	"44/0412-14-9CS1038"		
EP1299-000			
323601K001	"3-1192449-0"		
636111-000	"44A0141-20-MST4CS2109", "7-1195029-0"		

018763-000	"6-1190146-7", "44A9966-10-9CS2745BAR REL"		
812531K001	"2-1196321-4"		
564919-000	"1194462-9", "EPD-RWC-14915"		
678405K001	"2-1195333-8"		
050667-000	"4-1190388-8", "44A1121-22-0/9-9CS406"		
770642-000	"6-1199125-9", "FLDWC0311-20-9CS2722"		
A72853-000	"44A0111-18-940-2KF", "1-1200547-2"		
F60898-000	"5-1202125-5", "44A0311-16-9CS3030"		
E85781K001	"3-1200393-9"		
376605-000	"44A0321-24-0/9"		
C61239-000	"7-1200394-9", "EPD-RWC-17591"		
3W0625-000	"1-1193019-7", "EPD20020C"		
355443K001	"6-1192668-3"		
491861-001	"44B5131-22-MST3-9CS1728", "7-1193678-6"		
185988-001	"7-1191350-1", "44A9440-22-9/96-9CS527"		
550603K001	"3-1194345-9"		
CP1694-000	"44A0111-10-9-4-L232"		

887047-000	"4-1196901-7", "EPD40386B"		
EG5690-000	"EPD-RWC-24142-L348"		
420403K002	"2-1193167-1"		
142729K001	"3-1191033-3"		
383473-000	"3-1192875-4", "44A1131-26-9/93/96-9"		
422905-000	"8-1193184-0", "44A9586-26-9-2"		
045049-000	"1190346-8", "EPD-ROK-10023"		
829972-000	"1200289-1", "FLDWC0311-20-9CS2979"		
226865K001	"6-1191670-1"		
442183K001	"4-1193324-4"		
253753-000	"7-1191857-5", "44A9416-14-9CS1981"		
CL7163-000	"44A9748-20-9-9CS3185"		
646917K001	"2-1195108-5"		
214734K001	"8-1199130-7"		
825869K001	"9-1196450-2"		
CZ9873-000	"EPD-DND-21489"		
600759F001	"5-1194753-8"		
CB0604-000	"EPD-RWC-20080"		
475881-000	"4-1193564-1", "EPD-ADD-10071"		
CS7718-000	"EPD-RWC-22254-L099"		

CB6885-000	"EPD37262A-US-CS3207-L099"		
120375K001	"6-1190875-8"		
CM5015-000	"44A0811-20-9CS3259"		
635675-000	"44A9083-16-90CS2745BARREL", "3-1195026-3"		
973667K001	"2-1197525-1"		
CX0391-000	"44A0221-18-9/9"		
704479K002	"1195526-2"		
C35188-000	"1200371-1", "EPD-RWC-16889"		
C22476-000	"9-1200370-8", "EPD-RWC-16888"		
241987-000	"6-1191777-4", "44AM1121-22-9/93-9CS1726"		
ER6392-000	"44A0111-18-9CS3531"		
471156K001	"2-1201177-1"		
427387-000	"8-1193215-6", "44A9675-20-0/9-9CS2746"		
282625-002	"6-1192120-5", "44A0111-22-92-US"		
294597K001	"1192232-8"		
EP1356-000			
258597-000	"1191892-2", "EPD-RWC-10303"		
C62566-000	"44A1122-24-0/9-9CS358", "7-1200721-7"		

282766-000	"6-1192125-2", "44A0111-22-926-US"		
427875K001	"3-1193219-2"		
452191-000	"44B1221-24-6/9-925CS1815", "5-1193395-1"		
506344-000	"44A0711-18-9CS1354", "5-1193928-4"		
400505-000	"3-1193024-1", "EPD51033A-22-0"		
CA7738-000	"EPD-NAV-85108"		
CR9130-000	"44A0221-12-9/9C3030-1KF/1"		
306139-000	"2-1192318-8", "44AM1121-22-0/9-3"		
512405K001	"6-1194026-3"		
345717-000	"7-1192602-0", "44A9673-22-90CS2745BARREL"		
382528-000	"8-1192864-8", "44A4131-22-0/2/9-9"		
CX5292-000	"EPD-DND-21488-L016"		
694141-000	"345M06B-22-36-0CS2041", "5-1195446-6"		
CY1270-000	"EPD-DND-21508"		
181319-000	"5-1191317-9", "EPD52620A-22-0"		
429932K001	"1-1197928-6"		

767941-001	"44AM1111-22-9-90", "4-1195984-2"		
155429-000	"8-1197856-6", "44A0221-14-0/9-1KF/1"		
943521-000	"44/7004-22-9CS1059", "4-1197304-2"		
CL6669-000			
054027K001	"5-1190412-0"		
346085-000	"2-1192605-0", "FB-44-7026A-0223CS896"		
681853-000	"44A9673-22-9CS2745BAR REL", "1195360-1"		
285759-012	"8-1192162-0", "44A0111-26-9-US"		
CL4466-000	"44A9748-26-9-9CS3185"		
382924-000	"4-1192869-7", "44A0121-26-9/90-US"		
383325-000	"1201781-7", "44A0131-22-9/93/96"		
CL6860-000			
382827-000	"3-1192868-4", "44A1122-24-0/9-9-US"		
203597K001	"9-1191475-8"		
610553-000	"44AM1111-18-922-9", "3-1194828-8"		
160531K001	"2-1191159-0"		
239289-000	"8-1191758-4", "44AM1111-18-900-9"		
CP1695-000	"44A0111-10-9-5-L232"		
851591K001	"4-1196639-2"		

CN9509-000	"EPD-RWC-21749"		
CA3529-000			
123153-000	"8-1190895-0", "44/9362-22-9CS1706"		
CW7556-000			
E54762K001	"5-1200297-0"		
384958-000	"6-1192888-2", "44A7600-26-0/9"		
CY0515-000	"44B5111-12-9-9CS1401-L302"		
C56267-000	"EPD-RWC-19902"		
E23127-000	"44B1131-18-MST3-9CS3018", "6-1200111-2"		
941943-000	"44A9586-26-9", "1-1197293-8"		
666551-000	"44A1211-24-9-9CS984", "7-1195250-6"		
466115K001	"3-1193494-2"		
215213-000	"4-1191554-3", "EPD-CAN-10025"		
CF9775-000	"44A4201-22-A048-0"		
CM1060-000			
C12496K001	"6-1200354-1"		
321139-000	"7-1192433-7", "EPD-ROK-10043"		
CU6480-000	"EPD-DND-21489-L099"		
125827-000	"7-1190914-9", "44A0111-18-962"		
CY1877-000	"EPD-DND-21451"		

378271-000	"4-1192832-5", "44A0131-22-3/6/9-MX"		
282511-000	"7-1192117-3", "44A0311-14-9-US"		
545863K001	"7-1194295-9"		
285779-000	"2-1192163-7", "EPD40418A-US"		
472615K001	"8-1193540-1"		
709424-000	"44A0211-22-9-5CF/1", "9-1200090-7"		
636503-000	"44AM1121-22-0/9-2", "6-1195032-9"		
709341-000	"6-1195558-0", "FB-44-7026A-0201CS896"		
F25935-000	"44A0211-20-9CS3030", "2-1200354-8"		
412059K001	"7-1193107-6"		
CL0864-000	"44A4122-18-1/9-9CS3185"		
CS8049-000	"EPD-DND-21535-L016"		
389504-003	"7-1201439-6", "44A0161-22-0/2/3/4/6/9-US"		
837191-001	"44A9442-22-MST4-9CS527", "4-1196534-5"		
090309-000	"1190662-9", "FB-44-7026A-0217CS896"		
CA6110-000	"EPD-CAN-10019-5CF/1CS2979", "1-1899124-6"		

482171K002	"3-1193609-4"		
382928-000	"5-1192869-2", "44A0121-26-9/96"		
C78388-000	"9-1202141-8", "44A1221-16-9/96-9CS3030"		
641703-000	"7-1195071-2", "EPD-RWC-15744"		
007709-000	"7-1190059-5", "44A9586-26-9-4"		
CZ5308-000			
831121-000	"8-1196489-3", "EPD51025A-22-0"		
282657-000	"8-1192121-1", "44A0111-22-94"		
255375K001	"5-1191869-7"		
384883-000	"9-1199757-6", "44A1131-18-3/6/9-9"		
923275-000	"44A9586-26-9-1", "9-1197162-0"		
282689-002	"9-1192122-9", "44A0111-18-92-MX"		
213358-000	"2-1199656-0", "44A1221-14-9/9-9-1KF/1"		
947569-000	"44/0414-26-9CS2251", "8-1197331-2"		
062845-000	"2-1190475-8", "EPD51037A-22-0"		
175783-000	"1-1191278-6", "EPD52151A-CS2721"		

CY2223-000	"EPD-DND-21461-L016"		
C01255K001	"2-1200384-2"		
044229K001	"9-1190339-6"		
036633K001	"9-1190282-4"		
636813K001	"1-1195035-0"		
CL1329-000	"44A0811-20-9CS1465-L013"		
376865-000	"6-1192822-1", "44A0121-22-1/91"		
529509K001	"9-1197830-2"		
774479-000	"44AM1121-26-2/9-3", "1-1196031-4"		
CN2030-000	"44A1322-22-9/96-9"		
367063-000	"9-1192751-1", "EPD-RWC-14226"		
CS2960-000	"44A1141-18-ELC4-9-F871"		
CB2390-000	"FLDWC0311-24-9CS2979", "1899161-4"		
111249K001	"3-1190812-5"		
397699K001	"5-1192982-2"		
EM6445-000			
C27079-000	"8-1201917-1", "44A2111-26-9-9CS2979"		
677314-000	"44A1221-14-0/9-9-1KF/1", "6-1198781-8"		
518763K002	"4-1194071-9"		

495747K001	"7-1193707-9"		
387127-000	"44A3111-26-9-US"		
581871-000	"6-1194609-9", "EPD-RWC-10424"		
489097K001	"4-1193659-5"		
672873-000	"8-1195293-9", "EPD52742A-18-0"		
526227-000	"4-1194135-7", "EPD52979A"		
005364-000	"8-1198311-3", "44A1221-16-9/96-9"		
866117K001	"2-1196744-8"		
383341-000	"9-1192873-6", "44A1121-22-0/9-90-US"		
939896K001	"1-1199140-8"		
335111K001	"5-1192531-2"		
169343-000	"8-1191232-1", "CMC-0441-22-20-0"		
ER5143-000	"44A0111-12-9CS3529"		
EM7715-000	"EPD-RWC-22042"		
306271-000	"5-1192319-2", "44AM1121-26-6/9-9"		
080097-000	"4-1190594-9", "EPD51463A-22-6"		
488933-000	"1-1193658-5", "EPD-RWC-15761"		
911641K001	"1-1197080-4"		

168653-000	"7-1197915-6", "EPD-NAV-32502"		
387328-000	"5-1200800-2", "44A1111-22-9-96-US"		
388602-000	"1-1201147-5", "EPD100256 A-US-L099"		
CF4753-000	"44B4121-16-1/9-9CS3224"		
282836-001	"1-1192127-3", "44A0111-22-916-US"		
510839-000	"44AM1121-26-0/9-9CS984", "1-1194015-3"		
998655K001	"5-1197721-6"		
CA2935-000			
388130-000	"44A1311-12-9-9"		
376874-000	"6-1192822-6", "44A0121-22-2/92"		
D98524-000	"EPD-NAV-93319"		
A62631K001	"5-1200354-9"		
320195-000	"9-1192427-1", "EPD-RWC-15306"		
591119-000	"345M15B-22-60-0CS2041", "9-1194675-7"		
EP6373-000	"44/9186-26-0/9-9CS2251"		
375861-000	"5-1192815-0", "EPD51030A-22-0"		
386928-000	"44A0121-22-9/907"		
306354-000	"5-1192320-6", "44AM1131-22-9/93/96-9"		

941285-000	"44A9665-20-0/2/5/9-0", "2-1197288-8"		
631325K001	"6-1194995-8"		
736907K001	"8-1195753-7"		
150702-000	"1200099-3", "44B1121-22-98/901-9CS3018"		
145877-000	"4-1191054-1", "EPD-ROK-10030"		
CF5278-000	"44A2124-24-1/9-9CS3226"		
289951-000	"3-1192198-6", "44AM2111-18-9-9"		
CS0743-000	"EPD-RWC-21943"		
114137K001	"2-1190832-5"		
CA2936-000			
CA1537-000	"EPD-RWC-19733-L161"		
F30644-000	"44B1121-12-F097-9CS3018", "6-1200000-0"		
F14566K001	"7-1200354-3"		
CY7952-000	"EPD-RWC-23464-L142"		
188350K001	"3-1198852-3"		
282624-000	"6-1192120-1", "44A0111-22-928-US"		
F14413-000	"44A0111-18-921-2KF", "8-1200546-5"		
330825-000	"3-1192499-9", "CSC-0188-22-0"		

756100-000	"44A1141-22-9/92/93/96-9", "8-1199212-2"		
688004-000	"2-1195404-1", "FB-44-7026A-0239CS896"		
509773K001	"3-1194007-5"		
520699-000	"44A1121-22-9/92-9", "1-1194093-8"		
382245-002	"9-1192858-1", "44A2121-26-0/9-9-US"		
383344-000	"1-1192874-1", "44A1121-22-0/9-95"		
839731K001	"2-1196552-1"		
285084-000			
438393K001	"8-1193294-9"		
EG3832-000	"44A1321-16-9/9-9"		
CY0587-000	"FLDWC1331-16-F023-9CS2959"		
523609-000	"5-1194113-1", "EPD-RWC-15040"		
771521-000	"1-1196010-9", "EPD-RWC-15513"		
850179-000	"9-1196628-0", "EPD51160A"		
659829-000	"1-1195201-1", "EPD52162A-18-0"		
F15827K001	"7-1200354-4"		
865209K001	"1-1196738-6"		
386920-000	"44A0121-22-9/97"		

926483-000	"4-1197185-6", "EPD-RWC-13430"		
282302-000	"5-1192112-1", "44A0211-12-9-MX"		
CY1470-000	"EPD-RWC-23384"		
255591K001	"9-1191870-1"		
403307-000	"5-1193044-2", "44A7444-26-1/9-9CS009"		
C00135-000	"1-1202115-6", "EPD-RWC-19733"		
A96758-000	"2-1201692-8", "44A0111-10-9-5"		
758165-000	"6-1195907-1", "EPD-RWC-11147"		
C80066-000	"1-1201883-1", "44A0112-12-9-L095"		
348349-000	"4-1192621-4", "44A9647-14-9-MIL"		
098362K001	"7-1199501-0"		
101667K001	"1190744-9"		
3C0304-000	"2-1193002-7", "EPD5276-X-0"		
CF9906-000			
CA7493-000	"EPD-NAV-32507"		
CP1691-000	"44A0111-10-9-1-L232"		
657571-000	"1195185-7", "EPD-RWC-10817"		
730065-000	"44AM1111-18-955-9", "8-1195703-0"		
793615-000	"7-1196144-0", "EPD37112B"		

CU3974-000	"EPD-RWC-22875"		
328823-000	"5-1192486-3", "EPD-RWC-15751"		
282655-002	"6-1192121-5", "44A0111-22-905"		
128959-000	"7-1190936-2", "EPD-ROK-10024"		
282257-000	"7-1192110-8", "44A0211-16-9-MX"		
CF2182-000	"44A9605-16-9-L183"		
457813-000	"345M09A-22-48-0CS2041", "2-1193435-8"		
153963K001	"3-1191112-2"		
199599K001	"8-1191445-7"		
E42966-000	"7-1202031-2", "EPD-IRL-35503-L114"		
565058-001	"44AM1121-22-0/9-96", "1194463-3"		
EP2428-000	"EPD-RYQ-23616-L012"		
718375K002	"3-1195619-6"		
877655-000	"6-1196825-3", "EPD-RWC-14069"		
566997-000	"44AM1121-22-9/95-9CS1726", "1-1194477-0"		
770412K001	"7-1199129-6"		
652389K001	"7-1195149-3"		
052109K001	"8-1190398-7"		

988081-000	"345M15B-22-6-0CS2041", "9-1197633-8"		
692117-000	"6-1195433-7", "EPD-RWC-14214"		
257418-000	"3-1199730-2", "44A1141-22-0/2/6/9-0-US"		
CU3826-000	"EPD27724A-L099"		
EH6661-000	"EPD-DND-21972"		
327969-000	"1-1192481-4", "44A9676-22-0/2/9-9CS2746"		
CR3939-000	"EPD-RWC-22059-L009"		
F83260-000	"ASC15865A-20-0", "7-1199617-1"		
671259-000	"4-1195282-1", "EPD-RWC-15758"		
E72081-000	"4-1200571-4", "EPD4708-US-L075"		
267935-000	"5-1191977-3", "44A1831-20-3/6/9-9"		
F34059-000	"9-1201151-6", "EPD-IRL-85111"		
D42382-000	"5-1200497-3", "FLDWC1321-20-9/90-9"		
282068-000	"9-1192100-4", "44A0114-20-9"		
699747K001	"2-1195492-3"		
CF6956-000	"44AM1121-18-0/9-9CS2979", "3-1899230-2"		

308883K001	"5-1192339-6"		
CA3514-000			
191327-000	"8-1191387-1", "EPD51034A-22-0"		
303904-000	"4-1199824-1", "44A0221-14-9/9-1KF/1"		
CU4339-000	"EPD-RWC-22985"		
942470-000	"44A0111-18-9-1KF/1", "1-1199146-2"		
CB4564-000	"EPD37262A-US-L099"		
CY7948-000			
648607-000	"1195120-1", "EPD52193A-22-0"		
606416-001	"44A9416-22-9CS1981", "5-1194797-9"		
A91756-000	"44A1221-12-9/9-9CS3030", "3-1200359-8"		
C24279-000	"7-1200570-2", "EPD4694-US-L073"		
519199K001	"4-1194074-3"		
951283K001	"5-1197356-9"		
306492-000	"1192322-3", "44AM1121-22-0/9-95"		
056473K001	"9-1190429-7"		
107159K001	"6-1190782-8"		
383863-000	"3-1192879-5", "44A0131-26-0/2/9-US"		
595241-000	"4-1194707-3", "EPD51388A-22-0-F599"		

CA2764-000	"EPD-RWC-19630"		
858071-000	"44AM1144-22-3/5/6/9-9", "3-1196687-6"		
591189K001	"4-1194676-8"		
CM6005-000	"44A0221-20-9/96"		
205619-000	"1-1191490-4", "44A9436-14-9/96CS2312"		
046343-000	"9-1190355-2", "EPD51484A-22-0"		
879847-000	"1196850-2", "EPD52693A-X-0"		
279951-000	"6-1192071-6", "EPD-RWC-13838"		
386935-000	"44A0121-22-9/916"		
287045-000	"2-1192174-3", "44A0211-20-90-MX"		
840927K001	"7-1196560-9"		
205821K001	"7-1191491-7"		
C93989-000	"7-1201508-8", "44/0612-14-9CS2634"		
383345-000	"1-1192874-5", "44A1121-22-0/9-96"		
893403-000	"1196949-1", "CMC-0403-X-0"		
CW0244-000	"EPD-RWC-19936-L151"		
630881K001	"5-1194992-8"		
477735-000	"44A9665-18-0/2/5/9-0", "8-1193577-4"		

817429-000	"9-1196369-3", "EPD-RWC-13948"		
476897K001	"7-1193571-0"		
976328-000	"44A0221-16-9/9-1KF/1", "8-1199822-8"		
453451K001	"2-1193404-4"		
816541K001	"5-1196363-5"		
CS2803-000	"44A0111-12-9-F871"		
618949-000	"10525-X-8CS1405", "9-1194889-9"		
639061-000	"44A0211-22-9-1KF/1", "1-1195051-3"		
282094-009	"6-1192103-0", "44A0211-20-9-MX"		
D43594-000	"4-1201146-1", "EPD-PFM-10104-L105"		
CS7761-000	"EPD-DND-21462-L099"		
E30566-000	"7-1199874-2", "EPD37109B-US-CS2979"		
CY4264-000	"CEC-RWC-23011"		
283115-002	"4-1192131-4", "44A0111-22-96-US"		
329529-000	"1-1192491-8", "EPD-RWC-14230"		
382331-008	"6-1192861-2", "44A0121-22-0/9-MX"		
902115K001	"4-1197011-6"		

306610-000	"8-1192322-2", "44AM1141-22-0/2/6/9-9"		
732160-001	"44AM4131-22-0/2/9-9", "5-1195719-0"		
D84899-000	"3-1200594-7", "FB-44-4022-0001-L082"		
742277K001	"4-1195792-6"		
C57682-000	"1201138-4", "44A0112-12-9CS2979"		
068949K001	"4-1190519-0"		
382623-000	"2-1192866-1", "44A1122-20-0/9-9-US"		
CA6178-000			
753415K001	"8-1195873-0"		
647363-000	"44A0211-12-92", "5-1195111-2"		
CA8244-000			
368051-000	"1192759-3", "44A1821-20-6/9-9"		
CR9070-000	"44A1231-16-MST3-9CS3030"		
CS7721-000			
CS1781-000	"EPD-RWC-14917-L012"		
616781K001	"5-1194874-0"		
203672-000	"5-1198311-5", "44A1221-12-9/96-9"		
306309-000	"1192320-4", "44AM1131-18-0/2/9-9"		
EH9421-000	"EPD-RWC-14668CS2888-L365"		

037396-000	"4-1198274-8", "44AM1121-20-9/96-9CS2109"		
739247K001	"4-1195770-0"		
D86741-000	"8-1200691-2", "EPD-RWC-10945-L087"		
384107-002	"2-1192881-6", "44A1121-22-3/9-9-US"		
770373K001	"1-1196002-3"		
311529-000	"7-1192357-5", "EPD-RWC-14228"		
282102-000	"2-1192104-9", "44A0311-18-9-US"		
390348-000	"6-1198276-8", "44A0141-16-MST4CS2109"		
D80922-000	"5-1200497-9", "EPD-RWC-13838-L064"		
719505-000	"3-1195627-1", "FLDWC0311-12-9"		
857637-000	"44A9605-16-9", "1196684-4"		
397351-000	"1-1192980-3", "EPD-RWC-15762"		
576120K001	"2-1199147-0"		
CL7540-000	"44A9770-20-1/6/9-9CS3185"		
564739K001	"8-1194460-7"		
E93424K001	"2-1200809-0"		

306039-000	"3-1192317-3", "44AM1121-18-9/96-9"		
774085K001	"1196028-9"		
EP0253-000	"44A0231-16-9/9/9"		
383101-000	"3-1192871-9", "44A1231-20-0/2/9-9"		
EG5141-000	"EPD-RWC-24080"		
384998-000	"1192889-5", "44A0121-22-3/93"		
F54924-000	"7-1201860-1", "EPD101773 A-US"		
225280-001	"4-1191659-3", "44B5121-22-9/96-9CS1728"		
867417-000	"5-1196753-1", "FB-44-7026A-0229CS896"		
706113K001	"2-1195537-2"		
CU8798-000	"EPD-DND-21492-L067"		
737547-000	"6-1197860-5", "EPD-RWC-16234"		
CL9342-000	"EPD-NAV-18302"		
571283K001	"6-1194530-7"		
601735-000	"6-1194763-7", "EPD-RWC-10650"		
694917-000	"44A0124-20-0/9-US", "5-1197861-3"		
600369K001	"2-1194748-5"		
C72503K001	"3-1200524-7"		

715081-000	"1195596-2", "EPD52977A "		
CJ8590-000	"44A1321-14- 9/9-9CS3030"		
CZ4625-000			
545513-000	"44A9605-16- 97", "4- 1194293-5"		
691717-000	"9-1195430- 7", "EPD52741A- 18-0"		
826363-000	"1196455-9", "EPD64090A "		
441515K001	"8-1193319- 5"		
CS2763-000	"44A0311-14- 9-F871"		
282927-000	"1192129-7", "44A0211-20- 92"		
033197-000	"4-1190257- 4", "EPD51043A- 26-0"		
282769-000	"7-1192125- 5", "44A0111-22- 936"		
CL6672-000	"EPD-RWC- 20901"		
425671K001	"1-1193204- 2"		
846082-000	"4-1198263- 9", "EPD92660A- US"		
EG2541-000	"EPD-RWC- 23968"		
285799-000	"7-1192163- 3", "44A0111-26- 91-US"		
372345-000	"8-1192788- 7", "EPD74283A- US"		

404380-001	"4-1193052-4", "44A0114-26-9CS448"		
593633K001	"5-1194693-3"		
CU8799-000			
257767K001	"1-1191886-2"		
EM3344-000	"EPD-RWC-14668CS2888-L258"		
A26532-000	"1-1200691-3", "EPD-ROK-10332-L086"		
CP2426-000	"EPD-DND-21459-L108"		
241041K001	"8-1191770-9"		
436581-000	"8-1193281-6", "EPD-RWC-10815"		
355879K001	"5-1192671-1"		
CP2439-000	"EPD-DND-21508-L108"		
052135-000	"9-1190398-8", "44A0311-20-9CS2745"		
282758-000	"2-1192125-2", "44A0111-22-98-US"		
344695-000	"6-1192595-3", "44AM1121-22-9/94-9CS1726"		
645393-000	"44/0414-22-9CS2251", "3-1195097-3"		
276421-000	"1-1192047-6", "44A7446-26-9-9CS011"		
742211K001	"1195792-1"		
D26779-000	"44AM1121-18-0/9-9CS561", "2-1200554-8"		

610814-000	"1202041-4", "FLDWD031 1-12-9"		
384443-002	"7-1192884- 7", "44A1321- 20-0/9-9"		
694885K001	"6-1195451- 4"		
562248-000	"44B4121-22- 9/96- 9CS3018", "2- 1199950-0"		
EM4414-000			
498373K001	"2-1193726- 1"		
CL5543-000	"44A1324-24- 9/9-9"		
D02252K001	"6-1200354- 6"		
606723-000	"6-1194799- 3", "EPD43502D- US"		
517073-000	"1194060-8", "EPD-ROK- 10286"		
F36266-000	"2-1201758- 1", "345/70- 12-4-0"		
CS7986-000	"EPD-DND- 21508-L016"		
822711-000	"5-1196417- 3", "CMC- 0574-18- 0CS2327"		
353153-000	"6-1192652- 5", "FB-44- 7026A- 0220CS896"		
515375-000	"44A0819-20- 9", "8- 1194047-7"		
EG1448-000	"44A1341-16- 0/2/6/9-9"		
A65936-000	"1201691-5", "44A0111-10- 9-11"		
551741K001	"2-1194361- 2"		

386923-000	"44A0121-22-9/902"		
169789-000	"8-1191235-0", "44A0121-22-9/96CS1741"		
467469-000	"345M09B-22-38-0CS2041", "9-1193503-5"		
382234-000	"5-1192858-1", "44A1121-26-0/9-9-US"		
383384-000	"5-1192874-9", "44A1131-22-0/2/9-92"		
601488-001	"44/7004-16-9CS1059", "8-1194761-8"		
747166-000	"7-1199941-6", "EPD95433A-US"		
A75280-000	"7-1200524-1", "EPD62607A-MTI"		
656699-000	"44AM1111-18-942-9", "8-1195178-7"		
639613-000	"44A9970-14-9CS2745", "5-1195055-6"		
C22534-000	"6-1200354-3", "EPD-RWC-17603"		
306416-001	"2-1192321-1", "44AM1141-22-0/2/5/9-9"		
791181K001	"1196128-2"		
719123K001	"8-1195624-4"		
D87947K001			
099349-000	"1-1190728-1", "EPD-RWC-11685"		
839587K001	"1-1196551-4"		
565381K001	"2-1194465-2"		

CN9484-000	"345/95-12-8-0"		
CW7557-000	"EPD-DND-22784-L016"		
418391K001	"9-1193152-1"		
245444-000	"9-1199830-6", "44A9966-10-9CS2979"		
524357K001	"1194119-3"		
377477K001	"6-1192826-1"		
838545-000	"1-1196544-1", "EPD52970A"		
306144-001	"3-1192318-2", "44AM1121-22-0/9-9"		
382789-000	"9-1192867-2", "44A1121-26-6/9-9-US"		
271492-000	"2-1199140-4", "EPD-OLF-10167"		
193169K001	"2-1191401-4"		
292123-000	"7-1192214-1", "EPD-RWC-15397"		
746037-000	"44A9675-22-0/9-9CS2746", "2-1195820-6"		
111095K001	"1-1190811-0"		
D33676-000	"5-1201691-1", "44A0111-10-9-7"		
229138-000	"9-1199130-1", "EPD95158A-US"		
551795K001	"6-1194361-1"		
349336K001	"2-1201196-3"		

761159-000	"4-1195928-9", "EPD51463A-22-0"		
724720-001	"345/63B-26-84-0CS1913", "9-1195664-6"		
CS8245-000	"EPD-DND-21667-L016"		
CA8128-000	"44A0112-16-9CS3184"		
705083-000	"44A9678-22-0/9CS2747", "2-1195530-9"		
357841K002	"7-1192684-9"		
344389-000	"6-1192593-6", "EPD-ROC-10041"		
EF8115-000	"EPD-RWC-23496CS3420"		
938147-000	"7-1197267-4", "EPD38848A"		
863693-000	"2-1196726-1", "EPD8492B"		
D32329K001	"2-1200576-8"		
CS7716-000			
752085K001	"1195864-3"		
283786-000	"2-1192142-7", "44A0211-22-90-US"		
839747-000	"44AM1111-18-925-9", "3-1196552-1"		
F64419-000	"EPD-RWC-17741", "2-1200578-8"		
894855-003	"6-1197970-1", "EPD68620A-ING"		

F51863-000	"EPD-RWC-17626", "1200406-5"		
CL3969-000			
978665-000	"44A9625-12-9", "2-1197967-1"		
287573-000	"4-1192180-1", "44A0211-18-90"		
C79816K001	"9-1201447-9"		
802849K001	"7-1196206-0"		
F21409K001	"7-1200354-5"		
D63216-000	"1201782-3", "44A0211-12-9CS3030"		
306350-000	"5-1192320-0", "44AM1131-22-3/6/9-9"		
EK8979-000	"44A0311-22-9-E634"		
507423-000	"7-1193973-1", "EPD51685A-22-0CS2629"		
049085K001	"5-1190376-1"		
916713K001	"1197116-6"		
129619-000	"3-1190941-6", "EPD51417A-X-0"		
898093-000	"6-1196981-0", "EPD51070A-22-0"		
624772-000	"44A0211-18-9-1KF", "8-1199511-2"		
981947K001	"8-1197586-1"		
472141K001	"4-1193537-5"		

235355-000	"1-1191731-4", "EPD51036A-22-0"		
CJ0237-000	"EPD-RWC-16889-L191"		
953285-000	"44/0412-24-9CS1235", "7-1197381-8"		
240151K001	"8-1191764-7"		
343579-000	"2-1192588-6", "44A0111-26-9CS2896-N"		
CU8797-000			
F84011-000	"44A0211-22-9CS3030", "2-1200301-4"		
646362K001	"6-1200693-6"		
362999-000	"345M15B-22-74-0CS2041", "6-1192721-0"		
D12553-000	"6-1201493-1", "44A9605-16-93CS2979"		
387001-012	"6-1192902-5", "44A1111-22-9-9-MX"		
CM5955-000	"44AM1131-18-MST3-9CS3209"		
592945-000	"9-1194688-9", "EPD51072A-22-0"		
C77653-000	"44A0211-16-9CS3030", "6-1200301-9"		
517333-000	"8-1194061-2", "EPD-RWC-15749"		
043567K001	"7-1190334-6"		
187239-000	"2-1191359-1", "EPD-RWC-15756"		

536653-000	"5-1194212-0", "CMC-0440-22-10-2CS2320"		
CA3513-000			
628073K001	"6-1194972-9"		
779769-000	"9-1196067-7", "EPD52289A-10-0CS2749"		
392333K001	"9-1192943-2"		
098871-000	"3-1190724-7", "44AM1111-18-962-9"		
593529-000	"8-1194692-9", "EPD-RWC-14424"		
CP8076-000	"EPD-RWC-21804-L245"		
218481-000	"7-1200521-8", "ASC15865-20-0"		
300079F003	"1192273-1"		
908535-000	"3-1197057-7", "FB-44-7026A-0205CS896"		
223771-000	"4-1191648-9", "44AM1121-22-0/9-9CS561"		
CL6666-000			
382735-000	"2-1192867-6", "44A1221-22-0/9-9-MX"		
250461K001	"1191836-6"		
548533-000	"3-1194317-8", "EPD52884A-18-0"		
639582-000	"44A1711-22-9-9CS1354", "3-1195055-2"		
EK1636-000	"44A0311-24-9-E634"		

382503-000	"3-1192864-7", "44A1141-22-0/1/2/9-9"		
583265-000	"345M09B-22-14-0CS2041", "9-1194619-3"		
092795-000	"8-1190680-4", "44A9436-24-9/96CS2312"		
384765-002	"1192887-9", "44A1221-22-9/92-9"		
622511K001	"5-1194920-2"		
452149-000	"1-1193395-8", "EPD-RWC-14596"		
348866-000	"8-1200501-2", "FLDWC1331-20-9/90/92-9"		
689953-000	"1195418-3", "EPD47319A-18-0"		
090423-000	"1190663-6", "EPD-RWC-11286"		
744452-001	"44A4121-22-1/9-9CS009", "6-1195807-4"		
003993-000	"4-1190030-1", "44B1811-20-9-9CS2018"		
187231K001	"1-1191359-3"		
A03252-000	"8-1201690-2", "44A0111-10-9-9"		
815573-000	"1196356-3", "FB-44-5022-0146"		
123451K001	"8-1190897-9"		
EJ5457-000	"EPD52370A-22-0-L172"		

501533K001	"3-1193749-9"		
293251K001	"7-1192222-2"		
CF2252-000	"EPD-RWC-18798CS3092"		
CP1692-000	"44A0111-10-9-2-L232"		
EG4082-000	"44AM1131-22-MST3-9CS3209"		
285790-000	"5-1192163-4", "44A0111-26-98-US"		
222407-000	"2-1191638-8", "EPD50481A"		
CS2886-000	"44A0311-18-9-F871"		
386917-000	"9-1192901-7", "44A0121-22-9/93"		
374303-000	"5-1192803-9", "44A0141-18-0/2/6/9"		
ER6400-000	"44A0811-20-9CS3529"		
F11841-000	"44A1291-22-G073-0", "2-1200973-7"		
158379-000	"1-1191144-8", "44A9083-14-9CS2745BAR REL"		
EL5429-000	"44A1113-22-9-9"		
306274-000	"5-1192319-5", "44AM1121-26-9/96-9"		
CZ5306-000			
D68592K001	"1-1201864-5"		
562363K002	"4-1194443-6"		

801333K001	"3-1196195-1"		
801295K001	"1196195-3"		
777501-000	"4-1196052-8", "EPD51067A-22-0"		
706497K001	"6-1195539-4"		
378997-000	"7-1192835-2", "44A1151-22-2/4/5/6/9-9"		
EH7211-000	"EPD-RWC-22254-L016"		
447391-000	"1193362-9", "FB-44-4026-0007CS2245"		
536791-000	"5-1194213-6", "EPD-RWC-12643"		
211587-000	"8-1191532-1", "FB-44-24-7006CS2827"		
374135-000	"3-1192802-0", "44A3131-22-0/2/9"		
CA7492-000			
405805-000	"3-1193062-0", "44AM1121-18-6/9-9"		
907730-000	"44A9416-22-9", "3-1197051-2"		
692451K002	"9-1195435-3"		
E18349-000	"7-1202031-1", "EPD-IRL-35503-L106"		
432189-000	"7-1193250-0", "44A7389-22-0/9CS2804"		
CB6784-000	"EPD52955B-CS2979", "1899181-4"		
881217K001	"2-1196860-2"		

211143K001	"7-1191529-8"		
654795-001	"345/63B-26-48-0CS1913", "9-1195165-4"		
358488-000	"4-1199655-7", "44A1221-12-9/9-9-1KF/1"		
ER2072-000			
735473-000	"9-1195743-6", "EPD52265A-18-0"		
285789-000	"5-1192163-0", "44A0111-26-94-US"		
679281K002	"1-1195340-5"		
714899-000	"44A1131-22-9/92/96-9", "1199213-2"		
CS5230-000	"EPD-RWC-21849"		
427127K001	"8-1193213-8"		
204313-000	"9-1191480-7", "345M15B-22-48-0CS2041"		
080625-000	"3-1190598-8", "44AM1131-22-3/6/9-9CS2399"		
922483-000			
834131-000	"5-1196512-4", "EPD-ADD-10091"		
104922K001	"8-1199862-9"		
361743-000	"8-1192712-9", "EPD-CAN-10020"		
158935-000	"4-1191148-9", "EPD-RWC-15748"		

339355K001	"2-1192561-0"		
000321-000	"6-1190002-6", "345/52B-18-21-0CS1913"		
537800-000	"8-1198907-3", "FLDWC1331-20-F023-9CS2959"		
451009-000	"44A0311-18-9CS2745BARREL", "2-1193387-5"		
574109-000	"44A9586-18-9CS2897", "1-1194557-1"		
540384K001	"5-1199501-2"		
CA9801-000	"EPD-RWC-19733-L149"		
768428-001	"1-1195988-9", "FB-44-7026A-0237CS896"		
240783K001	"1191769-6"		
383493-000	"6-1192875-6", "44A1121-22-0/9-98"		
911011-000	"44A9085-14-0/9CS2747", "5-1197075-9"		
921581-000	"44A9681-20-0/9-9CS2748", "3-1197150-9"		
732467K001	"8-1195721-5"		
816382-000	"3-1197982-4", "EPD-RWC-16409"		
282353-000	"2-1192114-5", "44A0311-10-9-US", "44A0311-10-9-US"		
489197K002	"1193660-9"		

282760-002	"3-1192125-3", "44A0111-22-902"		
827257-000	"3-1196461-4", "FLDWC0311-16-9"		
160555-000	"3-1191159-4", "44B9534-22-9-9CS3023"		
D11588K001	"9-1200523-8"		
403853K001	"6-1193048-6"		
555447-000	"44A9440-22-9/96-905CS2778", "2-1194382-9"		
307099-000	"2-1192326-0", "EPD70319A-22-0"		
CY0509-000	"44B5121-12-MT29C1401-L302"		
CJ6847-000	"EPD-RWC-10438-L202"		
012765-000	"4-1190100-0", "44A0211-24-9CS2831"		
CY9209-000	"44A1231-14-0/5/9-9"		
503503K001	"6-1193789-4"		
282099-000	"1192104-5", "44A0311-24-9"		
592807K001	"9-1194687-4"		
254141K001	"6-1191860-2"		
571817-000	"44A9650-18-0/9-0", "4-1194534-5"		
669061-000	"44A1111-22-9-9CS406", "1195268-9"		

070738K001	"4-1199943-7"		
282098-002	"9-1192103-6", "44A0211-24-9-US"		
CZ5307-000			
CY1467-000			
CN3187-000	"EPD-RWC-20643"		
482431-000	"1193611-8", "EPD45287B-US"		
752635-000	"44A9089-16-0/9-9CS2746", "8-1195867-2"		
E10891-000	"44A1241-20-G090-0", "9-1200974-0"		
CB8759-000	"EPD52955B-L179CS2979", "1899194-5"		
539453-001	"44A0111-20-9CS448", "7-1194232-7"		
F36636K001	"6-1200393-7"		
144215-000	"4-1191042-3", "44AM1111-18-940-9"		
255517-000	"4-1191870-6", "EPD52142A-X-0"		
509025K001	"1194002-9"		
C34338-000	"9-1201863-3", "EPD-RWC-19387"		
A89505-000	"4-1201420-6", "EPD-IRL-35503"		
A25409-000	"3-1200501-0", "EPD62591A-MTI"		
CR3180-000	"EPD-RWC-16009-L012"		

328367-000	"5-1192483-1", "EPD37111B-US"		
054681K001	"2-1190417-9"		
347137-000	"7-1192612-9", "EPD51948A-18-0"		
364529-000	"7-1192733-6", "WXA-0165-20-90"		
311329K001	"2-1192356-9"		
285114-000			
CU4338-000			
566179-000	"44AM1121-22-9/96-9CS1726", "4-1194471-3"		
058513K001	"1-1190444-4"		
377749K001	"6-1192828-4"		
EG4311-000	"EPD-RYQ-23423-L012"		
425961K001	"9-1193205-6"		
769933K001	"2-1195999-0"		
293807K001	"6-1192226-5"		
695890-000	"44AM1111-18-922-9-1KF", "9-1198058-1"		
046073-000	"1190354-2", "EPD43503E-US"		
911109K001	"2-1197076-4"		
387022-008	"9-1192903-2", "44A1111-26-9-9-US"		
EM7786-000	"44A0321-14-9/9CS3030"		
478343K001	"9-1193581-7"		

371177K001	"5-1192780-0"		
266837-000	"6-1191969-8", "EPD-RWC-13769"		
282686-000	"8-1192122-8", "44A0111-22-935"		
932433-000	"44A0711-22-9CS1354", "4-1197227-4"		
870367K002	"7-1196774-1"		
337073-000	"1-1197907-6", "44A0111-22-9-INT"		
A74984-000	"7-1201447-9", "EPD100898 A-US-L099"		
F82687K001	"2-1202115-9"		
CJ7847-000	"44AM1121-16-9/96-9CS3209"		
CN8359-000	"44/0412-12-9CS1038"		
475821K001	"9-1193563-5"		
CF4838-000			
E90807K001	"4-1200393-0"		
842483-000	"1196572-4", "EPD52627A-22-0"		
803403K001	"1-1196211-1"		
801107-000	"8-1196193-6", "EPD43504G-US"		
777517-000	"44A9664-14-0/2/9-0", "5-1196052-8"		
512827K001	"5-1194029-5"		
634367K001	"3-1195017-8"		

721847-000	"44A9586-24-9", "2-1195644-6"		
E51876-000	"EPD-NAV-93321"		
852113K001	"1196643-7"		
414834-000	"1-1197951-5", "44A1221-12-9/96-9-1KF/1"		
913592-000	"44A0221-12-9/9-1KF/1", "7-1199822-0"		
205685K001	"6-1191490-6"		
224943K001	"9-1191656-2"		
CU8805-000	"EPD-DND-21488-L067"		
409067-000	"3-1193085-2", "44A9673-20-90CS2745BARREL"		
387385-000	"9-1192908-5", "44A1111-22-9-92-US"		
386205-000	"3-1192897-9", "44A1122-20-6/9-9"		
CN8366-000	"44/0412-22-9CS1038"		
CA0597-000	"EPD-RWC-19734-L161"		
373457K001	"3-1192797-2"		
005401-000	"2-1190041-5", "44A9673-20-9CS2745BARREL"		
975547-000	"4-1197538-4", "EPD5395-X-8CS1584"		
D05283-000	"7-1202024-3", "EPD52415A-12-0-L072"		

983435-000	"44A9964-14-9CS2514", "9-1197597-0"		
118003-000	"8-1190858-9", "44B5121-22-9/96-9CS1401"		
F45343-000	"2-1201759-2", "44A0111-12-94-1KF"		
383263-000	"9-1192872-7", "44A0121-18-0/9-MX"		
282614-000	"2-1192120-1", "44A0111-22-947"		
301086-000	"8-1192280-3", "44AM1111-26-9-9"		
391681K001	"4-1192939-2"		
903271K001	"8-1197019-4"		
CU6393-000	"EPD-CAN-10020-L099"		
155131K001	"1-1191121-5"		
CX5296-000			
282692-000	"1-1192123-6", "44A0111-18-95"		
CJ8983-000	"ASC15865-20-0-LEADED"		
383725-000	"2-1192877-8", "44A1121-26-2/9-9"		
036635-000	"9-1190282-6", "CMC-0573-18-0CS2327"		
A62685-000	"6-1200812-9", "EPD-RWC-18086"		
CA2806-000	"44A0111-18-904-2KF"		

CX1183-000	"EPD-DND-21451-L016"		
754171-000	"44AM1161-22-MST6-9", "9-1195878-7"		
EG0849-000	"44A1123-20-0/9-9"		
E43493-000	"44/7004-16-9CS1059-L102", "1-1200984-2"		
EP1355-000			
CU9607-000	"EPD-CAN-10019-L016"		
CU1046-000	"FLDWC1321-16-9/90-9CS2959"		
149077K001	"1191078-5"		
CW2534-000	"44A4121-12-9/96-9"		
672221K001	"3-1195289-3"		
035871K002	"1190277-1"		
605659-000	"345/41B-22-20-0CS1913", "1194792-2"		
A26561-000	"8-1201737-4", "EPD98877A-US"		
674201F001	"2-1195303-7"		
165603K001	"4-1191195-8"		
EP1298-000			
295894K001	"3-1199501-6"		
040683-000	"2-1190311-5", "44B5141-22-MST4-9CS1401"		
F36871-000	"1201715-4", "44A0211-16-9-2KF/1"		
504667-000	"345M09A-22-38-0CS2041", "9-1193811-9"		

308931K001	"8-1192339-2"		
274039-000	"6-1192029-1", "44AM1131-26-F207-9CS2248"		
CZ7560-000	"EPD-RWC-14915-L012"		
EP1749-000	"44A0811-20-9CS3030"		
951759-000	"44A0312-14-9-US", "1197370-5"		
290450-001	"9-1192201-9", "345M15B-22-20-0CS2041"		
A62800-000	"6-1200524-2", "EPD62609A-MTI"		
507113-000	"1197832-4", "EPD61896B-US"		
757949-000	"8-1195905-9", "EPD-ADD-10002"		
857825-000	"3-1196685-9", "EPD-RWC-15512"		
A56593K001	"5-1201073-3"		
441561-000	"1-1193320-6", "44B5131-22-MST3-9CS1401"		
074705-000	"9-1190558-9", "44AM1121-22-9/92-9CS1726"		
228623-000	"9-1191681-5", "44A9442-24-MST4-9CS527"		
285818-000	"9-1192163-8", "44A0111-26-97-US"		

155943-000	"6-1191126-4", "EPD52371A"		
E25942-000	"2-1202052-3", "EPD-CAN-10020-5CF/1CS2979"		
349257K001	"8-1192627-1"		
637229-000	"44A0111-20-9(FS)", "5-1197968-9"		
387014-000	"7-1192903-0", "44A7042-18-9-9"		
185869-000	"8-1191349-2", "EPD-RWC-10937"		
124861K001	"8-1190907-1"		
CA3531-000			
611571-000	"44A0111-18-9CS289", "9-1194835-6"		
023386-000	"6-1199501-2", "EPD-NAV-88411"		
F81802-000	"44A4221-18-6/9-0", "1201070-6"		
EM1303-000	"44A1221-14-9/9-9C3030L013"		
543641K001	"7-1194264-6"		
282761-002	"3-1192125-9", "44A0111-22-906-US"		
013021K001	"1-1190102-6"		
383071-000	"8-1192870-1", "44A7553-22-0"		
044292-000	"6-1190340-6", "44A0141-22-3/5/6/9"		

656055-000	"6-1195174-2", "EPD-RWC-14594"		
627519-000	"8-1194968-8", "44A9964-16-9"		
EK1635-000	"44A0311-20-9-E634"		
EM8552-000	"44A1221-12F985C3030-5CF/1"		
175355K001	"1191275-7"		
187647-000	"9-1191361-8", "44AM1121-22-0/9-92"		
512851K001	"7-1194029-3"		
222821-000	"5-1191641-8", "44A9587-24-9/96-9CS2337"		
666339-000	"44AM1111-18-904-9", "3-1195249-2"		
CX1606-000	"EPD-DND-21535"		
545167-000	"9-1194289-7", "EPD-RWC-13425"		
362449K001	"7-1192717-3"		
CR5076-000	"EPD-DND-21973"		
561037K001	"9-1194431-4"		
928233-000	"44B9536-22-MST3-9CS3023", "7-1197197-0"		
157607-000	"7-1191138-5", "EPD-ADD-10011"		
817153K001	"8-1196367-5"		
CB6884-000	"EPD37260A-US-CS3207-L099"		
EG4278-000	"EPD-RWC-24097-L346"		

384935-000	"44A1141-18-0/2/6/9-9-MX"		
383059-000	"6-1192870-6", "44A0131-22-0/2/9-MX"		
254507-000	"1-1191863-9", "CMC-0575-18-0CS2327"		
418753-000	"2-1193155-3", "FB-44-7024A-0203"		
417837K001	"1193149-5"		
148145K001	"7-1191070-6"		
208976-000	"3-1199818-1", "FB-44-4026-0007CS2979"		
293595-000	"1-1192225-4"		
387735-002	"9-1192911-7", "44A1311-20-9-9"		
116181K001	"3-1190846-8"		
513489-000	"4-1194034-6", "EPD-RWC-13506"		
073241-000	"4-1190548-1", "EPD52962A"		
C04276K001	"6-1200394-3"		
939685-000	"7-1197276-5", "EPD52681A-22-0"		
801253K001	"8-1196194-0"		
CZ4726-000	"EPD-RWC-23496"		
EP9201-000	"44A1321-12-9/9-9C3030L338"		
386916-000	"9-1192901-4", "44A0121-22-9/92"		

622132-000	"44AM1111-1 8-900-9- 1KF", "5- 1199379-9"		
418649K001	"6-1193154- 4"		
244321K001	"2-1191792- 6"		
797627-000	"345M12B- 26-84- 0CS2041", "6- 1196171-6"		
252847K001	"2-1191850- 8"		
572215K001	"1-1194542- 5"		
CF2250-000			
384456-000	"9-1192884- 9", "44A0121- 26-6/9-US"		
238089-000	"3-1191750- 1", "EPD- RWC-13951"		
894305-000	"1-1196955- 4", "FB-44- 0626-0001"		
604670-000	"10515-X- 8CS791", "4- 1194784-9"		
CM4418-000	"EPD29633A- US"		
281529-000	"9-1192085- 0", "EPD- RWC-15025"		
CF4677-000	"44B9530-24- 1/9-9CS3216"		
489417K001	"6-1193661- 9"		
241737K001	"3-1197909- 8"		
198613K001	"6-1191438- 5"		
977229-000	"44A9439-22- 9-9CS527", "4-1197550- 8"		
CJ3447-000	"EPD-CAN- 10019CS2979 ", "1- 1899274-5"		

539649K001	"1194234-7"		
282770-000	"8-1192125-0", "44A0111-22-948"		
CU3023-000	"44A0212-12-92"		
276095K001	"1192045-1"		
848467-000	"6-1196616-5", "EPD-RWC-14920"		
133361K001	"5-1190968-4"		
A85309-000	"5-1201073-7", "EPD-RWC-18313CS3092"		
763911-000	"5-1195947-0", "EPD51023A-22-0"		
616119-000	"44A9623-10-ELC4-9CS2746", "2-1194868-3"		
192707-000	"9-1191397-4", "EPD22878C-X-0"		
CS7725-000			
C05418-000	"3-1201692-0", "44A0111-10-9-4"		
853962-000	"44A0114-24-9CS045", "2-1196657-4"		
465607-000	"9-1193490-6", "EPD52192A-12-0"		
F11965-000	"44A0111-18-90-2KF", "8-1200546-2"		
EK7993-000	"EPD-RWC-17035-L012"		
305085K001	"1-1192310-7"		
383675-000	"9-1192876-5", "44A1121-18-2/9-9-US"		

305609-000	"1192314-9", "EPD52955B"		
E52048K001	"6-1201151-9"		
282101-003	"2-1192104-0", "44A0311-20-9-US", "44A0311-20-9-US"		
317977-000	"7-1192408-9", "44/7011-26-9CS1760"		
062351K001	"6-1190471-8"		
702946K001	"1-1198263-2"		
361999-000	"6-1192714-6", "44AM4121-22-6/9-9"		
CR3717-000	"44B5121-12-9/96-9CS1401-L050"		
751357K001	"9-1195858-1"		
381003-000	"7-1192848-2", "44A0221-14-0/9"		
194025K001	"9-1191407-2"		
645263-000	"4-1195096-1", "FB-44-7026-0225CS2527"		
871472-000	"8-1201546-0", "EPD5795"		
437401K001	"7-1193287-4"		
604761-000	"44A9678-20-0/9CS2747", "1-1194785-3"		
3W0627-000	"2-1193019-2", "EPD20023C"		
CU8795-000			
EF5981-000	"EPD-RWC-13644-L342"		

001152-000	"1-1199146-8", "EPD64686A-US"		
126240-000	"3-1199377-2", "44AM1111-18-954-9-1KF"		
733708-000	"44AM1111-18-9-9-1KF", "1200270-2"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.