



17-Feb-2022

**PCN #:** P-22-022181

**Subject :** Spec 44 and FLDW Wires

**Description of Change :** TE Connectivity is changing the sourcing and grade for PVDF resin used as insulation material for Spec 44 and FLDW Wires. This change is to an alternate grade with similar performance and characteristics.

**Reason :** Part status change. The technical assessment on alternate PVDF grade has been completed by TE's technical team and the results demonstrate similar properties and performance to the existing PVDF grades. These results are obtained through validation trials of various finished parts using the alternate grade as insulation material. No change to form, fit and function of the finished parts has been observed. Test reports on the wire characteristics can be provided upon request.

**Key Dates :**

**Contact By Date:** 28-Mar-2022

**Implementation Date:** 28-Mar-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
CX4708-000	"EPD-DND-21541"		
432189-000	"7-1193250-0", "44A7389-22-0/9CS2804"		
C92241-000	"6-1201926-6", "44A0111-16-900-L030"		
973311K001	"6-1197522-6"		
118003-000	"8-1190858-9", "44B5121-22-9/96-9CS1401"		
424023-000	"8-1193192-2", "44A0121-20-9/97CS1741"		

620977-000	"44/0411-18-9CS470", "5-1194906-6"		
D84959-000	"44A4121-16-9/90-0", "5-1200556-2"		
647991-000	"44A0121-24-9/91CS1741", "8-1195115-3"		
267843-000	"8-1191976-9", "EPD-ROK-10345"		
ER5165-000	"44AM1121-20-9/96-9CS3529"		
CU6393-000	"EPD-CAN-10020-L099"		
EG2500-000	"EPD-RWC-23951"		
682135K001	"9-1195361-7"		
D90818-000	"5-1201885-5", "44A0114-24-9-L095-US"		
E76785K001	"9-1201653-2"		
E872683001	"4-1201229-9", "44A0121-22-0/9CK0001"		
283114-000	"4-1192131-1", "44A0111-24-915-US"		
CB1389-000	"EPD-RWC-20081"		
C78388-000	"9-1202141-8", "44A1221-16-9/96-9CS3030"		
027423-000	"2-1190212-4", "EPD-ROC-10003"		
398813K001	"5-1192990-5", "EPD51412A-COB-KIT-9"		

D67436-000	"44A7241-26-9-L081", "3-1200586-3"		
285788-000	"4-1192163-4", "44A0111-26-93-US"		
887047-000	"4-1196901-7", "EPD40386B"		
CY3978-000	"EPD-RWC-20307-L314"		
694917-000	"44A0124-20-0/9-US", "5-1197861-3"		
456143-000	"44A9586-22-9", "7-1193423-0"		
F74141-000	"6-1202039-2", "CTC-0046-22-9/4-9"		
274039-000	"6-1192029-1", "44AM1131-26-F207-9CS2248"		
A76557K001	"9-1200697-1"		
A84395K001	"1200571-3"		
948603K001	"5-1197339-2"		
519743-000	"44B9537-12-MST4-9CS1728", "1194078-8"		
540384K001	"5-1199501-2"		
CZ4625-000			
947569-000	"44/0414-26-9CS2251", "8-1197331-2"		
373451-000	"2-1192797-8", "EPD48810B-24-0"		
382844-000	"4-1192868-6", "44A1124-24-6/9-9"		
EG8795-000	"400R0111-18-9"		

818048K001	"7-1200585-2"		
CN2580-000			
392457K001	"6-1192944-3"		
974307-000	"5-1197529-6", "EPD52192A-CS2749"		
CU4339-000	"EPD-RWC-22985"		
CN5826-000	"EPD96873A-US"		
CS7718-000	"EPD-RWC-22254-L099"		
565646-000	"44A9341-X-0", "9-1194466-8"		
CR8527-000			
517333-000	"8-1194061-2", "EPD-RWC-15749"		
CU9603-000	"EPD-DND-22022-L016"		
F81802-000	"44A4221-18-6/9-0", "1201070-6"		
021531K001	"2-1190167-0"		
187239-000	"2-1191359-1", "EPD-RWC-15756"		
E20527-000	"44A0121-12-9/96CS2994", "5-1200400-1"		
543641K001	"7-1194264-6"		
704479K002	"1195526-2"		
382361-000	"1-1192862-3", "44A1131-18-0/2/9-9-MX"		
013021K001	"1-1190102-6"		
383071-000	"8-1192870-1", "44A7553-22-0"		

719795-000	"1-1195629-8"		
CJ1794-000	"44A0111-20-9-7CS3144-L193", "2-1899270-2"		
189839-000	"2-1191377-5", "44A0311-20-9CS1062"		
285799-000	"7-1192163-3", "44A0111-26-91-US"		
CU3772-000			
CB7095-000	"EPD-RWC-19930"		
100239K001	"2-1190734-7"		
A75466-000	"9-1201011-4", "EPD-NAV-79121"		
797461-000	"44B1121-16-0/9-93CS2025", "5-1196170-7"		
EG3461-000	"EPD-RWC-21561-L335"		
382687-000	"6-1192866-9", "44A1221-16-0/9-9"		
306271-000	"5-1192319-2", "44AM1121-26-6/9-9"		
EK1636-000	"44A0311-24-9-E634"		
602253-000	"44A9664-12-0/2/9-0", "5-1194767-6"		
070738K001	"4-1199943-7"		
834191-000	"9-1196512-4", "EPD51208A-16-0"		
282098-002	"9-1192103-6", "44A0211-24-9-US"		
CZ3155-000			

164143K001	"7-1191184-7"		
344695-000	"6-1192595-3", "44AM1121-22-9/94-9CS1726"		
CP6420-000	"EPD-RWC-21576"		
689953-000	"1195418-3", "EPD47319A-18-0"		
CY1335-000			
C93989-000	"7-1201508-8", "44/0612-14-9CS2634"		
CY3918-000	"EPD-RWC-20306-L314"		
898565-000	"44/1414-26-9-9CS2251", "6-1196984-0"		
387240-000	"1192907-8", "44A1112-22-9-9"		
EH8639-000	"400R0311-14-9"		
360615K001	"1-1192705-0"		
383345-000	"1-1192874-5", "44A1121-22-0/9-96"		
F95858K001	"1-1199862-5"		
EG3682-000	"EPD-RYQ-23617-L087"		
562248-000	"44B4121-22-9/96-9CS3018", "2-1199950-0"		
065887-000	"9-1190496-3", "EPD51190A-16-0"		
148145K001	"7-1191070-6"		
816541K001	"5-1196363-5"		

EG4082-000	"44AM1131-22-MST3-9CS3209"		
383141-002	"7-1192871-7", "44A4121-18-0/9-9-US"		
CS2803-000	"44A0111-12-9-F871"		
CU9567-000	"EPD-RWC-22799"		
282019-049	"3-1192093-3", "44A0111-18-9-MX"		
409558K001	"2-1200287-0"		
542909K001	"6-1194258-6"		
CN5901-000			
CL4466-000	"44A9748-26-9-9CS3185"		
CZ4726-000	"EPD-RWC-23496"		
CR3658-000	"EPD-RWC-22218"		
CR6266-000	"EPD-RWC-17033-L012"		
551086K001	"1-1199950-8"		
E37291K001	"8-1200584-5"		
378013-002	"6-1192830-0", "44A7620-20-9/5-9"		
282757-000	"1-1192125-6", "44A0111-22-95"		
CF4677-000	"44B9530-24-1/9-9CS3216"		
875339K001	"3-1196809-4"		
495421K001	"3-1193705-2"		
F31927K001	"6-1200393-3"		
457143-000	"6-1193430-3", "EPD-RWC-15765"		

768709K001	"2-1195990-0"		
CB7168-000	"EPD-RWC-19933"		
CN9509-000	"EPD-RWC-21749"		
306810-000	"2-1192324-0", "44AM4121-24-0/9-9"		
C09389-000	"8-1202073-6", "44A0811-10-94-1KF"		
801333K001	"3-1196195-1"		
099349-000	"1-1190728-1", "EPD-RWC-11685"		
349952K001	"2-1198867-9"		
082747-000	"4-1190612-9", "345M09J-22-14-0CS2041"		
449781K001	"5-1193378-1"		
418391K001	"9-1193152-1"		
D23032K001	"1-1199873-5"		
C52967-000	"44AM1141-22-F003-9CS2979", "1199658-1"		
378997-000	"7-1192835-2", "44A1151-22-2/4/5/6/9-9"		
034109-000	"1-1190264-9", "44AM1191-24-A501"		
CW5082-000	"EPD-RWC-12611-L028"		
CA0207-000			
CJ1990-000	"EPD-RWC-17793CS2979", "5-1899258-6"		



260787K001	"8-1191907-4"		
C96029-000	"1-1201316-3", "44AM4821-18-6/9-9CS2994"		
898217-000	"4-1196982-7", "EPD-ROK-10343"		
A08861-000	"5-1201763-1", "EPD-RWC-17097-L022"		
061324K001	"1199502-5"		
CU8701-000	"EPD-DND-21441-L279"		
E72043K001	"1-1200694-2"		
260777-000	"7-1191907-8", "44A9440-26-9/96-9CS527"		
381003-000	"7-1192848-2", "44A0221-14-0/9"		
306307-000	"1192320-2", "44AM1131-16-9/93/96-9"		
016301K001	"5-1190127-5"		
911017-000	"6-1197075-3", "EPD50884B-24-0"		
CL6594-000	"EPD5372CS1569"		
282690-000	"1192123-4", "44A0111-18-93"		
873305-002	"9-1198253-9", "EPD32868A-US"		
A51320K001	"2-1201000-7"		
EG6067-000	"EPD-RWC-17748-L040"		
CU8795-000			

CN4744-000	"EPD48861A-US-L077"		
382396-000	"7-1192862-9", "44A0121-16-9/9-MX"		
641703-000	"7-1195071-2", "EPD-RWC-15744"		
CW9667-000			
552821-000	"1194369-7", "EPD4755D"		
EK3794-000	"EPD-RWC-24452"		
565913K001	"7-1197828-1"		
737547-000	"6-1197860-5", "EPD-RWC-16234"		
CP1694-000	"44A0111-10-9-4-L232"		
361239K001	"3-1192709-1"		
382252-000	"1192859-7", "44A1131-22-0/1/9-9"		
CS5207-000	"EPD-ROK-10545-L106"		
CP7516-000	"44A1131-16-2/2/9-9-US"		
CX2062-000			
395845K001	"4-1192969-2"		
504213-000	"4-1193808-9", "EPD23778A"		
165610-000	"4-1199385-1", "44A0111-18-964-2KF"		
CW0105-000	"EPD-RWC-19984-5CF/1"		
CN5814-000			
902861K001	"5-1197016-7"		
E74258-000	"3-1201692-7", "44A0111-10-9-3"		

D76255-000	"2-1201380-4", "EPD-RWC-18486"		
240151K001	"8-1191764-7"		
886579K001	"8-1196897-7"		
162545-000	"4-1191173-4", "44A7715-22-0CS2230"		
282618-000	"3-1192120-4", "44A0111-22-938"		
280795-000	"8-1192078-8", "44/7004-20-9"		
923652-000	"5-1197165-6", "EPD8471B-US"		
119621-000	"3-1190870-5", "44AM1141-20-MSL4-9CS1663"		
124861K001	"8-1190907-1"		
364107-000	"1192730-4", "44AM1121-16-25/9-9"		
848439K001	"4-1196616-8"		
973667K001	"2-1197525-1"		
CR9509-000	"44A1821-18-0/9-3"		
EG3681-000			
518763K002	"4-1194071-9"		
A00173K001	"2-1199643-5"		
D27468-000	"3-1200690-8", "EPD-RWC-17882"		
936655-000	"44A0821-12-90/94", "4-1197256-0"		

656055-000	"6-1195174-2", "EPD-RWC-14594"		
CZ6931-000			
743041-000	"44AM1111-16-925-9", "7-1195797-2"		
518023-000	"1-1199930-6", "EPD91413A"		
382562-000	"3-1192865-4", "44A0131-20-0/2/9-MX"		
902491K001	"9-1197013-6"		
382307-000	"6-1192860-8", "44A1131-12-0/2/9-9-US"		
848229-000	"44/0424-20-0/9", "9-1196614-5"		
CW4837-000	"EPD-RWC-20162-L009"		
EP1356-000			
EK9471-000			
C41241K001	"4-1200595-1"		
506344-000	"44A0711-18-9CS1354", "5-1193928-4"		
306419-000	"2-1192321-4", "44AM1141-22-2/5/6/9-3"		
242377K001	"2-1191779-0"		
A25403K001	"3-1200579-2"		
277935-000	"1-1192058-4", "EPD-RSL-10002"		
CN2361-000			
258225-000	"4-1191889-9", "44A7690-22-0CS2231"		
CN6848-000			

107977-000	"8-1190788-0", "44/7006-26-9CS2491"		
D53560K001	"8-1200579-5"		
746037-000	"44A9675-22-0/9-9CS2746", "2-1195820-6"		
690403K001	"2-1195421-3"		
094325-000	"2-1190691-5", "44AM1121-16-0/9-9CS1702"		
390348-000	"6-1198276-8", "44A0141-16-MST4CS2109"		
240156-000	"1-1197976-9", "EPD-ROC-10066"		
E10891-000	"44A1241-20-G090-0", "9-1200974-0"		
C94229K001	"4-1200809-7"		
849315-000	"44/2454-26-F150-9CS024", "6-1196622-3"		
CM2859-000	"44B1141-12-0/1/4/9-9"		
EP6373-000	"44/9186-26-0/9-9CS2251"		
253431-001	"5-1191855-6", "44A9441-26-MST3-9CS527"		
CX8760-000			
226981K001	"3-1191671-3"		
363369-000	"7-1192724-7", "EPD51059A-18-0"		
CF3716-000			

397903-000	"1192984-5", "EPD-RWC-13544"		
A89505-000	"4-1201420-6", "EPD-IRL-35503"		
836299K001	"2-1196528-6"		
387012-000	"5-1192903-6", "44A1111-18-9-9"		
A71325-000	"9-1200406-9", "EPD-RWC-17031"		
282039-017	"6-1192097-9", "44A0111-22-9-MX"		
CS2962-000	"44A1141-20-ELC4-9-F871"		
688004-000	"2-1195404-1", "FB-44-7026A-0239CS896"		
374700-000	"2-1192806-9", "44A9089-16-0/9-9"		
ER6400-000	"44A0811-20-9CS3529"		
195657-000	"3-1197846-6", "44A1851-20-0/2/4/6/9-9"		
227313K001	"3-1191673-5"		
947973-000	"44AM1121-22-0/9-93", "2-1199509-2"		
280123-000	"2-1192073-7", "44/7004-26-9"		
E97224K001	"6-1200764-4"		
CS2762-000	"44A4121-18-0/9-9-F871"		
CR1756-000	"44A0111-20-9-L050"		

579419-000	"44A2124-26-0/9-9CS457", "6-1194592-3"		
926483-000	"4-1197185-6", "EPD-RWC-13430"		
F114063001	"44A0111-12-9CK0001", "8-1200989-0"		
524886-000	"345/31B-16-4-0", "7-1194122-2"		
275061-000	"3-1192037-1", "EPD-ROC-10010"		
888429K001	"5-1196911-5"		
A96758-000	"2-1201692-8", "44A0111-10-9-5"		
921251-000	"44AM1121-16-9/925-9", "1197148-7"		
343543K001	"9-1192587-9"		
268233K001	"5-1191979-8"		
EH2501-000	"44A9089-16-0/9-9CS3433"		
376686-000	"1192821-3", "44A0121-16-9/90"		
E18349-000	"7-1202031-1", "EPD-IRL-35503-L106"		
204545-000	"4-1191482-6", "EPD-ADD-10090"		
545863K001	"7-1194295-9"		
261261-000	"7-1191912-9", "44A9083-16-9-US"		
041639-000	"1190319-5", "EPD51064A-18-0"		

279624-000	"9-1199170-8", "EPD-RWC-11178"		
EM7442-000	"44A1121-20-9/928-9"		
E06825-000	"8-1201381-0", "EPD-EXP-18488"		
973697-000	"7-1201747-0", "44AM4141-20-0/2/5/9-9"		
A94684-000	"5-1201860-9", "EPD101677 A-US"		
F13375K001	"2-1200584-0"		
735473-000	"9-1195743-6", "EPD52265A-18-0"		
224755-000	"5-1191655-9", "345/31-14-4-0CS1913"		
A21391-000	"5-1200354-7", "EPD-RWC-17601"		
427919-000	"5-1193219-7", "44/1424-24-9/96-9"		
064273-000	"7-1190485-6", "EPD52416A-L151"		
282692-000	"1-1192123-6", "44A0111-18-95"		
247361K001	"3-1191814-4"		
193281-000	"2-1191402-2", "44A9087-16-0/2/9/90"		
CM2771-000	"44B1121-12-0/9-9"		
134845K001	"9-1190979-0"		
E94604K001	"1200711-5"		



F51863-000	"EPD-RWC-17626", "1200406-5"		
CS7461-000	"EPD-DND-21441-L099"		
E85781K001	"3-1200393-9"		
C27792-000	"7-1200571-3", "EPD-RWC-17032"		
722481-000	"7-1195648-5", "EPD-ADD-10088"		
538811K001	"5-1194228-5"		
513407-000	"7-1194033-9", "EPD69889A-US"		
403855-000	"6-1193048-7", "44A7657-22-2/9CS1574"		
257418-000	"3-1199730-2", "44A1141-22-0/2/6/9-0-US"		
EG2509-000			
105323-000	"9-1190769-3", "EPD-RWC-12005"		
012091-000	"4-1190095-8", "44A9650-12-0/9-0"		
703818K001	"1-1199140-5"		
349041K001	"2-1192626-7"		
A56593K001	"5-1201073-3"		
285792-000	"6-1192163-3", "44A0111-26-92-US"		
972749-000	"44B1143-16-0/2/5/9-8", "5-1197518-5"		
103006-000	"6-1190753-8", "44/0424-26-6/9"		

D43056-000	"44/7360-26-9CS2979", "1-1199662-6"		
CJ7990-000	"EPD-RWC-20678"		
738367-000	"1195764-9", "EPD-RWC-14739"		
CU7740-000	"EPD-DND-22861-L277"		
CY0513-000	"44B5121-20-MT29C1401-L302"		
CA7739-000			
466715K001	"3-1193498-6"		
551885K001	"2-1194362-0"		
306031-000	"2-1192317-7", "44AM1121-18-0/9-9"		
D40904K001	"1200594-7"		
061901K001	"1-1190468-9"		
218481-000	"7-1200521-8", "ASC15865-20-0"		
EG5963-000			
ER5143-000	"44A0111-12-9CS3529"		
531320-000	"44B1121-24-0/9-95CS2024", "5-1194172-5"		
C26844-000	"4-1201185-0", "EPD100257 B-US-L099"		
400505-000	"3-1193024-1", "EPD51033A-22-0"		
982284-000	"44A7434-20-9/5CS2979", "1-1199826-7"		

CB7274-000	"EPD-RWC-19940"		
383333-000	"8-1192873-5", "44A1121-20-0/9-93"		
080097-000	"4-1190594-9", "EPD51463A-22-6"		
095465K001	"8-1190699-7"		
CB6878-000	"EPD-RWC-15185CS3207-L099"		
645393-000	"44/0414-22-9CS2251", "3-1195097-3"		
043833-000	"9-1197969-6", "44A0111-24-9(FS)"		
CM2011-000	"44A0711-18-93"		
921649-000	"1197151-1", "EPD-RWC-14793CS2832"		
ER1220-000			
CZ1119-000	"EPD-DND-23478"		
CL6591-000			
824012K001	"3-1199953-2"		
382002-000	"9-1192855-2", "44A1121-22-9/9-9"		
EL6427-000	"44AM1131-20-0/2/9-9CS3451"		
940855-000	"1-1197285-4", "EPD-RWC-15750"		
CA2350-000	"EPD-RWC-19791"		
C05080K001	"1201139-4"		
CY2851-000			
CA2936-000			
293807K001	"6-1192226-5"		

CP4318-000	"44B1121-12-927/928-9C3018"		
E04733-000	"5-1200931-3", "EPD74451A-US"		
418649K001	"6-1193154-4"		
C27695K001	"1-1200588-4"		
277566K001	"3-1198867-9"		
893777K001	"5-1196951-9"		
F11841-000	"44A1291-22-G073-0", "2-1200973-7"		
875386-001	"44A0111-22-9CS289", "6-1196809-7"		
183659K001	"9-1191333-8"		
CF1043-000			
913303-000	"5-1197091-9", "EPD-RWC-15043"		
742277K001	"4-1195792-6"		
605151K001	"2-1194788-5"		
659829-000	"1-1195201-1", "EPD52162A-18-0"		
D96049-000	"4-1201700-4", "44AM1111-16-920-9-1KF"		
CL1435-000			
411957-000	"8-1193106-9", "EPD52631A-16-0"		
562363K002	"4-1194443-6"		
CW7556-000			

900811-000	"44A0121-20-9/95CS1741", "1197002-6"		
622507-000	"4-1194920-9", "EPD-RWC-14756"		
EF6529-000	"EPD-RWC-23882"		
734699-000	"44/1421-24-2/9-9", "1-1195738-8"		
384098-000	"2-1192881-0", "44A1121-24-9/96-9-MX"		
447391-000	"1193362-9", "FB-44-4026-0007CS2245"		
F33372-000	"EPD-ROK-10373-L004", "2-1200556-1"		
280814-000	"4-1192079-2", "44/7004-24-9"		
271492-000	"2-1199140-4", "EPD-OLF-10167"		
270149-000	"3-1191997-7", "44/0611-20-9"		
405805-000	"3-1193062-0", "44AM1121-18-6/9-9"		
CS8529-000	"EPD-DND-21972-L016"		
709424-000	"44A0211-22-9-5CF/1", "9-1200090-7"		
636503-000	"44AM1121-22-0/9-2", "6-1195032-9"		
EP7160-000	"CEC-RWC-25439-L227"		
EH9622-000			
344389-000	"6-1192593-6", "EPD-ROC-10041"		

582235-000	"5-1194612-5", "EPD61790A"		
679281K002	"1-1195340-5"		
871472-000	"8-1201546-0", "EPD5795"		
383725-000	"2-1192877-8", "44A1121-26-2/9-9"		
565058-001	"44AM1121-22-0/9-96", "1194463-3"		
CM1057-000	"EPD4665D-IRL"		
204313-000	"9-1191480-7", "345M15B-22-48-0CS2041"		
CB8619-000			
877655-000	"6-1196825-3", "EPD-RWC-14069"		
746881K001	"9-1195826-3"		
225280-001	"4-1191659-3", "44B5121-22-9/96-9CS1728"		
000321-000	"6-1190002-6", "345/52B-18-21-0CS1913"		
533119-000	"6-1194185-6", "CMC-0577-18-0CS2327"		
672221K001	"3-1195289-3"		
365213-000	"9-1192738-0", "44AM1111-18-921-9"		
900161-000	"2-1196997-1", "EPD44226A-US"		

CP6418-000	"EPD-RWC-21574"		
804283K001	"4-1196217-4"		
383487-000	"5-1192875-3", "44A1121-20-0/9-95"		
497283K001	"1-1193718-6"		
507423-000	"7-1193973-1", "EPD51685A-22-0CS2629"		
608205-000	"7-1194810-8", "CMC-0572-18-0CS2327"		
445158-000	"10515-X-8", "5-1193345-8"		
EG2543-000	"EPD-RWC-23969"		
699747K001	"2-1195492-3"		
CP3572-000			
EL6823-000	"44A1821-12-2/9-0"		
CX1597-000	"EPD-DND-22560"		
370808-000	"6-1192777-8", "44/1421-24-9/9-9"		
EG7206-000	"44A0121-22-9/938"		
CM2012-000	"44A0711-18-97"		
D12553-000	"6-1201493-1", "44A9605-16-93CS2979"		
945966-000	"4-1199199-3", "EPD-ROK-10376"		
A85427-000	"5-1200943-7", "EPD21145B-US"		

635675-000	"44A9083-16-90CS2745BARREL", "3-1195026-3"		
559957-000	"3-1194419-6", "EPD-ROC-10006"		
718616K001	"1201219-9"		
719246-000	"44A4141-12-0/2/5/9-9", "6-1199207-2"		
260447K001	"6-1191905-0"		
CS2760-000	"44A4121-16-0/9-9-F871"		
389764-000	"6-1192925-1", "44A1121-26-2/9-3"		
398869K001	"8-1192990-6"		
387127-000	"44A3111-26-9-US"		
C22476-000	"9-1200370-8", "EPD-RWC-16888"		
EH2503-000	"44A9090-16-0/2/9-9CS3433"		
CJ6249-000	"EPD4761C-IRL"		
593633K001	"5-1194693-3"		
232257K001	"2-1191706-0"		
367886-000	"5-1199499-8", "EPD-NAV-88409"		
368061-002	"2-1192759-0", "44A7434-20-9/5"		
EG7275-000	"44A0121-22-9/923"		
565228K001	"7-1200089-2"		
EH8651-000	"400R0311-26-9"		
436581-000	"8-1193281-6", "EPD-RWC-10815"		



919079-000	"44/9093-24-9-9CS1222", "4-1197132-1"		
306302-000	"9-1192319-1", "44AM1131-12-9/93/96-9"		
EF4912-000	"EPD-RWC-19984-L319"		
292123-000	"7-1192214-1", "EPD-RWC-15397"		
359543-000	"5-1192697-3", "44AM1151-24-A002"		
CX8628-000	"EPD-DND-23325"		
CW0111-000	"EPD-RWC-19929-L320"		
758789K001	"1-1195912-0"		
C66149K001	"8-1201379-1"		
CU3773-000	"EPD27738A-L099"		
EM8269-000			
694141-000	"345M06B-22-36-0CS2041", "5-1195446-6"		
EG3687-000			
630881K001	"5-1194992-8"		
CZ7671-000	"EPD-RWC-22257"		
166336K001	"1-1200279-9"		
EP2910-000	"EPD-RWC-13288-L012"		
232588K001	"9-1197925-0"		
328269K001	"9-1192482-5"		
153906-000	"9-1191111-5", "EPD6747-20-0"		

D41556K001	"2-1200805-6"		
EG8836-000	"400R1121-24-0/9-9"		
CJ3573-000	"EPD-RWC-19930-L195"		
619433K001	"4-1194893-9"		
790651K001	"1-1196124-6"		
609465-000	"5-1194819-8", "EPD52291A-14-0"		
CX1603-000	"EPD-DND-21485"		
241269K001	"6-1191772-0"		
664823-000	"6-1195238-6", "EPD51051A-18-0"		
756100-000	"44A1141-22-9/92/93/96-9", "8-1199212-2"		
572215K001	"1-1194542-5"		
CF2250-000			
509773K001	"3-1194007-5"		
CX8421-000			
CS1830-000	"EPD-NAV-79117-L012"		
282686-000	"8-1192122-8", "44A0111-22-935"		
826509K001	"1196456-6"		
870367K002	"7-1196774-1"		
198613K001	"6-1191438-5"		
384917-000	"1-1192888-6", "44A0121-16-9/96"		
CA9976-000	"EPD-RWC-19735-L149"		

EP5917-000	"44A0221-22-9/9CS3030"		
364411-000	"4-1192732-1", "44A1131-20-9/93/96-0"		
838535-000	"44/2441-26-F156-9CS1506", "1196544-4"		
733524-000	"44B1111-20-9-9CS3018", "8-1199950-4"		
385517-000	"6-1192892-7", "44A0124-24-6/9"		
475821K001	"9-1193563-5"		
031577K001	"1190245-1"		
384057-000	"8-1192880-1", "44A4121-24-1/9-9"		
C31648K001	"1-1200693-1"		
705189-000	"44AM1121-16-6/9-0F897", "1195531-1"		
A85309-000	"5-1201073-7", "EPD-RWC-18313CS3092"		
CU4073-000	"EPD100167 A-US"		
754399-000	"1195881-2", "EPD52957A"		
382589-000	"7-1192865-5", "44A7428-X-0"		
306309-000	"1192320-4", "44AM1131-18-0/2/9-9"		
556432K001	"1-1198255-6"		
EP9990-000	"EPD-RWC-19813-L021"		
407627K001	"1193075-9"		

751855-000	"4-1195862-7", "EPD52974A"		
C32442K001	"4-1200403-8"		
370088-000	"2-1192773-1", "44/2421-24-9/9-9"		
359729K001	"1-1192699-7"		
230451K001	"4-1191693-9"		
CW5040-000			
834353K001	"2-1196514-5"		
CU6390-000	"EPD-DND-22841"		
279181K001	"4-1192066-4"		
051146-000	"7-1190391-0", "44A1114-24-9-9CS448"		
406433K001	"5-1193066-9"		
194025K001	"9-1191407-2"		
CR3173-000	"EPD-RWC-17030-L012"		
049571-000	"8-1190379-0", "EPD51016A-20-0"		
CA9990-000			
418885K001	"1-1193156-7"		
A72853-000	"44A0111-18-940-2KF", "1-1200547-2"		
376605-000	"44A0321-24-0/9"		
478178-000	"5-1201758-2", "44A0111-12-92-1KF"		
CU8798-000	"EPD-DND-21492-L067"		

CD49703001	"44A0111-18-9(B01)", "2-1899330-5"		
534305-000	"44A9440-12-9/96-9CS527", "1-1194194-2"		
375211-002	"9-1192810-6", "44/2414-26-9-9"		
EG7217-000	"44A0121-22-9/978"		
711585-000	"7-1195574-0", "EPD86151A"		
CM1777-000			
CJ1797-000	"44A0111-22-9-9CS3144-L193", "2-1899270-4"		
CX5539-000	"EPD-RWC-20307-L295"		
763223K001	"9-1195942-2"		
CW5042-000			
EM0456-000			
025568-000	"3-1190198-9", "44B1121-24-0/9-91CS2024"		
CZ2510-000	"EPD-DND-21746-L016"		
613646-000	"44B4121-24-9/96-9CS3018", "2-1199954-8"		
100505K001	"1190736-6"		
CY2223-000	"EPD-DND-21461-L016"		
EG7209-000	"44A0121-22-9/947"		
113496-000	"4-1200162-7", "EPD-RWC-16771"		
187957-000	"1-1191364-3", "44/2422-20-9/96-9"		

F94083K001	"9-1200815-3"		
CJ2064-000	"EPD-RWC-17775CS2979", "6-1899258-1"		
EH1443-000	"44A0811-10-922-1KF"		
CJ2061-000	"EPD-RWC-17746CS2979", "6-1899258-2"		
CX1366-000			
206853-000	"5-1191499-7", "EPD-RWC-15763"		
F80785-000	"EPD62598A-MTI", "6-1200500-7"		
935173-000	"44A1811-10-90-9", "1-1197246-8"		
E44752K001	"8-1200592-9"		
384893-000	"9-1192887-2", "44A0131-20-9/93/96"		
631711-000	"44AM1131-20-0/2/9-9CS561", "5-1194998-8"		
EM4417-000			
CR6260-000	"EPD-RWC-17031-L012"		
280985K001	"9-1192080-1"		
177030-000	"8-1197951-8", "44A1221-16-9/96-9-1KF/1"		
C46472-000	"6-1200354-4", "EPD-RWC-17607"		
CW9140-000			
779769-000	"9-1196067-7", "EPD52289A-10-0CS2749"		

620637-000	"2-1194904-8", "EPD-RWC-15358"		
301015-000	"8-1192279-5", "44AM1111-16-9-9"		
217437-000	"1191587-4", "44A1111-20-9-9-5CF/1"		
383341-000	"9-1192873-6", "44A1121-22-0/9-90-US"		
003744K001	"1199954-8"		
F81869K001	"3-1200584-3"		
CN6735-000			
CP2177-000	"EPD-DND-21478-L108"		
306409-000	"1-1192321-1", "44AM1141-20-0/2/5/9-9"		
773975-000	"2-1196027-9", "CSC-0215-18-0"		
D46711K001	"6-1200354-8"		
CM2537-000			
922513-000	"44AM1131-16-90/900/92-9", "4-1197157-8"		
944541K001	"2-1197311-4"		
473767-000	"44A9674-18-9-9CS2746", "4-1193549-1"		
111095K001	"1-1190811-0"		
116139-000	"1190846-3", "EPD-ROC-10058"		
D90804-000	"1-1201721-0", "44/7004-26-9CS2979"		

384104-000	"2-1192881-4", "44A1124-26-9/96-9"		
197719K001	"1191433-4"		
383059-000	"6-1192870-6", "44A0131-22-0/2/9-MX"		
EH7672-000			
052387-000	"6-1190400-0", "EPD-CAN-10018"		
024667-000	"2-1190191-1", "44AM1141-20-3/5/6/9-9"		
CS7486-000	"EPD-DND-21451-L099"		
EG7201-000	"44A0121-22-9/928"		
822181-000	"1196412-5", "EPD51080A-22-0"		
282788-000	"4-1192126-6", "44A0111-24-907-US"		
CF2252-000	"EPD-RWC-18798CS3092"		
556403K001	"3-1194389-6"		
101287K001	"4-1190741-2"		
336375-000	"8-1192539-7", "44AM3121-22-9/92"		
958182K001	"5-1201236-1"		
CU7812-000	"EPD-DND-21483-L016"		
A54184-000	"1-1202066-6", "44AM1181-22-MST8-9CS2994"		
215843-000	"9-1191558-4", "44AM1111-16-905-9"		



073241-000	"4-1190548-1", "EPD52962A"		
425961K001	"9-1193205-6"		
A64391K001	"3-1200585-9"		
177393-000	"4-1191289-5", "44B1121-24-0/9-902CS2024"		
CY7952-000	"EPD-RWC-23464-L142"		
A75323K001	"4-1200173-6"		
797627-000	"345M12B-26-84-0CS2041", "6-1196171-6"		
536234K001	"2-1198846-3"		
262196-000			
007673K001	"4-1190059-6"		
584675K001	"9-1194629-6"		
478343K001	"9-1193581-7"		
141251-000	"8-1191023-2", "EPD-ROK-10036"		
CR3729-000	"EPD-RWC-21559"		
241737K001	"3-1197909-8"		
850179-000	"9-1196628-0", "EPD51160A"		
F23508-000	"1-1201555-5", "44A1131-20-9/9/9-9CS2976"		
373005-000	"2-1199909-1", "44A1821-24-0/9-9-US"		
133361K001	"5-1190968-4"		

F85037-000	"1202115-2", "44A9550-20- 9-US"		
501065K001	"4-1193746- 2"		
CA8108-000	"EPD-RWC- 15187-L099"		
861181K001	"3-1196709- 6"		
770695K001	"2-1196004- 7"		
F69455-000	"5-1201566- 2", "EPD- ROK-10543"		
C86457-000	"44A0811-10- 904-1KF", "3- 1200547-1"		
897982K001	"5-1201141- 8"		
984099K001	"7-1197602- 9"		
CS7707-000			
EG7279-000	"44A0121-22- 9/908"		
189998-000	"3-1191378- 4", "44B1111- 24-9- 94CS1271"		
382432-011	"3-1192863- 2", "44A1121- 18-0/9-9-MX"		
CU8794-000	"EPD-DND- 21447-L281"		
CB1712-000			
A95269K001	"7-1200629- 8"		
368757K001	"6-1192763- 3"		
CB6883-000	"EPD37259A- US-CS3207- L099"		
CJ1815-000	"44A0111-22- 9- 23CS3144L19 3", "3- 1899270-8"		
EP4151-000	"44B9202-X- 9-L072"		

086318-000	"9-1190636-9", "44/2411-24-90-9CS1506"		
517813-000	"1194065-8", "CMC-0201-0CS2775"		
E05730-000	"1200269-5", "EPD-RWC-17212"		
299691-000	"6-1192268-2", "44AM1121-20-9/9-9"		
909367-000	"6-1197063-4", "EPD52733A-14-0"		
CA6110-000	"EPD-CAN-10019-5CF/1CS2979", "1-1899124-6"		
834131-000	"5-1196512-4", "EPD-ADD-10091"		
566997-000	"44AM1121-22-9/95-9CS1726", "1-1194477-0"		
929435-000	"44AM1111-20-9-9CS2399", "7-1197205-7"		
052109K001	"8-1190398-7"		
CF5370-000	"44A4121-16-1/9-9CS3231"		
355443K001	"6-1192668-3"		
185988-001	"7-1191350-1", "44A9440-22-9/96-9CS527"		
181165K001	"4-1191316-5"		
378394K001	"6-1200587-0"		
481873-000	"44AM1131-24-MST3-9CS2109", "1193607-5"		

929001-000	"8-1197202-9", "EPD-ROC-10012"		
E73392K001	"9-1201270-5"		
EG8789-000	"400R0111-12-9"		
212887K001	"5-1191539-5"		
378197K001	"9-1192831-5"		
A66586-000	"4-1200939-4", "EPD-RWC-18109CS1663"		
213358-000	"2-1199656-0", "44A1221-14-9/9-9-1KF/1"		
CR6521-000			
290450-001	"9-1192201-9", "345M15B-22-20-0CS2041"		
CU4068-000			
E77220K001	"1200691-3"		
473439-000	"1193547-4", "EPD-ROC-10040"		
415107-000	"7-1193128-7", "44/0434-26-0/2/9CS2537"		
C19075K001	"3-1201282-2"		
CR2012-000	"44A9605-18-9"		
911011-000	"44A9085-14-0/9CS2747", "5-1197075-9"		
896750-000	"7-1199502-9", "EPD-RWC-17097-L338"		
EG2640-000			

726959-000	"44A9970-14-9CS2745BAR REL", "8-1195681-0"		
F43994-000	"5-1201417-9", "EPD-RWC-18522CS3127-L119"		
D72756K001			
CF8502-000	"EPD-RWC-20334"		
049102K001	"5-1199947-8"		
465244-000	"44AM1111-16-906-9-1KF", "2-1199383-0"		
EM9796-000	"44A0111-22-9CS3030"		
382243-015	"6-1192858-9", "44A1121-24-0/9-9-MX"		
CY6749-000	"EPD-DND-21491"		
CU3940-000			
D63862-000	"EPD8780B-US"		
784878-000	"7-1199420-0", "EPD-REA-10010-18"		
592927-000	"8-1194688-3", "EPD52734A-10-0"		
375028-002	"5-1192809-8", "44/1411-24-9-9"		
265898-000	"1191963-1", "44A0811-10-92"		
951283K001	"5-1197356-9"		
282761-002	"3-1192125-9", "44A0111-22-906-US"		

A87321-000	"4-1201926-0", "44A0111-16-924-L030"		
CA2764-000	"EPD-RWC-19630"		
241987-000	"6-1191777-4", "44AM1121-22-9/93-9CS1726"		
CZ6922-000	"EPD-RYQ-23554"		
336245-000	"1192539-7", "44B1121-16-0/9-9"		
CJ3953-000	"44A9749-24-1/9-9CS3185"		
254141K001	"6-1191860-2"		
548533-000	"3-1194317-8", "EPD52884A-18-0"		
427875K001	"3-1193219-2"		
782197-000	"5-1196075-5", "44AM4121-24-0/9-9CS262"		
884399K001	"8-1196882-6"		
315566-000	"6-1199421-6", "EPD-REA-10010"		
345717-000	"7-1192602-0", "44A9673-22-90CS2745BARREL"		
157607-000	"7-1191138-5", "EPD-ADD-10011"		
CJ3703-000			
C91290K001	"9-1200626-3"		
801482K001	"1-1199140-6"		

311529-000	"7-1192357-5", "EPD-RWC-14228"		
321219K001	"3-1192434-8"		
573674-001	"7-1194553-9", "EPD23571B"		
CF3430-000	"44AM1131-22-MST3-9CS2994", "7-1899210-1"		
446987-000	"345/34-16-7-0CS2026", "3-1193359-5"		
752635-000	"44A9089-16-0/9-9CS2746", "8-1195867-2"		
CB4821-000	"EPD-RWC-20268-L172"		
CP1570-000	"44A0711-16-9CS3030"		
CB9481-000	"EPD43500G-US-CS3210", "9-1899196-2"		
678629-000	"7-1195334-9", "EPD-RWC-15766"		
D73525K001	"9-1200628-3"		
EK9473-000	"EPD-RWC-24328"		
382409-000	"1192863-5", "44A0131-16-3/6/9"		
617331K001	"8-1194878-0"		
880617-000	"7-1196855-8", "EPD-RYM-79118"		
EG0359-000	"EPD-RWC-22225-L012"		
954469-000	"44/2431-26-F023-9CS1506", "1197390-6"		
ER6271-000	"44AM1111-20-9-9CS3529"		

CS7986-000	"EPD-DND-21508-L016"		
639061-000	"44A0211-22-9-1KF/1", "1-1195051-3"		
285114-000			
D43594-000	"4-1201146-1", "EPD-PFM-10104-L105"		
114137K001	"2-1190832-5"		
EG8822-000	"400R1121-10-0/9-9"		
054649-000	"1190417-3", "EPD32071B-US"		
CJ3140-000	"345/M02J-14-3-0CS2041"		
282624-000	"6-1192120-1", "44A0111-22-928-US"		
EH8643-000	"400R0311-18-9"		
265015-000			
270083-000	"4-1191996-9", "44/0412-16-9"		
380902-000	"3-1200236-8", "44A0111-12-9-L038"		
425926-000	"8-1200266-8", "EPD-RWC-17206"		
371177K001	"5-1192780-0"		
778763K001	"1-1196061-9"		
876717K001	"4-1196819-2"		
545849K001	"6-1194295-8"		
299055-000	"2-1192264-6", "44/4441-22-F137-9CS1784"		



EG8838-000	"400R1121-26-0/9-9"		
858987K001	"5-1196693-0"		
EG9287-000	"EPD-RWC-24142-L012"		
378962-000	"3-1192835-9", "44A1131-20-0/2/9-3"		
CB7181-000			
539065-000	"44B1121-24-0/9-9", "1-1194230-7"		
F01967-000	"EPD-ROK-10512-L022", "7-1201069-6"		
E90807K001	"4-1200393-0"		
758165-000	"6-1195907-1", "EPD-RWC-11147"		
640725K001	"7-1195064-3"		
330751-000	"8-1192498-9", "44AM1121-20-9/957-9"		
CY2086-000	"EPD-DND-21823-L013"		
812967K001	"6-1196324-5"		
C95456K001	"4-1201391-9"		
256838-000	"2-1198067-6", "44AM1131-16-G030-9-1KF"		
907730-000	"44A9416-22-9", "3-1197051-2"		
CS7001-000	"EPD-DND-21478-L099"		
CU3974-000	"EPD-RWC-22875"		
383675-000	"9-1192876-5", "44A1121-18-2/9-9-US"		

CB6784-000	"EPD52955B-CS2979", "1899181-4"		
E93424K001	"2-1200809-0"		
CL7057-000	"44A4181-22-F875-0CS3249"		
CP3495-000	"EPD-RWC-20754"		
504375-000	"7-1193809-5", "EPD-ROC-10015"		
482513-000	"6-1193611-4", "EPD-RWC-11194"		
209185-000	"1191516-5", "EPD-RWC-14919"		
C93857-000	"6-1200976-3", "EPD97446A-US"		
902499K002	"1197014-1"		
036635-000	"9-1190282-6", "CMC-0573-18-0CS2327"		
CX0038-000	"EPD-DND-21485-L099"		
A02897K001	"2-1201147-3"		
413975-000	"9-1193120-2", "EPD-RWC-13424"		
754171-000	"44AM1161-22-MST6-9", "9-1195878-7"		
668807-000	"2-1195266-9", "EPD52953A"		
CA2911-000			
980455K001	"4-1197576-4"		
656435K001	"1-1195177-0"		
104922K001	"8-1199862-9"		

126240-000	"3-1199377-2", "44AM1111-18-954-9-1KF"		
270201-000	"8-1191998-2", "44/7011-22-9"		
C41659K001	"2-1201127-6"		
D73073-000	"44A0111-20-9-L038", "7-1200236-0"		
876921-000	"44/2421-20-9/90-9CS1506", "6-1196820-7"		
918813-000	"44A1121-16-5/9-0-US", "2-1200975-5"		
C81460-000	"6-1201926-3", "44A0111-16-97-L030"		
282069-000	"1192101-1", "44A0112-16-9"		
022892-000	"9-1199499-1", "EPD-NAV-85409"		
308931K001	"8-1192339-2"		
CU7730-000	"EPD-DND-22841-L274"		
EG7211-000	"44A0121-22-9/957"		
282689-002	"9-1192122-9", "44A0111-18-92-MX"		
CA9801-000	"EPD-RWC-19733-L149"		
EG7200-000	"44A0121-22-9/927"		
CS6946-000	"EPD-DND-21535-L099"		
436235K001	"4-1193279-8"		
EK0690-000	"EPD-DND-21745-L016"		

022501-000	"3-1190174-2", "44A9704-24-9-9-9"		
A65240K001	"4-1200589-5"		
CZ7617-000	"EPD-RWC-22253"		
CU6634-000			
CN8571-000			
819723K001	"1-1196388-2"		
034591K001	"7-1190267-2"		
F06218-000	"9-1201378-8", "EPD94606A-US"		
670355-000	"1195277-9", "44AM1131-24-0/2/9-9CS262"		
211547K001	"5-1191532-5"		
EF9964-000	"EPD-DND-21746"		
608643-000	"44AM1111-16-904-9", "1-1194814-0"		
EJ0249-000			
563795-000	"1194454-8", "EPD52619A-20-0"		
CX0391-000	"44A0221-18-9/9"		
595241-000	"4-1194707-3", "EPD51388A-22-0-F599"		
096519-000	"8-1190707-7", "EPD-RWC-14840"		
A22782-000	"44/0611-24-9CS2979", "9-1199657-5"		
866117K001	"2-1196744-8"		
CU0517-000	"44A7358-24-G204-9CS228"		

D24125K001	"8-1200583-9"		
187647-000	"9-1191361-8", "44AM1121-22-0/9-92"		
CX7190-000	"EPD-RWC-23210-L296"		
368353-000	"8-1192760-2", "44A7434-22-9/5"		
877594-000	"1199195-5", "EPD-ROK-10373-L028"		
382503-000	"3-1192864-7", "44A1141-22-0/1/2/9-9"		
CU5740-000			
879847-000	"1196850-2", "EPD52693A-X-0"		
387758-000	"2-1192912-0", "44A1111-20-9-3"		
CP2439-000	"EPD-DND-21508-L108"		
583265-000	"345M09B-22-14-0CS2041", "9-1194619-3"		
793247-000	"1-1196142-5", "EPD-BRZ-10004"		
6367803001	"44A1121-20-0/9-9CK0001", "8-1198932-3"		
493921K001	"2-1193694-4"		
951197K001	"8-1197355-8"		
CN8004-000	"EPD-RWC-21403"		
744452-001	"44A4121-22-1/9-9CS009", "6-1195807-4"		

788059-000	"44A9626-12-0/9-9CS2746", "9-1196107-4"		
CA7493-000	"EPD-NAV-32507"		
283806-000	"9-1192142-0", "44A0111-14-92-US"		
A55340K001	"5-1200163-5"		
A03252-000	"8-1201690-2", "44A0111-10-9-9"		
549993-000	"44/0411-12-9CS1038", "1194327-5"		
CY0519-000	"44B5111-20-9-9CS1401-L302"		
922773-000	"44/1421-20-6/9-9", "4-1197159-3"		
241503-000	"8-1199170-9", "EPD71255A-US"		
EM0496-000			
591119-000	"345M15B-22-60-0CS2041", "9-1194675-7"		
458231-000	"345M16B-18-38-0CS2041", "1193438-2"		
CM1780-000			
501533K001	"3-1193749-9"		
293251K001	"7-1192222-2"		
202381-000	"2-1191467-6", "EPD52337A-14-0"		
CZ2122-000	"44A0111-26-9-1KF/1"		
D23500K001	"8-1200583-8"		

CZ2709-000			
388811-000	"345M18B-18-57-0CS2041", "1192919-3"		
793849K001	"3-1196146-3"		
054681K001	"2-1190417-9"		
703793-000	"44A1231-18-0/2/9-9", "3-1195521-9"		
680589-000	"1-1195353-7", "EPD-RWC-15759"		
873187K001	"6-1196794-3"		
D69701-000	"2-1201652-9", "EPD-ROK-10545"		
CS5348-000	"44A0811-10-966"		
F00629-000	"EPD-PFM-10049CS2962", "4-1200088-8"		
CJ8693-000	"FB-RWC-20698"		
183802K001	"8-1199199-7"		
352737-000	"9-1192649-1", "EPD51407A-24-0"		
CM4935-000			
EG2510-000	"EPD-RWC-23962"		
850581-000	"44AM1121-16-904/95-9", "1196632-1"		
300253-000	"5-1192274-0", "44AM1131-20-0/1/9-9"		
266837-000	"6-1191969-8", "EPD-RWC-13769"		
990527K001	"2-1197659-4"		

530457-000	"44AM1151-16-F913-9", "5-1194166-1"		
370222-000	"1-1192774-5", "44/2421-22-9/9-9"		
382373-000	"3-1192862-3", "44A1221-18-0/9-9"		
134403-001	"7-1190976-9", "44B5141-20-MST4-9CS1728"		
EG7213-000	"44A0121-22-9/956"		
CZ2711-000	"EPD-RWC-23535CS3372 "		
647363-000	"44A0211-12-92", "5-1195111-2"		
803403K001	"1-1196211-1"		
139409K002	"1191011-3"		
717737K001	"2-1195614-9"		
D04838-000	"9-1200552-4", "FLDWC1331-20-ELC3-9CS3050"		
CF8505-000	"44A1151-14-9/9/9/9/9-0"		
283808-000	"9-1192142-7", "44A0111-12-90"		
611386-000	"44B1121-16-0/9-90CS2025", "4-1194834-9"		
290509-000	"3-1192202-8", "EPD51486A-16-0"		
CU4071-000			



838545-000	"1-1196544-1", "EPD52970A"		
927229-000	"44/4434-24-F001-9CS1784", "5-1197190-0"		
466115K001	"3-1193494-2"		
CS6991-000	"44A1821-18-0/9-3-1KF/1"		
109753K001	"6-1190801-1"		
E37224K001	"1200584-4"		
204506-000	"1-1200027-3", "44A0311-22-9-1KF/1"		
222989K001	"9-1191642-8"		
CS8245-000	"EPD-DND-21667-L016"		
CM0557-000	"44B1121-18-9/96-9CS2994", "4-1899386-8"		
654321-000	"44B5124-24-9/96-9CS1821", "5-1195162-3"		
E52048K001	"6-1201151-9"		
F55809-000	"44A0811-10-90-1KF", "1-1200249-7"		
358488-000	"4-1199655-7", "44A1221-12-9/9-9-1KF/1"		
C24263K001	"7-1200522-7"		
377177K001	"5-1192824-3"		
EL7178-000			
549243K001	"1-1194322-5"		
061289-000	"9-1190463-6", "44/0414-26-9CS1038"		

1433003001	"4-1198722-2", "44A0111-20-9CK0001"		
752085K001	"1195864-3"		
485591K001	"9-1193633-1"		
EG7284-000	"44A0121-22-9/918"		
678405K001	"2-1195333-8"		
385498-000	"5-1192892-3", "44A0121-22-9/90"		
CM6775-000			
837191-001	"44A9442-22-MST4-9CS527", "4-1196534-5"		
090309-000	"1190662-9", "FB-44-7026A-0217CS896"		
EK3061-000	"400R1141-20-0/2/6/9-0"		
383485-000	"4-1192875-7", "44A1121-20-0/9-92"		
050667-000	"4-1190388-8", "44A1121-22-0/9-9CS406"		
475388-000	"6-1199104-5", "EPD-RWC-16564CS2966"		
F95834-000	"EPD-RWC-17740", "3-1200578-2"		
C61239-000	"7-1200394-9", "EPD-RWC-17591"		
029343K001	"2-1190227-8"		
C02590K001	"5-1200583-8"		
246513-000	"4-1191808-9", "EPD-RWC-15404"		

CN3402-000	"EPD90234A-US"		
283294-000	"3-1192134-2", "44A0211-12-90"		
958707-000	"4-1197421-5", "EPD4666E"		
263013K001	"1191936-6"		
666477-000	"2-1195250-3", "WXA-0085-14-9"		
007709-000	"7-1190059-5", "44A9586-26-9-4"		
753609-000	"2-1195875-0", "EPD51405A-24-0"		
244458-001	"2-1191793-7", "44B5121-12-9/96-9CS1728"		
003597-000	"2-1190027-4", "44A1221-14-0/9-9-5CF/1"		
112595K001	"7-1190821-4"		
728171-000	"1-1195690-4", "EPD-RWC-13957"		
951759-000	"44A0312-14-9-US", "1197370-5"		
282096-000	"7-1192103-9", "44A0211-22-9-MX"		
F64100-000	"FLDWC6004-14-9"		
258825K001	"3-1197843-6"		
525923K001	"7-1194132-2"		
366344-000	"1201504-2", "44A1111-16-9-1"		

306428-002	"3-1192321-3", "44AM1141-24-0/2/5/9-9"		
CR7697-000	"44AM1121-22-9/96-9-1KF/1"		
261209-000	"5-1191911-7", "44A0312-24-9"		
953285-000	"44/0412-24-9CS1235", "7-1197381-8"		
139345K001	"6-1191010-0"		
925957-000	"6-1197181-0", "EPD52695A-16-0"		
362015-000	"9-1192714-2", "44AM1121-16-6/9-9CS2399"		
343579-000	"2-1192588-6", "44A0111-26-9CS2896-N"		
197147-000	"2-1191429-3", "EPD-ROK-10219"		
CF3586-000	"EPD-RWC-17594CS2979", "2-1899213-1"		
971208-000	"44A0121-16-9/96CS2994", "1200132-8"		
425671K001	"1-1193204-2"		
CP6359-000			
023386-000	"6-1199501-2", "EPD-NAV-88411"		
045167-000	"1190347-2", "EPD51157A"		
487335-000	"5-1193646-5", "EPD52956A"		

320161-000	"7-1192427-7", "EPD52774A-18-0"		
EG2546-000			
736445K001	"8-1195750-4"		
CJ1988-000	"EPD-RWC-17790CS2979", "6-1899258-3"		
CM1546-000	"EPD-RWC-20840"		
282755-000	"1192125-2", "44A0111-22-91"		
3C0583-000	"6-1193002-0", "EPD5908-14-0"		
F11438-000	"44A0111-14-924-1KF", "8-1200546-1"		
866635-000	"9-1196747-5", "EPD51401A-24-0"		
C62566-000	"44A1122-24-0/9-9CS358", "7-1200721-7"		
CP3774-000	"EPD100259 A-US"		
CY7494-000			
D26736K001	"9-1200583-0"		
390211-000	"6-1192929-6", "44/1432-20-0/2/9-9"		
887477K001	"8-1196904-1"		
128135-000	"1-1190931-0", "FLDWC0311-18-9CS2722"		
CR9947-000			
483029-000	"44A0131-24-3/6/9", "3-1193615-6"		

305085K001	"1-1192310-7"		
CZ4486-000			
409067-000	"3-1193085-2", "44A9673-20-90CS2745BARREL"		
CA2935-000			
705227-000	"44A0111-20-STRIPE-KIT-38", "2-1195531-9"		
669907-000	"44A0711-16-9-1KF/1", "3-1195274-0"		
428845-000	"9-1193225-7", "44AM1131-20-F209-9CS2248"		
009627-000	"6-1190074-8", "EPD52628A-X-0"		
181319-000	"5-1191317-9", "EPD52620A-22-0"		
EM6369-000			
084047-000	"1-1190621-4", "EPD43498B-US"		
557064-000	"44A0331-20-0/2/9CS2747", "6-1200248-2"		
382714-000	"1192867-8", "44A1122-22-0/9-9-US"		
CB7184-000			
301018-001	"9-1192279-0", "44AM1111-18-9-9"		
382230-000	"1199107-8", "44A1121-16-9/9-9-MX"		

394149-002	"6-1198260-4", "EPD32867A-US"		
F14566K001	"7-1200354-3"		
A44387-000	"6-1201112-7", "EPD24525D-RYQ-L099"		
E23424-000	"2-1200899-7", "EPD-RWC-18032"		
384959-000	"6-1192888-5", "44A0121-24-9/96"		
E17748K001	"4-1201922-1"		
358097K001	"2-1192687-6"		
306610-000	"8-1192322-2", "44AM1141-22-0/2/6/9-9"		
281529-000	"9-1192085-0", "EPD-RWC-15025"		
917392-000	"44A0841-10-9/90/92/95", "1199346-8"		
CF4838-000			
276095K001	"1192045-1"		
240718-000	"5-1191768-5", "EPD4745F"		
CN5753-000			
777517-000	"44A9664-14-0/2/9-0", "5-1196052-8"		
711112-000	"345/30-16-3-0CS1913", "5-1195571-5"		
718987-000	"1-1197925-4", "EPD62584A-ING"		
E07375-000	"9-1200579-5", "EPD-RWC-17763"		
524357K001	"1194119-3"		

721847-000	"44A9586-24-9", "2-1195644-6"		
CX4900-000	"44A1321-12-9/9-9CS3030"		
754767K001	"5-1195883-7"		
465607-000	"9-1193490-6", "EPD52192A-12-0"		
922724K001	"8-1199500-1"		
CN8274-000	"EPD-RWC-21402-L004"		
E77965K001	"9-1201653-3"		
A02792K001	"5-1200287-1"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.