



17-Feb-2022

PCN #: P-22-022185

Subject : Spec 44 and FLDW Wires

Description of Change : TE Connectivity is changing the sourcing and grade for PVDF resin used as insulation material for Spec 44 and FLDW Wires. This change is to an alternate grade with similar performance and characteristics.

Reason : Part status change. The technical assessment on alternate PVDF grade has been completed by TE's technical team and the results demonstrate similar properties and performance to the existing PVDF grades. These results are obtained through validation trials of various finished parts using the alternate grade as insulation material. No change to form, fit and function of the finished parts has been observed. Test reports on the wire characteristics can be provided upon request.

Key Dates :

Contact By Date: 28-Mar-2022

Implementation Date: 28-Mar-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
CZ6936-000	"EPD-RYQ-23558"		
292133-000	"8-1192214-4", "EPD-ROC-10013"		
CZ6930-000			
361112K001	"1-1200999-6"		
CX8467-000			
724720-001	"345/63B-26-84-0CS1913", "9-1195664-6"		
CZ4674-000			
058100-000	"9-1199499-7", "EPD-NAV-91405"		

282614-000	"2-1192120-1", "44A0111-22-947"		
275675-000	"7-1192041-7", "44A1131-16-F870-0"		
CP1693-000	"44A0111-10-9-3-L232"		
CL0864-000	"44A4122-18-1/9-9CS3185"		
EK8980-000	"44A0311-12-9-E634"		
CF3489-000			
337585-000	"6-1192548-0", "44A9673-18-9CS2745BAR REL"		
527743-000	"44A9172-X-9-9CS1663", "1-1194146-6"		
375035-000	"6-1192809-6", "44AM1121-22-9/91-9CS1726"		
976059-000	"3-1197542-4", "EPD-ADD-10161"		
CL5427-000			
741043K001	"6-1195783-7"		
972015-000	"44A0311-18-90CS2745", "3-1197513-2"		
886437-002	"7-1197924-4", "EPD70027A-ING"		
A32146-000	"1-1202115-1", "EPD-RWC-19735"		
729271-000	"44A9674-20-9-9CS2746", "8-1195697-7"		
EP1355-000			

756875-000	"2-1195898-0", "EPD52212A"		
802849K001	"7-1196206-0"		
3822293013	"1-1192858-0", "44A1121-20-0/9-9"		
107475K002	"2-1190785-5"		
732517-000	"44A7620-16-9/5-9", "1-1195722-7"		
729747K001	"4-1195701-2"		
363007-000	"6-1192721-9", "44A1811-22-9-9-US"		
526689K001	"8-1194138-5"		
CJ1793-000	"44A0111-20-9-6CS3144-L193", "2-1899270-1"		
155911-000	"4-1191126-0", "44AM1121-20-9/936-9CS1726"		
805420K001	"9-1198861-6"		
CF5297-000	"44A2121-16-1/9-9CS3230"		
265052-003	"8-1191951-2", "44A0811-12-9-MX"		
592005K001	"3-1194682-8"		
348679-000	"6-1192623-9", "EPD44228B-16-0"		
CF3426-000			
CB0921-000			
728053-000	"44/4424-26-0/9-9CS2251", "2-1195689-7"		

882677-000	"4-1196870-8", "EPD-PRC-10021"		
EP7724-000			
984405K001	"1197605-3"		
272829K001	"9-1192020-9"		
818647K001	"9-1196379-3"		
564837K001	"5-1194461-2"		
589611K001	"1194665-4"		
324089K001	"7-1192452-2"		
451851K001	"1193393-8", "EPD-RWC-15432-COA-KIT-1"		
756261K001	"8-1195893-2"		
CU5303-000	"44A1111-10-9-9"		
798565K001	"1-1196176-9"		
264569-000	"1191947-7", "44A0121-12-90/92"		
E25942-000	"2-1202052-3", "EPD-CAN-10020-5CF/1CS2979"		
191327-000	"8-1191387-1", "EPD51034A-22-0"		
303904-000	"4-1199824-1", "44A0221-14-9/9-1KF/1"		
CA8023-000	"EPD97015B-US"		
CU8712-000	"EPD-DND-21489-L281"		
344409K001	"8-1192593-3"		
121814-000	"3-1199186-0", "44/4424-26-1/9-9"		

533145K001	"8-1194185-4"		
CJ1641-000			
EM0457-000			
282029-031	"6-1192095-6", "44A0111-20-9-MX"		
CR5317-000	"44A0222-20-0/9"		
029328-000	"2-1200870-4", "44AM1821-18-9/96-9-L005"		
384027-000	"5-1192880-0", "44A9090-14-0/2/9-9CS2746"		
669901K001	"5-1197823-4"		
550995K001	"4-1194354-0"		
141115-000	"9-1191022-3"		
D55644-000	"8-1200290-5", "FLDWC0311-22-9CS2979"		
CJ9796-000	"44A1114-26-9-9-3"		
F81865-000	"EPD-RWC-17617", "2-1200355-4"		
EM9837-000	"EPD-DND-21818-L280"		
904765-000	"8-1197030-9", "EPD52264A-14-0"		
490735-000	"1193671-9", "EPD52634A-12-0"		
CJ0103-000	"EPD-RWC-20563"		
384216-000	"4-1192882-1", "44A0121-20-9/90"		

212599-000	"1-1191538-8", "345/45B-22-38-0CS1913"		
E78744-000	"3-1202129-2", "EPD37262A-US"		
510017-000	"44A9242-16-8CS1795", "2-1194009-2"		
120649-000			
883793K001	"3-1196878-7"		
C87665-000	"44B5111-16-9-9CS3012", "7-1200301-1"		
583219K001	"6-1194619-8"		
593681-000	"9-1194693-3", "EPD52694A-20-0"		
D66575-000	"3-1201692-4", "44A0111-10-9-1"		
BM8770-000	"UB2-26C131BG11-9-E630"		
CJ4658-000	"EPD51047A-18-0CS2979", "6-1899288-9"		
382528-000	"8-1192864-8", "44A4131-22-0/2/9-9"		
241999-000	"7-1191777-4", "EPD45266A"		
657571-000	"1195185-7", "EPD-RWC-10817"		
513665-001	"8-1194035-1", "EPD5845-20-0CS1898"		
EL7807-000	"EPD-RWC-24728"		

966517-000	"6-1197473-8", "EPD-RWC-12012"		
A92623K001	"9-1200587-7"		
421804-000	"1193177-2", "44B1121-16-0/9-92"		
404207-000	"3-1193051-2", "44AM1131-16-945/942/954-9"		
389757-000	"5-1192925-5", "44A0121-22-90/92"		
818063K001	"1196376-1"		
A61710-000	"5-1201196-5", "EPD91412A-US"		
418753-000	"2-1193155-3", "FB-44-7024A-0203"		
126437K001	"9-1190918-7"		
C23809-000	"6-1200583-5", "EPD-RWC-17744"		
177587-000	"1-1191291-0", "EPD-CAN-10095"		
334561-000	"2-1192527-7", "EPD52203A-CS2835"		
E57330K001	"1200626-5"		
CP1692-000	"44A0111-10-9-2-L232"		
919142-000	"44AM1131-16-G031-9-1KF", "1-1198065-2"		
CB6420-000	"44A9615-26-0/9CS3203", "3-1899180-6"		
871019-000	"44/0434-24-0/2/9CS2537", "1196779-7"		

CS7805-000			
028187-000	"5-1190218-6", "44A1131-24-92/94/96-9"		
CS8548-000			
476797-000	"9-1193570-3", "EPD-ROK-10038"		
F07012-000	"EPD-RWC-17766", "4-1200591-0"		
CN9341-000	"FLDWC0311-16-9CS2979"		
460719K001	"7-1193455-0"		
CS2885-000	"44A0311-12-9-F871"		
571493-000	"1-1194532-6", "EPD-RWC-14221"		
387022-008	"9-1192903-2", "44A1111-26-9-9-US"		
734295K001	"9-1195734-3"		
369962-000	"4-1201422-3", "44A0331-20-0/2/9-US"		
469964-000	"44AM1121-16-9/925-9-1KF", "1-1198060-4"		
298129-000	"6-1192257-6", "44A0121-24-0/9-S166"		
393193-000	"1-1192950-6", "44/1422-22-9/96-9"		
306274-000	"5-1192319-5", "44AM1121-26-9/96-9"		
292439-000	"9-1192216-4", "44A0111-18-955"		
CR3176-000	"EPD-RWC-17028-L012"		

EG6695-000	"FLDWC0311-20-9CS3422"		
589964-000	"44AM1111-18-92-9-1KF", "3-1199379-6"		
729405-000	"7-1195698-6", "EPD6207-26-0/9-9CS2315"		
387307-000	"4-1200800-9", "44A1111-16-9-90-US"		
061625K001	"2-1190466-0"		
D35841-000	"6-1201712-8", "44AM1121-18-9/96-9CS2994"		
CB1268-000	"44B9202-X-9-L050"		
CZ7672-000	"EPD-RWC-22262"		
536791-000	"5-1194213-6", "EPD-RWC-12643"		
573626-000	"7-1198907-2", "FLDWC1341-20-F019-9CS2959"		
EP6141-000	"44A1221-22-9/9-9CS3030"		
748863-001	"44A9064-24-0CS1638", "2-1195841-4"		
277156-000	"5-1199827-1", "44A7620-16-9/5-9CS2979"		
CB6848-000			
CB3889-000			
261184-000	"2-1191911-1", "44A0212-10-9"		
CN6737-000			
172537-000	"7-1191254-7", "EPD-RWC-14746"		

E38030-000	"2-1201281-8", "EPD4746D-IRL-L016"		
CS7472-000			
CX8627-000			
613143K001	"8-1197888-8"		
411797K001	"5-1193105-8"		
A62685-000	"6-1200812-9", "EPD-RWC-18086"		
306478-000	"9-1192321-2", "44AM1121-14-6/9-9"		
CS7764-000	"EPD-DND-21486-L099"		
452010-001	"44B5141-16-MST4-9CS1728", "1-1193394-2"		
393007-000	"5-1192948-7", "4J2S-16-F10-8"		
608403-000	"1-1194812-8", "EPD-RWC-15432"		
E43493-000	"44/7004-16-9CS1059-L102", "1-1200984-2"		
378270-000	"4-1192832-2", "44A0121-12-6/9"		
F60898-000	"5-1202125-5", "44A0311-16-9CS3030"		
EG2511-000			
283878-000	"9-1192143-6", "44A0111-10-9-MX"		
991899K001	"2-1197672-3"		
200397-000	"1-1191452-6", "EPD-RWC-14595"		

368580-000	"1199140-6", "EPD-OLF- 10171"		
265580-000	"3-1199501- 5", "EPD- NAV-79417"		
356621K001	"5-1192676- 2"		
462149-000	"1-1193466- 8", "EPD68113A "		
606171-000	"44A9615-26- 0/9CS910", "6-1194795- 8"		
308345-000	"3-1192335- 8", "44AM1131- 16-9/9/9-9"		
374902-000	"4-1192808- 4"		
CS3830-000	"EPD-DND- 21535-L263"		
799178-000	"44A1221-14- 9/96-9", "6- 1198309-7"		
EG2504-000	"EPD-RWC- 23953"		
416654-000	"8-1198271- 6", "44A0121- 16- 9/96CS2109"		
332765-000	"1-1192514- 5", "44AM1121-1 6-905/924-9"		
386919-000	"44A0121-22- 9/95"		
455645-000	"1-1193420- 4", "EPD40799A "		
155943-000	"6-1191126- 4", "EPD52371A "		
907168K001	"7-1199500- 8"		
CS7475-000	"EPD-DND- 21445-L099"		

456451-000	"8-1193425-1", "EPD-RWC-12122"		
348868-000	"9-1201137-3", "EPD100259 A-US-L099"		
223465K001	"3-1191646-3"		
F44483-000	"44AM1111-22-9-9CS2994", "6-1200987-1"		
CS9405-000	"44/0414-24-9CS2902"		
444420-000	"2-1201555-1", "44A1141-16-9/9/9/9-9C2976"		
CB7177-000	"EPD-RWC-19938"		
CR5783-000	"EPD-DND-22099-L251"		
692481-000	"44A9605-16-98", "1-1195436-5"		
116726-000	"4-1198287-4", "44A9673-24-9CS2745"		
CB7536-000			
514897-000	"44AM1111-24-9-9CS2109", "3-1194044-8"		
EM8484-000	"EPD-RWC-24364"		
EM6794-000	"EPD-RWC-24957"		
085797-000	"2-1190633-6", "44B1121-24-0/9-90"		
EK9402-000	"EPD-RWC-24327"		
CY1334-000			
846295-000	"44A9416-20-90CS1981", "4-1196601-9"		

011675-000	"4-1190092-1", "EPD51885A-20-0"		
603851-000	"44AM1141-22-9/92/93/96-9", "6-1194778-2"		
E53963-000	"1-1201700-0", "44A0111-18-95-2KF"		
296339K001	"8-1192244-1"		
F21955K001	"6-1200586-6"		
669061-000	"44A1111-22-9-9CS406", "1195268-9"		
EG3684-000	"EPD-RYQ-23396-L323"		
C40996-000	"1201279-3", "EPD4666E-IRL-L016"		
CS7711-000	"EPD-RWC-22257-L099"		
909702-000	"1198990-7", "EPD-ROK-10493"		
382578-000	"5-1192865-4", "44A2121-22-1/9-9"		
CB7176-000			
817153K001	"8-1196367-5"		
E17715-000	"9-1201926-7", "44A0111-16-94-L030"		
CB3879-000			
630511-000	"44/1424-20-9/96-9", "1194990-3"		
678903K002	"8-1195336-9"		
C36664-000	"8-1201426-2", "EPD-RWC-18834-L099"		

CU6275-000	"EPD-DND-21491-L016"		
071919-000	"7-1190539-6", "345/43B-20-10-0CS1913"		
E62433-000	"9-1201376-8", "44A1114-26-9-9-1"		
CM1778-000			
A81788-000	"44A0111-22-9-L038", "9-1200553-9"		
803021-000	"44A9416-12-9CS1981", "1196208-2"		
039057-000	"1-1190299-2", "WXA-0165-20-92"		
CF9302-000	"44B1131-20-MST3-9CS2994", "3-1899242-4"		
CB1711-000			
750321-000	"5-1195851-6", "EPD-RWC-11423"		
572409-000	"6-1194543-9", "EPD51026A-26-0"		
282691-000	"1-1192123-0", "44A0111-18-94"		
829069-000	"44A9416-18-9CS1981", "7-1196473-7"		
EM0401-000	"EPD-RWC-22257-L016"		
CB7538-000	"EPD-RWC-19941"		
CA2184-000			
EG6696-000	"FLDWC0311-14-9CS3422"		
296929-001	"1-1192249-6", "44A4121-16-1/9-9CS009"		

969653-000	"44AM1121-20-9/91-9CS1726", "4-1197496-0"		
EM8268-000	"EPD-RWC-25167"		
924194-000	"5-1199368-2", "EPD95612A-US"		
840613K001	"4-1196558-8"		
D62200-000	"8-1200629-8", "EPD-RWC-17958"		
CN5902-000			
909257-000	"44AM1111-16-9-9CS2399", "8-1197062-2"		
393032-000	"1192949-2", "4J2S-10-F10-8"		
888851-000	"8-1196914-8", "EPD51949A-12-0"		
328940-000	"7-1199382-7", "44AM1111-16-925-9-1KF"		
606235K001	"1-1194796-1"		
053935-000	"8-1190411-7", "44B9534-12-9-9CS1728"		
F57013-000	"EPD95429A-US", "1200589-8"		
777501-000	"4-1196052-8", "EPD51067A-22-0"		
794090-000	"1-1199162-4", "FLDWC0311-24-9"		
918117-000	"7-1197125-9", "EPD-RWC-12127"		

ER5144-000	"44A0111-16-9CS3529"		
980186-000	"9-1201757-4", "44A9037-24-9/96-9-9"		
EG5695-000	"EPD-RWC-24097-L348"		
A72881-000	"2-1200976-0", "EPD-RWC-18278CS3085-L101"		
493623K001	"9-1193691-0"		
919599-000	"345M06B-22-14-0", "2-1197136-8"		
382948-000	"7-1192869-3", "44A1131-16-9/90/92-9"		
CB6881-000	"EPD-RWC-20062CS3207-L099"		
375219-000	"1192811-5", "44A9664-18-0/2/9-0"		
146473-000	"7-1191058-5", "EPD-RWC-15741"		
834495-000	"44/2411-20-9-9CS024", "1-1196515-7"		
414156-000	"9-1198838-5", "44A0111-10-9-L017"		
654795-001	"345/63B-26-48-0CS1913", "9-1195165-4"		
077937-000	"8-1190580-8", "44A9083-16-9CS2382"		
213886-000	"1-1191545-4", "345/29-16-2-0CS1913"		
A91723K001	"1200693-1"		
951333-000	"44/7009-26-9CS2491", "8-1197356-2"		

761192K001	"3-1200584-8"		
E30558-000	"6-1200279-2", "EPD-RWC-17215"		
383101-000	"3-1192871-9", "44A1231-20-0/2/9-9"		
CL3970-000	"EPD-RWC-14668CS2497"		
C07671-000	"6-1200583-0", "EPD-RWC-17792"		
A41389K001	"8-1200692-1"		
991885K001	"1197672-7"		
ER6269-000	"44A0131-22-9/93/96CS3529"		
3W0627-000	"2-1193019-2", "EPD20023C"		
CX9001-000	"EPD-DND-23319"		
986573K001	"8-1197870-3"		
EG4281-000	"EPD91514A-US-L012"		
CY8601-000	"EPD-DND-23390"		
037793-001	"9-1190291-5", "44A2121-22-1/9-9CS006"		
CB8620-000	"EPD-RWC-20309CS3092"		
841155-000	"6-1196562-3", "EPD-ADD-10089"		
C43817-000	"1-1200693-6", "EPD-RWC-17878"		
589453-000	"9-1194663-2", "EPD-RWC-14225"		
CR5118-000	"4J2N-12-F6-0"		

CR3939-000	"EPD-RWC-22059-L009"		
795987-000	"44A9586-26-9-5", "8-1196161-7"		
415400K001	"9-1199146-5"		
D42281-000	"1-1201229-8", "CXA-0197-22-0/9-9"		
054643K001	"9-1190416-8"		
320693K001	"2-1192431-5"		
A94316-000	"4-1200727-0", "EPD98877A-US-CS2979"		
421569-000	"5-1193175-3", "44A9665-14-0/2/5/9-0"		
932560-000	"44AM1111-16-924-9-1KF", "1-1199381-1"		
619235-000	"9-1194891-7", "EPD51831A-10-0"		
265053-000	"8-1191951-7", "44A0811-14-9-US"		
CA0599-000	"EPD-RWC-19735-L086"		
D08897K001	"9-1201426-6"		
CR3174-000	"EPD-RWC-17046-L012"		
CS8052-000	"EPD-DND-22560-L016"		
976893-000	"2-1197548-3", "EPD-RWC-13958"		
EL6403-000	"44AM1141-20-MSL4-9CS2378"		
225927K001	"8-1191663-9"		

035137-000	"7-1190271-5", "44A9164-20-8CS2058"		
CF4855-000	"44B4122-16-1/9-9CS3225"		
285818-000	"9-1192163-8", "44A0111-26-97-US"		
011009-000	"9-1190086-6", "EPD7369A-US"		
E57305-000	"1200291-3", "EPD-RWC-17033"		
383159-000			
CJ1801-000	"44A0111-22-9-11CS3144L193", "2-1899270-6"		
A00354-000	"2-1201390-0", "44A0111-24-9-BARREL"		
688881-000	"345/50-16-10-0CS2026", "4-1195410-2"		
EG7202-000			
651289-000	"3-1195142-7", "EPD52964A"		
051179-000	"9-1190391-2", "EPD-ROC-10057"		
186861K001	"4-1191356-7"		
691865-000	"8-1195431-3", "EPD-RWC-14917"		
282839-000	"2-1192127-9", "44A0111-24-95-MX"		
CX1601-000	"EPD-DND-21667"		
CP3571-000			
CN3175-000			

306027-000	"2-1192317-2", "44AM1121-16-9/96-9"		
200513K001	"1191453-2"		
974605K001	"7-1197531-5"		
889662K001	"3-1200584-9"		
591847-000	"44A4124-24-1/9-9", "3-1194681-3"		
D50965K001	"2-1200583-7"		
EG4927-000	"44AM1141-20-MST4-9CS3209"		
EF4917-000	"EPD-RWC-19939-L027"		
858071-000	"44AM1144-22-3/5/6/9-9", "3-1196687-6"		
658911-000	"6-1195194-2", "CMC-0441-22-6-0"		
382308-004	"7-1192860-3", "44A1131-16-0/2/9-9-MX"		
398841K001	"7-1192990-2"		
116717K001	"4-1190850-2"		
725331-000	"4-1195669-9", "EPD52137A-24-0"		
639582-000	"44A1711-22-9-9CS1354", "3-1195055-2"		
467938K001	"1199953-8"		
D69378-000	"2-1202032-0", "EPD-RWC-17045-L028"		
433793-000	"7-1193262-2", "FB-44-7024A-0202"		

EM0396-000	"EPD-RWC-22262-L016"		
F53395-000	"3-1201183-1", "44/7005-22-9CS1890"		
EH2671-000	"44A9966-12-9CS3433"		
F17110K001	"2-1200584-1"		
F14552K001	"9-1200581-5"		
238487-000	"4-1191753-4", "44A9674-22-9-9CS2746"		
720423-000	"6-1195633-2", "EPD-RWC-14750"		
363006-000	"6-1192721-6", "44A1811-20-9-9-US"		
CZ6934-000			
366123K001	"7-1192744-9"		
CM1217-000	"44A0711-18-90"		
282881-000	"1-1192128-6", "44A0111-24-914-US"		
769933K001	"2-1195999-0"		
CS1899-000	"EPD66779B-US-L012"		
153229K001	"1-1191107-2"		
306377-000	"8-1192320-0", "44AM1131-26-0/2/9-9"		
899997K001	"7-1196995-9"		
EP7610-000	"EPD-RWC-23464-L005"		
886415-000	"7-1196896-9", "EPD52842A-22-0"		

E60829-000	"8-1200690-9", "EPD-RWC-10937-L091"		
306876-000	"6-1192324-3", "44AM4121-22-0/9-9"		
282873-000	"7-1192127-1", "44A0111-24-94-MX"		
CN8273-000			
117737-000	"1-1190857-0", "EPD40417A-US"		
477619-000	"44A9673-22-9CS2745", "1-1193577-3"		
480313-000	"6-1193595-4", "EPD-RWC-14833"		
225971K001	"2-1191664-0"		
E06265K001	"8-1200592-0"		
801295K001	"1196195-3"		
CJ6343-000	"EPD4746D-IRL"		
CY0511-000	"44B5121-16-MT29C1401-L302"		
835351K001	"1-1196521-0"		
306411-000	"1-1192321-3", "44AM1141-20-9/93/95/96-9"		
EH9421-000	"EPD-RWC-14668CS2888-L365"		
031791-000	"5-1190246-6", "44AM4121-24-0/9-0"		

991911-000	"2-1197672-9", "44AM1141-20-ELC4-9CS262"		
528515-000	"44A0111-24-9-US-1KF/1", "1-1194151-7"		
F11965-000	"44A0111-18-90-2KF", "8-1200546-2"		
CS7470-000	"EPD-DND-21443-L099"		
CJ3138-000	"345/M02J-16-3-0CS2041"		
802910-000	"44A1121-12-9/96-0", "9-1199147-6"		
CR0327-000	"44A7620-20-9/5-9CS3303"		
CX1595-000	"EPD-DND-21441"		
CX0664-000	"EPD-RWC-23001"		
349849K001	"1-1192632-0"		
475023-000	"44AM1121-20-6/9-9CS2399", "3-1193558-5"		
9656663001	"44A0111-16-9CK0001", "6-1198731-9"		
086211K001	"3-1190636-1"		
476601-000	"44A9632-16-0/9-9CS2748", "5-1193569-2"		
CA1046-000			
183511-000	"9-1191332-3", "EPD8486B"		
C40356K001	"7-1201164-8"		
CB4842-000			

EG7210-000	"44A0121-22-9/948"		
393011-000	"6-1192948-2", "4J4S-16-F10-8"		
368088-000	"5-1192759-0", "44A7440-22-3/6/9-9-9"		
A60275K001	"1-1200695-1"		
966947-000	"44/2464-26-F040-9CS024", "7-1197476-7"		
234455K001	"4-1191722-3"		
276757-000	"6-1192049-6", "WXA-0085-18-9"		
C24293K001	"9-1200393-3"		
F64419-000	"EPD-RWC-17741", "2-1200578-8"		
944871K001	"4-1197313-3"		
725131-000	"2-1195668-3", "EPD51060A-18-0"		
CU0182-000	"EPD-RWC-10937-L016"		
241273-000	"2-1197844-2", "44A4121-12-6/9-9"		
736759-000	"44/2471-26-A071-9CS1506", "8-1195752-5"		
868361-001	"44B5121-16-9/96-9CS1728", "3-1196760-6"		
420403K002	"2-1193167-1"		
EH6661-000	"EPD-DND-21972"		
CZ6935-000			
ER1221-000	"CEC-RWC-25419"		

270896-000	"8-1192006-8", "44/7011-26-9"		
F34059-000	"9-1201151-6", "EPD-IRL-85111"		
F65978-000	"44A0221-14-9/9CS3030", "4-1200354-4"		
738987K001	"6-1195768-1"		
667861-000	"7-1195259-2"		
240783K001	"1191769-6"		
CB4565-000	"EPD37259A-US-L099"		
929540-001	"44A9065-24-0CS1637", "5-1197206-2"		
061593K001	"1190466-4"		
CN6855-000			
405629-000	"1-1193061-3", "EPD52960A"		
529509K001	"9-1197830-2"		
005800K001	"8-1198262-3"		
962405K001	"9-1197444-8"		
EF4145-000	"44A9970-14-90CS2745"		
282932-000	"1-1192129-7", "44A0111-22-911"		
384940-000			
C40888-000	"9-1201652-4", "EPD88660C-US"		
356581K001	"2-1192676-9"		
495098-000	"2-1193702-8", "FB-44-1522-0001"		

235481K001	"1191732-9"		
282720-000	"1-1192124-9", "44A0111-20-92-MX"		
853825K001	"2-1196656-5"		
532133K001	"6-1194178-0"		
F65965-000	"EPD97242A-US", "6-1200521-9"		
270039-000	"1191995-8", "44/0411-22-9"		
EK1635-000	"44A0311-20-9-E634"		
003551-000	"9-1190026-0", "44/4441-20-F137-9CS1784"		
F61432-000	"EPD-RWC-17775", "4-1200587-3"		
622343K001	"3-1194919-9"		
643637K001	"2-1195085-1"		
370810-000	"7-1192777-2", "44/0421-24-0/9"		
269251K001	"2-1191987-1"		
911641K001	"1-1197080-4"		
276949-000	"9-1192050-2", "44A0111-22-933"		
168653-000	"7-1197915-6", "EPD-NAV-32502"		
071910K001	"2-1199140-7"		
557719K001	"2-1194399-0"		
D44841-000	"9-1200580-5", "EPD-RWC-17786"		

415347-000	"2-1193130-4", "EPD52151A-CS2816"		
327307-001	"3-1192476-9", "CMV-0061-20-0CS2103"		
CX7684-000	"EPD-RWC-23110"		
928068-000	"44A0211-16-9-1KF/1", "1198733-5"		
011320-000	"5-1190089-9", "44/0411-20-9CS1038"		
EG9076-000	"EPD23420A-US"		
167977-000	"1191223-6", "44A1231-12-9/90/92-9CS984"		
CS2890-000	"44A0321-20-0/9-F871"		
016359-000	"9-1190127-8", "44A0121-14-0/9-S166"		
037889-000	"7-1190292-3", "EPD32371B"		
A25409-000	"3-1200501-0", "EPD62591A-MTI"		
538601-000	"44A9436-22-9/96CS2312", "9-1194226-5"		
694161-000	"44A9416-26-9CS1981", "7-1195446-0"		
F75720-000	"5-1202142-5", "44A0211-10-9CS3030"		
CW5081-000	"EPD-RWC-12611-L119"		
E37075-000	"1201927-4", "44A0111-16-9-L030"		

444271-000	"8-1193338-4", "44A0111-12-9CS448"		
850304K001	"3-1198868-8"		
487807K001	"1-1193650-0"		
397624-000	"2-1197903-1", "EPD-RWC-14669CS2888-L006"		
424573-000	"5-1193196-9", "EPD-RWC-11555"		
461293-000	"44A0121-20-9/96CS1741", "9-1193459-9"		
417905-000	"4-1193149-7", "44A9966-10-90CS2745"		
C62438K001	"2-1200693-5"		
F61806-000	"1200572-5", "FB-RWC-17654-L080"		
598449K001	"6-1194731-6"		
E49749-000	"5-1201759-8", "44AM1111-14-902-9-1KF"		
F00736K001	"1-1200587-7"		
282302-000	"5-1192112-1", "44A0211-12-9-MX"		
CA3705-000	"44A9748-24-9-9CS3185"		
734903K001	"5-1195739-9"		
CX1604-000	"EPD-DND-21452"		
ER6399-000	"44AM1131-16-MST3-9CS3529"		
EG6683-000	"FLDWC0311-16-9CS3422"		

435929-000	"3-1193277-1", "EPD51902A-20-0CS2530"		
086505K001	"2-1190638-3"		
CA9994-000	"EPD-RWC-20161-L009"		
C58525-000	"8-1201763-6", "EPD-RWC-17097-L142"		
049131-000	"8-1190376-3", "44AM1131-20-0/1/9-9CS1702"		
CW5034-000	"EPD-RWC-22254-L012"		
242643K001	"3-1191780-9"		
099809K001	"3-1190731-7"		
EH2546-000	"44A9675-18-0/9-9CS3433"		
CN8366-000	"44/0412-22-9CS1038"		
884616K001	"7-1198861-6"		
864019-000	"4-1196729-6", "EPD-RWC-10270"		
975547-000	"4-1197538-4", "EPD5395-X-8CS1584"		
E45948K001	"3-1201281-2"		
CN6849-000			
384342-000	"1192884-2", "44A1121-16-2/9-9"		
557319-000	"1-1194396-3", "EPD52438A-CS2815"		
282693-000	"9-1197942-8", "44A0211-22-92-US"		

CS7646-000	"EPD-RWC-22253-L099"		
CS5303-000	"44A0811-10-922"		
CX0040-000	"EPD-DND-21485-L016"		
389616-000	"7-1192924-3", "44A1131-12-3/6/9-9"		
635388-000	"4-1199125-3", "FLDWC0311-14-9CS2722"		
301169-000	"5-1192281-3", "44AM1114-20-9-9"		
CN9508-000			
905159-000	"44AM1121-22-9/97-9CS1726", "6-1197033-7"		
383602-000	"2-1201189-1", "44A1131-22-2/6/9-9-US"		
737807K001	"1-1195760-3"		
401497-000	"5-1193031-1", "EPD52987A"		
A28513K001	"6-1202049-0"		
645557-000	"4-1195098-0"		
314993K001	"7-1192383-8"		
EM0387-000	"EPD-RWC-22228-L016"		
CM4211-000	"44A1221-24-9/92-9CS2812"		
919045K001	"1-1197132-8"		
E81330-000	"7-1202049-0", "EPD-NAV-36501"		
140907K001	"5-1191021-2"		

717209-000	"4-1195610-2", "EPD52775A-20-0"		
451009-000	"44A0311-18-9CS2745BAR REL", "2-1193387-5"		
919647-000	"6-1197136-5", "EPD-RWC-10074"		
292505-001	"4-1192217-4"		
CA3084-000			
CA8695-000			
E16904K001	"2-1201417-3"		
D44855-000	"4-1201038-0", "EPD-RWC-10950-L103"		
230185K001	"5-1191691-3"		
CF4629-000	"44A0712-20-9CS2979", "6-1899218-9"		
EG8850-000	"400R1131-20-0/6/9-9"		
EM7711-000	"EPD-RWC-22044"		
E14631-000	"4-1201130-4", "EPD-RWC-17047"		
380929-000	"2-1192848-6", "EPD51412A-24-0"		
791091-000	"4-1196127-7", "EPD52947A-12-0"		
686771K001	"9-1195392-9"		
CN7930-000	"EPD-RWC-17612CS3287"		
831645-000	"6-1196493-9", "EPD68105A-US"		

297775-000	"1-1192255-5", "EPD8477B"		
EH2576-000	"44A9677-20-ELC4-9CS3433"		
396281-000	"4-1192972-1", "EPD51047A-18-0"		
D42382-000	"5-1200497-3", "FLDWC1321-20-9/90-9"		
384261-000	"2-1192883-9", "44A0121-20-9/96"		
CJ7744-000	"EPD52416A-L200"		
000742-000	"3-1200082-8", "EPD-RWC-17305"		
383357-000	"2-1192874-8", "44A1121-22-9/96-9"		
383156-000	"1192872-7", "44A0124-26-6/9"		
631171-000	"6-1194994-3", "EPD-RWC-15752"		
316837-000	"6-1192400-7", "EPD-RWC-15754"		
053423K001	"9-1190407-6"		
282762-000	"4-1192125-4", "44A0111-22-913"		
734213K001	"3-1195734-2"		
C85069K001	"4-1201002-4"		
387001-012	"6-1192902-5", "44A1111-22-9-9-MX"		
883295K001	"8-1196874-0"		
CB7448-000	"44A4231-20-0/2/9-9"		

CL6052-000			
378867-000	"1192835-2", "44A1121-20- 92/96-9"		
533993-000	"44B1111-24- 9-90CS1271", "1-1194192- 6"		
A76985-000	"2-1200577- 6", "EPD- RWC-17038"		
494475-000	"9-1193697- 0", "EPD- ADD-10111"		
384933-000	"3-1192888- 5", "44A1221- 24-9/92-9"		
ER5386-000	"EPD-RWC- 25871-L206"		
CS7766-000	"EPD-DND- 21488-L099"		
341901-000	"8-1192577- 6", "EPD33489A- US"		
CS9467-000	"EPD40420A- US"		
CZ3156-000	"EPD-RWC- 19941-L016"		
467863K001	"6-1193506- 9"		
061249-000	"7-1190463- 2", "44A9625- 12-9CS2745"		
E70943-000	"2-1202115- 2", "EPD- RWC-19734"		
470491-000	"44/0414-26- 9CS2346", "6- 1193525-4"		
928233-000	"44B9536-22- MST3- 9CS3023", "7- 1197197-0"		
EG8793-000	"400R0111- 16-9"		
CN5755-000			
CJ0162-000			

CR7938-000	"EPD-RWC-22367"		
535595-000	"1-1194205-1", "EPD-RWC-14668CS2888"		
539453-001	"44A0111-20-9CS448", "7-1194232-7"		
441541-001	"345/37B-22-6-0CS1913", "1193320-1"		
301047-001	"2-1192280-6", "44AM1111-22-9-3"		
CA3620-000			
A93907K001	"1201056-2", "EPD-ROK-10512-COC-KIT-1"		
EF9972-000	"EPD-RWC-22251"		
A54326-000	"7-1201138-3", "EPD100540 A-ISR-L099"		
547345-000	"44A9681-18-0/9-9CS2748", "1-1194309-7"		
384382-000	"3-1192884-7", "44A0121-26-2/9-US"		
531697-000	"44AM1111-16-951-9", "3-1194175-2"		
CR1663-000	"44A0811-12-9-L050"		
628380-000	"44B1111-24-9-91CS1271", "1194975-3"		
408403-000	"7-1193080-3", "44AM3121-22-6/96"		
530327-000	"44A9966-10-9CS2745", "3-1194165-9"		

421087K001	"3-1193172-5"		
730369-000	"44AM1151-16-F917-9", "9-1195705-0"		
885776-000	"44AM3121-20-2/9", "9-1199163-0"		
025247-000	"9-1190195-1", "CMC-0576-18-0CS2327"		
096413K001	"2-1190707-0"		
EK8652-000	"44A1221-12-0/9-9-L386"		
543199-000	"9-1194260-0", "EPD52745A-18-0"		
C07709K001	"6-1200583-1"		
452119-000	"345/69-14-3-0", "9-1193394-7"		
283115-002	"4-1192131-4", "44A0111-22-96-US"		
297275-000	"5-1192251-0", "44AM1111-18-954-9"		
519147K001	"1-1194074-3"		
CU3840-000			
158379-000	"1-1191144-8", "44A9083-14-9CS2745BAR REL"		
998699K001	"9-1197721-0"		
376304-000	"1-1201203-7", "44A1321-22-0/9-9-US"		
A12699K001	"2-1200501-2"		

523609-000	"5-1194113-1", "EPD-RWC-15040"		
CU0506-000	"44AC1121-22-9/96-9"		
CS7726-000			
382623-000	"2-1192866-1", "44A1122-20-0/9-9-US"		
CF8496-000	"44A1131-22-0/2/9-9CS406"		
C12522-000	"44B5141-12MST4-9C1401L092", "5-1200715-2"		
977229-000	"44A9439-22-9-9CS527", "4-1197550-8"		
791181K001	"1196128-2"		
753415K001	"8-1195873-0"		
960494-000	"4-1199140-7", "EPD-OLF-10168"		
824225-000	"1-1196437-1", "EPD51901A-14-0"		
071885K001	"5-1190539-2"		
434405-000	"9-1193266-5", "EPD42681A"		
154057-000	"1191113-5", "FLDWC0311-18-9"		
258913-000	"3-1191894-8", "EPD-ADD-10013"		
206285K001	"6-1191495-1"		
204949-000	"2-1191485-4", "EPD-CAN-10021"		

180841-000	"4-1191314-7", "EPD-RWC-10944CS2656"		
357011K001	"1-1192679-6"		
301051-001	"3-1192280-2", "44AM1111-22-9-5"		
751401-000	"44AM1111-16-950-9", "1-1195859-9"		
C04002-000	"8-1201447-3", "EPD100897 A-US-L099"		
D18740-000	"EPD5846"		
636111-000	"44A0141-20-MST4CS2109", "7-1195029-0"		
414908-000	"9-1198059-3", "44A0111-12-904-1KF"		
300173K001	"7-1192273-2"		
282786-000	"3-1192126-7", "44A0111-24-902"		
CB2594-000	"44AM1811-22-9-9CS3191", "9-1899159-1"		
3C0392-000	"3-1193002-5", "EPD5376"		
439259K001	"1193301-3"		
CU8796-000	"EPD-DND-21490-L177"		
015447K001	"3-1190121-3"		
CY4263-000			
CS7807-000			
617064K001	"7-1198866-6"		

541415-000	"44/0414-26-9CS1706", "9-1194245-5"		
CY1271-000	"EPD-DND-21668"		
EL5746-000	"44AM1141-22-F003-9CS3450"		
387025-000	"1-1192904-5", "44A2111-22-9-9-US"		
CB0925-000			
CW4992-000	"EPD-RYQ-23559-L012"		
282598-002	"6-1192119-6", "44A0111-16-92-MX"		
926203K001	"4-1197183-6"		
263365-000	"1-1197864-4", "44A0711-18-9-BARREL"		
103711-000	"8-1190758-2", "EPD50631A"		
464155-000	"4-1193480-7", "EPD-RWC-15740"		
CS2606-000			
CU3941-000	"EPD21826G-L099"		
151667K001	"3-1191096-0"		
D87485K001	"8-1200876-8"		
571283K001	"6-1194530-7"		
732406-000	"44B1121-24-0/9-94", "3-1195721-0"		
758891K001	"7-1195912-3"		
386872-000	"4-1200236-0", "44A1121-20-9/95-9-US"		

178573K001	"5-1191298-9"		
CA2353-000			
EH5855-000			
CR2065-000	"EPD-DND-21479-L106"		
383342-000	"1192874-3", "44A1121-22-0/9-91"		
231625-000	"7-1191701-2", "44/4421-22-92/96-9CS1784"		
145927-000	"7-1191054-8", "EPD47168A"		
BM9086-000	"44A1221-16-0/9-9CS3432"		
384306-002	"6-1192883-5", "44A1141-20-3/5/6/9-9"		
F83260-000	"ASC15865A-20-0", "7-1199617-1"		
CA6564-000	"44A4122-22-1/9-9CS3185"		
671259-000	"4-1195282-1", "EPD-RWC-15758"		
733407-000	"4-1195728-4", "EPD-RWC-13644"		
C53898K001	"2-1200588-5"		
371303K001	"2-1192781-7"		
301013-000	"8-1192279-0", "44AM1111-14-9-9"		
600759F001	"5-1194753-8"		
C60355-000	"44B1111-22-9678-9CS3018", "3-1200072-1"		

683778-000	"44B5111-20-9-9", "4-1195373-2"		
227321K001	"4-1191673-0"		
501315-000	"1-1193748-4", "EPD86148A"		
CU9606-000	"EPD-DND-21452-L016"		
E64988K001	"3-1202129-0"		
CS7774-000	"EPD-DND-22560-L099"		
606416-001	"44A9416-22-9CS1981", "5-1194797-9"		
EM1354-000	"400R1141-14-0/2/5/9-0"		
961923K001	"6-1197441-6"		
003239K001	"6-1190024-4"		
CJ6847-000	"EPD-RWC-10438-L202"		
911482-001	"44B5131-16-MST3-9CS1728", "9-1197078-7"		
CY9209-000	"44A1231-14-0/5/9-9"		
CS1829-000			
469091K001	"6-1193515-6"		
231181-000	"5-1191698-9", "EPD51410A-24-0"		
259645K001	"5-1191899-5"		
124423-000	"6-1190904-9", "EPD6566-22-0"		
937763K001	"6-1197264-3"		
CM4937-000	"EPD-RWC-21091"		

267968-000	"3-1198990-2", "EPD-ROK-10491"		
F80799-000	"8-1201189-1", "44/1421-16-9/9-9"		
CX1606-000	"EPD-DND-21535"		
287807-000	"2-1192183-8", "44A0111-18-964"		
955155-000	"44A0711-16-9-US-1KF/1", "1197395-4"		
CP3579-000	"EPD-RWC-16867"		
E86023K001	"6-1200449-3"		
CF3491-000	"44AM1141-22-MST4-9CS2994", "6-1899210-8"		
186315K001	"1191353-3"		
382533-000	"9-1192864-4", "44A4121-22-0/9-9"		
343519K001	"7-1192587-7"		
D54959K001	"5-1201003-8"		
D74180-000	"44A9625-12-90CS2745BARREL", "8-1200380-3"		
444061-000	"2-1193337-7", "EPD4744D"		
336827-000	"2-1192543-3", "44/0424-26-0/9CS2537"		
628672K001	"2-1198862-8"		
123451K001	"8-1190897-9"		
893403-000	"1196949-1", "CMC-0403-X-0"		
CF3713-000			

CJ3830-000	"345/M03J-14-4-0CS2041"		
734458-000	"44AM1121-16-905/924-9-1KF", "6-1198058-7"		
302885-000	"4-1192294-1", "EPD-RWC-14184"		
388580-000	"4-1192917-7", "44T1111-20-9-9"		
335981K001	"5-1192537-7"		
EH2499-000	"44A9632-16-0/9-9CS3433"		
306344-000	"4-1192320-1", "44AM1131-22-0/5/9-9"		
C00359-000	"7-1199868-6", "EPD-ROK-10476"		
017751-000	"6-1190138-1", "EPD37963A-US"		
086181K001	"1190636-9"		
386916-000	"9-1192901-4", "44A0121-22-9/92"		
CU8802-000	"EPD-DND-23034-L146"		
114231K001	"8-1190832-6"		
357749-000	"1-1192684-4", "44/1434-24-9/93/96-9"		
EG4277-000			
CV6023-000	"EPD-RWC-23763-5CF/1"		
317339-000	"3-1192404-6", "EPD52965A"		
704989K001	"6-1195529-4"		
021267K001	"4-1190165-8"		

534687-001	"44A2131-22-1/6/9-9CS453", "9-1194196-3"		
D62282-000	"7-1201003-3", "EPD65195A-US"		
270832-000	"1192006-9", "44/0411-12-9"		
CN2576-000			
701510-000	"44A1811-10-90-9-1KF", "9-1198058-6"		
758343K001	"8-1195908-6"		
971125-001	"44/0412-24-9CS1220", "8-1197506-1"		
D60328-000	"5-1201391-3", "EPD-ROK-10326-L027"		
589641-000	"2-1194665-8", "EPD51482A-18-0"		
375341-000	"8-1192811-9", "44/1414-26-9-9"		
730249-000	"1195705-4", "EPD-RWC-13837"		
772290-000	"5-1196015-7", "EPD23074A"		
435643K001	"4-1193275-1"		
CS2816-000	"44A1121-18-0/9-9-F871"		
CL5380-000	"44A4122-24-1/9-9CS3185"		
747555K001	"7-1195831-9"		
CY1455-000	"EPD-DND-21461"		

C66874-000	"1201179-4", "EPD-RWC- 18569-L099"		
008815-000	"5-1190068- 1", "44A9341- X-0CS2000"		
250094-000	"5-1201055- 9", "EPD- ROK-10511"		
CJ5174-000			
253311-000	"5-1191853- 3", "44B9536- 16-MST3- 9CS1728"		
930229K001	"3-1197211- 5"		
209836K001	"4-1200286- 9"		
ER2072-000			
CR1562-000	"44A1131-16- 2/2/9-9-1KF- 1"		
945411-000	"44A1111-12- 9-0", "9- 1197316-1"		
839002-000	"44A1121-20- 9/93-0-US", "2-1199169- 9"		
CW0103-000	"EPD-RWC- 20307-L028"		
262005-000	"9-1191926- 0", "44A0711- 12-9-US"		
583047K001	"5-1194618- 0"		
080625-000	"3-1190598- 8", "44AM1131- 22-3/6/9- 9CS2399"		
D64963-000	"44AM1821- 22-9/96- 9CS2994", "8- 1200962-1"		
350937K001	"7-1192638- 2"		
022371K001	"2-1190173- 9"		

EP1359-000	"EPD-RWC-25207"		
092783-000	"7-1190680-7", "44/7006-24-9CS2491"		
297515K001	"3-1192253-0"		
EG4276-000			
122529K001	"4-1190891-4"		
D74999-000	"1-1200881-7", "EPD-RWC-18031"		
CU1804-000			
447703K001	"2-1193364-5"		
CZ7560-000	"EPD-RWC-14915-L012"		
259699K001	"9-1191899-1"		
E42155K001	"1200809-5"		
CP4245-000	"44A1122-16-9/96-9"		
F65473K001	"8-1201818-3"		
CA4835-000	"EPD20077D-US"		
378004F003	"5-1192830-6"		
CU3841-000	"EPD40654D-L099"		
453999K001	"9-1193407-6"		
826363-000	"1196455-9", "EPD64090A"		
364523K001	"7-1192733-3"		
CW9668-000			
182910-000	"4-1202073-7", "44A0111-14-90-2KF"		
263929K001	"4-1191942-9"		

123533-001	"6-1190898-2", "FB-44-7026A-0213CS896"		
EK8328-000	"EPD-RWC-17201-L012"		
340291K001	"2-1192567-7"		
EG3683-000			
CA7753-000	"EPD-NAV-32504"		
810219-000	"3-1196296-6", "EPD52187A-12-0"		
D87301-000	"EPD-RWC-19899"		
ER5167-000	"44AM1121-22-9/96-9CS3529"		
655221-000	"8-1195168-4", "EPD-RWC-13715-L027"		
EG8844-000	"400R1131-14-0/6/9-9"		
595329-001	"345/50B-16-37-OCS1913", "1194708-4"		
CR8081-000	"44A1101-20-A048-9"		
CX1587-000	"EPD-DND-21459"		
471156K001	"2-1201177-1"		
CX6623-000			
954821-000	"44A9627-12-0/2/9-9CS2746", "6-1197392-3"		
885875K001	"1196893-7"		
386925-000	"44A0121-22-9/904"		
CU2614-000	"EPD-DND-21499-L016"		
393029-000	"9-1192948-7", "4J3S-14-F10-8"		

828797-000	"44AM1111-1 6-966-9", "1196472-3"		
CN2362-000	"EPD-RWC- 21433"		
568707K001	"8-1194515- 0"		
104997-000	"6-1190767- 5", "44T1121- 20-0/9-9"		
CR8529-000	"EPD98824A- US"		
393036-000	"1192949-4", "4J4S-18-F10- 8"		
375005-002	"4-1192809- 1", "44/2414- 24-9-9"		
382026-000	"1-1192856- 1", "44A1121- 20-6/9-9-MX"		
282102-000	"2-1192104- 9", "44A0311- 18-9-US"		
996599K001	"2-1197706- 4"		
105721K001	"6-1190772- 0"		
EM5643-000	"EPD-RWC- 24980"		
282704-000	"6-1192123- 4", "44A0111-14- 95"		
405381-000	"3-1193059- 4", "44A9673- 20-9CS2745"		
740463-000	"44A0841-20- MAS4CS2017 ", "6- 1195779-8"		
E47392K001	"5-1200586- 1"		
144215-000	"4-1191042- 3", "44AM1111-1 8-940-9"		
ER2899-000	"44A0111-14- 9CS3030"		

037209-000	"4-1190287-8", "44/4444-26-F137-9CS1784"		
531089-000	"44AM1111-16-900-9", "9-1194170-0"		
C80265K001	"5-1201863-0"		
F63795-000	"3-1201927-2", "44A0111-16-92-L030"		
389852-000	"4-1192926-6", "44A3131-18-0/2/9"		
270465K001	"2-1192001-3"		
CN5900-000			
832883K001	"7-1196502-1"		
518483K001	"6-1194069-7"		
719139-000	"9-1195624-4", "EPD-RWC-11195"		
134919-000	"3-1190980-4", "44/0411-20-9CS470"		
911199-000	"8-1197076-9", "EPD48805B-US"		
502413K001	"7-1193773-1"		
383737-000	"4-1192877-5", "44A0121-26-3/9-US"		
C26863-000	"8-1200764-7", "EPD-RWC-17894"		
ER5174-000	"44AM1111-22-9-9CS3529"		
438354-000	"5-1193294-6", "EPD4750C-US"		
EH9624-000			

F00612K001	"1-1201055-9"		
938661K001	"5-1197271-9"		
CJ5186-000	"EPD-CAN-10022-L016CS2979", "8-1899292-1"		
636163-000	"9-1195029-9", "EPD52207A-CS2834"		
CB7004-000	"EPD-NAV-07507"		
E72128K001	"1200403-6"		
929925-001	"2-1197209-2"		
CU3933-000	"EPD27727A-L099"		
447003-000	"4-1193359-6", "EPD-RWC-14219"		
E13165-000	"4-1199951-7", "EPD4707-US"		
659918-000	"4-1201141-6", "EPD100242 A-US-L099"		
161943-000	"4-1191169-3", "44A1131-20-F862-90"		
C57780K001	"2-1200588-6"		
267453-000	"2-1191974-1", "44A9091-16-0/2/5/9-9"		
141121K001	"9-1191022-8"		
265013-000	"7-1197969-6", "44A0812-20-9-US"		
EM6120-000	"44A9970-14-90CS3433"		
EM6585-000	"EPD-RWC-25123"		
389783-000			

306266-001	"4-1192319-8", "44AM1121-26-0/9-9"		
CU9234-000			
506488K001	"1-1199140-0"		
471443-000	"44/0411-14-9CS470", "5-1193532-9"		
436341K001	"2-1193280-1"		
762819-000	"1195940-1", "EPD-RWC-14218"		
EG5966-000	"EPD62289A-US"		
CW4838-000	"EPD-RWC-20258-L108"		
351433-000	"1192642-2", "44A9677-18-ELC4-9CS2746"		
CA8027-000			
EP1302-000	"EPD-RWC-25206"		
932097-000	"44A9089-16-0/9-9CS2514", "7-1197224-9"		
CP2252-000	"EPD-DND-21667-L108"		
947339K001	"2-1197330-1"		
056861-000	"6-1190432-0", "EPD-RWC-11674"		
503015-000	"2-1193786-7", "EPD-RWC-14223"		
054672-001	"2-1190417-2", "44A0111-18-9CS448"		
358083-001	"1-1192687-8", "44A0111-20-9CS289"		
644547-001	"44B1811-18-9-9CS2018", "4-1195091-8"		

CF1667-000	"FLDWC0311-14-9CS2736"		
829972-000	"1200289-1", "FLDWC0311-20-9CS2979"		
CR9946-000			
255959-000	"3-1191873-8", "44A9177-20-8CS1747"		
514977-000	"1-1194045-3", "CMC-0009-22-0"		
CX2625-000	"EPD-RWC-21527CS3092"		
044229K001	"9-1190339-6"		
578566-000	"44/0411-22-9CS2979", "6-1199657-6"		
562273-000	"44A9966-12-9CS2745BARREL", "9-1194442-4"		
328346-000	"7-1198065-4", "44AM1121-16-905/962-9-1KF"		
CJ6172-000	"EPD52946A-CS2979", "4-1899297-3"		
583891-000	"44A1231-18-F862-9", "3-1194624-2"		
843697-000	"44AM1121-16-6/9-0", "1196582-2"		
121161-000	"2-1190881-7", "44/0411-22-9CS470"		
CP6360-000	"EPD-DND-22022"		
EG5965-000	"EPD62288A-US"		
C22407-000	"6-1200880-0", "EPD-RWC-18029"		

425062-001	"9-1193199-6", "FB-44-4624-0209CS1578"		
CJ1792-000	"44A0111-20-9-5CS3144-L193", "2-1899270-0"		
EL5750-000			
EL7179-000	"EPD-RWC-24644"		
CR9463-000	"EPD-RWC-22062"		
059045K001	"1190448-8"		
D04966K001	"7-1201073-4"		
548796K001	"5-1200087-1"		
389613-000	"6-1198898-7", "44A1121-14-6/9-9"		
705449-000	"44B1121-24-0/9-97CS2024", "5-1195532-4"		
396416-000	"1-1197951-1", "44A1221-14-9/96-9-1KF/1"		
C92432K001	"2-1201012-6"		
404380-001	"4-1193052-4", "44A0114-26-9CS448"		
CW5807-000	"EPD108228 A-US"		
743447-000	"345M18B-18-21-0CS2041", "5-1195800-2"		
CY4093-000	"EPD-RWC-19928-L316"		
CJ6327-000			
386593-000	"1199214-9", "44A0121-12-9/96"		
A94350K001	"5-1200589-3"		

E23690K001	"2-1200593-4"		
CN5754-000			
CA2668-000			
375027-000	"5-1192809-6", "44/1411-20-9-9"		
3C0304-000	"2-1193002-7", "EPD5276-X-0"		
952915K001	"1197379-5"		
CP3789-000	"EPD20323B-US"		
383239-000	"7-1192872-0", "44A1131-26-3/6/9-9-US"		
CZ6138-000	"EPD-RWC-23448-L012"		
E34689K001	"4-1200581-3"		
EM7717-000	"EPD-RWC-23542"		
EL5751-000			
860612K001	"2-1199501-5"		
CA8028-000	"EPD104250 A-US"		
381971-000	"2-1201719-1", "345M04J-20-30-0CS2041"		
955822-000	"44AM1121-22-0/9-91", "3-1197400-0"		
139105-000	"8-1191008-4", "EPD52692A-X-0"		
123496-000	"6-1198061-3", "44AM1121-16-904/95-9-1KF"		
379163-002	"1-1192836-1", "44A9237-24-0"		

469757K001	"5-1193520-4"		
149739-001	"6-1191082-9", "44A9416-24-9CS1981"		
956923K001	"1-1197408-4"		
CF4748-000	"44B4124-24-1/9-9CS3217"		
C22417-000	"1-1200803-4", "EPD46193A-US"		
CX1589-000	"EPD-DND-21536"		
303511K001	"6-1192298-9"		
051163K001	"9-1197852-6"		
CF9540-000	"EPD44056A-US"		
995201K002	"1-1197698-1"		
EP9201-000	"44A1321-12-9/9-9C3030L338"		
776413-000	"44AM1111-16-962-9", "9-1196044-6"		
881397-000	"4-1196861-5", "EPD-CAN-10019"		
EM6584-000			
739787-000	"3-1195774-1", "EPD51404A-24-0"		
363014-000	"8-1192721-4", "44A1811-16-9-9"		
CJ9698-000	"44A7907-16-0CS2116-L109"		
382827-000	"3-1192868-4", "44A1122-24-0/9-9-US"		
A51233-000	"1-1201833-1", "44A7241-26-9-L148"		

973543K001	"2-1197524-8"		
745940-000	"5-1199176-3", "EPD-RWC-16796"		
306091-001	"8-1192317-4", "44AM1121-20-9/96-9"		
D78830K001	"1-1201448-8"		
306748-000	"7-1192323-9", "44AM1121-24-9/96-3"		
CU1225-000	"EPD-DND-21441-L016"		
495277-000	"44A0111-22-9(FS)", "1-1197968-0"		
383379-000	"5-1192874-2", "44A1131-20-0/2/9-91"		
306416-001	"2-1192321-1", "44AM1141-22-0/2/5/9-9"		
714967-000	"1-1195595-8", "EPD52159A-16-0"		
840807K001	"8-1196559-4"		
282698-000	"3-1192123-6", "44A0111-20-96-US"		
ER5795-000	"44AM1121-18-9/96-9CS3529"		
CF3420-000			
346993K001	"1192612-5"		
EH8647-000	"400R0311-22-9"		
CM9792-000	"EPD-RWC-21232"		
282928-000	"1192129-9", "44A0111-18-900"		

732021-000	"5-1195718-3", "FB-44-7026A-0215CS896"		
565965-000	"44A9673-18-90CS2745BARREL", "3-1194469-4"		
CB1558-000	"EPD-RWC-20086"		
348349-000	"4-1192621-4", "44A9647-14-9-MIL"		
382711-000	"9-1192866-9", "44A1121-20-2/9-9"		
C05418-000	"3-1201692-0", "44A0111-10-9-4"		
387036-000	"3-1192904-3", "44A1211-22-9-9-US"		
334459-000	"5-1192526-7", "EPD-RWC-10097"		
597815-000	"44A9650-14-0/9-0", "8-1194726-4"		
758154K001	"9-1197924-5"		
C73333-000	"9-1201407-0", "44AM1111-16-955-9-1KF"		
CB4390-000	"EPD21886A-US-L106", "2-1899168-9"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.