



17-Feb-2022

PCN #: P-22-022184

Subject : Spec 44 and FLDW Wires

Description of Change : TE Connectivity is changing the sourcing and grade for PVDF resin used as insulation material for Spec 44 and FLDW Wires. This change is to an alternate grade with similar performance and characteristics.

Reason : Part status change. The technical assessment on alternate PVDF grade has been completed by TE's technical team and the results demonstrate similar properties and performance to the existing PVDF grades. These results are obtained through validation trials of various finished parts using the alternate grade as insulation material. No change to form, fit and function of the finished parts has been observed. Test reports on the wire characteristics can be provided upon request.

Key Dates :

Contact By Date: 28-Mar-2022

Implementation Date: 28-Mar-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
382928-000	"5-1192869-2", "44A0121-26-9/96"		
E24774-000	"1200597-8", "EPD-ROK-10373-L083"		
EG5690-000	"EPD-RWC-24142-L348"		
089272-000	"6-1198719-7", "44A9710-22-5/9-9"		
336190-000	"9-1192538-2", "44B4121-24-9/96-9"		
771801K001	"2-1196012-9"		
422905-000	"8-1193184-0", "44A9586-26-9-2"		

C72503K001	"3-1200524-7"		
037789-000	"9-1190291-2", "EPD68119A-US"		
F09625-000	"1-1201927-9", "44A0111-16-96-L030"		
923275-000	"44A9586-26-9-1", "9-1197162-0"		
386616-000	"1201394-4", "44A1131-24-2/6/9-9-US"		
507113-000	"1197832-4", "EPD61896B-US"		
361257K001	"4-1192709-5"		
935243-000	"5-1197857-2", "EPD-ADD-10188"		
700919-000	"7-1195501-8", "EPD71636A"		
129619-000	"3-1190941-6", "EPD51417A-X-0"		
624772-000	"44A0211-18-9-1KF", "8-1199511-2"		
383493-000	"6-1192875-6", "44A1121-22-0/9-98"		
CB5919-000	"44/0421-24-9/9"		
EM5438-000	"EPD-RWC-23496CS3490"		
EM3775-000	"44AM1121-22-0/9-9-L227"		
EH7673-000	"EPD-DND-21444"		
CU8797-000			

355389-000	"2-1192668-4", "44B1121-24-0/9-93"		
884073K001	"7-1196880-4"		
711771-000	"44A2121-20-1/9-9CS006", "9-1195575-4"		
E66085K001	"1-1200692-8"		
E81076-000	"7-1200581-4", "EPD-RWC-17783"		
977787-000	"4-1197554-8", "EPD-ROK-10344"		
CR1999-000	"44B1121-20-0/9-9"		
A56982K001	"6-1200803-1"		
442393-001	"7-1193325-9", "44A0111-26-9CS289"		
946535-000	"6-1197324-3", "EPD-RWC-12382"		
370778-000	"1-1201799-3", "44/1441-22-9/9/9/9-9"		
C77653-000	"44A0211-16-9CS3030", "6-1200301-9"		
740419K001	"2-1195779-5"		
737172-000	"9-1201920-6", "44AM1131-20-MST3-9CS2994"		
677314-000	"44A1221-14-0/9-9-1KF/1", "6-1198781-8"		
D64961K001	"2-1200712-8"		
384641-000	"1-1197969-1", "44A7245-20-6/9-9"		
EF4946-000	"EPD-RWC-19934-L341"		

EG5962-000			
282072-000	"2-1192101-3", "44A0112-22-9-US"		
389940-002	"7-1192927-4", "44A9051-X-0"		
722000-001	"44B5141-12-MST4-9CS1728", "2-1195645-1"		
939896K001	"1-1199140-8"		
836797-000	"44AM1151-16-F918-9", "6-1196531-7"		
004545-000	"7-1190034-4", "EPD51068A-22-0"		
591189K001	"4-1194676-8"		
EH2690-000	"44A4331-22-0/2/9-9CS3433"		
382735-000	"2-1192867-6", "44A1221-22-0/9-9-MX"		
EM8270-000			
D14158-000	"7-1200589-3", "EPD-RWC-17768"		
791909-000	"44B1121-24-0/9-901", "1-1196133-5"		
011033K001	"2-1190087-4"		
092795-000	"8-1190680-4", "44A9436-24-9/96CS2312"		
348866-000	"8-1200501-2", "FLDWC1331-20-9/90/92-9"		
CP5189-000			
EM6121-000	"44A9966-12-90CS3433"		

A87860-000	"6-1200552-5", "FLDWD132 1-10-0/9-9CS3050"		
E02098K001	"9-1200583-8"		
905897-000	"44AM1121-20-9/918-9CS1726", "6-1197038-6"		
C49115-000	"8-1201265-4", "44A7620-20-9/5-9F947C2979"		
550900-000	"9-1199198-8", "EPD-ROK-10374"		
735497K001	"1-1195744-3"		
CJ7477-000	"FLDWC1321-18-9/90-9CS2959"		
386936-000	"44A0121-22-9/917"		
A62631K001	"5-1200354-9"		
CN3183-000			
D02252K001	"6-1200354-6"		
116181K001	"3-1190846-8"		
328367-000	"5-1192483-1", "EPD37111B-US"		
CJ1814-000	"3-1899270-7", "44A0111-22-9-22CS3144L193"		
F36266-000	"2-1201758-1", "345/70-12-4-0"		
909334-000	"44A0113-24-9CS2979", "3-1199961-5"		
961145K001	"4-1197436-9"		
EG8830-000	"400R1121-18-0/9-9"		

060347K001	"4-1190457-7"		
847951K001	"1-1196613-9"		
382382-000	"4-1192862-7", "44A0121-20-0/9-MX"		
EG2505-000			
681853-000	"44A9673-22-9CS2745BAR REL", "1195360-1"		
C31327K001	"9-1201652-0"		
CR2146-000	"44A1121-24-0/9-0-US"		
CA7393-000	"EPD-RWC-18522CS3127-L155"		
382234-000	"5-1192858-1", "44A1121-26-0/9-9-US"		
778796-000	"7-1200714-6", "EPD-RWC-17612"		
CF3423-000			
775957K001	"7-1196041-3"		
384496-000	"4-1200089-7", "EPD-PFM-10048CS2962"		
C57682-000	"1201138-4", "44A0112-12-9CS2979"		
584047-000	"345M12B-26-12-0CS2041", "4-1194625-7"		
CS5793-000			
CA3085-000	"EPD-RWC-20163-L172"		
912179K001	"9-1197083-4"		
653107K001	"6-1195154-0"		
F54070K001	"1200994-9"		

366623-000	"9-1192748-3", "44A1131-24-9/90/92-9"		
CB7021-000			
CS2550-000	"44A0111-20-9-F871"		
CN8359-000	"44/0412-12-9CS1038"		
836455-000	"4-1196529-1", "EPD-RWC-13718"		
349336K001	"2-1201196-3"		
3N0010-000	"9-1193011-7", "EPD8477A"		
C62919K001	"7-1200583-1"		
A86572-000	"44A1111-16-9-96-US", "7-1200801-2"		
476013K001	"3-1193565-0"		
459357-000	"8-1193445-3", "EPD-RWC-15738"		
E65732-000	"44B1111-22-9-9CS3018", "8-1200021-0"		
669273-000	"44AM1121-20-9/937-9CS1726", "7-1195269-6"		
593808-000	"1-1194695-5", "EPD4745D-US"		
389624K001	"7-1198260-4"		
374864-000	"1192808-7", "44A1121-24-9/90-9"		
CR3720-000			
CX5296-000			
EG8599-000	"EPD40634D-US"		
F01864K001	"1-1200711-0"		

C12596K001	"6-1200354-2"		
261228-000	"1-1191912-6", "44A9083-15-9-US"		
CS6943-000	"EPD-DND-21479-L099"		
D54862K001	"2-1200583-8"		
752667-000	"44A9441-20-MST3-9CS527", "1195868-6"		
270830-000	"1192006-2", "44/0414-20-9"		
370779-000	"3-1192777-9", "44/1431-22-0/2/9-9"		
158935-000	"4-1191148-9", "EPD-RWC-15748"		
255591K001	"9-1191870-1"		
103519K001	"2-1190757-1"		
854989-000	"3-1196664-7", "EPD-RWC-10938"		
E39232-000	"6-1201237-7", "EPD92240A-US"		
C20350-000	"1-1200280-3", "EPD-RWC-17204"		
245444-000	"9-1199830-6", "44A9966-10-9CS2979"		
068880-000	"4-1199423-8", "44A0111-26-9CS2896"		
377477K001	"6-1192826-1"		
813465-000	"1196329-5", "EPD5663-X-0"		
181899-000	"7-1191321-6", "44A0811-10-920"		

282785-000	"2-1192126-8", "44A0111-24-96-MX"		
664153-000	"1195234-6", "CMC-0578-18-0CS2327"		
193169K001	"2-1191401-4"		
EM0371-000	"EPD108173 A-US"		
072337-000	"4-1190542-8", "EPD-RWC-13610"		
CC8747-000	"44A1121-22-9/96-6"		
383346-000	"2-1192874-0", "44A1121-22-0/9-97"		
EF7262-000	"44A1131-22-0/2/9-9CS3068"		
EH2511-000	"44/4432-22-F001-9CS3434"		
E37341-000	"9-1200290-7", "EPD-RWC-17029"		
110343-000	"8-1190805-3", "EPD5667-X-0"		
C91489-000	"44A7657-22-2/9CS2979"		
550603K001	"3-1194345-9"		
504667-000	"345M09A-22-38-0CS2041", "9-1193811-9"		
C02834-000	"4-1201391-1", "EPD-RWC-18510-L016"		
CX5072-000	"44A0221-18-9/9CS3030"		
418829K001	"7-1193155-0"		
411991-000	"1-1193107-5", "EPD-RWC-14837"		

F60683-000	"EPD-RWC-16769", "1-1200163-4"		
504933K001	"7-1193813-7"		
127643-000	"8-1190927-4", "44A9675-18-0/9-9CS2746"		
387994-000	"1192914-1", "44A1313-20-9-9"		
E30916K001	"8-1201282-8"		
A56342-000	"4-1201280-1", "EPD4744D-IRL-L016"		
CU8791-000	"EPD-DND-21536-L146"		
644455K001	"6-1195090-5"		
954559-000	"44/1422-26-9/96-9", "6-1197390-9"		
833054-000	"8-1197956-2", "EPD-RWC-16329"		
362999-000	"345M15B-22-74-0CS2041", "6-1192721-0"		
CX2064-000			
829889K001	"4-1196480-6"		
D89002-000	"5-1201653-8", "EPD86559B-US"		
536653-000	"5-1194212-0", "CMC-0440-22-10-2CS2320"		
740199-000	"5-1195777-4", "EPD52093A-CS2808"		
728668-001	"44A0111-24-9CS289", "7-1195693-9"		

306492-000	"1192322-3", "44AM1121- 22-0/9-95"		
012765-000	"4-1190100- 0", "44A0211- 24-9CS2831"		
C35188-000	"1200371-1", "EPD-RWC- 16889"		
481113-000	"3-1193601- 8", "EPD- ROK-10153"		
A38409K001	"4-1201885- 6"		
CX1599-000	"EPD-DND- 21479"		
980815-000	"44/0414-24- 9CS470", "2- 1197579-0"		
CB7088-000	"EPD-RWC- 19927"		
688342-000	"44B1111-24- 9-97", "7- 1195406-1"		
107384-000	"8-1200272- 4", "EPD- RWC-17213"		
3W0122-000	"1193017-1", "EPD4648C"		
257767K001	"1-1191886- 2"		
539574K001	"6-1201055- 4"		
A26532-000	"1-1200691- 3", "EPD- ROK-10332- L086"		
779827-000	"44/0414-24- 9CS2251", "8- 1196068-6"		
F41827-000	"EPD-RWC- 17879", "4- 1200692-9"		
488933-000	"1-1193658- 5", "EPD- RWC-15761"		
CB3820-000	"345/68-14-2- 0"		

287045-000	"2-1192174-3", "44A0211-20-90-MX"		
362106-000	"4-1192715-8", "44A7657-22-2/9"		
CB6849-000	"EPD-RWC-18864"		
D81365-000	"1-1201885-1", "EPD20078A-US"		
CU7741-000	"EPD-DND-22842-L278"		
376874-000	"6-1192822-6", "44A0121-22-2/92"		
828073-000	"8-1196466-8", "EPD-ADD-10009"		
BM8769-000			
205769K001	"1-1191491-9"		
171331-000	"3-1191246-7", "44A9416-16-9CS1981"		
306025-001	"1-1192317-7", "44AM1121-16-6/9-9"		
C00329K001	"8-1199947-5"		
D24126K001	"1-1200712-5"		
CY1679-000	"EPD-ROK-10545-L044"		
548841K001	"6-1194319-5"		
370004-000	"7-1192772-1", "44/1421-22-9/9-9"		
EG8840-000	"400R1131-10-0/6/9-9"		
CS7761-000	"EPD-DND-21462-L099"		
EM6366-000	"CEC-RWC-25164"		

396173-000	"6-1192971-4", "44A0111-22-STRIPE-KIT-112"		
A65936-000	"1201691-5", "44A0111-10-9-11"		
294053-000	"2-1192228-9", "EPD52167A-24-0"		
188350K001	"3-1198852-3"		
D10426-000	"6-1200163-8", "EPD-RWC-16772"		
A51372K001	"2-1200582-1"		
384456-000	"9-1192884-9", "44A0121-26-6/9-US"		
EG9500-000	"EPD-RWC-24080-L352"		
EG3679-000			
032895-000	"1-1190255-0", "EPD-RWC-12814"		
705201-000	"44A0121-14-0/9CK0224", "4-1197967-4"		
344357K001	"4-1192593-7"		
D24809-000	"44AM1111-16-962-9-1KF", "3-1200547-7"		
471453K001	"6-1193532-3"		
D84899-000	"3-1200594-7", "FB-44-4022-0001-L082"		
013879-000	"8-1190108-2", "EPD25528C-US"		
A45242K001	"5-1200803-9"		

306000-000	"8-1192316-9", "44AM1121-12-0/9-9"		
CJ7847-000	"44AM1121-16-9/96-9CS3209"		
EG8797-000	"400R0111-20-9"		
836211K001	"6-1196527-0"		
CJ3447-000	"EPD-CAN-10019CS2979", "1-1899274-5"		
CN4695-000	"44A1121-20-6/9-9CS3275"		
F20652K001	"5-1200088-0"		
692451K002	"9-1195435-3"		
CA8018-000			
CA0597-000	"EPD-RWC-19734-L161"		
191815-000	"2-1191391-6", "EPD52345A-CS2735"		
EG7198-000	"44A0121-22-9/925"		
709341-000	"6-1195558-0", "FB-44-7026A-0201CS896"		
CW0107-000	"EPD-RWC-19939-L321"		
383263-000	"9-1192872-7", "44A0121-18-0/9-MX"		
126509-000	"5-1190919-2", "44A1133-16-0/2/9-8"		
282655-002	"6-1192121-5", "44A0111-22-905"		
EF8115-000	"EPD-RWC-23496CS3420"		

863693-000	"2-1196726-1", "EPD8492B"		
383343-000	"1192874-6", "44A1121-22-0/9-92-US"		
178585-000	"6-1191298-4", "EPD-ADD-10085"		
584893-000	"44B1121-24-0/9-91", "5-1194631-1"		
CZ4487-000	"EPD111021 A-US"		
CF2166-000			
EP0253-000	"44A0231-16-9/9/9"		
909215-000	"44AM1111-22-9-1", "5-1197062-5"		
739597-000	"9-1195772-4", "EPD53134A-16-0"		
221101K001	"8-1191629-7"		
665123K001	"9-1195240-6"		
384958-000	"6-1192888-2", "44A7600-26-0/9"		
C95038-000	"44A0111-14-9CS2896", "6-1200416-1"		
064485K001	"2-1190487-4"		
927305-000			
211587-000	"8-1191532-1", "FB-44-24-7006CS 2827"		
384107-002	"2-1192881-6", "44A1121-22-3/9-9-US"		
EG8074-000	"44/0411-20-9 5"		
A03913-000	"2-1200450-7", "EPD-ROK-10326-L063"		

CU6480-000	"EPD-DND-21489-L099"		
946509K001	"4-1197324-7"		
017722-000	"2-1199625-3", "44AM1171-24-MSL7-9"		
957061-000	"44AM1121-20-9/928-9CS1726", "1-1197409-1"		
847385K001	"1-1196609-5"		
CU3928-000	"EPD27743A-L099"		
CU0516-000	"44A1101-24-A971CS228"		
165603K001	"4-1191195-8"		
170485-000	"7-1191240-2", "44/1434-26-0/2/9-9CS2537"		
382305-002	"5-1192860-1", "44A1121-12-0/9-9-US"		
743179K001	"7-1195798-0"		
753003-000	"44/0424-24-0/9CS2537", "5-1195870-3"		
CW2958-000			
197765K001	"3-1191433-3"		
680731-001	"44B1811-16-9-9CS2018", "1-1195354-8"		
096988-000	"1-1190711-1", "44B1111-24-9-96CS1271"		
692547-000	"5-1195436-6", "EPD53083A-X-0"		
265023-009	"8-1191950-4", "44A0811-22-9-MX"		

253914-000	"9-1191858-5", "FB-44-0220-0104"		
816382-000	"3-1197982-4", "EPD-RWC-16409"		
CS2605-000			
205657K001	"4-1191490-9"		
CF4098-000	"44A0111-16-9-L183"		
CR3731-000	"EPD-RWC-21562"		
CJ1807-000	"44A0111-22-9-16CS3144L193", "3-1899270-1"		
574591-000	"6-1194560-6", "EPD52141A-X-0"		
387014-000	"7-1192903-0", "44A7042-18-9-9"		
033197-000	"4-1190257-4", "EPD51043A-26-0"		
280805-000	"1192079-5", "44/7004-22-9"		
509617-000	"2-1194006-5", "EPD-RWC-12124"		
CA3531-000			
885521K001	"5-1196890-8"		
EG8791-000	"400R0111-14-9"		
645201-000	"9-1195095-8", "EPD-RWC-13609"		
EG5959-000			
074677-000	"8-1190558-5", "44A0121-20-9/93CS1741"		

838777-000	"44A9625-12-9CS2745BAR REL", "7-1196545-6"		
270374-000	"4-1192000-6", "44/7360-26-9"		
495747K001	"7-1193707-9"		
231054-000	"8-1200287-8", "EPD-RWC-17028"		
514869-000	"2-1194044-0", "EPD6833-22-0"		
489097K001	"4-1193659-5"		
382390-000	"6-1192862-8", "44A1141-20-0/1/2/9-9"		
A41845-000	"4-1201882-8", "44A0114-18-9-L095-US"		
CJ5176-000			
E76053K001	"7-1201056-6", "EPD-ROK-10512-CO1-KIT-25"		
169637-000	"7-1191234-7", "44AM1121-20-9/913-9CS1726"		
CJ5177-000	"EPD94314A-US"		
294597K001	"1192232-8"		
EG4266-000	"EPD-RWC-23836-L346"		
055337-001	"2-1190422-2", "44/2421-24-9/90-9CS1506"		
CZ7562-000	"44A0161-22-G239"		
381315K001	"6-1192850-4"		

282784-000	"2-1192126-0", "44A0111-24-91-MX"		
198359-000	"8-1191436-6", "EPD68109A"		
282100-003	"1-1192104-1", "44A0311-22-9-US", "44A0311-22-9-US"		
EG2769-000	"44A0111-24-9-E626"		
215711-000	"1-1191558-0", "44A9676-18-0/2/9-9CS2746"		
282758-000	"2-1192125-2", "44A0111-22-98-US"		
CN4700-000	"44A1131-20-3/6/9-9CS3274"		
C96961-000	"9-1201705-9", "44A0111-12-9-1CS3144"		
090423-000	"1190663-6", "EPD-RWC-11286"		
398215-000	"2-1192986-9", "EPD52253A"		
998655K001	"5-1197721-6"		
C82501K001	"4-1200695-6"		
CR6402-000			
CZ0629-000	"EPD-DND-21447"		
EK8006-000	"EPD-RWC-17212-L012"		
498373K001	"2-1193726-1"		

976328-000	"44A0221-16-9/9-1KF/1", "8-1199822-8"		
523023K001	"4-1194109-6"		
513489-000	"4-1194034-6", "EPD-RWC-13506"		
691647-000	"44A0121-20-9/94CS1741", "5-1195430-0"		
A93944K001	"5-1200578-8"		
600779-000	"7-1194753-0", "EPD-RWC-14669CS2888"		
301076-002	"6-1192280-1", "44AM1111-24-9-9"		
807539-000	"3-1196258-3", "44A1111-20-9-90CS406"		
897281K001	"7-1196975-1"		
CU6385-000			
CY4264-000	"CEC-RWC-23011"		
386923-000	"44A0121-22-9/902"		
421657K001	"1-1193176-3"		
677805K001	"1195329-1"		
610553-000	"44AM1111-18-922-9", "3-1194828-8"		
A75280-000	"7-1200524-1", "EPD62607A-MTI"		
839731K001	"2-1196552-1"		
EG3832-000	"44A1321-16-9/9-9"		

D14956-000	"7-1200501-8", "EPD88351A-MTI"		
F37006-000	"EPD-RWC-17772", "3-1200587-5"		
D68592K001	"1-1201864-5"		
D78389K001	"5-1201378-4"		
CM1713-000	"EPD-RWC-20872"		
CS7709-000			
D80922-000	"5-1200497-9", "EPD-RWC-13838-L064"		
005401-000	"2-1190041-5", "44A9673-20-9CS2745BAR REL"		
737050-000	"44AM1121-22-0/9-97", "5-1199113-9"		
C54245-000	"44AM1111-20-9-9CS3069", "5-1200703-7"		
CR6259-000	"EPD-RWC-17029-L012"		
D98537-000	"44AM1111-20-9-9CS2994"		
594367-000	"44A1181-20-A707-9", "1194699-8"		
383834-000	"9-1192878-8", "44A1121-14-9/96-9"		
306039-000	"3-1192317-3", "44AM1121-18-9/96-9"		
A67867K001	"4-1200583-9"		
310237K001	"8-1192348-1"		
CA6179-000			

CF3585-000			
EF5981-000	"EPD-RWC-13644-L342"		
CJ6248-000	"EPD-RWC-18397"		
CN9484-000	"345/95-12-8-0"		
CW7557-000	"EPD-DND-22784-L016"		
111735K001	"5-1190815-5"		
C69765-000	"5-1201759-2", "44A0111-18-96-2KF"		
282841-000	"4-1192127-2", "44A0111-16-94"		
500497K001	"6-1193741-1"		
CM0924-000	"EPD52416A-L206"		
CJ6251-000	"EPD4756C-IRL"		
306144-001	"3-1192318-2", "44AM1121-22-0/9-9"		
386637-000	"1192900-6", "44A4121-12-0/9-9"		
CN5815-000			
EM7725-000	"EPD-RWC-22038"		
202495K001	"1191468-4"		
326809-000	"9-1192472-0", "WXA-0165-22-9"		
592211K001	"7-1194683-2"		
981203-000	"44AM1121-16-945/950-9", "8-1197581-8"		
308813K001	"9-1192338-5"		

301093-000	"9-1192280-0", "44AM1114-22-9-9"		
CS2766-000	"44A1131-18-0/2/9-9-F871"		
812655-000	"44AM1131-16-3/6/9-9CS2399", "1-1196322-0"		
393709K001	"6-1192953-9"		
A43150-000	"7-1201407-9", "44AM1121-20-9/96-9CS2994"		
396425-000	"5-1192973-1", "EPD52618A-X-0"		
306350-000	"5-1192320-0", "44AM1131-22-3/6/9-9"		
060051K001	"5-1190455-0"		
200981K001	"2-1191457-8"		
F20529-000	"5-1202074-8", "44A0811-10-95-1KF"		
996361K001	"7-1197704-6"		
439579-000	"4-1193303-3", "EPD48861A-US"		
CR3657-000			
763091K001	"9-1195941-5"		
CX8475-000			
139191K001	"4-1191009-6"		
CJ7989-000			
EF6528-000			
CS2763-000	"44A0311-14-9-F871"		

737555-000	"44AM1122-16-0/9-9", "3-1195758-2"		
CB4564-000	"EPD37262A-US-L099"		
160555-000	"3-1191159-4", "44B9534-22-9-9CS3023"		
EG7215-000	"44A0121-22-9/967"		
EM1303-000	"44A1221-14-9/9-9C3030L013"		
056473K001	"9-1190429-7"		
538341K001	"1194225-3"		
607177-000	"44A0831-22-92/94/96CS2017", "8-1194802-1"		
235271K001	"6-1191730-4"		
CA9992-000			
CA9985-000			
317571-000	"1192406-7", "44AM1131-20-F207-9CS2248"		
296969-000	"4-1192249-5", "44A1111-16-9-93CS773"		
980337-000	"44A3131-20-0/2/9", "4-1197575-3"		
238809-000	"4-1191755-5", "EPD-RWC-11727"		
CN6853-000			
C58668-000	"5-1201926-8", "44A0111-16-93-L030"		
951623K002	"9-1197368-7"		
520978K001	"3-1199499-2"		

292383-000	"9-1201503-8", "44A1111-16-9-5"		
550851K001	"2-1194348-1"		
F94468K001	"3-1200711-9"		
150702-000	"1200099-3", "44B1121-22-98/901-9CS3018"		
578673K001	"9-1197827-9"		
859565-000	"44AM1131-20-9/9/9-9", "6-1196697-6"		
021389-000	"2-1190166-9", "EPD52700A-X-0"		
CZ4485-000			
943521-000	"44/7004-22-9CS1059", "4-1197304-2"		
D93806-000	"8-1201791-2", "EPD-RWC-17097-L135"		
CS7717-000			
468883K001	"1-1193514-3"		
625849-000	"6-1194955-4", "EPD52983A"		
566179-000	"44AM1121-22-9/96-9CS1726", "4-1194471-3"		
911228K001	"7-1198896-5"		
127547K001	"4-1197916-9"		
613457-000	"44AM1131-16-922/944/946-9", "6-1194849-4"		

A46750-000	"6-1201437-1", "EPD-BRZ-10004-L027"		
463913-000	"44A1221-16-9/96-9-5CF/1", "7-1193478-5"		
846963-000	"1196606-9", "EPD-RWC-13380"		
803446K001	"3-1199953-0"		
CN1936-000	"44A1111-20-9-9CS3270"		
EG7273-000	"44A0121-22-9/905"		
894305-000	"1-1196955-4", "FB-44-0626-0001"		
880111K001	"5-1196852-2"		
CM2838-000	"44B1131-12-0/4/9-9"		
CS2807-000	"EPD-RWC-21804"		
746559-000	"345M13B-26-8-0CS2041", "4-1195824-0"		
ER5549-000	"44A0111-20-9CS3531"		
E85966-000	"44A0112-24-9CS3184"		
932433-000	"44A0711-22-9CS1354", "4-1197227-4"		
C84519-000	"1201758-9", "345/70-10-4-0"		
CN5822-000			
969287K001	"8-1197493-7"		
D26723K001	"2-1200586-2"		
CB7271-000	"EPD-RWC-19936"		
241755K001	"1191776-9"		

EG2545-000	"EPD-RWC-23959"		
387385-000	"9-1192908-5", "44A1111-22-9-92-US"		
857637-000	"44A9605-16-9", "1196684-4"		
454657-000	"7-1193412-6", "EPD52690A-20-0"		
282511-000	"7-1192117-3", "44A0311-14-9-US"		
472615K001	"8-1193540-1"		
CN3178-000			
EH8645-000	"400R0311-20-9"		
CJ3710-000	"EPD-RWC-20562-L192"		
EG8489-000			
E20981-000	"9-1201926-8", "44A0111-16-911-L030"		
C17753-000	"6-1200583-4", "EPD-RWC-17785"		
185705-000	"7-1191348-4", "44/0411-14-9CS1038"		
F43303K001	"3-1200587-8"		
CS1831-000			
CJ8983-000	"ASC15865-20-0-LEADED"		
CS1905-000			
CU4067-000			
317173K001	"1-1192403-4"		
857305K001	"4-1196681-7"		
633431K001	"7-1195010-6"		

640853K001	"7-1195065-2"		
C57613-000	"44AM1121-20-9/96-0", "9-1200764-6"		
A81239-000	"7-1201263-5", "EPD-RWC-18456"		
801107-000	"8-1196193-6", "EPD43504G-US"		
848467-000	"6-1196616-5", "EPD-RWC-14920"		
475279-000	"1193560-7", "FB-44-7026A-0225CS896"		
941943-000	"44A9586-26-9", "1-1197293-8"		
641895-000	"1-1195073-1", "EPD69160A-20-0"		
419863K001	"1-1193163-4"		
752013-000	"44AM1111-16-96-9", "5-1195863-2"		
389513-000	"9-1192923-7", "44A1141-24-2/4/6/9-9-US"		
855056-000	"8-1196664-6", "EPD20347A"		
CL6668-000			
606179-000	"44A0111-20-9-INT", "4-1197891-4"		
CX5295-000			
119289-000	"9-1190867-0", "EPD51028A-26-0"		

D22391-000	"44AM1121-16-0/9-0", "1200395-3"		
CS2956-000	"44A1131-20-0/2/9-9-F871"		
747606-001	"44A9416-20-9CS1981", "1195832-9"		
CF3717-000			
339355K001	"2-1192561-0"		
652389K001	"7-1195149-3"		
C27760-000	"1-1201142-8", "EPD100538 A-ISR-L099"		
A03948K001	"2-1200579-3"		
412899-000	"5-1193113-5", "44B9534-20-9-9CS1728"		
CX8556-000	"EPD-RWC-23210"		
A26561-000	"8-1201737-4", "EPD98877A-US"		
CP1760-000	"44A9748-22-9-9CS3185"		
CW4836-000	"EPD-RWC-20162-L056"		
306011-000	"9-1192316-9", "44AM1121-14-0/9-9"		
D40046K001	"7-1201818-6"		
816255K001	"2-1196361-3"		
442133-000	"1-1193324-2", "EPD51830A-10-0"		
538419K001	"6-1194225-1"		
CA9803-000	"EPD-RWC-19731-L149"		

EK8979-000	"44A0311-22-9-E634"		
CJ1804-000	"44A0111-22-9-14CS3144L193", "2-1899270-9"		
545513-000	"44A9605-16-97", "4-1194293-5"		
917393K001	"8-1197120-6"		
757949-000	"8-1195905-9", "EPD-ADD-10002"		
EG5998-000			
301054-002	"3-1192280-6", "44AM1111-22-9-9"		
EH9936-000	"FLDWC1331-20-1/5/9-8"		
326494-000	"5-1192470-5", "EPD8472C"		
CN6854-000			
774479-000	"44AM1121-26-2/9-3", "1-1196031-4"		
CJ1802-000	"44A0111-22-9-12CS3144L193", "2-1899270-7"		
F84011-000	"44A0211-22-9CS3030", "2-1200301-4"		
090359-000	"5-1190662-7", "44B5111-16-9-9CS1401"		
CY0084-000	"EPD-RWC-19002-L021"		
886634-000	"EPD-NAV-85111"		
EH8641-000	"400R0311-16-9"		
EG2661-000	"EPD-RWC-23956"		

C27079-000	"8-1201917-1", "44A2111-26-9-9CS2979"		
C92962K001	"1200712-5"		
044292-000	"6-1190340-6", "44A0141-22-3/5/6/9"		
CU6222-000	"EPD-DND-21499-L099"		
A86590K001	"7-1200711-4"		
100987K001	"2-1190739-5"		
357754-000	"4-1198846-4", "EPD93546A-US"		
D86179K001	"7-1200577-5"		
833473-000	"9-1196507-4", "EPD-CAN-10097"		
430594-001	"8-1193238-7", "44B5131-12-MST3-9CS1728"		
026283K001	"1190204-3"		
586871K001	"1194645-7"		
840927K001	"7-1196560-9"		
E11020K001	"3-1200581-2"		
144925-000	"6-1191047-3", "44AM1111-22-9-9CS2109"		
EM0485-000			
382581-000	"44A1121-14-0/9-9-MX"		
644253-000	"3-1195089-5", "EPD-ROK-10035"		
916093K001	"6-1197111-3"		

306354-000	"5-1192320-6", "44AM1131-22-9/93/96-9"		
826796-000	"44A0111-22-9CS448", "1-1196458-8"		
429932K001	"1-1197928-6"		
257921K001	"1-1191887-7"		
618949-000	"10525-X-8CS1405", "9-1194889-9"		
353153-000	"6-1192652-5", "FB-44-7026A-0220CS896"		
C32005-000	"9-1201422-9", "FLDWC0311-22-9CS2979-1KF"		
382229-019	"9-1192857-6", "44A1121-20-0/9-9-MX"		
262615-000	"4-1191933-2", "44AM1121-24-4/9-9"		
346085-000	"2-1192605-0", "FB-44-7026A-0223CS896"		
EG2508-000	"EPD-RWC-23960"		
027349K001	"6-1190211-4"		
343093-000	"7-1192584-7", "44A9650-16-0/9-0"		
120473-000	"3-1190876-8", "EPD-ROK-10046"		
600329-000	"9-1194747-2", "EPD5840-20-0CS1898"		
051356-004	"1197970-4", "EPD23928A-US"		

222379-000	"1-1191638-1", "EPD90236A-US"		
432999-000	"8-1193256-7", "EPD68116A-US"		
887483K001	"8-1196904-4"		
203597K001	"9-1191475-8"		
383344-000	"1-1192874-1", "44A1121-22-0/9-95"		
CL4518-000	"EPD-RWC-20306-L208"		
656699-000	"44AM1111-18-942-9", "8-1195178-7"		
EM0493-000			
238019-000	"8-1191749-3", "44A1111-24-9-91CS2056"		
CU8793-000			
383015-007	"1-1192870-0", "44A1121-24-6/9-9-MX"		
EG2539-000	"EPD-RWC-23963"		
CM1218-000	"44A0711-18-95"		
CR8528-000			
D87947K001			
EG2544-000			
CJ1622-000			
CX4571-000	"EPD-DND-21534"		
CP4118-000	"44B1121-20-0/9-0"		
215732-000	"2-1191558-4", "44/1424-24-6/9-9"		
F25935-000	"44A0211-20-9CS3030", "2-1200354-8"		

040657-000	"1190311-6", "44A9699-22-9"		
EP1299-000			
EG2512-000	"EPD-RWC-23964"		
382757-000	"4-1192867-8", "44A0121-24-6/9-MX"		
CS8049-000	"EPD-DND-21535-L016"		
283786-000	"2-1192142-7", "44A0211-22-90-US"		
ER5172-000	"44AM1131-22-MST3-9CS3529"		
290651K001	"5-1192203-2"		
718375K002	"3-1195619-6"		
134527-000	"6-1190977-1", "EPD-ROK-10034"		
978665-000	"44A9625-12-9", "2-1197967-1"		
741463-000	"44A1143-16-0/2/5/9-8", "7-1195786-6"		
383082-000	"9-1192870-7", "44A1121-18-6/9-9-MX"		
A99211-000	"6-1201663-3", "EPD-RWC-18194"		
EL7211-000	"EPD-RWC-24645"		
903895-000	"2-1197024-1", "EPD37964A"		
409455K001	"9-1193087-7"		
378283-000	"6-1192832-1", "44A0151-20-2/3/5/6/9"		
CA7492-000			

CU8805-000	"EPD-DND-21488-L067"		
730065-000	"44AM1111-18-955-9", "8-1195703-0"		
CX1594-000	"EPD-DND-21440"		
3477333001	"9-1192616-6", "44A0111-14-9(B01)"		
607719-000	"4-1194807-8", "EPD52262A-14-0"		
668743-000	"8-1195265-1", "EPD-RWC-14030"		
388128-000	"7-1192914-3", "44A1111-14-9-0-US"		
601735-000	"6-1194763-7", "EPD-RWC-10650"		
CZ3911-000	"44A1121-24-0/9-9-L004"		
841967-000	"44A0121-14-6/9", "2-1196568-8"		
327969-000	"1-1192481-4", "44A9676-22-0/2/9-9CS2746"		
388137-000	"8-1192914-2", "44A3111-16-9"		
296567K001	"6-1192246-8"		
CM6773-000			
124879-000	"9-1190907-3", "EPD51053A-16-0"		
158143-001	"5-1191142-7", "44B5114-24-9-9CS1821"		
916713K001	"1197116-6"		
453165K001	"5-1193402-2"		

A72610K001	"5-1200578-5"		
626227-000	"44B9536-20-MST3-9CS3023", "1-1194960-7"		
981947K001	"8-1197586-1"		
282882-000	"2-1192128-0", "44A0111-24-916-US"		
531167K001	"5-1194171-4"		
C01255K001	"2-1200384-2"		
028809K001	"2-1190223-6"		
F63335-000	"EPD62583A-MTI", "2-1200498-4"		
F30611K001	"5-1199951-6"		
CF6956-000	"44AM1121-18-0/9-9CS2979", "3-1899230-2"		
441515K001	"8-1193319-5"		
D20979K001	"5-1200695-7"		
CS2960-000	"44A1141-18-ELC4-9-F871"		
EG9471-000			
120375K001	"6-1190875-8"		
562567-000	"345M05B-20-20-0CS2041", "1194445-1"		
CU9022-000	"EPD-DND-23027-L146"		
EG2541-000	"EPD-RWC-23968"		
C24279-000	"7-1200570-2", "EPD4694-US-L073"		

270186-002	"3-1191998-1", "44/0414-24-9"		
595671-000	"44/1434-24-0/2/9-9CS2537", "5-1194710-8"		
594157K001	"6-1194697-3"		
CZ8810-000	"EPD106324 A-US"		
E58219-000	"7-1201556-6", "44A0111-20-9CS2976"		
C64413-000	"7-1201280-1", "EPD4750C-IRL-L016"		
533461-000	"44AM1111-16-95-9", "8-1194187-8"		
768747K001	"4-1195990-5"		
948781-000	"44A1331-18-0/2/9-9CS2746", "7-1197340-5"		
300079F003	"1192273-1"		
CA6181-000	"EPD-RWC-20021"		
CX7547-000	"EPD-DND-21447-L016"		
282099-000	"1192104-5", "44A0311-24-9"		
CF5368-000	"44A2131-22-1/6/9-9CS3229"		
CU8799-000			
969106K001	"8-1200710-1"		
365015-000	"1-1192737-8", "44A9549-X-9-9CS1663"		
CA7738-000	"EPD-NAV-85108"		
694961-000	"1195452-8", "EPD32265A"		

301046-001	"2-1192280-4", "44AM1111-22-9-2"		
C72931-000	"44A9237-24-0CS2979", "4-1199831-2"		
A41097-000	"1-1202115-2", "EPD-RWC-19731"		
711297K001	"7-1195572-7"		
205821K001	"7-1191491-7"		
EG4278-000	"EPD-RWC-24097-L346"		
161351-000	"1191165-8", "44/7004-26-9CS1059"		
711427K001	"6-1195573-4"		
000173K001	"5-1190001-0"		
CB3818-000	"EPD-RWC-20259-L172"		
CX1155-000	"EPD40652C-L099"		
465398-001	"44B5131-20-MST3-9CS1401", "4-1193489-4"		
CY1031-000	"44AM1121-20-9/96-2"		
CN6856-000			
CJ1644-000	"EPD100584 A-US"		
208976-000	"3-1199818-1", "FB-44-4026-0007CS2979"		
941285-000	"44A9665-20-0/2/5/9-0", "2-1197288-8"		
338687K001	"5-1192556-7"		
736907K001	"8-1195753-7"		

E72147-000	"7-1200816-3", "EPD94682A-US"		
502923K001	"6-1193785-5"		
E86254-000	"44A0811-10-9CS3044", "5-1200508-8"		
894532-000	"3-1200269-2", "EPD-RWC-17202"		
041163K001	"8-1190314-1"		
186819-000	"2-1191356-0", "EPD-ADD-10081"		
CJ1976-000	"EPD-RWC-17741CS2979", "6-1899257-6"		
282094-009	"6-1192103-0", "44A0211-20-9-MX"		
357289-000	"1192681-7", "EPD52630A-20-0"		
724369-000	"44B9535-16-9/96-9CS1728", "4-1195662-0"		
270320-000	"9-1191999-5", "44/0414-22-9"		
888364K001	"1200277-8"		
742415-000	"44A1121-20-9/96-0", "3-1195793-5"		
596341-000	"9-1194716-0", "EPD-ROC-10056"		
244321K001	"2-1191792-6"		
718535K001	"6-1195620-2"		
619471-000	"7-1194893-4", "EPD-RWC-12813"		
238089-000	"3-1191750-1", "EPD-RWC-13951"		

CA7489-000	"44A9749-26-1/9-9CS3185"		
072823K001	"7-1190545-1"		
489417K001	"6-1193661-9"		
303851-000	"3-1192301-4", "EPD86150A-US"		
EM6758-000	"CEC-RWC-25201"		
865209K001	"1-1196738-6"		
F95835-000	"EPD-RWC-17035", "6-1200287-6"		
CA8244-000			
906255-000	"44A9698-14-F955-0", "1197041-6"		
EM7720-000			
EH2492-000	"44A9083-16-9CS3433"		
D53505-000	"44A7620-20-9/5-9CS3058", "1-1200674-6"		
851287-000	"1-1196637-8", "EPD-ROC-10011"		
EG7281-000	"44A0121-22-9/913"		
211143K001	"7-1191529-8"		
CS5228-000	"EPD-RWC-18864-L106"		
415817K001	"9-1193133-8"		
383094-000	"1-1192871-8", "44A0131-16-0/2/9-MX"		
285789-000	"5-1192163-0", "44A0111-26-94-US"		
D30958-000	"44A4121-22-9/90-0", "9-1200481-5"		

469097K001	"6-1193515-7"		
377911-000	"8-1192829-7", "EPD-RWC-15747"		
427127K001	"8-1193213-8"		
387319-000	"1192908-7", "44A1111-20-9-92"		
E42966-000	"7-1202031-2", "EPD-IRL-35503-L114"		
CU5268-000			
CM2538-000	"EPD-RWC-20964-L248"		
EG5141-000	"EPD-RWC-24080"		
894855-003	"6-1197970-1", "EPD68620A-ING"		
A71714-000	"4-1200585-4", "EPD-RWC-17787"		
203672-000	"5-1198311-5", "44A1221-12-9/96-9"		
192117K001	"4-1191393-5"		
616119-000	"44A9623-10-ELC4-9CS2746", "2-1194868-3"		
CL4461-000	"EPD-RWC-19272"		
666551-000	"44A1211-24-9-9CS984", "7-1195250-6"		
192707-000	"9-1191397-4", "EPD22878C-X-0"		
739247K001	"4-1195770-0"		
EG6693-000	"FLDWC0311-18-9CS3422"		

242697-000	"6-1191780-2", "44B9537-12-MST4-9CS3023"		
EH7211-000	"EPD-RWC-22254-L016"		
EP2066-000	"CTC-0076-22-9/4-93CS3511"		
471398-000	"44AM1111-16-961-9-1KF", "9-1200270-3"		
473871-000	"2-1193550-1", "EPD52865A"		
F21409K001	"7-1200354-5"		
452320K001	"1199176-8"		
725065-000	"44A9089-14-9/9-9", "6-1195667-4"		
375158-002	"5-1192810-4", "44/1411-26-9-9"		
E32184K001	"1-1200404-4"		
D22176-000	"2-1201886-5", "44A0114-26-9-L095"		
EH2509-000	"44/4434-24-F001-9CS3434"		
CU8710-000	"EPD-DND-21445-L280"		
240755-000	"8-1191768-7", "EPD-ROK-10173"		
224867-000	"3-1191656-8", "44A1831-10-0/2/9-9"		
2820493017	"9-1192099-6", "44A0111-24-9"		
D54127K001	"7-1200691-1"		
715081-000	"1195596-2", "EPD52977A"		

618844K001	"8-1199976-6"		
CV7306-000	"EPD40416A-RYQ-L099"		
821841K001	"5-1196409-3"		
372677-000	"2-1192791-7", "EPD51039A-18-0"		
691717-000	"9-1195430-7", "EPD52741A-18-0"		
370104-000	"4-1197869-8", "44/2454-26-2/4/5/6/9-9"		
A55241K001	"8-1200587-3"		
764866-000	"44B1121-16-0/9-91CS2025", "7-1195954-1"		
383251-000	"8-1192872-6", "44A1121-24-3/9-3-US"		
667247-000	"44A0111-14-902", "4-1195255-5"		
840341K001	"4-1196556-3"		
CL1329-000	"44A0811-20-9CS1465-L013"		
CZ4626-000	"EPD-RWC-23583"		
382524-002	"7-1192864-9", "44A1141-20-0/2/6/9-9-MX"		
A13277-000	"8-1202108-4", "44A0231-10-9/93/96"		
CN8019-000	"EPD90506A-US-L044"		
F97600-000	"6-1201885-9", "EPD4651-US"		

CP3853-000	"EPD8477B-US"		
763259-000	"1195943-7", "EPD52343A-16-0CS2578"		
D44125K001	"2-1200586-7"		
CB6885-000	"EPD37262A-US-CS3207-L099"		
320213-000	"1192428-3", "EPD30623A-US"		
F84516K001	"3-1200711-5"		
EM5739-000	"44AM4141-12-0/2/5/9-9"		
CZ8809-000			
CW9139-000			
098871-000	"3-1190724-7", "44AM1111-18-962-9"		
EK8007-000	"EPD-RWC-17211-L012"		
116757-000	"6-1190850-9", "EPD-ROK-10309-L027"		
053411K001	"7-1190407-6"		
241489-000	"3-1197909-6", "EPD-ROK-10428"		
447133-000	"3-1193360-6", "EPD-RWC-15285"		
399113-000	"7-1192993-1", "44B5121-12-9/96-9CS1401"		
253895K001	"8-1191858-2"		
CY8606-000			
287346-000	"1192178-6", "44A0111-22-9-26"		
817731K001	"1-1196372-8"		

620853-000	"6-1194905-2", "EPD-RWC-12638CS2749"		
047291K001	"4-1190363-6"		
CX5292-000	"EPD-DND-21488-L016"		
566245-001	"44A9439-24-9-9CS527", "8-1194471-4"		
388602-000	"1-1201147-5", "EPD100256 A-US-L099"		
CR9511-000	"44A1821-18-0/9-6"		
069531-000	"1-1190523-5", "44/1424-24-0/9-9CS2537"		
320195-000	"9-1192427-1", "EPD-RWC-15306"		
175423-001	"5-1191275-9", "44A9441-24-MST3-9CS527"		
CY7496-000	"EPD87062A-US"		
D39425K001			
432296-001	"4-1193251-1", "44A4131-20-1/6/9-9CS288"		
293595-000	"1-1192225-4"		
E15531-000	"9-1201926-6", "44A0111-16-91-L030"		
CR9507-000	"44A1821-18-0/9-2"		
C82313-000	"3-1201922-3", "EPD-RWC-19452-L016"		

383607-000	"6-1192876-2", "44A1141-26-0/2/5/9-9"		
285790-000	"5-1192163-4", "44A0111-26-98-US"		
270748-000	"2-1192003-8", "44/0411-16-9"		
797355K001	"8-1196169-1"		
801253K001	"8-1196194-0"		
251657-000	"3-1191844-9", "EPD-RWC-10425"		
CL6860-000			
891212-000	"44A1121-20-30/9-0", "5-1198872-0"		
618101K001	"1194884-1"		
202373K001	"2-1191467-3"		
CX1050-000	"EPD-RWC-20754-L253"		
631831K001	"3-1194999-9"		
317715K001	"9-1192406-9"		
856533-000	"44A0321-20-0/9CS2747", "9-1196675-9"		
CY1328-000			
958185K001	"6-1197417-1"		
CJ6198-000	"EPD4722C-US"		
F51910K001	"5-1201165-7"		
CY1470-000	"EPD-RWC-23384"		
368051-000	"1192759-3", "44A1821-20-6/9-9"		

495661-000	"44/4484-26-A553CS1784", "1-1193707-4"		
282101-003	"2-1192104-0", "44A0311-20-9-US", "44A0311-20-9-US"		
199073-000	"1191442-8", "44A0121-22-7/97"		
CJ1810-000	"44A0111-22-9-18CS3144L193", "3-1899270-3"		
F45343-000	"2-1201759-2", "44A0111-12-94-1KF"		
893191-002	"7-1197924-5", "EPD70028A-ING"		
301086-000	"8-1192280-3", "44AM1111-26-9-9"		
460041-000	"7-1193450-5", "EPD-ROC-10042"		
071689K001	"1-1190538-9"		
CS1779-000	"EPD-RWC-14918-L012"		
035943-000	"4-1190277-8", "EPD52975A"		
CS7460-000			
407497-000	"1-1193074-5", "EPD52855A-20-0"		
888492-000	"8-1198850-7", "CMC-0125CS1791"		
CJ6341-000	"EPD4666E-IRL"		

F54924-000	"7-1201860-1", "EPD101773 A-US"		
F54437-000	"44A0231-16-9/9/9CS3030", "1-1200301-3"		
361743-000	"8-1192712-9", "EPD-CAN-10020"		
810826K001	"2-1199501-3"		
683121-000	"44B9535-20-9/96-9CS3023", "9-1195368-5"		
A47821K001	"8-1200764-0"		
386687-000	"2-1192900-9", "44A1131-16-3/6/9-9-MX"		
CL4886-000	"44A0811-16-9CS3030"		
884487K002	"4-1196883-8"		
958907K001	"9-1197422-4"		
154567-000	"3-1191116-9", "EPD-MPP-10046"		
144567-001	"9-1191044-5", "44A2131-24-1/6/9-9CS453"		
A40105K001	"1-1200088-0"		
EG9416-000			
974647-000	"44A9966-12-90CS2745", "9-1197531-9"		
374135-000	"3-1192802-0", "44A3131-22-0/2/9"		
942069K001	"1-1197294-2"		
EG3617-000	"EPD-RYQ-23616-L333"		

CP1691-000	"44A0111-10-9-1-L232"		
EG4280-000			
978413K001	"2-1197559-8"		
770412K001	"7-1199129-6"		
EG8848-000	"400R1131-18-0/6/9-9"		
CU1046-000	"FLDWC1321-16-9/90-9CS2959"		
001131-000	"4-1190008-6", "44AM1111-16-90-9"		
EG8832-000	"400R1121-20-0/9-9"		
297084-000	"9-1199423-0", "44A0111-20-9CS2896"		
743035-000	"44A2131-16-1/6/9-9CS453", "6-1195797-4"		
307314-000	"9-1197927-6", "EPD92308A-US"		
CA2667-000			
736933K001	"1195754-5"		
EG7207-000	"44A0121-22-9/945"		
387004-015	"1-1192903-8", "44A1111-24-9-9-MX"		
F58387-000	"7-1201380-7", "EPD-RWC-18490"		
CS2608-000			
605546K001	"8-1198866-1"		
070635K001	"1-1190531-7"		
A62800-000	"6-1200524-2", "EPD62609A-MTI"		

CU8702-000	"EPD-DND-21443-L279"		
E72081-000	"4-1200571-4", "EPD4708-US-L075"		
159029-000	"1-1191149-5", "44A9586-26-9-6"		
646917K001	"2-1195108-5"		
452541-000	"44A9416-22-9126CS1981", "1193398-3"		
E75794K001	"1200163-6"		
283787-000	"7-1201021-3", "44A0111-12-92-US"		
CX5298-000			
F14435-000	"EPD-ROK-10512", "9-1201056-3"		
CB1713-000			
732467K001	"8-1195721-5"		
CB8373-000			
110495-000	"1-1190807-3", "EPD-RWC-10947"		
377179-000	"5-1192824-4", "44A1111-16-924-9"		
282760-002	"3-1192125-3", "44A0111-22-902"		
047177-000	"5-1190362-8", "44B9536-20-MST3-9CS1728"		
ER5388-000	"EPD-RWC-25872-L027"		
CB2390-000	"FLDWC0311-24-9CS2979", "1899161-4"		

606270-001	"44A4121-20-1/9-9CS009", "3-1194796-5"		
CR3172-000	"EPD-RWC-17034-L012"		
707853K001	"6-1195548-5"		
CY2853-000	"44A7905-16-0CS2116"		
D94967-000	"44A1141-16-MST4-9-US", "7-1200385-9"		
443717K001	"9-1193334-2"		
CS6999-000	"EPD-DND-21508-L099"		
E13199K001	"1200586-9"		
634661-002	"4-1197825-3", "EPD5512D-US"		
392333K001	"9-1192943-2"		
CA2351-000	"EPD-RWC-19706-L040"		
646645-000	"44B1111-24-9-97CS1271", "5-1195106-6"		
964139-000	"2-1197457-2", "EPD-RWC-14224"		
306633-000	"1192323-1", "44AM1141-24-3/5/6/9-9"		
552620-000	"44A0111-14-9-1KF/1", "2-1199017-7"		
118117K001	"7-1190859-4"		
543435K001	"5-1194262-9"		
A69782-000	"3-1201926-6", "EPD-RWC-10944"		
ER6397-000	"44AM1111-16-9-9CS3529"		

D02604K001			
892069K001	"4-1196939-0"		
382232-015	"2-1192858-6", "44A1131-20-0/2/9-9-MX"		
CN2442-000	"4J3N-10-F6-0"		
475621-000	"44/2431-24-F023-9CS1506", "3-1193562-6"		
610237K001	"4-1194825-6"		
260692-001	"2-1191907-6", "44B5111-12-9-9CS1728"		
867961-000	"44AM1121-22-0/9-0", "1-1196757-7"		
306139-000	"2-1192318-8", "44AM1121-22-0/9-3"		
CA8698-000	"EPD-RWC-19813-L025"		
CR5076-000	"EPD-DND-21973"		
261848-000	"5-1191924-2", "44A7890-18-9"		
CX0035-000			
EG6601-000	"EPD-RWC-23836-L005"		
D26779-000	"44AM1121-18-0/9-9CS561", "2-1200554-8"		
CN3187-000	"EPD-RWC-20643"		
282836-001	"1-1192127-3", "44A0111-22-916-US"		
281047-000	"7-1192081-3", "EPD-RWC-14597"		

752837K001	"1-1195869-8", "EPD51412A-COA-KIT-15"		
383465-000	"2-1192875-0", "44A1121-18-9/96-9"		
817429-000	"9-1196369-3", "EPD-RWC-13948"		
CN2578-000			
C17975-000	"2-1201497-2", "44B1121-16-G118-9CS3018"		
213734-000	"2-1199951-4", "EPD4709-US"		
CU4338-000			
896412-000	"9-1198925-9", "EPD-RWC-16529"		
EK9399-000			
054027K001	"5-1190412-0"		
551741K001	"2-1194361-2"		
046073-000	"1190354-2", "EPD43503E-US"		
F55808-000	"44A0121-20-9/96CS2994", "4-1200087-0"		
383644-000	"4-1199953-7", "EPD-RWC-17149"		
029509-001	"7-1190228-3", "EPD5850-16-0CS1898"		
CN3185-000			
564059K001	"9-1194455-7"		
383413K001	"8-1192874-3"		
CA8697-000			

285259-000	"1-1201726-7", "44A0114-26-98-US"		
978910-000	"2-1200906-9", "EPD29649A-US-L099"		
578817-000	"1194588-2", "EPD-RWC-10050"		
525444-000	"44B1121-24-0/9-92CS2024", "4-1194129-6"		
240049K001	"2-1191764-5"		
383468-000	"9-1197869-4", "44A1131-20-9/93/96-9"		
141545-000	"8-1191025-8", "44/4431-22-F001-9CS1784"		
C16873K001	"5-1200589-9"		
308062K001	"6-1199861-9"		
EF4916-000	"EPD-RWC-19929-L044"		
564739K001	"8-1194460-7"		
832077K001	"9-1196496-8"		
449247-000	"1193375-3", "4J3S-16-F10-8"		
282066-010	"7-1192100-4", "44A0111-12-9-MX"		
270049-000	"8-1191995-0", "44/0411-20-9"		
CN8361-000	"44/0412-14-9CS1038"		
747437-000	"44AM1114-24-9-9CS012", "7-1195830-0"		

CB4844-000	"EPD-RWC-20270-L172"		
457813-000	"345M09A-22-48-0CS2041", "2-1193435-8"		
C31680-000	"1-1200331-7", "EPD-RWC-17030"		
748405-000	"44A9647-16-9-MIL", "8-1195837-8"		
889331-000	"9-1196918-2", "EPD-RWC-14222"		
306369-002	"6-1192320-7", "44AM1131-24-0/2/9-9"		
579863-000	"6-1194595-9", "EPD32869C"		
CS2804-000	"44A0111-14-9-F871"		
EP2428-000	"EPD-RYQ-23616-L012"		
375002-000	"2-1192809-9", "44/2411-24-9-9"		
E67676-000	"4-1201404-3", "44/7004-24-9CS2979"		
EL6400-000	"44AM1131-18-0/2/9-9CS3451"		
842483-000	"1196572-4", "EPD52627A-22-0"		
E23127-000	"44B1131-18-MST3-9CS3018", "6-1200111-2"		
CR9070-000	"44A1231-16-MST3-9CS3030"		
C80066-000	"1-1201883-1", "44A0112-12-9-L095"		
CR2278-000	"EPD-RWC-22225"		

620513K001	"3-1194903-6"		
E51876-000	"EPD-NAV-93321"		
CU9235-000			
839049-000	"4-1202094-4", "345/68-12-2-0"		
229138-000	"9-1199130-1", "EPD95158A-US"		
EM6455-000	"FLDWC6004-18-9"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.