



17-Feb-2022

PCN #: P-22-022183

Subject : Spec 44 and FLDW Wires

Description of Change : TE Connectivity is changing the sourcing and grade for PVDF resin used as insulation material for Spec 44 and FLDW Wires. This change is to an alternate grade with similar performance and characteristics.

Reason : Part status change. The technical assessment on alternate PVDF grade has been completed by TE's technical team and the results demonstrate similar properties and performance to the existing PVDF grades. These results are obtained through validation trials of various finished parts using the alternate grade as insulation material. No change to form, fit and function of the finished parts has been observed. Test reports on the wire characteristics can be provided upon request.

Key Dates :

Contact By Date: 28-Mar-2022

Implementation Date: 28-Mar-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
587285K001	"1194648-5"		
286333-000	"1192169-4", "44AM1151-20-0/1/2/3/9-9"		
373457K001	"3-1192797-2"		
460414-002	"44A1182-24-A986-0-US", "2-1198298-9"		
284693-000	"1-1201726-6", "44A0114-26-92-US"		
983435-000	"44A9964-14-9CS2514", "9-1197597-0"		

317977-000	"7-1192408-9", "44/7011-26-9CS1760"		
387007-000	"4-1192903-5", "44A2111-16-9-9"		
CM4936-000			
CS2795-000	"44A0111-16-9-F871"		
950709-000	"44A1121-12-2/9-9-US", "8-1200928-4"		
587463-000	"4-1194649-5", "EPD-RWC-12372CS2749"		
CN5905-000	"EPD103978 A-US"		
791423K001	"7-1196129-6"		
EM8675-000	"EPD-RWC-24363"		
416461-000	"4-1193138-8", "EPD52415A-12-0-L290"		
267285-000	"1191973-6", "EPD-ROK-10287"		
150725-000	"5-1191089-7", "44/2451-26-MST5-9"		
211425K001	"8-1191531-0"		
651503K001	"7-1195143-9"		
302480-000	"1-1199826-9", "44A7620-20-9/5-9CS2979"		
809333K001	"7-1196289-1"		
F84585K001	"2-1200298-5"		
447790K001	"3-1199171-9"		

CJ1798-000	"44A0111-22-9-10CS3144L193", "2-1899270-5"		
439063K001	"4-1193299-8"		
D29791-000	"7-1201926-3", "44A0111-16-90-L030"		
ER2736-000	"44/7011-18-9-L218"		
EG7208-000	"44A0121-22-9/946"		
CM6005-000	"44A0221-20-9/96"		
CW4825-000	"EPD-RWC-20157-L152"		
571817-000	"44A9650-18-0/9-0", "4-1194534-5"		
082153K001	"6-1190608-6"		
349926-001	"6-1192632-2", "44B5111-16-9-9CS1728"		
CR3598-000			
017891-000	"6-1190139-7", "EPD52164A-18-0"		
CX5294-000			
911603K001	"8-1197079-8"		
452149-000	"1-1193395-8", "EPD-RWC-14596"		
F11443K001	"1-1201236-6"		
177051K001	"1-1191287-2"		
701253K001	"6-1195503-1"		
384443-002	"7-1192884-7", "44A1321-20-0/9-9"		

215441-000	"9-1191555-8", "44AM1121-20-0/9-9F970"		
CA9977-000	"EPD-RWC-19734-L149"		
3822433012	"8-1192858-1", "44A1121-24-0/9-9"		
046545-000	"5-1190357-4", "44A0111-16-9F970"		
772117-001	"4-1196014-2", "FB-44-7026A-0236CS896"		
CS7808-000	"EPD-RWC-22260-L099"		
873780-000	"44AM1831-18-9/93/96-9", "8-1200877-2"		
002475K001	"1190019-6"		
543390-000	"2-1194262-9", "EPD27383A-90/92"		
A92639K001	"9-1200587-8"		
C38375-000	"1-1201691-9", "44A0111-10-9-8"		
946113K001	"8-1197321-7"		
555723-000	"1-1194384-8", "EPD51312A-10-0"		
387002-011	"8-1192902-4", "44A1111-16-9-9-MX"		
960873-000	"44B9535-20-9/96-9CS1728", "6-1197434-3"		
839135-000	"2-1196548-2", "EPD-RWC-12888"		

306631-000	"9-1192322-8", "44AM1141-24-0/2/6/9-9"		
CX8423-000			
888083-000	"2-1196909-9", "EPD52968A"		
383325-000	"1201781-7", "44A0131-22-9/93/96"		
858165K001	"1196688-1"		
CU0917-000	"EPD-DND-21479-L016"		
CX8764-000	"EPD-DND-23320"		
CX1365-000			
382331-008	"6-1192861-2", "44A0121-22-0/9-MX"		
282838-000	"2-1192127-2", "44A0111-24-MX"		
172649-000	"6-1191255-8", "EPD51035A-22-0"		
CB1132-000	"44/0411-18-9-US"		
C46695-000	"8-1202026-5", "44A1131-20-6/93/96-9"		
CW9141-000	"EPD-RWC-23790"		
468871K001	"1193514-4"		
EK8004-000	"EPD-RWC-17213-L012"		
CL1782-000			
D94145K001	"3-1200583-5"		
282009-018	"6-1192091-6", "44A0111-16-9-MX"		
CL6862-000			
CY9614-000	"EPD-RWC-14920-L012"		

349458-000	"4-1192629-2", "44B1121-24-0/9-94CS2024"		
848967-000	"44AM1151-22-MST5-9", "1-1196620-4"		
207323-000	"7-1191502-2", "EPD-RWC-16009"		
CW0097-000	"EPD-RWC-19930-L098"		
577427-000	"44/4421-14-9 2/96-9CS1784", "3-1194580-7"		
D79405-000	"5-1201279-4", "EPD4748C-IRL-L016"		
182243-000	"3-1191324-5", "44A0121-22-9/96CS2109"		
D63530K001	"3-1200592-7"		
998943K001	"4-1197723-5"		
CU3937-000	"EPD21832F-L099"		
EM6773-000	"400R1111-22-9-9"		
237021K001	"6-1191742-5"		
EF9127-000	"44AM1121-22-9/96-9CS3030"		
EM0498-000	"EPD-RWC-22226-L016"		
442183K001	"4-1193324-4"		
551179-000	"44A9701-18-0/9", "2-1194357-3"		
437583K003	"9-1193288-8"		
282068-000	"9-1192100-4", "44A0114-20-9"		

828001K001	"4-1196466-0"		
CX2061-000			
117861-000	"9-1190857-6", "44A0211-12-94"		
576132-000	"44A0811-14-9-L013", "8-1199134-5"		
674611K001	"1-1195306-2"		
EM7709-000	"EPD-RWC-22043"		
C87618-000	"5-1200406-1", "EPD-RWC-17034"		
CA8047-000	"EPD-RWC-20062-L099"		
285263-000	"1-1201726-9", "44A0114-26-904-US"		
CW9669-000	"EPD-RWC-23400"		
D34119K001	"1200592-3"		
252847K001	"2-1191850-8"		
354418-000	"4-1201422-2", "44A0341-20-0/2/6/9-US"		
580800-000	"5-1198989-9", "EPD-ROK-10492"		
CR3899-000	"EPD-RWC-21557"		
010063K001	"5-1190078-8"		
EM5439-000	"EPD-RWC-23495CS3489"		
190639K001	"9-1191382-3"		
160546K001	"5-1198264-4"		
382451-003	"6-1192863-1", "44A4121-20-0/9-9-US"		

753949K001	"5-1195877-4"		
946583-000	"44A1221-18-9/96-9", "1197325-1"		
CM1779-000	"EPD-RWC-20843"		
F82687K001	"2-1202115-9"		
D15853-000	"1-1201555-2", "44A1121-20-9/9-9CS2976"		
828445-000	"6-1196469-0", "CSC-0218-C-X-0"		
150441K001	"7-1191087-8"		
427781K001	"6-1193218-8"		
770641-000	"8-1196003-6", "CTC-0039-20-9/5-9"		
282767-002	"6-1192125-6", "44A0111-22-927"		
CJ1791-000	"44A0111-20-9-4CS3144-L193", "1-1899270-9"		
CY8600-000			
215193-000	"3-1191554-1", "CSC-0189-20-0CS2439"		
393012-000	"6-1192948-5", "4J4S-12-F10-8"		
057087-000	"1-1190434-2", "44A9086-16-0/9/90"		
265024-000	"9-1191950-8", "44A0811-24-9-MX"		
259135K001	"8-1191895-5"		
CA8053-000	"EPD-RWC-15185-L099"		

666131-000	"44A0141-26-3/5/6/9", "9-1195247-3"		
777745-000	"2-1196054-6", "FLDWC0311-20-9"		
D05283-000	"7-1202024-3", "EPD52415A-12-0-L072"		
F45837-000	"44A0111-18-950-2KF", "2-1200268-6"		
237287-000	"5-1191744-2", "EPD64091A"		
EG5999-000	"EPD-DND-23327-L016"		
163818-000	"2-1191182-6", "44A0111-12-904"		
E06200K001	"6-1200867-1"		
918831K001	"7-1197130-6"		
220991K001	"2-1191629-1"		
387681-000	"5-1192911-6", "44A3111-22-9"		
255477K001	"2-1191870-0"		
861311K001	"2-1196710-1"		
436567-000	"7-1193281-4", "44/4421-12-92/96-9CS1784"		
483539-000	"1193619-3", "EPD-RWC-14918"		
282766-000	"6-1192125-2", "44A0111-22-926-US"		

734863-000	"3-1195739-1", "EPD45267A"		
CJ7479-000	"FLDWC1331-18-9/90/92-9CS2959"		
187883-000	"5-1191363-9", "44A9673-18-9CS2745"		
F45850-000	"EPD48804B-US-CS2979", "8-1200205-0"		
D93815-000	"2-1201872-8", "44A0111-16-9-G135"		
EH6663-000	"EPD-DND-21487"		
306188-001	"7-1192318-9", "44AM1121-22-6/9-9"		
306306-000	"9-1192319-8", "44AM1131-16-3/6/9-9"		
109363-000	"9-1190798-5", "EPD47319A-18-0CS2829"		
551738-000	"44B1121-20-90/91-9CS3018", "8-1199963-5"		
003993-000	"4-1190030-1", "44B1811-20-9-9CS2018"		
882541K001	"6-1196869-2"		
CX8626-000			
694885K001	"6-1195451-4"		
CU3944-000			
CZ7352-000	"345M09B-22-28-0CS2041"		
570437-000	"44AM2111-22-9-9", "6-1194521-5"		

EJ5457-000	"EPD52370A-22-0-L172"		
CF3718-000			
D72808-000	"1-1201706-4", "44A0111-12-9-2CS3144"		
CM5742-000	"FLDWC0311-12-9CS2736"		
C15020-000	"3-1200876-0", "EPD8467B-US-L099"		
283221-002	"2-1192133-7", "44A0111-16-90-MX"		
E46013K001	"4-1200586-9"		
CX2616-000	"44A0321-16-9/9CS3030"		
347137-000	"7-1192612-9", "EPD51948A-18-0"		
F10755K001	"1-1200403-4"		
782821-000	"44A9615-26-6/96CS910", "1196080-4"		
CS9473-000	"EPD-DND-21534-L016"		
427727-000	"3-1193218-3", "EPD71032A-24-0"		
E30566-000	"7-1199874-2", "EPD37109B-US-CS2979"		
CF5047-000	"44BC2121-16-1/9-9CS3222"		
924173-000	"44AM1111-16-954-9", "1-1197169-3"		
848222-000	"44B4141-24-ELC4-9CS1873", "9-1196614-0"		

EG7280-000	"44A0121-22-9/912"		
CB7290-000	"EPD-RWC-19984"		
589024-000	"44B1121-24-0/9-97", "9-1194660-0"		
903271K001	"8-1197019-4"		
976642-000	"44A1131-22-9/90/92-9", "7-1199189-2"		
EG7205-000	"44A0121-22-9/937"		
F31444K001	"5-1200808-4"		
CX6374-000	"EPD-RWC-23210-L201"		
CB0926-000	"EPD-RWC-20162-L180"		
483638-000	"44B1121-24-0/9-98", "6-1193619-7"		
CY2164-000			
306490-000	"1192322-1", "44AM1121-22-0/9-90"		
232433-000	"3-1191707-2", "44A0211-12-9-1KF/1"		
733413-000	"4-1195728-6", "EPD-RWC-10818"		
426973-000	"9-1193212-3", "EPD68112A-US"		
208327K001	"7-1191509-7"		
C70663-000	"1202032-9", "EPD-RWC-17026-L106"		
510249K001	"7-1194010-4"		
969257-000	"7-1197493-0", "EPD51022A-22-0"		

437373-000	"5-1193287-2", "44A0121-24-9/96CS2109"		
678486-000	"44A0131-12-3/6/9", "8-1195333-4"		
F61911-000	"44AM1121-24-9/96-0", "6-1200764-9"		
382509-002	"5-1192864-1", "44A1141-20-0/2/5/9-9-MX"		
EG2514-000	"EPD-RWC-23965"		
631661K001	"2-1194998-0"		
CS7643-000	"EPD-RWC-22228-L099"		
382121-006	"1192857-9", "44A1131-24-0/2/9-9-MX"		
CX8022-000	"FLDWC1331-16-F023-0CS2959"		
376248-000	"44A0124-24-5/9"		
F94594-000	"3-1201183-6", "44A1821-24-6/9-9"		
E42953-000	"8-1201378-1", "EPD-RWC-18483"		
120137-000	"1190874-3", "EPD68104A-US"		
E06191-000	"8-1201997-8", "44A0131-20-6/93/96"		
CW5806-000			
CJ6331-000	"EPD4648E-IRL"		
E84697K001	"2-1200977-1"		
253753-000	"7-1191857-5", "44A9416-14-9CS1981"		

F40431-000	"EPD-NAV-17303"		
282763-000	"4-1192125-9", "44A0111-22-917-US"		
C03875-000	"1200693-6", "EPD-RWC-10946-L087"		
930035-000	"44/2411-22-9-9CS024", "9-1197209-7"		
381063-000	"1-1192849-6", "EPD52675A-22-0"		
998462-000	"44A7620-22-9/5-3", "8-1199502-6"		
E40872K001	"1-1200393-3"		
D66115K001	"7-1201127-6"		
CN5816-000			
472401-000	"3-1193539-7", "EPD-RWC-15024"		
085187-000	"8-1190628-9", "44A9083-16-90CS2745"		
617065-000	"44A9090-16-0/2/9-9CS2746", "1-1194877-5"		
EG2503-000			
A72611K001	"2-1201235-0"		
362977K001	"4-1192721-7", "EPD-PRC-10021-CO2-KIT-4"		
614715K001	"2-1194859-2"		
382467-000	"8-1192863-4", "44A1121-24-2/9-9"		
CL1788-000	"EPD-RWC-20669"		

ER2276-000	"EPD-RWC-19929-5CF/1"		
384287-000	"4-1192883-5", "44A0131-20-2/9/92-US"		
282049-023	"8-1192099-4", "44A0111-24-9-MX"		
CZ5309-000	"EPD-DND-21538"		
041115-000	"4-1190314-9", "CTC-0039-20-9/5-0"		
572291-000	"44B1121-16-0/9-92CS2025", "7-1194542-5"		
CU8292-000	"44A0212-12-95"		
358907K001	"1-1192693-2"		
EG8828-000	"400R1121-16-0/9-9"		
A41350K001	"1-1200541-7"		
977379K001	"5-1197809-9"		
A57811K001	"3-1201147-4"		
902115K001	"4-1197011-6"		
689948-000	"3-1200287-0", "EPD-RWC-17026"		
833702-000	"44A1131-14-0/5/9-0", "5-1199917-8"		
258159K001	"1191889-4"		
282884-000	"2-1192128-7", "44A0111-24-923"		
105587K001	"7-1190771-8"		
012281-000	"8-1190096-2", "44AM1131-24-9/93/96-3"		

604927-000	"3-1194786-9", "EPD51502A-X-0"		
D64156K001	"9-1200976-0"		
535343-000	"3-1194203-8", "EPD52188A-14-0"		
F70107-000	"2-1201391-4", "44A0111-22-9-BARREL"		
CM1715-000			
CX8476-000			
071841K001	"2-1190539-4"		
E03620K001	"5-1200938-7"		
306322-000	"2-1192320-1", "44AM1131-20-3/6/9-9"		
494819-000	"44B9536-22-MST3-9CS1728", "4-1193700-2"		
D93936-000	"6-1201279-2", "EPD4665D-IRL-L016"		
EP6204-000	"EPD-RWC-25556"		
378984-002	"4-1192835-9", "44A9064-24-0"		
EG9943-000	"44A7418-X-0-L016"		
CB5749-000	"44A1171-22-0/2/4/5/6/8/9-9"		
EG2548-000			
393043K001	"1192949-9"		
742291K001	"5-1195792-5"		
E86658-000	"6-1201759-2", "44AM1111-16-94-9-1KF"		

583494K001	"1199199-2"		
D79303-000	"7-1202081-8", "44AM1111-16-96-9-1KF"		
CN6734-000			
056679-000	"4-1190431-2", "44A9636-24-9/96-9CS2337"		
164861K001	"1191190-8"		
871464K001	"7-1198861-9"		
368109-000			
285786-000	"3-1192163-5", "44A0111-26-96-US"		
CA1045-000			
EM0397-000	"EPD-RWC-22251-L016"		
EM9813-000	"400R1141-18-0/2/4/9-0"		
113645K001	"9-1190828-5"		
005879K001	"9-1190044-0"		
515031K001	"4-1194045-7"		
CN5743-000	"EPD90506A-US"		
EK3793-000			
029083-000	"3-1190225-4", "44B1821-16-92/96-9CS2018"		
540243-000	"9-1194237-0", "EPD52636A-20-0"		
282625-002	"6-1192120-5", "44A0111-22-92-US"		
531941K001	"1-1194177-5"		

889663-002	"3-1196921-8", "EPD23572B-US"		
822329-000	"44AM1121-20-9/938-9CS1726", "2-1196413-2"		
492053-000	"44/2431-22-F023-9CS1506", "2-1193680-7"		
D06024K001	"9-1201277-6"		
340707-000	"9-1192569-7", "44B9537-20-MST4-9CS1728"		
362803-000	"2-1192720-0", "EPD68117A-US"		
CS7806-000			
CP1025-000	"FLDWC0311-20-9CS2736"		
CR5785-000	"EPD-DND-22099-L236"		
EJ1070-000	"EPD43502D-US-L012"		
196841-000	"1-1191427-7", "44AM1121-20-0/9-9CS262"		
D98146K001	"1-1202052-9"		
CN3400-000			
254507-000	"1-1191863-9", "CMC-0575-18-0CS2327"		
527005-000	"1-1194141-0", "EPD68106A-US"		
431660-000	"5-1193246-5", "44/7024-26-9-9"		
448305K001	"6-1193368-3"		

944051-000	"9-1197307-6"		
C72592K001	"7-1200583-6"		
461023-000	"7-1193457-8", "EPD52797A-22-0"		
840233-000	"44/4424-26-9 2/96- 9CS1784", "6- 1196555-9"		
374962-000	"3-1201789-5", "44A1321-24-0/9-9-US"		
401873-000	"1193034-7", "EPD51153A "		
C21680-000	"2-1201124-5", "EPD-IRL-18306"		
387437-000	"5-1192909-0", "44A1111-20-9-90"		
C03812-000	"1201127-6", "EPD60087A-US"		
844971-000	"44AM1121-20-0/9-9CS1702", "9-1196591-9"		
939685-000	"7-1197276-5", "EPD52681A-22-0"		
CL5548-000	"44A1161-22-0/1/2/3/4/9-9"		
285759-012	"8-1192162-0", "44A0111-26-9-US"		
966349-000	"5-1197472-9", "EPD29766A "		
763353-000	"44A9665-16-0/2/5/9-0", "7-1195943-5"		
CA6779-000			
CY2149-000	"EPD-DND-23195-L308"		

CR3717-000	"44B5121-12-9/96-9CS1401-L050"		
994039-000	"44AM1131-16-0/09/92-9", "1197689-6"		
D56733-000	"44A1221-18-6/9-0-US", "2-1200933-6"		
148920-000	"6-1201759-7", "44AM1111-14-90-9-1KF"		
525939K001	"8-1194132-4"		
950343-000	"7-1197349-9", "CMC-0124-8"		
093531K001	"3-1190686-1"		
CJ9794-000	"44A1114-26-9-9-2"		
836843-000	"9-1196531-6", "FB-44-7026A-0219CS896"		
CA9982-000	"EPD-RWC-20160-L172"		
820437-000	"44A0811-10-904", "2-1196397-9"		
378774-000	"1-1200075-9", "44A1121-26-4/9-9"		
900874-000	"44A0131-26-3/6/9", "4-1197002-3"		
211983-000	"3-1191535-3", "345M09J-22-38-OCS2041"		
382765-000	"6-1192867-0", "44A1121-18-0/9-0-MX"		
CB7273-000			
CU2539-000	"44AM4161-22-MST6-9CS3330"		

389941-002	"7-1192927-7", "44A9052-X-0"		
EF5948-000	"EPD-RWC-23972"		
853023K001	"6-1196649-5"		
405201-000	"1-1193058-0", "EPD-RWC-10945"		
436357-000	"3-1193280-1", "EPD-RWC-11166"		
340819K001	"8-1192570-3"		
EG7276-000	"44A0121-22-9/924"		
467481K001	"1193504-4"		
319887K001	"9-1192425-7"		
920179K001	"2-1197140-7"		
267935-000	"5-1191977-3", "44A1831-20-3/6/9-9"		
CF9381-000	"44A0111-12-922-1KF"		
282064-000	"5-1192100-5", "44A0111-14-9-MX"		
F20706K001	"9-1200578-7"		
404841K001	"4-1193055-8"		
074705-000	"9-1190558-9", "44AM1121-22-9/92-9CS1726"		
382506-000	"4-1192864-1", "44A1121-22-6/9-9-MX"		
534823-000	"44/7004-26-9CS1890", "8-1194197-2"		
CL9784-000	"EPD-ROK-10476-L212"		

457233-000	"44/0414-24-9CS2346", "2-1193431-5"		
732363-000	"9-1195720-1", "EPD-ROC-10043"		
327479-000	"5-1192477-9", "EPD-RWC-10819"		
338341K001	"5-1192553-8"		
D70482-000	"2-1201098-6", "EPD8710B-US-L099"		
331469-000	"3-1192504-6", "EPD-ROK-10314"		
387068-000	"4-1201286-3", "44A1111-24-9-1-US"		
F65902-000	"EPD24566D-RYQ", "1-1200937-8"		
549489-000	"7-1194323-6", "EPD-RWC-14908"		
CA7512-000	"44A9749-16-1/9-9CS3185"		
083763-000	"1190619-9", "44AM1111-16-906-9"		
F67004-000	"EPD24557D-RYQ", "2-1200937-0"		
CN4459-000	"44A0141-20-MST4CS2994"		
068949K001	"4-1190519-0"		
951007K001	"4-1197354-3"		
949458-000	"44AM1111-14-92-9-1KF", "7-1198068-1"		
441169K001	"4-1193317-1"		

777123-000	"8-1196049-9", "EPD33336A-US"		
310009K001	"3-1192347-1"		
809923-000	"1196294-8", "EPD50605A"		
072830-000	"5-1197983-4", "EPD-RWC-16410"		
D84863-000	"7-1200572-1", "EPD-RWC-17027"		
345591-000	"8-1192601-5", "EPD52210A-22-0"		
853962-000	"44A0114-24-9CS045", "2-1196657-4"		
CB1691-000	"EPD-RWC-20171"		
414834-000	"1-1197951-5", "44A1221-12-9/96-9-1KF/1"		
314249K001	"7-1192378-6"		
224943K001	"9-1191656-2"		
F87031K001	"3-1200404-0"		
766455-000	"5-1195973-8", "EPD8104B-US"		
EG3686-000	"EPD-RYQ-23426-L334"		
EM7444-000	"44A1121-20-9/901-9"		
459668-001	"10515-X-8CS1285", "9-1193447-1"		
305609-000	"1192314-9", "EPD52955B"		
CB4832-000			

194184-000	"9-1191408-5", "44B1221-24-9/96-925"		
F80706-000	"44A0111-14-9-L038", "7-1200553-4"		
403853K001	"6-1193048-6"		
441491-000	"6-1193319-9", "EPD50965A"		
119647-000	"5-1190870-3", "44B5141-12-MST4-9CS1401"		
274705K001	"7-1192034-8"		
F37121-000	"44A4121-26-3/9-9", "1-1201058-8"		
273391-000	"2-1192025-2", "EPD-ROC-10046"		
CX0070-000	"EPD-DND-21668-L016"		
078666-000	"7-1200173-7", "44A1161-16-0/2/3/4/5/9-9"		
274098-000	"2-1200284-2", "EPD-RWC-17025"		
109929-000	"5-1197850-8", "EPD-RWC-15994"		
219319K001	"3-1191618-2"		
772536-000	"9-1199976-9", "EPD5611"		
D46193K001	"2-1200938-9"		
872855K002	"2-1196792-3"		
075781-000	"6-1190566-7", "EPD52372A-22-0"		

473283-001	"44B9202-X-9", "9-1193545-1"		
EL5681-000	"EPD-RWC-24462"		
D93014K001	"6-1199862-5"		
027877K001	"7-1190215-7"		
387328-000	"5-1200800-2", "44A1111-22-9-96-US"		
127923-000	"7-1190929-2", "EPD51050A-18-0"		
838654K001	"1-1200162-0"		
EP4900-000	"EPD-RWC-19813-L305"		
225823K001	"1-1191663-6"		
931033-000	"345/41B-22-14-0CS1913", "9-1197216-0"		
285791-000	"5-1192163-8", "44A0111-26-90-US"		
EH2541-000	"44A9673-18-9CS3433"		
295883-000	"7-1192241-4", "EPD-RWC-11684"		
EK9400-000	"EPD-RWC-24330"		
155429-000	"8-1197856-6", "44A0221-14-0/9-1KF/1"		
630947-000	"44A9083-16-9CS2745", "1194993-7"		
374315-000	"7-1200383-3", "44A1141-12-0/2/5/9-9-US"		
F74453K001	"2-1201182-2"		
CM1759-000			

CU3765-000	"EPD66485A-L099"		
163557K001	"4-1191180-3"		
C39813K001	"5-1201719-8"		
985637-000	"44B1831-20-MAS3-9CS2018", "3-1197614-5"		
F64040-000	"EPD24565D-RYQ", "1-1200937-6"		
197915-000	"3-1191434-6", "44B9537-20-MST4-9CS3023"		
241097K001	"2-1191771-3"		
CS5230-000	"EPD-RWC-21849"		
266217-000	"1-1197843-1", "EPD92433A-US"		
CR7932-000	"CTC-0039-16-9/5-9"		
CX9123-000	"EPD-DND-23310-L016"		
839747-000	"44AM1111-18-925-9", "3-1196552-1"		
E63619K001	"1-1200694-0"		
226681-000	"1-1191669-1", "44B5141-20-MST4-9CS1401"		
CN1188-000	"44AM1121-18-9/96-9CS3209"		
792367-000	"1196136-9", "EPD51903A-14-0"		
688995-000	"2-1195411-5"		
383549K001	"1-1192876-6"		
CL6589-000			

123857-000	"9-1190900-7", "EPD-RWC-12125"		
A942803001	"7-1201388-6", "44A1121-18-0/9-9CK0001"		
408955-000	"6-1193084-6", "EPD-ADD-10008"		
957314-000	"3-1200089-4", "EPD-PFM-10050CS2962"		
954573-000	"44A9677-22-ELC4-9CS2746", "8-1197390-2"		
138655-000	"5-1191005-5", "44A1231-18-0/2/9-0"		
867417-000	"5-1196753-1", "FB-44-7026A-0229CS896"		
E30586K001	"1200692-7"		
503543-000	"44/2414-24-9-9CS1222", "9-1193789-4"		
149077K001	"1191078-5"		
537800-000	"8-1198907-3", "FLDWC1331-20-F023-9CS2959"		
858271-000	"6-1196688-8", "EPD6032-18-0"		
706113K001	"2-1195537-2"		
462455-000	"5-1193468-1", "CMC-0560-X-0"		
460201K001	"8-1193451-6"		
208705K001	"6-1191512-3"		

D34931-000	"2-1200805-4", "EPD-RWC-17943"		
CX2318-000	"44AM1821-12-0/9-9CS262"		
3N0065-000	"2-1193012-1", "EPD8950A"		
CS7765-000			
476102K001	"8-1198862-6"		
A06598-000	"2-1201147-5", "EPD100243 A-US-L099"		
CS2552-000	"44A4121-20-0/9-9-F871"		
491607K001	"1193677-2"		
CJ8042-000	"44AM1121-22-9/96-9CS3209"		
100001-000	"7-1190732-8", "44B1133-16-0/2/9-0"		
698405K001	"9-1195480-4"		
382314-002	"3-1192861-8", "44A0121-22-2/9-MX"		
475881-000	"4-1193564-1", "EPD-ADD-10071"		
356795-000	"1197969-6", "EPD70554A-US"		
782209-000	"44A9586-26-9-3", "6-1196075-6"		
885445-000	"1-1196890-3", "FB-44-4120-0002"		
009023K001	"9-1190069-6"		
CU2244-000	"CEC-RWC-22525"		
CF5069-000	"44BC2121-22-1/9-9CS3218"		

940287K001	"1-1197281-7"		
CS7778-000	"EPD27729A-US-L011"		
282756-000	"1192125-9", "44A0111-22-93"		
D50704K001	"8-1201420-8"		
CM5449-000	"44AM1141-22-MST4-9CS3209"		
345433-000	"4-1192600-7", "44A1121-26-9/90-9"		
CB1716-000			
CD61243001	"1-1899381-7", "44A0111-22-9CK0300"		
F40508-000	"8-1201818-1", "EPD5637"		
292685-000	"5-1192218-9", "44/2451-24-F547-9CS1506"		
950657-000	"9-1197351-2", "EPD51063A-18-0"		
CS2953-000	"44A0111-18-9-F871"		
CU5269-000	"EPD66213A-L099"		
306338-001	"3-1192320-6", "44AM1131-22-0/2/9-9"		
D92217K001	"3-1200583-4"		
CJ9230-000	"44AM1131-24-MST3-9CS3209"		
793647-000	"44B1141-24-MST4-9CS2638", "9-1196144-1"		
546009-000	"8-1194296-2", "EPD-ROK-10037"		

E07100-000	"4-1201737-6", "FB-RWC-19175"		
761159-000	"4-1195928-9", "EPD51463A-22-0"		
839689K001	"9-1196551-0"		
526285-000	"8-1194135-4", "EPD-RWC-13842"		
D96175K001	"1200355-9"		
CN6741-000	"EPD96719C-US"		
0110183001	"3-1198931-2", "44A1121-22-0/9-9CK0001"		
652661-000	"44AM1141-16-0/2/6/9-9", "6-1198940-5"		
CA6566-000	"44A4122-20-1/9-9CS3185"		
555927-000	"44AM1111-22-9-9CS2399", "7-1194385-4"		
389608-000	"5-1192924-4", "44A0121-16-6/9"		
CN6850-000			
667692-000	"44/0414-24-9CS1038", "6-1195258-2"		
681412-000	"1195358-3", "FB-44-4026-0047"		
192559K001	"9-1191396-7"		
479647-000	"8-1193590-3", "EPD-ROC-10049"		
412820-000	"9-1200140-7", "EPD-PFM-10059CS2974"		
592541K001	"1-1194686-1"		

383302-000	"5-1192873-8", "44A1121-20-0/9-90"		
640975K001	"4-1195066-1"		
173517-000	"1-1191262-4", "FB-RWC-12907"		
710149-000	"44A0121-20-9/91CS1741", "1195564-1"		
EM7722-000	"EPD-RWC-22037"		
778585-000	"345/37B-22-60-0CS1913", "9-1196059-5"		
820349K001	"6-1196396-0"		
382001-000	"1199107-6", "44A1121-20-9/9-9-MX"		
306003-000	"9-1192316-2", "44AM1121-12-9/96-9"		
CM2541-000	"EPD-RWC-20963"		
CS8547-000			
CX0443-000	"EPD-DND-21481-L016"		
3831593001	"1-1192872-0", "44A0221-16-0/9"		
277928-001	"1192058-9", "44B5121-20-9/96-9CS1728"		
383867K001	"4-1192879-5"		
382554-002	"2-1192865-6", "44A1141-24-0/2/5/9-9"		
282071-000	"1-1192101-3", "44A0112-20-9"		
241267K001	"5-1191772-8"		

176873-000	"9-1191285-2", "44A9586-18-9"		
545167-000	"9-1194289-7", "EPD-RWC-13425"		
331145K001	"1-1192502-0"		
C38469K001	"6-1201280-4"		
E86241-000	"1-1200355-6", "EPD-RWC-15769"		
510839-000	"44AM1121-26-0/9-9CS984", "1-1194015-3"		
CX0036-000	"EPD-DND-21547-L016"		
306253-000	"2-1192319-8", "44AM1121-24-0/9-9"		
169513K001	"9-1191233-0"		
741599-000	"44AM1841-10-0/2/5/9-1", "6-1195787-7"		
971610K001	"6-1199169-5"		
058007K001	"4-1190440-4"		
525090K001	"6-1198851-4"		
704839-000	"345/37B-22-30-0", "5-1195528-2"		
CL6669-000			
CB6546-000	"345/31-14-4-0CS3202", "8-1899180-0"		
CN5756-000			
764184-000	"44AM1131-22-MST3-9CS2109", "1198271-8"		

222407-000	"2-1191638-8", "EPD50481A"		
A23962-000	"8-1200403-9", "EPD96521A-US"		
A56630-000	"8-1201278-0", "EPD4664D-IRL-L016"		
194647-000	"1191412-8", "EPD8473B"		
A82639K001	"7-1200803-2"		
145499-000	"2-1191051-6", "EPD25501A"		
D76147K001	"6-1200588-6"		
382924-000	"4-1192869-7", "44A0121-26-9/90-US"		
EH9625-000	"EPD-RWC-24409-L172"		
D86141K001	"7-1200588-6"		
CR6265-000	"EPD-RWC-17038-L012"		
412059K001	"7-1193107-6"		
662879-000	"1-1195225-2", "EPD51007A-X-0"		
CS5794-000	"EPD-RWC-21427"		
CF2182-000	"44A9605-16-9-L183"		
256469-000	"8-1191876-8", "EPD-RWC-14216"		
099181K001	"1190727-2"		
417655-000	"8-1193146-8", "44/0411-16-9CS470"		
EM5812-000	"44A0221-22-9/9"		

EM3777-000	"44AM1131-16-0/2/9-9-L227"		
393765K001	"9-1197902-9"		
094005-000	"2-1190689-8", "EPD-RWC-14215"		
282304-000	"5-1200823-7", "44A0112-12-9-US"		
283223-000	"3-1192133-7", "44A0111-16-95"		
761279K001	"2-1195929-1"		
799359K001	"2-1196180-0"		
CB7127-000	"EPD-RWC-19932"		
CM6020-000			
732429K001	"4-1195721-8"		
C74772-000	"2-1201497-5", "44B1121-20-G058-9CS3018"		
E89413-000	"1201408-3", "44A0111-18-945-2KF"		
105057-000	"1190768-7", "EPD-ROC-10004"		
EG6830-000	"EPD62289A-US-L077"		
431665K001	"5-1193246-9"		
153915K001	"1191112-3"		
F36871-000	"1201715-4", "44A0211-16-9-2KF/1"		
692117-000	"6-1195433-7", "EPD-RWC-14214"		
306262-001	"3-1192319-9", "44AM1121-24-6/9-9"		

043911K001	"4-1190337-8"		
717075-000	"5-1195609-6", "EPD-RWC-10950"		
661587-000	"44AM1121-20-9/935-9CS1726", "4-1195215-6"		
CU9566-000			
518428-000	"3-1201164-4", "EPD-RWC-18316CS3100"		
375156-000	"5-1192810-1", "44/1411-16-9-9"		
CA2940-000			
839600-001	"44B5131-20-MST3-9CS1728", "2-1196551-2"		
C76437-000	"5-1200403-5", "EPD96520A-US"		
CU8716-000	"EPD-DND-21499-L177"		
575249K001	"4-1194565-4"		
182003K001	"5-1191322-5"		
EF5949-000			
544567K001	"7-1194271-5"		
066741K001	"3-1190503-4"		
864267-000	"1-1196731-6", "CTC-0039-22-9/5-9"		
CP2270-000	"44B9202-X-9CS3294"		
CW0109-000	"EPD-RWC-19928-L319"		
375196-002	"8-1192810-5", "44/1611-24-9-9-US"		

CS4976-000	"44A1821-18-0/9-2-1KF/1"		
C72808-000	"9-1202073-8", "44A0811-10-96-1KF"		
A97400-000	"7-1201395-2", "44B5141-12-MST4-9CS3012"		
D76490-000	"5-1201279-1", "EPD4747D-IRL-L016"		
993812-000	"44AM1111-14-922-9", "4-1197956-2"		
572169K001	"8-1194541-8"		
EL5429-000	"44A1113-22-9-9"		
471607-000	"6-1193533-3", "EPD51685A-22-0"		
261189-000	"4-1191911-1", "44A9083-20-9"		
C32546-000	"4-1201863-9", "EPD-RWC-19383"		
487557K001	"5-1197897-7"		
D54928-000	"8-1200579-7", "EPD-RWC-17745"		
805597-000	"7-1196226-0", "EPD-PRC-10023"		
EM8267-000			
E72706K001	"1-1201421-5"		
698164-000	"44AM1131-16-G029-9-1KF", "4-1198065-4"		
E33792-000	"5-1201345-6", "EPD-RWC-10937-L110"		

189583K001	"5-1191375-5"		
ER6312-000	"44A0321-16-0/9-US"		
283007-000	"2-1192130-7", "44AM1151-22-2/3/5/6/9-9"		
CA8026-000			
CF7333-000	"44AM1121-20-9/96-9CS3209"		
888777K001	"4-1196914-1"		
393785K001	"2-1192954-8"		
662203K001	"9-1195219-3"		
383332-000	"8-1192873-3", "44A1121-16-9/96-9"		
382763-000	"7-1200873-0", "44A1131-18-0/2/9-0-US"		
CN5825-000			
757032K001	"1-1198254-5"		
A44316K001	"4-1200583-6"		
343927-000	"6-1192590-6", "EPD4754D"		
CW0106-000	"EPD-RWC-19941-5CF/1"		
202189K001	"7-1191465-0"		
285779-000	"2-1192163-7", "EPD40418A-US"		
188763-000	"9-1191369-3", "EPD51237A-X-0"		
766779-003	"9-1197924-6", "EPD68607A-ING"		

484841-000	"44/1424-26-0/9-9CS2251", "2-1193629-0"		
648607-000	"1195120-1", "EPD52193A-22-0"		
733377-000	"2-1195728-9", "EPD-ROK-10283"		
CY0517-000	"44B5111-16-9-9CS1401-L302"		
A60079-000	"4-1201280-4", "EPD4745D-IRL-L016"		
EM9507-000	"FLDWD6004-12-9"		
576673-000	"44AM1144-24-3/5/6/9-9", "2-1194575-0"		
EG4835-000	"EPD-RWC-22985CS1584"		
CB7120-000	"EPD-RWC-19929"		
502363-000	"345M06B-22-14-0CS2041", "9-1193771-2"		
D54231-000	"1-1202074-2", "44A0111-14-95-2KF"		
CA2939-000			
445262K001	"7-1199198-7"		
CW4991-000	"EPD-RYQ-23558-L012"		
EL7210-000			
738837K001	"5-1195767-1"		
A56723-000	"3-1201926-0", "44A0111-16-922-L030"		
CJ1642-000			

F01466K001	"6-1200764-5"		
CP7521-000	"FLDWC0311-16-9CS2736"		
179914K001	"5-1199953-7"		
817861K001	"1-1196373-7"		
475453K001	"2-1193561-0"		
CA0493-000	"EPD-RWC-19833-L186"		
707893K001	"9-1195548-0"		
EG5958-000			
CY0038-000			
387239-000	"1192907-5", "44A1112-24-9-9-MX"		
465415-000	"44A7669-20-8", "6-1193489-3"		
974583K001	"6-1197531-1"		
282659-000	"9-1192121-3", "44A0111-22-912-US"		
2820393012	"8-1192097-0", "44A0111-22-9"		
EG9415-000			
319442K001	"2-1200081-5"		
CW5257-000	"EPD40416A-RYQ-L012"		
CR3161-000	"EPD-RWC-17025-L012"		
CA6180-000			
499675K001	"3-1193735-9"		
161801K001	"3-1191168-2"		
237593-000	"6-1191746-8", "EPD-RWC-13450"		

CZ0152-000	"EPD-DND-21490"		
382384-000	"6-1192862-1", "44A0131-20-0/1/9"		
383093-000	"1-1192871-1", "44A0121-12-0/9-US"		
842992-000	"7-1196575-3", "EPD23066B-US"		
693509K001	"9-1195441-8"		
035529K001	"7-1190274-0"		
6981343001	"44A0111-24-9CK0001", "3-1198728-0"		
A16976-000	"3-1200589-3", "EPD-RWC-17767"		
F77185K001	"7-1200354-8"		
CX2160-000	"EPD21695D-IRL"		
348563-000	"9-1192622-9", "EPD-RWC-11709"		
527893-000	"1-1194147-8", "EPD-ROK-10310"		
CN6857-000	"EPD108704 A-US"		
304000-000	"4-1192302-4", "44AM1811-12-9-9"		
366141-000	"8-1192744-8", "44A1811-18-9-3"		
404013K001	"9-1193049-4"		
CJ6932-000	"44A1321-16-9/9-9CS3030"		
418362-000	"1198066-4", "44AM1131-16-9/9/9-9-1KF"		

CF3421-000			
383783-000	"2-1192878-7", "44A0121-24-4/9-US"		
663049-000	"2-1195226-1", "EPD52626A-X-0"		
478231-000	"44A9964-16-9CS2514", "1-1193581-6"		
CW5804-000			
E24683K001	"1200692-5"		
CF3715-000			
CA4481-000	"FB-44-4624-0201CS3186", "2-1899114-4"		
263144-001	"9-1191936-8", "44A2121-24-1/9-9CS006"		
A33917K001	"1200592-7"		
171221K001	"6-1191245-3"		
C01680K001	"3-1200976-2"		
374544-000	"1-1192805-3", "44A1141-16-3/5/6/9-9-US"		
600369K001	"2-1194748-5"		
329775-000	"6-1192492-2", "44A9673-22-90CS2745"		
CN3176-000			
F72430-000	"9-1201284-2", "EPD4762C-IRL-L016"		
666253-000	"10473-X-8CS791", "7-1195248-2"		
108280-000	"6-1198311-5", "44A0141-24-3/4/6/9-MX"		

030610K001	"2-1197971-2"		
306303-000	"9-1192319-3", "44AM1131-16-0/2/9-9"		
EP2883-000	"400R1161-16-0/2/3/5/6/9-0"		
172871-000	"3-1191257-3", "CTC-0046-22-9/4-3"		
251629-002	"9-1197925-2", "EPD68645A-ING"		
E72104K001	"1-1200584-0"		
503403K001	"1193789-1"		
898093-000	"6-1196981-0", "EPD51070A-22-0"		
871161-000	"1-1196780-1", "EPD52373A-18-0"		
CJ0237-000	"EPD-RWC-16889-L191"		
2820293019	"7-1192095-7", "44A0111-20-9"		
CM1716-000	"EPD-RWC-20841"		
294611-000	"1-1192232-5", "CMC-0201-X-0"		
132697K001	"1-1190964-6"		
630893-000	"6-1194992-8", "EPD-RWC-10946"		
987955-000	"44A0841-10-9/92/95/96", "9-1197632-7"		
383028-000	"4-1192870-0", "44A1132-24-0/2/9-9-US"		

301109-001	"1-1192281-3", "44AM1111-20-9-90"		
383384-000	"5-1192874-9", "44A1131-22-0/2/9-92"		
C91468-000	"8-1201553-9", "CTC-0039-20-9/5-9CS2979"		
CP4825-000	"EPD-RWC-19003-L240"		
168351K001	"8-1191225-5"		
CS2549-000	"44A0111-18-90-F871"		
CX1367-000			
465097K001	"2-1193487-6"		
337073-000	"1-1197907-6", "44A0111-22-9-INT"		
CF1044-000	"EPD-RWC-19272-L140"		
206485-000	"8-1191496-6", "44A0121-20-91/915"		
916581-000	"1-1197115-6", "EPD51402A-24-0"		
814819-000	"44AM1111-16-961-9", "6-1196348-6"		
EG2641-000	"EPD-RWC-23971"		
961253-000	"1-1197437-4", "EPD26676A-0/9-US"		
CA7751-000	"EPD-NAV-93219"		
983936-000	"9-1200249-7", "EPD-RWC-17210"		
CR3724-000			

728723-000	"44A0121-24-90/92", "2-1195694-1"		
495281K001	"3-1193704-4"		
906315-000	"4-1197041-8", "EPD-RWC-15996"		
E47785-000	"2-1201885-2", "44A0114-22-9-L095-US"		
770373K001	"1-1196002-3"		
321139-000	"7-1192433-7", "EPD-ROK-10043"		
480979K001	"4-1193600-6"		
CJ1808-000	"44A0111-22-9-17CS3144L193", "3-1899270-2"		
612213-000	"44AM1131-16-0/1/9-9CS1702", "5-1194840-7"		
883310-000	"44B1111-24-9-92CS1271", "9-1196874-4"		
306431-000	"1-1198128-5", "44AM1141-24-9/93/95/96-9"		
416733-000	"4-1193140-9", "EPD23068B"		
F39898K001	"5-1201440-2"		
029587-000	"3-1190229-5", "EPD51403A-24-0"		
952483K001	"8-1197375-0"		
ER1226-000	"EPD-RWC-19941CS3524"		

3823063009	"6-1192860-1", "44A1121-16-0/9-9"		
A42738K001	"8-1199953-0"		
EG6143-000	"EPD-DND-23068-L016"		
CS7773-000			
243439-000	"4-1191786-1", "EPD52530A-14-0"		
CA3513-000			
628073K001	"6-1194972-9"		
F85104-000	"3-1201927-7", "44A0111-16-966-L030"		
494507K001	"1-1193698-8"		
CS1898-000			
908535-000	"3-1197057-7", "FB-44-7026A-0205CS896"		
938707-000	"1197272-2", "EPD-RWC-13717"		
CN5903-000			
999214-000	"44A0122-22-0/9", "8-1201014-7"		
CU5129-000	"EPD-DND-22683-L016"		
373309K002	"2-1192796-7"		
EG4559-000	"EPD-DND-21445-L016"		
881509K001	"2-1196862-7"		
CU9758-000	"EPD-DND-21534-L099"		
998383-000	"44/4424-24-9 2/96-9CS1784", "8-1197719-1"		

390720K001	"7-1199198-0"		
622511K001	"5-1194920-2"		
393001-000	"5-1192948-1", "4J3S-12-F10-8"		
384084-000	"1192881-3", "44A0121-26-9/91"		
239471-000	"1191760-7", "EPD43500G-US"		
384991-000	"1192889-1", "44A1141-16-0/2/6/9-9-MX"		
A71333K001	"4-1201000-8"		
CP3777-000	"EPD100897 A-US"		
219784-000	"4-1199657-3", "44/0411-20-9CS2979"		
009527-000	"9-1190073-5", "44AM1131-12-0/2/9-9"		
566449-000	"44A9673-20-90CS2745", "4-1194473-5"		
960653-000	"1197433-9", "EPD-RWC-16063-L300"		
266503-000	"4-1191967-7", "EPD-ROC-10014"		
404221-000	"4-1193051-3", "44A9083-14-90CS2745"		
542255K001	"7-1194251-5"		
CU3837-000	"EPD40634D-L099"		
495353-000	"8-1193704-7", "EPD-RWC-14904CS2833"		

EG8799-000	"400R0111-22-9"		
262006-000	"9-1191926-4", "44A0711-14-9-US"		
793631-000	"44AM3121-22-2/92", "8-1196144-3"		
CS7716-000			
CR3292-000	"EPD52193A-L012"		
D50902K001	"6-1200584-3"		
E00844-000	"9-1200691-1", "EPD-RWC-17923"		
849115-000	"44A7907-16-0CS2116", "2-1196621-0"		
606739-000	"7-1194799-6", "EPD52597A-26-0"		
EG4131-000	"44/9785-26-9/9-9"		
185849K001	"7-1191349-2"		
555926-000	"44A9605-16-9CS2979", "9-1199777-0"		
CS7804-000			
114167K001	"4-1190832-6"		
800213-000	"5-1196187-8", "FB-44-7026A-0222CS896"		
CY1336-000	"EPD-RWC-19863"		
733708-000	"44AM1111-18-9-9-1KF", "1200270-2"		
480794-000	"8-1199198-6", "EPD-ROK-10377-L027"		
496444-001	"1-1193712-8"		

A24558K001	"4-1201885-5"		
CB7182-000	"EPD-RWC-19939"		
CJ1979-000	"EPD-RWC-17748CS2979", "6-1899257-5"		
171891-000	"3-1191250-9", "44A1221-14-9/96-9-5CF/1"		
EG8697-000	"EPD-RWC-24022"		
383473-000	"3-1192875-4", "44A1131-26-9/93/96-9"		
E70503-000	"1200263-4", "EPD-RWC-17199"		
393026-000	"9-1192948-0", "4J4S-14-F10-8"		
417377K001	"1193145-8"		
CB3817-000			
711102-000	"44B1121-24-0/9-96CS2024", "4-1195571-7"		
EG6909-000	"44A0111-12-9-E627"		
049811K001	"5-1190381-6"		
CN5813-000			
726531-000	"8-1195678-7", "EPD-RWC-14378"		
568507-000	"44/1424-26-0/9-9CS2537", "3-1194514-8"		
CZ0621-000	"44A9673-18-90"		
C15163K001	"7-1200593-6"		
C63237-000	"6-1201860-2", "EPD101772 A-US"		

370202-000	"9-1192773-8", "44/2441-24-F156-9CS1506"		
3C0542-000	"5-1193002-0", "EPD5841-20-0"		
718306-000	"44/7880-26-9/9-9", "8-1195618-6"		
302441-000	"1192291-4", "EPD-ROK-10152"		
CZ7634-000	"EPD-RWC-22254"		
790813K001	"3-1196125-7"		
732160-001	"44AM4131-22-0/2/9-9", "5-1195719-0"		
D73144-000	"9-1201420-2", "EPD51774A-CS3128"		
383347-000	"2-1192874-2", "44A1121-22-9/90-9"		
539678K001	"3-1200689-7"		
909937K001	"1-1197068-5"		
EM6447-000	"EPD-RWC-25127CS3490"		
EG8801-000	"400R0111-24-9"		
653721-000	"3-1195158-9", "EPD5664-X-0"		
072713-000	"9-1190544-1", "44B1111-24-9-901CS1271"		
F35900K001	"6-1200689-8"		
849391-000	"1-1196623-4", "EPD-RWC-15753"		

119482K001	"9-1198863-7"		
174947-000	"2-1191272-5", "44A9085-16-0/9CS2747"		
A31681-000	"7-1201447-1", "EPD100916 A-US-L099"		
458702-000	"44B1121-24-0/9-92", "1-1193441-9"		
282654-000	"5-1192121-9", "44A0111-22-904"		
383467-000	"2-1192875-2", "44A1141-18-9/93/95/96-9"		
195255-000	"2-1191416-5", "44A1121-12-9/90-9"		
CS7801-000	"EPD40650D-US-L011"		
378868-000	"1192835-4", "44A1131-22-92/94/96-9"		
CA3709-000	"44A9749-22-1/9-9CS3185"		
563921-000	"1194455-8", "EPD-ROK-10284"		
382283-000	"1-1199107-0", "44A1141-16-9/9/9/9-9-US"		
875991-000	"4-1200449-2", "EPD21139B"		
246475-000	"1191808-5", "44AM1131-22-0/1/9-9CS1702"		
CX8762-000			
810503K001	"5-1196298-2"		
702946K001	"1-1198263-2"		
CU6479-000			

EM8272-000	"EPD-RWC-25168"		
678663-000	"1195335-7", "44A1231-16-0/2/9-9"		
EK5306-000	"44A4131-20-0/2/9-8"		
247092-000	"5-1199505-7", "EPD-RWC-17079"		
590393-000	"5-1194670-5", "EPD51045A-26-0"		
289439-000	"7-1192194-4", "44/2454-24-F150-9CS024"		
CJ1812-000	"44A0111-22-9-20CS3144L193", "3-1899270-5"		
383863-000	"3-1192879-5", "44A0131-26-0/2/9-US"		
681359-000	"8-1195357-6", "FB-44-1824-0024"		
CB6207-000			
175355K001	"1191275-7"		
190839K001	"3-1191384-2"		
627813K001	"1194971-9"		
037259K001	"9-1190287-4"		
3W0401-000	"2-1193018-7", "EPD21886A-US"		
EF7264-000	"44A1121-20-0/9-9CS3068"		
A39338K001	"4-1201652-5"		
CU6274-000			
221055-000	"5-1191629-5", "EPD4626F"		

A65237K001	"9-1200931-0"		
742211K001	"1195792-1"		
346817-000	"8-1192610-4", "EPD40416A-US"		
A20187-000	"44A1161-24-0/2/3/4/5/9-9", "4-1200173-2"		
839629K001	"4-1196551-3"		
436799-000	"3-1193283-7", "EPD52160A-14-0"		
216763-000	"1-1191582-6", "44A1131-16-92/94/96-9"		
EH2543-000	"44A9673-22-9CS3433"		
822711-000	"5-1196417-3", "CMC-0574-18-0CS2327"		
E97673-000	"9-1201653-9", "EPD-ROK-10544"		
CS6952-000	"EPD-DND-21459-L099"		
529385-000	"5-1194157-7", "EPD-RWC-15745"		
C92841-000	"6-1201556-9", "44A0121-20-9/9CS2976"		
661555K001	"2-1195215-4"		
992065K001	"8-1197673-2"		
CP4258-000	"44A1132-16-9/93/96-9"		
100759K001	"8-1190737-1"		
CR3649-000			
519005K001	"1194073-8"		

801430-000	"6-1200230-5", "FB-RWC-17576"		
CY1338-000	"EPD-DND-21823"		
443119K001	"8-1193330-8"		
389970K001	"3-1201388-3"		
D01557K001	"6-1200976-8"		
492593K001	"4-1193684-1"		
752365-000	"1195866-7", "EPD-ADD-10112"		
468193-000	"44A1111-24-9-92CS773", "1-1193509-8"		
CA6440-000	"44A9748-16-9-9CS3185"		
EK1637-000	"44A0311-26-9-E634"		
CN3179-000			
CW2534-000	"44A4121-12-9/96-9"		
CB0922-000			
CB6966-000	"44A1111-24-9-91-MX"		
A29104K001	"2-1201280-7"		
E91439-000	"1-1202166-8", "44A0313-12-9-US"		
564393-000	"44AM1141-22-0/2/4/94-0", "2-1194458-9"		
CJ8590-000	"44A1321-14-9/9-9CS3030"		
894485K001	"4-1196956-3"		
691781K001	"3-1195431-1"		
054867K001	"5-1190418-9"		

EM4416-000			
CN3181-000			
383297-000	"5-1192873-4", "44A1131-20-2/6/9-9"		
344615-000	"1192595-7", "EPD-RWC-14220"		
355715K001	"3-1192670-8"		
566864-000	"44AM1124-24-6/9-9CS2994", "2-1199874-3"		
342979K001	"1192584-7"		
287808-000	"2-1192183-9", "44A0111-18-966"		
278831K001	"1-1192064-5"		
CR6522-000	"EPD107988 A-US"		
D72793-000	"1201281-7", "EPD-RWC-18433-L002"		
EM4420-000			
566217K001	"7-1194471-0"		
520699-000	"44A1121-22-9/92-9", "1-1194093-8"		
281852-000	"2-1198711-8", "FLDWD031 1-10-9"		
D522093001	"2-1201229-1", "44A0121-20-0/9CK0001"		
884565-000	"1-1196884-2", "EPD-ROK-10045"		
639613-000	"44A9970-14-9CS2745", "5-1195055-6"		
771521-000	"1-1196010-9", "EPD-RWC-15513"		

306264-000	"4-1192319-2", "44AM1121-24-9/96-9"		
CL4519-000	"EPD-RWC-20307-L208"		
CF7139-000			
E70833K001	"7-1201056-4"		
F03237-000	"EPD-RWC-17201", "1-1200268-3"		
270243-002	"2-1191999-8", "44/9142-26-9"		
C47706-000	"6-1200583-9", "EPD-RWC-17790"		
383066-000	"7-1192870-4", "44A1121-22-2/9-9-MX"		
CB7102-000	"EPD-RWC-19928"		
F73394K001	"3-1200584-1"		
739615-000	"1195773-6", "EPD-RWC-12126"		
427575K001	"1-1193217-2"		
CN6739-000			
382309-022	"8-1192860-2", "44A1131-22-0/2/9-9-MX"		
245463K001	"8-1191800-6"		
382134-000	"3-1192857-3", "44A1124-26-6/9-9"		
3C0546-000	"5-1193002-6", "EPD5850-16-0"		
940205-000	"44A7714-22-0CS2230", "5-1197280-5"		

847029-000	"5-1196606-4", "EPD52093A-16-0CS2555"		
CY4080-000	"EPD-RWC-19930-L313"		
068582-001	"6-1190516-8", "44A9440-20-9/96-9CS527"		
A06967K001	"3-1200999-9"		
769337-001	"44AM1111-22-9-6", "8-1195994-5"		
E95721-000	"1200163-7", "EPD-RWC-16775"		
754529-000	"44A9416-22-915CS1981", "9-1195881-3"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.