



17-Feb-2022

**PCN #:** P-22-022182

**Subject :** Spec 44 and FLDW Wires

**Description of Change :** TE Connectivity is changing the sourcing and grade for PVDF resin used as insulation material for Spec 44 and FLDW Wires. This change is to an alternate grade with similar performance and characteristics.

**Reason :** Part status change. The technical assessment on alternate PVDF grade has been completed by TE's technical team and the results demonstrate similar properties and performance to the existing PVDF grades. These results are obtained through validation trials of various finished parts using the alternate grade as insulation material. No change to form, fit and function of the finished parts has been observed. Test reports on the wire characteristics can be provided upon request.

**Key Dates :**

**Contact By Date:** 28-Mar-2022

**Implementation Date:** 28-Mar-2022

<b>Product Affected</b>	<b>Alias Part Number</b>	<b>Substitute Part Number</b>	<b>AliasSub Part Number</b>
835938-000	"44AM1122-22-0/9-9", "6-1196525-6"		
793615-000	"7-1196144-0", "EPD37112B"		
986343K002	"7-1197618-2"		
EK2545-000	"44A0111-10-9CS3433"		
D75184-000	"8-1201791-0", "EPD-RWC-17097-L144"		
333461-000	"5-1192519-1", "44A4121-24-10/9-9"		

044237-000	"1190340-3", "44AM1121-1 6-950/96-9"		
297850K001	"7-1199975- 0"		
847565-000	"4-1196610- 0", "EPD83494B- US"		
F31874K001	"1200593-8"		
352989-001	"345/34-20-7- 0CS2026", "5- 1192651-4"		
EM6370-000	"CEC-RWC- 25166"		
292664-001	"4-1192218- 7", "44A0111- 16-9CS289"		
CU8718-000	"EPD-DND- 21508-L177"		
281238-000	"3-1192083- 1", "44/7004- 18-9"		
304609K001	"7-1192306- 8"		
382122-000	"1-1192857- 8", "44A1131- 26-0/2/9-9- US"		
A21717-000	"1-1200691- 0", "EPD- RWC-10937- L088"		
773963K001	"2-1196027- 1"		
EL5749-000			
876161K001	"6-1196815- 0"		
471270-000	"7-1199185- 3", "CTC- 0039-20-9/5- 9CS2968"		
408450K001	"4-1200089- 9"		
C19214-000	"7-1201277- 3", "EPD4757C- IRL-L016"		

383484-000	"4-1192875-4", "44A1121-20-0/9-91"		
630543-000	"44/1441-22-A841-9CS1363", "2-1194990-5"		
037385-000	"7-1190288-9", "345/97-20-10-0CS2026"		
637583-000	"44AM1111-16-922-9", "5-1195040-5"		
361393K001	"5-1192710-3"		
CF9363-000	"EPD-RWC-20527-L106"		
709335-000	"44A9966-10-9-US", "5-1195558-3"		
A41319K001	"9-1201055-0"		
D63549K001	"8-1201179-9"		
EG3685-000			
370194-000	"9-1192773-1", "44/2421-24-9/90-9"		
EP9165-000	"EPD-RWC-19928-L106"		
575171K001	"9-1194564-1"		
F43170-000	"2-1201927-7", "44A0111-16-95-L030"		
CS3448-000	"44A4121-22-9/96-9"		
CL7163-000	"44A9748-20-9-9CS3185"		
299387-000	"5-1192266-1", "EPD-RWC-14233"		
CX5299-000	"EPD-RWC-22192"		
282840-000	"3-1192127-8", "44A0111-24-917-US"		

EM6761-000			
CZ4005-000	"44A1231-10-MST3-9CS3030"		
C91782K001	"4-1201282-7"		
226667-000	"1191669-2", "EPD52093A-CS2718"		
089485K001	"6-1190656-5"		
746577K001	"5-1195824-3"		
118241K001	"5-1190860-0", "EPD51412A-CO1-KIT-21"		
A56866-000	"5-1202003-7", "44A1191-22-G137-9"		
EM8467-000	"UB2-26C131BG11-9"		
F37199K001	"3-1200802-0"		
968261-000	"1-1197486-9", "EPD24359A-US"		
424593K001	"7-1193196-2"		
382306-011	"5-1192860-5", "44A1121-16-0/9-9-MX"		
874039-000	"44AM1111-22-9-7", "5-1196800-2"		
A35414K001	"8-1201055-9", "EPD-ROK-10512-COD-KIT-1"		
358339-000	"1192689-2", "EPD51041A-18-0"		
523309K001	"3-1194111-6"		
A91756-000	"44A1221-12-9/9-9CS3030", "3-1200359-8"		

938903K001	"4-1197273-8"		
CR0857-000	"44A0321-22-9/96"		
723232-000	"44A1121-16-92/96-9", "2-1195654-8"		
A22548K001	"8-1201439-4"		
855891K001	"1-1196671-2"		
576191-000	"44AM1111-18-92-9", "5-1194571-6"		
182419-000	"5-1191325-0", "345/69-10-3-0"		
230171-000	"4-1191691-3", "345M16J-18-2-0CS2041"		
526227-000	"4-1194135-7", "EPD52979A"		
EM4421-000	"CEC-RWC-24951"		
080206-000	"6-1199386-6", "44A0811-10-920-1KF"		
EJ1842-000	"44A9676-18-0/2/9-9CS3433"		
258597-000	"1191892-2", "EPD-RWC-10303"		
452321K002	"4-1193396-4"		
737861-000	"4-1195760-5", "FB-44-7026A-0216CS896"		
443591K001	"1193334-3"		
308079-000	"5-1192333-4", "EPD6385-20-0"		
C43610K001	"7-1201416-4"		

CA2669-000	"EPD42817A-US"		
042312-000	"6-1200262-1", "EPD-RWC-17211"		
384935-000	"44A1141-18-0/2/6/9-9-MX"		
967745-000	"44AM1811-22-9-9CS1465", "5-1197482-8"		
466961K001	"1-1193500-8"		
955061K001	"1-1197394-4"		
CY0564-000	"44B5131-20-MT39C1401-L302"		
CS7451-000			
736999-000	"44A9083-16-9CS2745BARREL", "5-1195754-2"		
A72600-000	"6-1200524-7", "EPD62610A-MTI"		
EJ0250-000	"EPD-RWC-24401"		
CX1591-000	"EPD-DND-21478"		
E93614-000	"9-1200594-4", "EPD83354B-US"		
382279-000	"5-1192859-9", "44A0124-26-0/9"		
D72327K001	"3-1200583-0"		
F04014K001	"1200501-8"		
CR6403-000			
729105-000	"44A7713-22-0CS2230", "7-1195696-9"		
CY1329-000			

379971-000	"1192842-3", "44/2421-26- 9/90- 9CS1506"		
157951-000	"9-1191140- 8", "44A9441- 16-MST3- 9CS527"		
CS3449-000	"44A0311-12- 9CS3030"		
409725K001	"6-1193090- 6"		
140705-000	"2-1191020- 5", "EPD68121A- US"		
370534-000	"5-1192775- 6", "44/1421- 24-6/9-9"		
604670-000	"10515-X- 8CS791", "4- 1194784-9"		
919175K001	"1197133-5"		
602587-000	"44B1111-24- 9-95CS1271", "8-1194769- 6"		
795623K001	"6-1196159- 6"		
3C0490-000	"4-1193002- 4", "EPD5639-X- 0"		
851591K001	"4-1196639- 2"		
A74984-000	"7-1201447- 9", "EPD100898 A-US-L099"		
389615-000	"7-1192924- 0", "44A1121- 12-6/9-9-US"		
857595K001	"4-1196683- 4"		
CA3529-000			
CP2425-000			
026857K001	"1-1190208- 7"		
621709K001	"1-1194913- 6"		

839587K001	"1-1196551-4"		
508777-000	"8-1193999-4", "EPD52959A"		
403307-000	"5-1193044-2", "44A7444-26-1/9-9CS009"		
CS2609-000	"EPD96873B-US"		
CU8720-000	"EPD-DND-21534-L067"		
853219-000	"9-1196650-1", "EPD52967A"		
CF8630-000			
C69462-000	"1-1201314-1", "44A0111-16-955"		
544555-000	"6-1194271-7", "EPD51316A-20-0"		
098362K001	"7-1199501-0"		
EL6394-000	"44AM1121-18-0/9-9CS3451"		
A81793K001	"4-1200582-1"		
904539-000	"44A0311-20-9CS2745BARREL", "3-1197029-4"		
E51038-000	"1200694-5", "EPD61896D-US"		
EM0370-000	"EPD106293A-US"		
805974-000	"2-1199501-2", "EPD-NAV-79418"		
382778-000	"7-1200383-2", "44A1141-16-0/2/5/9-9-US"		



EM6399-000	"400R4141-20-0/2/6/9-0-WIP"		
282674-000	"3-1198069-7", "44AM1111-14-922-9-1KF"		
437267-000	"1201504-4", "44A1111-16-9-8"		
CX5921-000	"EPD38848A-US-L016"		
CF5269-000	"44BC2124-24-1/9-9CS3215"		
CB7270-000	"EPD-RWC-19934"		
CU4945-000	"EPD-DND-22844"		
521503-000	"7-1194098-1", "EPD-ROK-10155"		
CA8212-000			
156309-000	"2-1191129-5", "345/69-12-3-0"		
F93204K001	"3-1200584-6"		
007401-000	"1-1190057-9", "44A4121-24-1/9-9CS009"		
312625K001	"9-1192364-3"		
721113-000	"1195639-5", "EPD51234A-16-0"		
E75705K001	"7-1199862-8"		
749033-000	"3-1195842-8", "EPD52370A-22-0"		
A43967K001	"4-1200583-5"		
389504-003	"7-1201439-6", "44A0161-22-0/2/3/4/6/9-US"		

CW3127-000	"EPD-RWC-20046"		
647188-000	"4-1195110-0", "EPD4770C"		
EG0849-000	"44A1123-20-0/9-9"		
C95172-000	"5-1200406-5", "EPD-RWC-17046"		
276655-000	"1192049-2", "44B1121-24-0/9-98CS2024"		
322971K001	"7-1192444-1"		
261372-000	"4-1191914-6", "44A9083-14-9"		
F70704-000	"44A0111-18-9-L038", "7-1200553-0"		
EK9401-000			
CY7493-000			
CL9342-000	"EPD-NAV-18302"		
523723-000	"5-1194114-2", "44A9118-X-0CS1791"		
EM7440-000	"44A1121-20-9/926-9"		
D13045-000			
330221-000	"4-1192495-5", "EPD-RWC-13288"		
955281K001	"8-1197395-6"		
E74787-000	"6-1200297-3", "EPD-SVD-10023"		
926700-000	"44B1121-22-94/95-9CS3018", "3-1200113-4"		
EM5899-000	"44A0212-22-9"		
384687-000	"5-1192886-3", "44A0121-22-9/96"		

881299-000	"4J2S-18-F10-8", "7-1196860-6"		
175783-000	"1-1191278-6", "EPD52151A-CS2721"		
358071-000	"1-1192687-3", "EPD-RWC-11312"		
CJ1811-000	"3-1899270-4", "44A0111-22-9-19CS3144L193"		
716148-000	"44AM1121-16-950/96-9-1KF", "5-1198058-1"		
F35300-000	"8-1201389-9", "EPD-RWC-18800-L016"		
279195-000	"5-1192066-1", "345M15B-22-28-0CS2041"		
CP5935-000	"44A0112-18-9CS3184"		
EG2766-000	"44A0111-22-9-E626"		
835151K001	"7-1196519-8"		
EP2429-000	"EPD-RYQ-23426-L012"		
282708-004	"7-1192123-7", "44A0111-18-90-MX"		
548211K001	"1-1194315-6"		
CB4843-000			
111249K001	"3-1190812-5"		
843347K001	"1196579-5"		
556179K001	"3-1194387-8"		
416799-000	"1193141-7", "EPD51048A-18-0"		

629721-000	"44A1131-22-0/9/9-9", "2-1194984-6"		
021341K001	"9-1190165-9"		
784905K001	"1196092-7"		
398445K001	"9-1192987-7"		
361637K001	"1-1192712-0"		
248963K001	"8-1191825-8"		
261074-000	"8-1191909-3", "44A0212-18-9-US"		
CY4087-000	"EPD-RWC-19984-L315"		
270807-000	"1-1192005-9", "44/0611-22-9"		
CU8800-000	"EPD-DND-23026-L281"		
122981-000	"7-1197858-1", "EPD-GPM-10132"		
CA6433-000			
226611-000	"6-1191668-4", "EPD64092A"		
452191-000	"44B1221-24-6/9-925CS1815", "5-1193395-1"		
C15116-000	"5-1200592-7", "EPD-RWC-17769"		
D82021-000	"9-1202128-8", "EPD37259A-US"		
A21314-000	"9-1200694-5", "EPD-RWC-17884"		
539371-000	"44AM1111-18-945-9", "2-1194232-8"		

306845-001	"3-1192324-9", "44AM4121-16-0/9-9"		
794805K001	"9-1196152-0"		
F59254K001	"5-1201440-9"		
CS7757-000			
610814-000	"1202041-4", "FLDWD0311-12-9"		
815573-000	"1196356-3", "FB-44-5022-0146"		
380633K001	"3-1192846-3"		
371501-000	"9-1197901-8", "44A1221-12-9/96-9-5CF/1"		
277405K001	"3-1192054-0"		
CZ6932-000	"EPD-RYQ-23555"		
EH2677-000	"44A9625-12-9CS3433"		
903823-000	"6-1197023-7", "EPD51193A-22-0"		
811857K001	"7-1196314-0"		
382590-000			
279801K001	"6-1192070-9"		
370565-000	"7-1192775-3", "44/0424-26-9/96"		
EG1448-000	"44A1341-16-0/2/6/9-9"		
EP0030-000			
A21790-000	"7-1200541-5", "EPD-RWC-17701"		
319438-001	"7-1192422-1", "44A2111-20-9-9CS011"		

CY1332-000			
846109-000	"44AM1151-20-2/3/5/6/9-9", "1-1196600-4"		
184719K001	"1-1191341-7"		
374303-000	"5-1192803-9", "44A0141-18-0/2/6/9"		
495267-000	"2-1193704-7", "EPD-RWC-13999"		
325471K001	"9-1192462-4"		
160531K001	"2-1191159-0"		
562449-000	"44B9534-22-9-9CS1728", "1-1194444-0"		
394497-000	"5-1192959-0", "EPD50500A"		
101654K001	"4-1197928-9"		
CB6785-000	"EPD52957A-CS2979", "1899181-5"		
F15827K001	"7-1200354-4"		
152126K001	"8-1199172-7"		
E27375-000	"4-1200586-2", "EPD-RWC-17779"		
173474-000	"1-1200086-9", "44A0221-16-9/9-5CF/1"		
565381K001	"2-1194465-2"		
CY0515-000	"44B5111-12-9-9CS1401-L302"		
138965-000	"7-1191007-9", "44A1112-22-9-0"		
267289K001	"1197843-9"		

247079-000	"3-1191812-8", "345M10B-16-37-0CS2041"		
387138-000	"8-1192905-8", "44A1311-22-9-9-US"		
CF5366-000	"44BC2131-22-1/6/9-9CS3220"		
215213-000	"4-1191554-3", "EPD-CAN-10025"		
EG2008-000	"44A0121-24-0/9-L016"		
367003-000	"5-1192751-7", "44A1711-20-9-9"		
CY3359-000	"EPD-CAN-10019-L312"		
EK7993-000	"EPD-RWC-17035-L012"		
539463K001	"8-1194232-4"		
C03980-000	"6-1201700-0", "44AM1121-16-925/962-9-1KF"		
436223-000	"4-1193279-0", "44A1111-24-9-93CS773"		
033737-000	"3-1190261-9", "44/2424-24-0/9-9CS024"		
283788-000	"3-1192142-2", "44A0111-12-94-US"		
C11641K001	"6-1200522-8"		
292762-000	"9-1198733-8", "44A1161-18-0/2/3/4/5/9-9"		
384998-000	"1192889-5", "44A0121-22-3/93"		

351359K001	"4-1192641-8"		
257511K001	"3-1191884-9"		
489535-000	"44A9436-16-9/96CS2337", "4-1193662-9"		
CF8498-000	"44A1141-20-0/2/5/9-9CS406"		
608599-000	"8-1194813-1", "EPD-RWC-13423"		
295894K001	"3-1199501-6"		
D47406-000	"1201417-6", "EPD-RWC-18522CS3127-L116"		
759341K001	"9-1195915-5"		
CU3826-000	"EPD27724A-L099"		
F77100K001	"5-1200580-6"		
D63216-000	"1201782-3", "44A0211-12-9CS3030"		
EG7282-000	"44A0121-22-9/914"		
CB6879-000	"EPD-RWC-15187CS3207-L099"		
A35431-000	"6-1201177-1", "EPD-RWC-18504-L099"		
822495K001	"3-1196414-2"		
EG6690-000	"FLDWD031 1-12-9CS3422"		
441561-000	"1-1193320-6", "44B5131-22-MST3-9CS1401"		
3L0660-000	"4-1193010-5", "EPD9836-US"		



EG9418-000	"EPD117803 A-US"		
D93008K001	"5-1200867- 8"		
739147-000	"7-1195769- 0", "EPD71025A- 24-0"		
649537K001	"7-1195126- 7"		
D76778K001	"7-1200402- 8"		
477973-000	"44/1431-24- 9/9/9-9", "4- 1193579-1"		
099829-000	"4-1190731- 8", "44/4444- 24-F137- 9CS1784"		
282927-000	"1192129-7", "44A0211-20- 92"		
D13517K001	"9-1200591- 3"		
CB3118-000			
880757-000	"44AM1811- 10-9-9", "7- 1196856-2"		
179077-000	"9-1191301- 2", "EPD- RWC-12123"		
306324-000	"2-1192320- 8", "44AM1131- 20-9/93/96-9"		
282623-000	"5-1192120- 6", "44A0111-22- 923-US"		
311069-000	"5-1192354- 4", "EPD- ADD-10087"		
EG7199-000	"44A0121-22- 9/926"		
801146-000	"44A0111-14- 924-2KF", "4- 1198058-3"		
CU6642-000	"EPD-DND- 22842"		

EH2583-000	"44A9682-22-0/2/9-9CS3433"		
3C0390-000	"6-1199861-7", "EPD5374-X-0"		
CB1714-000	"EPD-RWC-20214-L172"		
005364-000	"8-1198311-3", "44A1221-16-9/96-9"		
383851-007	"1192879-8", "44A0121-26-0/9-US"		
123786-000	"1-1201138-6", "EPD100240 A-US-L099"		
427387-000	"8-1193215-6", "44A9675-20-0/9-9CS2746"		
720067K001	"2-1195631-8"		
CW4835-000	"EPD-RWC-20162-L058"		
EF4910-000	"EPD-RWC-19930-L077"		
458285-000	"3-1193438-9", "EPD-RWC-14867"		
CM6022-000	"44A1231-16-9/93/96-9"		
178811-000	"9-1191299-6", "44A9664-16-0/2/9-0"		
CA2665-000			
387301-000	"8-1192907-8", "44A1111-22-9-95"		
CZ5307-000			
EG7271-000	"44A0121-22-9/901"		
778701-000	"7-1196060-7", "EPD-ROC-10002"		
CY1467-000			
CP3494-000			

919901-000	"44A0111-16-9CS2396", "3-1197138-6"		
306376-000	"7-1192320-7", "44AM1131-24-9/93/96-9"		
CW0244-000	"EPD-RWC-19936-L151"		
081429-000	"1-1190604-6", "EPD51213A-18-0"		
631325K001	"6-1194995-8"		
053255-000	"7-1190406-1", "EPD-ROK-10324"		
CL5543-000	"44A1324-24-9/9-9"		
606723-000	"6-1194799-3", "EPD43502D-US"		
629105-000	"2-1194980-0", "EPD-RWC-11179"		
163651K001	"9-1191180-9"		
110173-000	"6-1190804-7", "EPD52622A-X-0"		
943774K001	"3-1200162-3"		
364529-000	"7-1192733-6", "WXA-0165-20-90"		
394383K001	"7-1192958-1"		
034237-000	"1-1190265-8", "EPD51418A-24-0"		
EH8635-000	"400R0311-10-9"		
CD61043001	"44A0111-16-9CK0300", "9-1899380-5"		

282661-000	"1192122-4", "44A0111-22-915-US"		
CS1832-000	"EPD66780B-US-L012"		
911109K001	"2-1197076-4"		
792743K001	"7-1196138-4"		
847002-000	"44A0811-10-92-1KF", "8-1199384-9"		
CM0515-000	"EPD4750C-IRL"		
160749K001	"7-1191160-2"		
CY2156-000	"EPD-DND-21440-L013"		
CY3674-000	"EPD-RWC-17884-L027"		
CS8379-000	"EPD-DND-21973-L016"		
970743K001	"1-1197504-3"		
759803K001	"2-1195919-3"		
F32615K001	"1-1201654-5"		
F17192-000	"44A1151-22-0/2/5/7/9-9", "7-1200559-3"		
CB7023-000	"44A3121-16-0/9"		
756008-000	"44B1111-24-9-902CS1271", "1-1195892-1"		
195008K001	"5-1199869-0"		
E13427-000	"8-1200586-8", "EPD91157L-US"		
764817-000	"44B1811-12-9-9CS2018", "2-1195954-5"		

167906-000	"6-1201175-2", "EPD-RWC-18502-L099"		
C00135-000	"1-1202115-6", "EPD-RWC-19733"		
675166-000	"44AM1111-16-921-9-1KF", "8-1199383-6"		
900375K001	"7-1196998-6"		
F15839K001	"9-1200578-6"		
901811K001	"2-1197009-5"		
747187K001	"1195829-3"		
CU3987-000	"EPD21808C-L099"		
913592-000	"44A0221-12-9/9-1KF/1", "7-1199822-0"		
CS1906-000	"EPD100949 A-US-L012"		
3C0391-000	"3-1193002-3", "EPD5375-22-0"		
D95637K001	"8-1200588-2"		
877507-000	"5-1196824-8", "EPD52553A-14-0"		
851555K001	"2-1196639-1"		
282892-000	"5-1192128-6", "44A0111-24-945"		
CC2287-000			
382403-000	"9-1192862-5", "44A1121-22-0/9-0"		
EG5953-000			
CU3483-000	"44A1151-24-A974CS228"		

CN9905-000			
A72650-000	"2-1200876-0", "EPD20323B-US-L099"		
023995-000	"8-1190185-8", "44/0414-24-9CS1235"		
361999-000	"6-1192714-6", "44AM4121-22-6/9-9"		
CB4569-000	"EPD37260A-US-L099"		
969953K001	"4-1197498-6"		
274959-000	"5-1192036-0", "EPD40415A-US"		
EG6829-000	"EPD62288A-US-L077"		
128276-000	"7-1199199-8", "EPD-ROK-10425"		
343677-000	"8-1192588-9", "CMC-0579-16-0CS2327"		
F16181-000	"5-1201281-9", "EPD-RWC-18397-L016"		
382847-001	"5-1192868-0", "44A7355-24-9"		
CN2446-000	"4J3N-14-F6-0"		
468079K001	"4-1193508-1"		
308889K001	"6-1192339-1"		
EJ1846-000	"44A9786-18-ELC6-9CS3433"		
D71562-000	"4-1201146-8", "EPD100257 A-US-L099"		

313436-000	"7-1201439-5", "EPD-RWC-18752-L135"		
471915K001	"7-1193535-7"		
E73954-000	"3-1201859-1", "EPD5841-20-0-5CF/1"		
395203-000	"10477-X-8CS791", "9-1192964-2"		
D37417K001	"1200592-8"		
347493-000	"1192615-2", "EPD37109B-US"		
CX1368-000	"EPD-RWC-22262-L099"		
866491-000	"44AM1121-16-905/962-9", "8-1196746-3"		
988081-000	"345M15B-22-6-0CS2041", "9-1197633-8"		
144663-000	"6-1191045-7", "44AM1151-20-MSL5-9CS2399"		
443139-000	"1193331-1", "44A0821-20-92/96CS2017"		
270029-000	"4-1191994-1", "44/0411-24-9"		
883828-000	"44B1121-24-0/9-95", "6-1196878-0"		
084909-000	"2-1190627-1", "44A0711-12-9CS1354"		
282657-000	"8-1192121-1", "44A0111-22-94"		
638059K001	"7-1195043-2"		

852077-000	"8-1196642-6", "CTC-0039-22-9/5-93CS1963"		
049085K001	"5-1190376-1"		
387028-000	"2-1192904-1", "44A1111-14-9-9-MX"		
270769-000	"1-1192004-8", "44/0414-26-9"		
527962-000	"2-1199485-5", "EPD-NAV-75105"		
CX2059-000			
C47763K001	"7-1200592-0"		
890480-000	"44AM1111-16-900-9-1KF", "4-1199381-2"		
463993K001	"3-1193479-4"		
306070-002	"6-1192317-2", "44AM1121-20-6/9-9"		
CB1717-000	"EPD-RWC-20215-L172"		
640530-000	"44AM1111-16-951-9-1KF", "7-1199383-2"		
827257-000	"3-1196461-4", "FLDWC0311-16-9"		
3C0541-000	"4-1193002-8", "EPD5840-20-0"		
256805-000	"4-1191879-2", "44A9440-16-9/96-9CS527"		
F73331K001	"3-1200584-0"		



306045-001	"3-1192317-9", "44AM1121-20-0/9-9"		
CY7948-000			
CM5955-000	"44AM1131-18-MST3-9CS3209"		
404053-000	"1-1193050-6", "44AM1121-24-91/96-9"		
EM6445-000			
652553K001	"9-1195150-7"		
472621-000	"44B5111-20-9-9CS1401", "8-1193540-4"		
306688K002	"5-1197975-3"		
911797K001	"3-1197081-8"		
CN2630-000			
EG5956-000			
794407-000	"1196150-2", "EPD-ROK-10311"		
CP7130-000	"44A0311-14-9CS3030"		
387024-000	"1192904-8", "44A2111-24-9-9-US"		
368144-000	"9-1192759-3", "44A0824-26-9/96"		
EG5997-000	"EPD-DND-23326-L016"		
265051-002	"7-1191951-6"		
ER6392-000	"44A0111-18-9CS3531"		
A09640K001			
463113-000	"44AM4131-20-3/6/9-9", "2-1193473-6"		

644765-000	"8-1195092-9", "EPD50596A"		
374402-000	"2-1192804-7", "44A0141-24-0/2/6/9"		
649905-000	"44A1221-24-9/92-9CS984", "4-1195129-5"		
D65229-000	"2-1201284-2", "EPD4761C-IRL-L016"		
242027K001	"8-1191777-7"		
563225-001	"44A7418-X-0CS038", "7-1194449-3"		
455743-002	"2-1197959-9", "EPD29659B-ING"		
CF8500-000			
EG9468-000			
D13057-000	"44A1161-12-0/2/3/4/5/9-9", "5-1200173-2"		
CB6884-000	"EPD37260A-US-CS3207-L099"		
328759K001	"1-1192486-4"		
791752-000	"44AM1111-18-966-9-1KF", "2-1199380-9"		
800103-000	"7-1196186-5", "EPD48806B-US"		
A65367K001	"6-1200711-8"		
A31014-000	"5-1201377-3", "EPD-RWC-18485"		
CF7928-000	"EPD52416A-L064"		

476897K001	"7-1193571-0"		
227315-000	"3-1191673-6", "EPD-ADD-10007"		
109449-000	"2-1197970-6", "EPD70555A-US"		
CU3936-000			
CF9907-000	"EPD-RWC-20536-L106"		
976981-000	"7-1197548-3", "EPD5849-16-0CS1898"		
ER6370-000	"44A0121-22-9/96CS3529"		
350981K001	"9-1192638-9"		
CA1537-000	"EPD-RWC-19733-L161"		
283772-000	"7-1201021-2", "44A0111-14-90-US"		
CZ7667-000	"EPD-RWC-22260"		
475891-001	"4-1193564-7", "44A7559-24-0/9-94CS448"		
493678-000	"2-1199383-9", "EPD-ROK-10373-L029"		
601488-001	"44/7004-16-9CS1059", "8-1194761-8"		
064530K001	"6-1198256-4"		
CX2065-000	"EPD106254 A-US"		
474636-000	"4-1199869-2", "EPD-ROK-10477"		
868437K001	"1197878-7"		
EG8803-000	"400R0111-26-9"		

381104K001	"4-1200258-1"		
CS7800-000			
500045K001	"1-1193738-2"		
265021-000	"5-1191950-7", "44A0811-18-9-MX"		
279873-000	"1-1192071-4", "EPD-RWC-14916"		
325649-000	"2-1192464-1", "44A2131-20-1/6/9-9CS453"		
D52336-000	"44AM4821-22-6/9-9CS2994", "5-1201031-8"		
592342K001	"6-1198926-8"		
026251-000	"8-1190203-1", "EPD-ADD-10086"		
A24354K001	"9-1200816-3"		
193566-000	"2-1199500-2", "EPD-NAV-91406"		
CZ9274-000	"EPD-DND-21543"		
551129-000	"345M09J-22-6-0CS2041", "8-1194356-2"		
485584-000	"345/46B-22-48-0CS1913", "8-1193633-2"		
236133K001	"4-1191736-6"		
498501K001	"1193727-4"		
EF5946-000			
062351K001	"6-1190471-8"		
CL6590-000			
CJ6334-000	"EPD4745D-IRL"		

CS7645-000			
376385-000	"3-1200329-2", "44A1121-20-2/9-2-US"		
282060-003	"3-1192100-0", "44A0114-26-9-US"		
282257-000	"7-1192110-8", "44A0211-16-9-MX"		
938147-000	"7-1197267-4", "EPD38848A"		
CJ1623-000	"EPD-RWC-20516"		
153963K001	"3-1191112-2"		
645263-000	"4-1195096-1", "FB-44-7026-0225CS2527"		
799376-000	"1-1200281-8", "EPD-RWC-17205"		
208086K001	"7-1200625-6"		
511741-000	"44A9665-12-0/2/5/9-0", "2-1194022-2"		
525457-000	"5-1194129-8", "EPD-RWC-13476"		
766273-000	"44A0811-20-9CS1465", "1-1195972-9"		
EG7204-000	"44A0121-22-9/936"		
491861-001	"44B5131-22-MST3-9CS1728", "7-1193678-6"		
CA3619-000			
658099-000	"44AM1161-26-0/2/3/5/6/9-9", "9-1195188-8"		

465579-000	"7-1193490-9", "EPD51061A-18-0"		
EM0494-000			
EF8114-000	"EPD-RWC-23495CS3419"		
843005K001	"8-1196575-9"		
CA3707-000	"44A9749-20-1/9-9CS3185"		
529879-000	"1-1194161-8", "EPD-RWC-14229"		
EF4914-000	"EPD-RWC-20306-L172"		
E26968-000	"3-1202074-1", "44A0111-14-92-2KF"		
757013-000	"10474-X-8CS791", "1-1195899-6"		
CL4308-000	"44A0121-20-9/96-TJ"		
005615-000	"8-1190042-7", "44B1821-20-92/96-9CS2018"		
675329-000	"44AM1151-16-F912-9", "1-1195311-6"		
630922-000	"44B1121-20-94/95-9CS3018", "8-1200023-3"		
F24080-000	"5-1201181-1", "EPD-RWC-18568-L099"		
102609-000	"9-1190750-0", "44/0411-16-9CS1038"		
356793-000	"6-1192677-7", "EPD51415A-X-0"		

458321-000	"5-1193438-8", "EPD52469A-12-0"		
312865-000	"8-1192366-1", "EPD52973A"		
CR3709-000	"44A0221-20-9/9CS3030"		
C12557-000	"44AM1141-20-MSL4-9CS3069", "1-1200741-9"		
154144-000	"6-1191113-1", "44B5121-16-9/96-9CS1401"		
CB0604-000	"EPD-RWC-20080"		
CP8890-000	"EPD-RWC-22059"		
EG4557-000	"EPD27729A-US-L016"		
435189K001	"5-1193272-1"		
360401-000	"6-1192703-8", "44AM1111-18-966-9"		
F73832-000	"3-1202054-9", "44A0212-18-9CS2979"		
EM0484-000			
159055-000	"3-1191149-3", "WXA-0085-16-9"		
389656-000	"1192925-3", "44A1131-20-9/90/92-9"		
094903K001	"3-1190695-8"		
834737-000	"7-1196516-5", "EPD52740A-18-0"		
581871-000	"6-1194609-9", "EPD-RWC-10424"		

372345-000	"8-1192788-7", "EPD74283A-US"		
159904-000	"EPD-NAV-79122"		
672873-000	"8-1195293-9", "EPD52742A-18-0"		
323991-000	"1-1192452-0", "44AM1121-20-9/94-9CS1726"		
847067-000	"9-1196606-1", "EPD51414A-24-0"		
984717K001	"1-1197607-7"		
169343-000	"8-1191232-1", "CMC-0441-22-20-0"		
891303-000	"44A1171-22-A071-9-US", "7-1198289-6"		
EM7715-000	"EPD-RWC-22042"		
352845-000	"5-1192650-5", "EPD49342A"		
EG2499-000			
036753K001	"8-1190283-7"		
097601K001	"7-1190715-5"		
CU9237-000	"EPD75140B-IRL"		
382381-000	"3-1192862-8", "44A0121-16-0/9-MX"		
933989-000	"44A0211-16-90", "7-1197237-6"		
CX3824-000			



289692-000	"4-1192196-1", "EPD6648-22-0"		
240078-000	"6-1200334-4", "44A1141-24-0/3/6/9-9-US"		
149127K001	"4-1191078-4"		
EG8854-000	"400R1131-24-0/6/9-9"		
497721-000	"4-1193721-3", "EPD51943A-18-0"		
925003-000	"44A1131-22-0/2/9-93", "1197175-1"		
CB6866-000	"EPD-RWC-15184CS3207-L099"		
CA3528-000			
817727-000	"44A1111-16-9-96CS773", "1-1196372-6"		
573584-000	"6-1198926-0", "EPD-RWC-16534"		
601630-000	"44A0111-16-9CS448", "8-1194762-3"		
145877-000	"4-1191054-1", "EPD-ROK-10030"		
CF5278-000	"44A2124-24-1/9-9CS3226"		
175263-000	"3-1191274-7", "44B1121-24-0/9-901CS2024"		
270148-000	"3-1191997-2", "44/0611-24-9"		
329957K001	"7-1192493-6"		
387003-012	"9-1192902-7", "44A1111-20-9-9-MX"		

495007-000	"7-1193701-1", "EPD5665-20-0"		
386917-000	"9-1192901-7", "44A0121-22-9/93"		
748507K001	"6-1195838-8"		
916983-000	"44A1141-20-2/4/5/9-0-US", "9-1197117-1"		
F14413-000	"44A0111-18-921-2KF", "8-1200546-5"		
467469-000	"345M09B-22-38-0CS2041", "9-1193503-5"		
206116-000	"1-1199875-0", "44A0124-24-9/6CS2994"		
270782-000	"5-1192004-3", "44/0411-14-9"		
F14596K001	"9-1200588-3"		
306359-000	"6-1192320-1", "EPD6032-18-0CS1892"		
152163-000	"8-1191099-6", "EPD-RWC-14768"		
E16209K001	"3-1200297-3"		
CJ0236-000	"EPD-RWC-16888-L191"		
282759-000	"2-1192125-7", "44A0111-22-901-US"		
352885-000	"8-1192650-3", "44B5131-16-MST3-9CS1401"		
616781K001	"5-1194874-0"		
CA8017-000			

C52500K001	"1-1200394-4"		
570509K001	"2-1194522-3"		
282682-000	"7-1192122-1", "44A0111-18-96-MX"		
CN4531-000	"EPD-RWC-17763-L182"		
825544K001	"8-1199194-1"		
835599-000	"7-1196522-5", "EPD52140A-24-0"		
CM1060-000			
CM6821-000	"44AM1131-16-MST3-9CS3209"		
384174-000	"1-1197969-0", "44A1141-18-0/2/5/9-9-US"		
E16081-000	"1200584-1", "EPD-RWC-17781"		
093507-000	"1190686-7", "EPD50592A"		
F20721K001	"9-1200578-8"		
591299K001	"1-1194677-1"		
916789-000	"44B5111-12-9-9CS1401", "5-1197116-3"		
719505-000	"3-1195627-1", "FLDWC0311-12-9"		
778963K001	"8-1196062-4"		
D13017-000	"44A0111-10-9CS2979", "7-1199808-7"		
316737-000	"1192400-1", "EPD30143B"		

514579K001	"2-1194042-4"		
705083-000	"44A9678-22-0/9CS2747", "2-1195530-9"		
382315-002	"4-1192861-4", "44A0121-22-6/9-MX"		
EH8637-000	"400R0311-12-9"		
333103K001	"1-1192517-8"		
832545-000	"3-1196500-7", "EPD-ADD-10095"		
382394-003	"7-1192862-3", "44A1141-22-0/2/6/9-9"		
771339-000	"44AM4121-22-0/9-95", "9-1196008-9"		
420599-000	"7-1193168-1", "44AM1111-18-924-9"		
363263K001	"1192724-7"		
605359-000	"8-1194789-4", "EPD51032A-22-0"		
ER5793-000	"44AM1121-16-9/96-9CS3529"		
930797-000	"44AM1131-20-3/6/9-9CS2399", "1-1197215-8"		
EF5951-000	"EPD-RWC-23973"		
928247-000	"44A0111-14-924", "7-1197197-9"		
636701K001	"1195034-4"		
CU9607-000	"EPD-CAN-10019-L016"		
E12045-000	"3-1200571-0", "EPD4710-US-L076"		

3W0625-000	"1-1193019-7", "EPD20020C"		
715883-000	"5-1195601-6", "EPD68111A-US"		
605659-000	"345/41B-22-20-0CS1913", "1194792-2"		
382004-000	"9-1192855-8", "44A1131-20-9/9/9-9-US"		
CB4688-000	"EPD-RWC-18278CS3085"		
CR9812-000	"EPD21117B-US"		
ER6268-000	"44A0811-10-9CS3529"		
219481-000	"5-1191619-6", "44A0131-18-2/7/9"		
172855-000	"2-1191257-0", "44B1121-24-0/9-96"		
023704-000	"6-1190183-0", "44B1111-24-9-98CS1271"		
301005-000	"7-1192279-2", "44AM1111-12-9-9"		
130447-000	"4-1190947-2", "EPD-RWC-15731"		
331370-000	"6-1200022-8", "44B4131-16-MST3-9CS3018"		
101117-000	"1190740-8", "44A9088-16-9-9CS2746"		
CF3510-000			
621295-000	"345M10B-16-9-0CS2041", "2-1194910-6"		
D06153K001	"1200712-7"		

945331-000	"3-1197316-6", "EPD-ROC-10047"		
058015K001	"4-1190440-9"		
EL7809-000	"EPD-RWC-24729"		
879562-000	"44A1131-24-1/2/9-9", "1196848-4"		
CB0924-000			
CA3514-000			
CD61183001	"44A0111-20-9CK0300", "1-1899381-0"		
265991K001	"6-1191963-6"		
403435-000	"5-1193045-4", "EPD-RWC-10527"		
071435-000	"4-1190536-6", "CSC-0002-18-0CS1958"		
540478K001	"1197957-4"		
D94943K001	"8-1200588-1"		
609781K001	"9-1194821-3"		
CW4995-000	"EPD-RWC-22257-L012"		
A76291-000	"6-1202043-4", "FLDWC0311-18-9CS2979"		
832563K001	"4-1196500-9"		
C81280K001	"1-1200586-2"		
D96705-000	"44A0221-16-9/9CS3030", "9-1200301-6"		
979483-001	"44A2121-16-1/9-9CS006", "1-1197566-0"		

ER5550-000	"44A0111-22-9CS3531"		
751217-000	"44/1422-26-2/9-9", "9-1195857-2"		
ER1031-000	"44AM1111-20-9-9CS3209"		
CP8076-000	"EPD-RWC-21804-L245"		
C88557-000	"6-1201926-5", "44A0111-16-944-L030"		
E88978-000	"3-1201692-8", "44A0111-10-9-2"		
956281-000	"44A1126-26-0/9-9", "4-1197403-8"		
262007-000	"9-1191926-8", "44A0711-16-9-US"		
CS2797-000	"44A0111-20-90-F871"		
954435-000	"44/2431-20-F023-9CS1506", "8-1197389-2"		
716393-001	"44B5111-20-9-9CS1728", "9-1195604-7"		
250461K001	"1191836-6"		
666339-000	"44AM1111-18-904-9", "3-1195249-2"		
225947K001	"1191664-3"		
CR9130-000	"44A0221-12-9/9C3030-1KF/1"		
355879K001	"5-1192671-1"		
D84156-000	"2-1200581-3", "EPD-RWC-17793"		
232486-000	"8-1191707-2", "EPD20021C"		

D66632-000	"1-1201370-0", "CMC-0572-16-0"		
181961-000	"2-1191322-2", "44A1831-22-3/6/9-9"		
955205K001	"3-1197395-5"		
409980-000	"4-1198115-0", "44AM1122-22-0/9-9-5CF/1"		
504157-000	"44B1111-24-9-93CS1271", "1-1193808-3"		
004999-000	"2-1190038-5", "345M12B-26-48-0CS2041"		
CB8759-000	"EPD52955B-L179CS2979", "1899194-5"		
258985K001	"8-1191894-1"		
CY1270-000	"EPD-DND-21508"		
C35016K001	"6-1200583-7"		
712857K001	"4-1195583-5"		
965957K001	"2-1197470-7"		
171641-000	"6-1191248-3", "44B9535-12-9/96-9CS1728"		
453451K001	"2-1193404-4"		
382515-000	"5-1192864-7", "44A4121-24-0/9-9-MX"		
952074K001	"8-1197924-8"		
314917-000	"2-1192383-9", "EPD52624A-16-0"		



517073-000	"1194060-8", "EPD-ROK-10286"		
306194-003	"8-1192318-9", "44AM1121-22-9/96-9"		
831821K001	"9-1196494-4"		
810980-000	"44A9615-26-0/9", "3-1200151-8"		
336801-000	"1192543-5", "EPD51066A-18-0"		
325553-000	"5-1192463-3", "44A1131-16-0/5/9-0"		
CS7760-000			
695890-000	"44AM1111-18-922-9-1KF", "9-1198058-1"		
CF9002-000	"EPD-RWC-20046-L175"		
D81746-000	"6-1201691-3", "44A0111-10-9-10"		
622132-000	"44AM1111-18-900-9-1KF", "5-1199379-9"		
563695K001	"3-1194453-0"		
CU8857-000	"EPD-DND-23031-L282"		
EG7283-000	"44A0121-22-9/915"		
CU9014-000	"EPD-DND-23066-L146"		
307930-000	"1-1201177-9", "EPD-RWC-18503-L099"		
C12961-000	"44B1141-12-MST4-9CS3018", "5-1199937-8"		
D44877K001	"9-1200583-7"		

CA6178-000			
326659K001	"8-1192471-3"		
719123K001	"8-1195624-4"		
804127-000	"44/2421-22-9/90-9CS1506", "3-1196216-5"		
C36892-000	"4-1200384-3", "EPD-RWC-17036"		
382588-000	"7-1192865-2", "44A7429-X-0"		
CR9807-000	"EPD72603A-US-L258"		
776522-000	"44AM1111-16-90-9-1KF", "1-1200270-8"		
375224-000	"1192811-9", "44/1414-24-9-9"		
453013K001	"3-1193401-2"		
E92133K001	"1-1200584-6"		
D93052-000	"44A7434-22-9/5CS2968", "6-1199520-9"		
CS1781-000	"EPD-RWC-14917-L012"		
112907-000	"7-1190823-4", "44A9113-22-8CS1681"		
EH5856-000			
885472K001	"2-1199952-0"		
512377-000	"44A0841-12-9/92/95/96", "4-1194026-2"		
EP7960-000			
D33676-000	"5-1201691-1", "44A0111-10-9-7"		

551795K001	"6-1194361-1"		
ER5146-000	"44A0111-22-9CS3529"		
386205-000	"3-1192897-9", "44A1122-20-6/9-9"		
188077-000	"9-1191364-5", "EPD-RWC-10424-334F"		
397351-000	"1-1192980-3", "EPD-RWC-15762"		
CF5287-000	"44A4124-24-1/9-9CS3227"		
D10602-000	"5-1201282-3", "EPD4756C-IRL-L016"		
D20921K001	"9-1200591-7"		
CB0923-000			
920823-000	"9-1197144-8", "EPD50914A-24-0"		
128959-000	"7-1190936-2", "EPD-ROK-10024"		
CX8343-000	"FB-RWC-23114CS3355"		
C46897K001	"6-1200583-8"		
383492-000	"6-1192875-4", "44A1121-22-0/9-94"		
CP2185-000	"EPD-DND-21479-L234"		
CB7191-000			
EP7725-000	"CEC-RWC-25683-L009"		
437401K001	"7-1193287-4"		
CJ1803-000	"44A0111-22-9-13CS3144L193", "2-1899270-8"		

CX8742-000			
564919-000	"1194462-9", "EPD-RWC-14915"		
EH2513-000	"44A0311-18-90CS3433"		
382679-000	"5-1192866-6", "44A4121-16-1/9-9"		
456211-000	"1-1193424-1", "EPD-ROK-10021"		
382848-001	"5-1192868-2", "44A7358-24-G204-9"		
486112-000	"2-1197928-3", "EPD92432A-US"		
674201F001	"2-1195303-7"		
EF4909-000	"EPD-RWC-19927-L077"		
927767-000	"44AM1111-18-94-9", "5-1197194-2"		
CX1154-000			
CL4004-000	"CMC-0440-22-10"		
4584443001	"44A0111-14-9CK0001", "3-1198932-1"		
170621-000	"6-1191241-2", "44A1221-14-0/9-9"		
512869-000	"8-1194029-2", "EPD52465A-20-0"		
833031-000	"44A9677-20-ELC4-9CS2746", "9-1196503-7"		
CS7722-000			
593786-000	"44AM1141-12-G048-9CS561", "5-1199150-0"		

538039-000	"9-1194222-2", "EPD-RWC-13543"		
592736-001	"3-1194687-9", "FB-44-40-7000"		
825869K001	"9-1196450-2"		
184683K001	"9-1197846-0"		
C51200-000	"44A4121-22-6/9-0", "6-1200589-3"		
EM7768-000	"EPD-RWC-19813-L338"		
968287-001	"3-1197486-5", "EPD5841-20-0CS1898"		
C71511-000	"44A1231-14-9/93/96-9"		
921581-000	"44A9681-20-0/9-9CS2748", "3-1197150-9"		
EG9075-000			
CB7291-000	"EPD-RWC-20306"		
EG3894-000	"EPD96868A-US"		
CX1647-000	"EPD-DND-21441-L289"		
637229-000	"44A0111-20-9(FS)", "5-1197968-9"		
CS2887-000	"44A0311-20-9-F871"		
301024-001	"1192280-3", "44AM1111-20-9-9"		
282769-000	"7-1192125-5", "44A0111-22-936"		
424021K001	"8-1193192-0"		
CL6672-000	"EPD-RWC-20901"		

932249-000	"44/4474-26-A552CS1784", "1197226-5"		
397699K001	"5-1192982-2"		
562235K001	"3-1194442-6"		
265022-008	"7-1191950-0", "44A0811-20-9-MX"		
E85235K001	"6-1201284-6"		
CY0509-000	"44B5121-12-MT29C1401-L302"		
060525-000	"8-1190458-0", "EPD-RWC-12133"		
E38995-000	"EPD-RWC-19482"		
313032K001	"1-1198261-5"		
296129-000	"3-1192243-2", "44AM1111-16-924-9"		
841573K001	"5-1196565-1"		
828081-000	"44A9605-16-96", "9-1196466-2"		
493863-000	"44A9666-16-0/9", "7-1193693-1"		
F33361-000	"44A0111-14-902-1KF", "1-1200546-2"		
335111K001	"5-1192531-2"		
370941-000	"5-1192778-9", "44/1421-20-9/9-9"		
CU1805-000	"EPD-DND-21543-L016"		
603782-000	"1194778-7", "EPD8710A"		
CP4458-000	"EPD-DND-21479-L239"		
396219K001	"1192972-1"		

023105-000	"7-1190178-5", "EPD63666A-US"		
726611-000	"4-1195679-3", "EPD52206A-CS2837"		
F81464K001	"3-1200584-2"		
425663K001	"1193204-8"		
527177K001	"2-1194142-2"		
CY8289-000	"EPD-DND-23195"		
394588-000	"1-1199386-7", "44A0111-14-92-1KF"		
953739K001	"3-1197872-7"		
F03387K001	"2-1200977-9"		
013757-000	"9-1190107-9", "44/0414-26-9CS470"		
EG6910-000	"44A0111-16-9-E627"		
CU3781-000	"EPD-RWC-14768-L012"		
C62129K001	"8-1201416-6"		
495468-000	"1-1197898-1", "EPD-RWC-14668CS2888-L006"		
509025K001	"1194002-9"		
387735-002	"9-1192911-7", "44A1311-20-9-9"		
CR3180-000	"EPD-RWC-16009-L012"		
479902-000	"44A0811-14-9-1KF/1", "7-1199204-1"		
142790-000	"1199386-7", "44A0111-18-961-2KF"		

282656-005	"7-1192121-0", "44A0111-22-90-MX"		
EH8649-000	"400R0311-24-9"		
468806-000	"44A2111-24-9-9CS011", "5-1193513-7"		
F34675K001	"7-1201281-0"		
E60866K001	"8-1200594-3"		
EG8842-000	"400R1131-12-0/6/9-9"		
382254-009	"1-1192859-1", "44A1121-22-0/9-9-MX"		
412791-000	"8-1193112-8", "44A9208-20-0CS1747"		
844935-000	"7-1196591-6", "FB-44-7026A-0230CS896"		
107752-000	"9-1200286-6", "EPD-RWC-17214"		
CF9769-000	"EPD4744D-IRL-L099"		
CA3083-000			
752573-000	"44AM1131-20-0/6/9-9", "1197820-4"		
928178-000	"1-1200251-3", "EPD-RWC-17200"		
330825-000	"3-1192499-9", "CSC-0188-22-0"		
CA7737-000			
C56890K001	"4-1200976-7"		
F03227-000	"44A1221-16-9/9-9-1KF/1", "8-1199656-9"		



376432-000	"8-1201014-1", "44A0122-20-0/9"		
E46080K001	"8-1200930-6"		
220163K001	"8-1191623-0"		
857582K001	"6-1197956-6"		
129859K001	"1-1190943-0"		
CY2148-000			
CS7721-000			
EM0388-000	"EPD-RWC-22253-L016"		
634367K001	"3-1195017-8"		
923133-000	"44A9666-14-0/9", "9-1197161-7"		
159961K001	"2-1191155-5"		
EG2513-000			
CS7725-000			
762753K001	"5-1195939-6"		
064113-000	"7-1190484-0", "44/7036-24-9"		
175889K001	"8-1191278-5"		
135678-000	"4-1190984-6", "44/9075-26-9/9-9"		
EG3893-000			
EG8491-000	"DVI-26B117D11F-0"		
859843K001	"8-1196699-8"		
CF9906-000			
270793-000	"9-1192004-5", "44/7011-24-9"		

084523-000	"1-1197970-5", "EPD86205A-US"		
881443-000	"7-1196861-8", "EPD4776D-US"		
386347-000	"2-1192898-9", "44A0121-20-6/9-MX"		
ER5385-000			
CX5297-000			
848610-000	"3-1200593-3", "EPD-RWC-17746"		
CU8788-000	"EPD-DND-21535-L146"		
300047K001	"7-1192272-9"		
746493-001	"5-1195823-7", "FB-44-7026A-0235CS896"		
199599K001	"8-1191445-7"		
657562-000	"5-1198907-5", "FLDWC1321-20-9/90-9CS2959"		
C66832K001	"4-1201235-7"		
195289-000	"5-1191416-0", "EPD52743A-18-0"		
CX2982-000	"FLDWD031-1-10-9CS2736"		
282621-000	"4-1192120-5", "44A0111-22-903"		
046691K001	"6-1190358-9"		
383248-002	"8-1192872-0", "44A1141-24-3/5/6/9-9-US"		
C49996K001			

CB6280-000	"44/4432-22-9 2/94/96-9"		
075006-000	"7-1200272- 3", "44AM1121-1 6-922/94-9- 1KF"		
255375K001	"5-1191869- 7"		
F11962K001	"1-1200711- 3"		
313017-000	"9-1192367- 2", "44AM1831- 22-3/6/9-9"		
390425-000	"2-1192931- 2", "44AM1141- 18-0/2/5/9-9"		
029883-000	"7-1190231- 1", "EPD71285A- US"		
546268-000	"5-1199501- 4", "EPD- NAV-85413"		
117567K001	"9-1190855- 8"		
370227-000	"1-1192774- 9", "44/1424- 24-0/9-9"		
CY2039-000	"EPD-DND- 21425"		
EM6446-000			
282872-000	"6-1192127- 6", "44A0111-24- 92-MX"		
949303K001	"7-1197343- 1"		
068894-000	"7-1198277- 2", "44AM1141- 22-MST4- 9CS2109"		
A60146K001	"9-1200692- 3"		
D60995-000	"44A1221-14- 9/9- 9CS3030", "3- 1200358-1"		

523160-001	"44A9441-22-MST3-9CS527", "2-1194110-9"		
306421-000	"2-1192321-8", "44AM1141-22-9/93/95/96-9"		
CU1851-000	"44A1131-16-3/6/9-9-L067"		
D13048-000	"44B1121-22-G063-9CS3018", "5-1200111-1"		
CR1662-000	"44A0811-10-9-L050"		
EM8552-000	"44A1221-12F985C3030-5CF/1"		
CA3530-000			
881235-000	"44B1121-16-0/9-90", "3-1196860-4"		
548389K001	"3-1194316-9"		
512851K001	"7-1194029-3"		
454924K001	"4-1197975-3"		
532699K001	"7-1194182-4"		
306317-000	"1-1192320-2", "44AM1131-20-0/2/9-9"		
F27065-000	"5-1201149-9", "44AM4831-22-3/6/9-9CS2994"		
377101-000	"1192824-2", "44/2422-24-9/9-9CS1222"		
D45536-000	"1201427-5", "EPD52416A-L072"		
383040-000	"5-1192870-2", "44A0141-22-9/9/9/9"		

512405K001	"6-1194026-3"		
854897-000	"6-1196663-2"		
109761-000	"6-1190801-7", "44A0141-20-9/90/92/96"		
383022-000	"3-1192870-0", "44A1141-22-3/5/6/9-9-US"		
C064693001	"44A1111-22-9-9CK0001", "1200894-5"		
306017-001	"1192317-7", "44AM1121-16-0/9-9"		
CN2375-000	"EPD68126A-US"		
071793K001	"9-1190538-7"		
907381-000	"44A0711-20-9F891", "9-1197048-3"		
390062-000	"7-1192928-2", "44A7418-X-0"		
C50539K001	"1201440-4"		
744151-000	"345M18B-18-42-0CS2041", "3-1195805-9"		
643247-000	"5-1195082-6", "EPD52961A"		
CF8606-000	"44A1131-14-9/9/9-0"		
EG2501-000			
691323K001	"1195428-3"		
A58304-000	"8-1202031-9", "EPD-RWC-17026-L028"		
CP8883-000	"44/9760-20-9/96-9CS2901"		
CL6863-000			

115113-000	"9-1190838-7", "EPD52598A-26-0"		
F77030-000	"EPD-RWC-17045", "1200292-4"		
973679K001	"2-1197525-9"		
259407-000	"6-1191897-7", "44AM1121-16-50/96-9"		
CB7185-000	"EPD-RWC-20307"		
D70969K001	"1-1200944-5"		
ER1423-000	"44A9089-16-0/9-9CS2378"		
559207-000	"3-1194414-3", "EPD-ROK-10285"		
644753-000	"7-1195092-8", "EPD52958A"		
EG4311-000	"EPD-RYQ-23423-L012"		
547099-000	"9-1197893-4", "EPD-ROK-10431"		
CY2091-000	"EPD-DND-21668-L307"		
191919K001	"1191392-3"		
214996-000	"5-1199385-6", "44A0111-14-922-1KF"		
EH2586-000	"44A9676-20-0/2/9-9CS3433"		
899679-000	"44B5111-22-9-9CS1401", "4-1196993-3"		
568857K001	"8-1194516-5"		

803366-000	"1-1200173-1", "EPD-PFM-10057CS2962"		
750339-000	"6-1195851-8", "EPD-RWC-13952"		
861777-000	"4-1197927-5", "EPD70023A-ING"		
562367-000	"4-1194443-9", "EPD51884A-20-0"		
971519K001	"8-1197509-1"		
468999-000	"1193515-5", "EPD-ADD-10092"		
CN0220-000	"44B1121-12-925/926-9C3018"		
CF3714-000			
382525-000	"8-1192864-2", "44A0124-24-0/9-US"		
963939K001	"7-1197455-8"		
799237K001	"3-1196179-2"		
306193-000	"8-1192318-7", "44AM1121-22-9/96-3"		
E54762K001	"5-1200297-0"		
F85922-000	"EPD8476B-US-L099", "1200883-6"		
CX0068-000			
849887-000	"44A9681-22-0/9-9CS2748", "8-1196626-8"		
507379K001	"4-1193973-3"		
CR0242-000			

F91962-000	"6-1201229-7", "WXA-0198-22-9"		
364133-000	"2-1192730-6", "44B1141-24-9/93/95/96-9"		
805113K001	"8-1197817-5"		
270019-000	"6-1191993-9", "44/0411-26-9"		
003097-000	"6-1190023-7", "EPD52629A-22-0"		
101667K001	"1190744-9"		
296895K001	"9-1192248-4"		
382789-000	"9-1192867-2", "44A1121-26-6/9-9-US"		
852113K001	"1196643-7"		
242685-000	"5-1191780-7", "EPD-ADD-10093"		
CA8167-000			
205685K001	"6-1191490-6"		
EG2507-000			
282722-003	"3-1192124-5", "44A0111-20-95-MX"		
F31876-000	"EPD-ROK-10511-L022", "8-1201069-4"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.



For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.