



07-Aug-2023

**PCN #:** P-23-024936

**Subject :** Controlled Electrical Cables as per attached parts list

**Description of Change :** TE Connectivity would like to inform the customers the change to foamed polyethylene is not going to be implemented as planned and previously communicated, ref. P-23-024487 and P-23-024488. Therefore, there will be no fit form function change in comparison to the product currently supplied.

**Reason :** Part status change.

**Key Dates :**

**Contact By Date:**07-Aug-2023

**Implementation Date:**07-Aug-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
CQ42083001	EPD119031A/2(CO)		
CQ17493001	EPD117860A		
C416523001	2-1201142-9, EPD94822M/1-1L(CO)		
CQ74493001	EPD100126ACK0298		
6771553001	5024A1P11-9(CO), 3-1195324-5		
4400263001	5-1193306-5, 5020A1311-9		
CQ42073001	EPD119031A/3(CO)		
1266373001	5-1190920-3, EPD77622L/1-1L(CO)		
E330723001	8-1201461-8, EPD4045-C/4(CO)		

CD40733001	EPD107072A, 8-1899287-0		
C568353001	4-1200755-9, EPD42233A/2-1L(CO)		
D537623001	9-1201508-1, EPD101624A		
CQ17573001	EPD117898A/2(CO)		
CQ82573001	EPD121661A		
2262433001	0020D0P11-9(CO), 1-1191666-0		
6647153001	9-1195237-0, 7530E1114-9(CO)		
4280513001	4-1193220-5, 5020A1311-0(CO)		
4425893001	2524E0311-0(CO), 2-1193327-4		
CQ21053001	EPD117759A		
200557-000	3-1191453-8, 7522A1P11-1L		
CQ72873001	EPD121340A		
CD93903001	EPD111034A/1-1L(CO), 7-1899514-7		
CT69753001	EPD114765A		
2948313001	6-1192233-9, EPD46612Q		
E977353001	EPD104312A/1-9(CO)		
6120093001	5020A3311-96(CO), 1194839-9		
2598313001	8-1191900-2, 7524A1311-0(CO)		
CQ77673001	CLFH316/1(FS)		
CT72213001	EPD115106Q/1-9(M)		
9488933001	1197811-1, EPD79182A/1-9(CO)		
CT74203001	EPD114357A/1-9(CO)		

7372113001	5012A3311-0(M), 9-1195755-2		
6073053001	6-1194803-0, EPD31322B		
810351-000	2-1196297-5, EPD32183C		
F04392-000	9-1201288-1, EPD96642A		
F484333001	2-1201403-2, EPD99112ACK09 00		
CQ83733001	EPD118179A/1- 6(CO)		
3248873001	7-1192458-6, EPD24187D/1- 0(M)		
CT69743001	EPD114765A/3(C O)		
CQ54533001	EPD107550GCK0 202/2		
4828353001	8-1193613-2, EPD60604B		
E029333001	1-1202061-0, EPD103085A/1(C O)		
E153103001	3-1201320-7, EPD95289L/1- 9(CO)		
0745493001	1-1197921-9, EPD91568Q/1- 1L(CO)		
CQ82623001	EPD121661A/2(C O)		
CQ04123001	EPD109318Q/1- 1L(M1)(FS)		
CD76893001	EPD105601A, 9- 1899448-9		
CD08983001	9524A1311- 0(CO), 9-1899132- 9		
6330733001	5020A3811- 0(CO), 1-1195008- 9		
CQ68903001	EPD108173ACK0 308/1		
CT69713001	EPD114765A/1- 1L(CO)		
CQ64673001	EPD120749A		

CD93883001	EPD111093A/1-1L(CO), 7-1899514-5		
D574843001	7526A1811-0(3M), 1200559-9		
CQ70133001	EPD118341B/1-0(CO)		
CQ71523001	EPD35077ACK0647/1		
CD56163001	EPD108040A/1-1L/9(CO), 5-1899362-6		
CD96893001	EPD111040A, 4-1899525-5		
7743333001	5018A1P11-1L(CO), 1196030-3		
CQ60643001	EPD120521A/1(CO)		
CQ56173001	EPD116267A/1-6(CO)		
5219113001	5026A1311-0-M, 6-1194101-9		
A901873001	1199839-8, EPD26168D/1-0(16M)		
CT78703001	EPD115223A/2(CO)		
CT88083001	EPD115994A/1(CO)		
4387893001	7-1193297-4, 5018D3P11-9(CO)		
EQ05053001	EPD122871A/4(CO)		
EQ02923001	EPD35077ACK0206/5		
CQ29923001	5020A1311-0(M2)CK2240		
CQ21283001	EPD35077ACK0206/3		
F410203001	2-1201263-5, 0024A0311-91(CO)		
6049923001	3-1198232-8, EPD94452A		
1830673001	8-1191329-8, 5028A1314-0(M)		

E126983001	3-1201284-5, EPD99442BCK04 00		
8674693001	8-1196753-7, EPD39105E		
CQ20533001	EPD109318Q/1- 9(MARK2)		
5519213001	4-1194362-0, EPD72464A		
A473193001	1201262-6, 0024A0311- 90(CO)		
CQ48053001	EPD67364QCK00 16		
7215273001	9-1195641-2, EPD63774C		
6619853001	1195218-1, EPD68931Q		
EQ01333001	EPD117603ACK0 624		
530939-000	9-1194169-6, CLFH178		
CD43333001	0028G1P14- 1L(CO), 2- 1899300-4		
1555713001	1191124-4, EPD67526M/1- 0(M)		
9275313001	7-1197192-6, EPD85875A/1- 9(CO)		
CQ28223001	EPD116816ACK0 206/1		
CQ77093001	EPD121138A/1- 6(CO)		
7392613001	5-1195770-2, EPD60301B		
F266063001	EPD25986A/1- 9(CO), 4-1201019- 9		
CD17373001	7528A1318-0(FS), 1-1899165-3		
604207-000	1194781-6, 7520A1811-0		
CQ74643001	EPD118341C		
3375233001	1-1192548-3, EPD76688Q		

8965773001	7-1196970-8, EPD69569B/2(CO )		
7766533001	4-1196046-8, EPD67888L		
420030K003	2-1193164-9, 5019D3318-0		
7763153001	7522A1811-0(M), 2-1196044-3		
CQ82603001	EPD121661A/1- 9(CO)		
CD81953001	EPD109698A/1(C O), 7-1899469-7		
0595263001	8-1200068-5, 7524A1311-9(CO)		
2475493001	0022D0311- 9(CO), 5-1191815- 7		
CQ28043001	EPD113842Q/1- 1L(M3)(FS)		
CQ93543001	EPD44091QCK02 02		
C922243001	8-1201321-1, EPD98739L		
1490913001	1-1191078-3, EPD60651B/1- 1L(CO)		
CD58413001	EPD108173A/1(C O), 6-1899370-5		
CD84253001	EPD107550A/2(C O), 3-1899479-7		
CQ78273001	EPD117603ACK0 298/2		
F953553001	2-1201445-3, EPD99409A		
EQ08403001	XXX-5024D3314- 0		
CQ34223001	EPD118757A		
6430333001	9-1195080-8, EPD67526M		
1506313001	9-1191088-8, EPD46419Q		
CQ91263001	0020D0311-9(M)		
C225323001	2524E0311- 9(4M), 2-1200811- 8		

E030303001	3-1201320-1, EPD95289L/1- 1L(CO)		
CD51393001	EPD107356A, 4- 1899338-6		
F519973001	EPD2029J/1- 9(CO), 1-1200773- 1		
4400773001	4-1193307-7, 7524A1311-0		
4233653001	2-1193188-4, 7528A1P14-9(CO)		
4869293001	9-1193643-8, EPD4044/1-0		
200074W002	2-1191449-0, 5024A1P12-1L		
F933853001	EPD98957B/2(CO ) , 2-1200773-0		
2999853001	6-1192270-1, EPD43063A		
CD51253001	0024E0P11- 9(CO), 8-1899337- 9		
D551283001	6-1201425-2, EPD96685Q/1- 1L(CO)		
7235153001	2-1195656-3, 7820G0P11- 1L(CO)		
CD04593001	CLFH179CK1001, 5-1899114-0		
CQ28033001	EPD113842Q/1- 1L(M1)(FS)		
CQ51963001	EPD119924A/1- 6(CO)		
CQ70293001	EPD120998A		
CD38803001	EPD66813R/1- 1L(CO), 5- 1899272-0		
598901W001	0024F0611-9, 1- 1194735-1		
EQ06033001	EPD121860B/2(C O)		
480314-000	6-1193595-6, 7530E1114-9		
E336753001	1201791-3, EPD101039L/1- 9(M)		

4408373001	8-1193314-3, 7530A1318-9		
F066903001	EPD99530A/1- 9(CO), 2-1200885- 1		
CD37403001	7-1899264-0, EPD104100A/1(C O)		
E260793001	9-1200884-5, EPD99528A/1- 1L(CO)		
CT69693001	EPD114764A/3(C O)		
1482863001	EPD104316A/1- 9(CO)		
CT36403001	120-OHM-2SJFR- 24-2(CO), 8- 1899562-4		
EQ02823001	EPD121962ACK0 624		
6622013001	9-1195219-1, EPD72947A(S101 )		
CQ31233001	EPD118470A		
CQ75313001	EPD94392BCK02 06/3		
CQ65763001	EPD60947QCK06 47		
CQ11943001	EPD117497A/3(C O)		
A201023001	5026A1811- 0(8M), 1-1200160- 4		
CD69983001	5026C1314- 06(CO), 8- 1899423-8		
0119933001	7-1190094-9, 5030A1P18-9(CO)		
3H07093001	1-1193004-4, EPD20697A		
C241953001	6-1202151-5, EPD77178R		
794567W002	2-1196151-2, EPD35077A		
CQ31993001	0024K1811-0(M)		
CQ21063001	EPD117760A		



815137-000	7524A1811-0, 3-1196352-0		
C312423001	6-1201021-2, EPD100319A/1-9(CO)		
CD84013001	EPD109365A/4(CO), 1-1899478-0		
CQ49573001	EPD100582BCK0355		
C741593001	2-1201351-3, 5018D3P11-N(CO)		
3346573001	1192528-3, 7524A1311-0(FS)		
E960333001	5020A1311-0(2M), 6-1200431-2		
2002083001	6-1191450-4, 7524A1P11-1L		
CQ17583001	EPD117898A/3(CO)		
9190933001	5-1197132-1, EPD70340L/1-9		
C546413001	3-1201401-2, EPD99111ACK0900		
CQ60853001	EPD116262A/1-6(CO)		
CQ67803001	EPD120650A/1-9(CO)		
CD89863001	EPD110891A, 2-1899499-7		
CQ04203001	EPD109318QCK5700		
CQ86223001	EPD98738LCK0558		
0014393001	6-1190010-2, EPD69568A/1-1L		
CT06353001	EPD112378Q/1-9(CO), 7-1899559-7		
440088-000	7-1193307-2, 7528A1318-0		
EQ06253001	EPD122605BCK0427/1		
7796773001	3-1196067-2, EPD78122A		

CD16623001	EPD105062B, 3-1899162-8		
5992353001	3-1194737-9, EPD62225Q/1-N(CO)		
179291-000	4-1197969-4, 5020A1P11-9(FS)		
CQ18873001	EPD117888A		
4800793003	1193594-7, 7530A1114-9		
C608913001	7524A1311-0(3M)		
CD54463001	0024K1811-0(2M), 4-1899355-8		
C112163001	3-1201192-9, EPD92473A		
EQ06303001	EPD123073A		
CT82773001	EPD115671A/2(CO)		
CD45773001	EPD107343A, 9-1899311-0		
EQ05843001	EPD100584B		
F518743001	2020E0811-0(CO), 8-1200596-4		
5543973001	4-1194376-3, EPD60326A/1-9(CO)		
D661573001	8-1200760-0, EPD94823L/2(CO)		
CQ96333001	EPD121857CCK0193		
CT82783001	EPD115671A		
3356933001	7-1192535-0, 9530E1P14-9(CO)		
6311793001	6-1197825-7, 7518A1P11-9(CO)		
CQ51953001	EPD119924A/1-2(CO)		
C995233001	1201320-4, EPD95289L/2(CO)		
CQ72603001	EPD121313A		
200010-000	0022D0P11-1L, 4-1191448-9		

CD58723001	7530A1P18-9(CO), 9-1899371-1		
CT85583001	EPD115579A/1(CO)		
445182-000	2524E0311-9, 7-1193345-9		
E509923001	2-1201498-8, EPD98738L/2(CO)		
4451823005	2524E0311-9, 8-1193345-1		
4710453001	6-1193529-0, EPD36313D		
3598473001	2524E0P14-1L(CO), 8-1192699-8		
1581553001	6-1191142-5, EPD60844C		
CQ45253001	EPD111050ACK0298/1		
8730553001	6-1196793-5, EPD45759A		
0191273001	4-1190149-5, EPD8851F/3-91(CO)		
CQ12323001	EPD45898QCK0596		
CT72203001	EPD115106Q/1-1L(M)		
A543163001	6-1200885-0, EPD99529A/4(CO)		
CT98853001	EPD115852A		
C152393001	2-1201287-0, CLFH316-0(CO)		
4400603006	1193307-1, 5024A1311-0		
CD56713001	0024K1811-0, 3-1899364-6		
1844293001	1-1191339-3, 9530E1014-0(CO)		
440680W002	5-1193313-0, 7528A1314-9		
CQ22193001	EPD106513ACK0213/3		

CQ51993001	EPD119924A/2(CO)		
9528153001	2524E0311-9(CO), 2-1197378-6		
4843333001	4-1193624-5, 5018D3P11-1L(CO)		
CQ70143001	EPD118341B/1-2(CO)		
956067-000	7518A1811-0, 1199164-8		
CT64503001	2020E0P11-1L(CO)		
CD71463001	EPD108750ACK0519/1, 2-1899431-4		
6573673001	0024A0311-0(M), 6-1195183-5		
D867393001	9-1200760-4, EPD94823L/1-1L(CO)		
CQ56193001	EPD116267A/2(CO)		
6367983001	5028A1314-9(S), 7-1195034-2		
CT60263001	EPD114107A, 8-1899591-2		
9443513001	1197310-4, EPD35589A		
CQ12833001	EPD117612A		
CQ77983001	0024A0311-1L/9-0(CO)		
CT74233001	5020A1P12-N(CO)		
CT68823001	7522D5311-0CK1150		
CD40573001	100-OHM-2SJFR-26-9(CO), 2-1899281-8		
CT69703001	EPD114764A		
E546883001	9-1200754-2, EPD42233A/2-9(CO)		
8933433001	0024A0311-0(FS), 5-1196948-1		

420106W003	1193165-6, 5020A3311-0		
440107-002	1-1193308-7, 5028A1314-0		
D099293001	1-1201345-8, EPD101254A		
CT99633001	EPD109318QCK0 456/3		
3057083001	9-1197945-4, EPD93972A/1(CO )		
D799103001	EPD104345A/1- 9(CO)		
C806053001	2-1201423-8, 7520A1811-0(CO)		
CD09063001	EPD105592A, 1899133-8		
CQ99233001	EPD122349A		
3H07103001	1-1193004-5, EPD20698A		
CD04043001	EPD98865Q/1- 6(CO), 8-1899110- 0		
3289523001	2-1200147-4, EPD93086R/1- 1L(CO)		
CD17673001	0024A0311- 9(4M), 1-1899166- 8		
CQ87583001	EPD120794ACK0 193		
CD29313001	CLFH400/1(FS), 9-1899222-5		
0590423001	2-1201141-2, EPD94822L/1- 1L(CO)		
440010W001	4-1193306-1, 5024A1314-0		
CT94893001	EPD116422A/1- 6(CO)		
4417333001	3-1193321-7, 7526A1P17- 1L(CO)		
EQ00893001	EPD67422ACK05 03/2		
CT69653001	EPD114761A		

A778873001	1-1201161-3, EPD93790A/1(CO )		
A528763001	9528A1P17- 9(CO), 1200600-4		
CQ04163001	EPD109318Q(FS)		
A127213001	1-1199548-6, EPD36388Q(CO)		
CQ40143001	CLFH-400		
CQ86213001	EPD84488ACK05 58		
5989013002	6-1201791-4, 0024F0611-9		
EQ14063001	EPD108173ACK0 308/3		
5089893001	3-1194001-6, 7524A1811-0(M)		
4860883001	2-1198298-6, EPD7032B/1- 1L5(CO)		
C857253001	6-1201287-2, CLFH- 316CK0135		
CT69783001	5020A1311-0(3M)		
EQ05123001	100-OHM-2SJR- 24-3(CO)		
E171533001	EPD104317A/1- 1L(CO)		
6042073001	1194781-7, 7520A1811-0		
CQ83563001	EPD121866ACK0 547/2		
EQ06223001	EPD44091QCK02 02/1		
CT04913001	EPD113319A/1(C O), 2-1899555-8		
CQ11543001	EPD117170ACK0 298/1		
CQ27973001	EPD113842Q/1- 9CK0399/4		
CD59683001	EPD106482A/1- 1L(CO), 3- 1899377-8		
A178843001	2524E0311- 0(6M), 2-1200752- 4		

8439593001	5019D3P18-1L(CO), 3-1196584-7		
CQ60593001	0024B0P11-9(CO)		
CQ07223001	EPD117416ACK0355		
EQ02403001	EPD122640A/1-9(CO)		
C315313001	7-1201929-7, EPD74283ACK0365		
CQ97323001	EPD120656A/1-6(CO)		
CQ72503001	EPD121303A		
581269-000	2020E0811-0, 8-1194605-1		
EQ05303001	EPD122879ACK0624		
EQ05063001	EPD122871ACK0654		
4399053001	6-1193305-3, 5026A1314-0(CO)		
9458733001	2524E0P14-9(CO), 2-1197320-4		
4643373001	8-1193481-3, EPD40252B/1(CO)		
CD48793001	EPD107297A, 1-1899326-5		
EQ06043001	EPD121860B/3(CO)		
CQ13723001	EPD117488A		
5093703001	4-1198950-1, EPD90687A		
EQ00263001	EPD121839ACK0308		
2000743001	1-1191449-9, 5024A1P12-1L		
200943-000	8-1191456-6, 5012A3P11-1L		
CQ83683001	EPD116265A/1-6(CO)		
CQ76103001	EPD121495A		
CQ05423001	EPD117331A		

5848243001	1199983-5, EPD96879Q/1- N(CO)		
CQ41893001	EPD116262B- 0CK0547/2		
CQ77023001	EPD117759ACK0 298		
5048283001	5-1199508-2, EPD64983B		
CD14953001	EPD105951A/1- 2(CO), 2-1899157- 9		
EQ05183001	EPD122871A/3- 2/3(CO)		
486167-000	2-1193638-1, 5024A1311-0(FS)		
E020763001	9-1201142-3, EPD94821M/2(C O)		
CD15653001	EPD86888C/1- 1L(CO), 8- 1899160-9		
2996603001	4-1192268-4, 7524A1311-0-M		
3157093001	9-1192388-7, EPD91802A		
CQ37763001	EPD31475QCK02 06/4		
8646013001	6-1196733-5, EPD44343A		
5331433001	8-1194185-3, EPD89109Q/1- 9(CO)		
CQ95583001	EPD121087A		
CQ86983001	EPD120896B/1- 9(M)		
CD72913001	EPD108704ACK0 210, 3-1899435-6		
5950633001	1194706-9, EPD4044/2-1L		
EQ07243001	0024F0611-9(CO)		
0364413001	4-1190281-9, EPD2028E-2(CO)		
762893-000	5-1195940-3, EPD26995Q		
4201153001	2-1193165-5, 5026A3311-0		



CQ77973001	EPD121558A		
CQ83603001	EPD116265A-0CK0547		
CQ41813001	EPD116262B/1-6(CO)		
E527573001	EPD104310A/1-9(CO)		
EQ10213001	EPD60947QCK0647/1		
CQ38213001	0028A1811-0(M)		
CQ73423001	EPD121379A		
2863093001	8-1192168-6, EPD22634B		
4201063001	1193165-5, 5020A3311-0		
7721303001	5-1196014-0, 9530A1114-9(M)		
0585903001	2-1198918-7, 5026A3311-0(16M)		
C642753001	1-1200807-3, EPD99113A		
CT00393001	EPD112330L, 4-1899540-6		
440026-000	2-1198283-2, 5020A1311-9		
1904673001	6-1191381-4, EPD91387A/1-1L		
EQ05093001	100-OHM-2SJR-24-0(CO)		
4201243001	3-1193165-5, 5012A3311-0		
4363873001	5-1193280-3, EPD72123B		
2009423001	0024A0P11-1L, 8-1191456-2		
CQ17363001	2024A0111-9(M)		
4418383001	1193322-5, 5020A1311-0(M)		
CQ93173001	EPD67422ACK0206/3		
1330133001	1190966-4, EPD64118L		
4957973001	1193708-6, EPD62976A/2-9(M)		

C576213001	6-1200884-2, EPD60603C/1- 1L(CO)		
CQ65773001	EPD67422ACK06 47		
CQ72963001	EPD121348A		
C77266-000	6-1202050-1, EPD101747B/2(C O)		
CT95703001	EPD116490A		
8688413001	2524E0311-0(M), 8-1196763-0		
CQ31913001	EPD117254A		
3157253001	1192389-8, EPD90041A/1- 1L(CO)		
CQ34113001	EPD117603ACK0 298		
CD74443001	EPD108696A/2(C O), 5-1899439-3		
0789433001	1190587-3, EPD73307R/1- 6(CO)		
E561433001	6-1201741-0, EPD98865Q		
CQ61863001	EPD120656A		
5877533001	5020A1P11- 9(CO), 4-1194651- 3		
CQ73543001	EPD121394A		
200165W002	3-1191450-0, 5028A1P14-1L		
440563-000	2-1193312-3, 7526A1317-0		
CQ72673001	EPD121320A		
CQ86263001	EPD121857BCK0 193/1		
F345173001	1201167-5, EPD100566A/1- 1L(CO)		
CQ07273001	EPD116370A/1(M )		
CQ41983001	EPD119030A/4(C O)		
CQ41903001	EPD116255A- 0CK0547/2		

F714463001	EPD99112A, 2-1200819-3		
CQ18903001	120-OHM-2SJFR-26-6(CO)		
2071713001	8-1191501-1, EPD20697A/1-9(CO)		
CQ95273001	2018A1811-0		
5684253001	7-1194513-3, EPD84052Q		
CD51403001	EPD107356A/1-1L(CO), 4-1899338-7		
CQ97683001	0022E0811-0(M)		
CD53543001	EPD107883B/1(CO), 2-1899350-6		
A102493001	6-1201018-5, EPD60608D		
CT67203001	EPD104317C/1-1L(CO)		
420115W003	2-1193165-7, 5026A3311-0		
317185-000	2-1192403-2, 5012A3811-0		
7021133001	3-1195509-1, EPD69713L/1-0(M)		
CD00993001	EPD104861A/2(CO), 3-1899094-8		
A099233001	3-1202045-7, EPD101753B		
5155673001	2-1194049-3, EPD65782L		
5614513001	8-1194434-8, EPD69569A/1-9		
1517773001	1-1191097-2, EPD32644A/3(CO)		
0484633001	3-1190372-3, EPD4673G/2-1L		
CQ33323001	EPD62444QCK0206/7		
CD71413001	7526A1P18-9(CO), 7-1899430-5		

4601893001	7-1193451-8, EPD77127L/1- 9(CO)		
CQ58013001	5018D3811- 0CK0206		
CQ74893001	EPD117248ACK0 298/1		
F212383001	2-1201424-0, EPD96295Q/1- 1L(CO)		
CT75893001	EPD115268A		
CQ37893001	EPD118396A		
7636953001	9-1195945-8, EPD76441L/1(CO )		
CQ44453001	EPD35077ACK05 03/1		
D737523001	EPD104319A/2(C O)		
CQ07513001	EPD64983BCK10 30		
CD31543001	120-OHM-2SJR- 22-1L(CO), 1899237-6		
4404993001	5-1193311-5, 5030A1314-0		
D815803001	6-1200498-0, EPD96117A		
1013913001	1-1190742-3, EPD24135A		
420115-000	2-1193165-4, 5026A3311-0		
CD57673001	0024K1811- 0(4M), 2-1899369- 3		
CT93363001	EPD107550GCK0 202/1		
EQ14373001	EPD106672ACK0 193		
5141673001	2-1194039-9, EPD67526M/1		
D535333001	8-1200628-9, EPD78249B		
0551773001	1-1190421-0, EPD38335A		
A942693001	0022E0311-0(CO)		

CQ88423001	EPD122014A		
4576943001	8-1199198-2, EPD95011L/1- 0(7M)		
9171573001	2-1197119-0, EPD73307R/1- 0(CO)		
D426553001	7-1202050-6, EPD101754B/2(C O)		
C525563001	9-1200885-2, EPD99529A/1- 1L(CO)		
CT68173001	EPD104297B		
2809253001	5-1192080-0, 5024A1P11- 1L(CO)		
A231303001	3-1201416-5, EPD97000ACK09 00		
440499-000	5-1193311-4, 5030A1314-0		
4348813001	2-1193270-2, EPD44774M/1-0		
CT98543001	EPD116687A		
5375753001	9-1194218-9, EPD31173A/1- 9(CO)		
CQ40643001	EPD118745ACK0 202		
0301643001	3-1197946-1, EPD90786Q/1- 9(CO)		
F040023001	EPD99036A, 9- 1200756-8		
CD46603001	5026C3814-0, 6- 1899315-7		
CT36413001	120-OHM-2SJFR- 24-6(CO), 8- 1899562-5		
CD31333001	CLFH179, 1899236-2		
CQ60893001	EPD116262A/3(C O)		
CQ34093001	EPD117757ACK0 298		
CQ76613001	EPD117755ACK0 298/1		

1364233001	1190989-9, 5020A3811-0		
CQ55903001	EPD77622M/1(C O)		
E010613001	9-1201142-2, EPD94822L/2(CO )		
CQ72803001	EPD121333A		
7608873001	0022D0P11- 9(CO), 4-1195926- 8		
1192453001	5-1190867-9, 5012A3P11- 1L(CO)		
1792913001	3-1191303-9, 5020A1P11-9(FS)		
CD51413001	EPD107356A/1- 9(CO), 4-1899338- 8		
CQ60843001	EPD116262A/1- 0(CO)		
CQ45153001	CLFH-179-0(M)		
6832133001	5-1195369-7, 7522A1311-0(M)		
7783873001	6-1196058-5, EPD29210A		
6068833001	6-1194800-9, 7520A1311-0(CO)		
CQ38193001	0028A0P11-9(CO)		
4406803001	4-1193313-9, 7528A1314-9		
200508-000	9-1191452-6, 5020A1P11-1L		
CD74033001	EPD106972A, 9- 1899437-2		
C276663001	5-1200879-5, EPD99036ACK03 39		
E426383001	EPD104345A/1- 1L(CO)		
2008493001	7-1191455-0, 7530E1P14-1L		
4450193001	6-1193344-0, CLFH178/1(CO)		
CQ71693001	EPD116816ACK0 206/3		

440672-000	3-1193313-0, 7520A1311-0		
7945673001	2-1196151-1, EPD35077A		
CQ72493001	EPD121302A		
1101353001	4-1190804-5, EPD78120A		
CQ14273001	8-1899772-2, EPD31475QCK02 06/3		
607305-000	5-1194803-9, EPD31322B		
CD15623001	EPD86888C/3- 1L/9(M), 8- 1899160-6		
CQ97213001	EPD122335A		
CQ91663001	0024K1811-0(M2)		
4404733010	3-1193311-7, 5024A1312-9		
144278-000	8-1191042-8, 7820G0111-9		
6779313001	9-1195329-2, EPD60326A/1- 1L(CO)		
3292153001	1192489-1, EPD20499Q/1- 9(CO)		
440060W012	1193307-7, 5024A1311-0		
D532133001	7-1201499-9, 5020A3811- 06(CO)		
3962683001	2524E0P11-9, 3- 1192972-3		
A816013001	6-1201726-7, 7530A1814-0		
6285913001	5-1194976-5, 7528A1314-0(CO)		
7023233001	9-1195510-7, EPD66401A		
CQ30063001	7524A1311- 0(M1)CK2240		
CQ83773001	EPD118179A/1- 5(CO)		
CT01933001	EPD113292A/1(C O), 8-1899547-3		

3224453001	1-1192441-1, 7522A1P11- 1L(CO)		
CQ07483001	EPD43063A/1(CO )		
CQ78373001	EPD102265ACK0 298		
3316743001	1-1199172-6, EPD67422A/1- 0(7M)		
CT71263001	EPD113842QCK0 456		
A728353001	2-1200761-6, EPD94823L/1- 9(CO)		
CQ31983001	EPD115512A		
CQ45573001	7528F5614-9(M)		
440680-000	4-1193313-8, 7528A1314-9		
4861673001	2-1193638-2, 5024A1311-0(FS)		
CQ87023001	EPD114955A		
3H00583001	1-1193003-4, EPD4044		
CD85143001	EPD109382A, 6- 1899482-5		
CQ19303001	EPD118014A/2(C O)		
1416913001	7-1191026-9, EPD68148A		
CQ79403001	2018A1P11-9(CO)		
420124W002	3-1193165-6, 5012A3311-0		
8887893001	4-1196914-9, EPD91801A		
A478223001	2524E0P11- 1L(SFS), 2- 1200676-7		
2289943001	5-1201021-6, EPD100319A/2(C O)		
CQ67833001	EPD120650A/4(C O)		
7733093001	5-1196022-4, EPD60603B		
CQ06993001	EPD116370A		



EQ09843001	EPD108852LCK0 298/3		
CQ21013001	EPD117755A		
D199013001	1201727-4, 7530A1P14-9(CO)		
A565123001	1200754-3, EPD42233A/1- 09(CO)		
F244303001	EPD98487CCK03 39, 8-1200878-7		
4838333001	1-1193621-0, EPD24357A		
420124-000	3-1193165-4, 5012A3311-0		
A459773001	9-1202052-3, EPD101729M/1- 9(CO)		
CQ17533001	EPD117864A		
CQ45853001	EPD67422ACK02 06/2		
CQ70473001	EPD72718ACK02 06/5		
2814313001	1-1192085-9, 5012A3811-0(CO)		
EQ05193001	EPD122871A/3- 2/5(CO)		
E135733001	5-1201496-9, EPD96420A/1(CO )		
CD12423001	7528A1P18- 9(CO), 7-1899146- 2		
CQ60653001	EPD120520A		
C757113001	6-1201504-0, EPD98738L/1- 9(CO)		
4451563001	2524E0314-9, 5- 1193345-6		
CD18343001	EPD106111BCK0 162, 8-1899171-4		
2699533001	5-1191992-3, EPD40487B		
CQ21023001	EPD117756A		
0448763002	7-1190344-6, EPD22008F		

CD93833001	6-1899514-8, EPD111035A/1- 9(CO)		
CD29653001	EPD106662A, 5- 1899224-7		
1147053001	1190836-5, EPD69713L		
CQ95353001	EPD121049A		
EQ05513001	EPD122014ACK0 193/1		
CQ74603001	EPD118342C/1- 0(CO)		
CQ70163001	EPD118341B/1- 5(CO)		
CQ88253001	7520A5611- 9CK0635		
A413943001	5-1200885-6, EPD99528A/3(CO )		
A736753001	1201761-9, EPD101186A/1- 9(CO)		
CQ03023001	EPD24357ACK02 98/1		
CQ66243001	EPD116687ACK0 398		
CT58143001	EPD109318QCK0 456/1		
CQ51423001	EPD113842QCK0 456/4		
CQ91633001	0024K1811- 0(M3)(FS)		
6551363001	9-1198297-8, EPD7032B/1- 1L4(CO)		
F043923001	9-1201288-2, EPD96642A		
CT55943001	EPD113887A		
1069893001	4-1190781-3, EPD83644L/2- 1L/9(M)		
CQ41763001	EPD116262B/2(C O)		
4402513001	6-1193309-9, 5020A1111-9		

C698673001	9-1201341-1, EPD98739L/2(CO )		
CT72193001	EPD115106QCK0 456		
2005563001	3-1191453-6, 7520A1P11-1L		
594223-000	1194698-6, EPD33307Q		
CQ83743001	EPD118179A/1- 96(CO)		
5268583001	1194140-3, EPD26875A		
9170713001	5-1197118-0, EPD39096E		
C950363001	1200886-7, EPD99528A/2(CO )		
D325533001	7-1202050-3, EPD101753B/1- 9(CO)		
4412333001	8-1193317-9, 5028A1P17-9(CO)		
CQ14333001	EPD117622A/6(C O)		
CT62673001	EPD96873B		
2524833001	2-1191848-8, EPD44774M/1- 0(M)		
4200793001	7-1193164-5, 5028A3318-9		
CQ19563001	0024A0311-9/9- 0(CO)		
CQ72103001	EPD77804ACK01 93		
A813343001	0022E0P11- 1L(CO), 1- 1200481-9		
CQ68143001	EPD109382ACK0 298/4		
A661153001	8-1201542-5, EPD101389A		
CQ83373001	EPD121047A		
7654613001	5026A1P18- 9(CO), 1195959-6		
CQ11893001	EPD117498A/1- 1L(CO)		

CD48083001	EPD107588A, 8-1899322-9		
CQ17503001	EPD117861A		
420079W002	7-1193164-6, 5028A3318-9		
D409143001	1-1200369-1, EPD97018A		
6080873001	9-1194809-8, EPD23197B/1-1L(CO)		
440010-000	3-1193306-8, 5024A1314-0		
4992713001	5-1193732-1, 7518A1311-0(CO)		
7785153001	5026A1318-0(CO), 4-1196059-7		
D347483001	1201342-8, EPD98739L/1-1L(CO)		
1054853001	1190771-7, EPD61457A		
8991113001	5-1196988-4, EPD20662B/2(CO)		
CQ41293001	EPD114381A		
1828093001	1-1191328-9, EPD36192A		
F932693001	5026A1P14-9(CO), 6-1199783-0		
2141283001	8-1199023-1, 7524A1311-0(2M)		
EQ02993001	EPD122537A		
7418513001	4-1195789-5, 9528A1P17-1L(CO)		
EQ04173001	EPD122605A/1(CO)		
CQ92593001	EPD120794ACK1100		
CD76943001	EPD105568A/1-2(CO), 1899449-5		
CD62363001	EPD108341A/2(CO), 7-1899385-6		
D498853001	2-1201800-8, 0024F0P11-9(CO)		

5628253001	8-1194446-8, EPD63054C/2		
CQ95363001	EPD121050A		
F490863001	1-1202051-7, EPD101754B/1- 9(CO)		
3110073001	1-1192354-0, EPD44031S/2- 9(CO)		
CQ27943001	EPD113842Q/1- 1LCK0399/1		
2005573001	3-1191453-9, 7522A1P11-1L		
9851513001	5024A1311- 9(CO), 3-1197610- 9		
144278K002	9-1191042-2, 7820G0111-9		
CQ86403001	EPD120887B		
EQ05213001	EPD122871A/3- 3/9(CO)		
440562-000	2-1193312-1, 5018A1311-0		
CQ74613001	EPD118342C/1- 2(CO)		
CQ48733001	EPD119159A		
CT65463001	EPD114512A		
CT70013001	0022E0311-0(2M)		
CQ78723001	EPD121586A		
4354333001	1-1193274-4, EPD70874L		
CQ72513001	EPD121304A		
1182693001	7-1190860-2, 5020A1P11- 1L(CO)		
2288493001	4-1191683-9, EPD69569A/2		
CT74183001	EPD114357A/2(C O)		
CQ28073001	EPD113842Q/1- 1L(M1)		
C800783001	7-1201321-8, EPD100317ACK0 900		

F265233001	3-1201426-0, EPD96685Q/1- 9(CO)		
E279793001	9-1202050-2, EPD101747B/1- 1L(CO)		
3713753001	9-1192781-2, EPD87108Q		
9345953001	6-1197241-8, EPD68346Q		
CT92533001	EPD116101A		
9484583001	6-1198918-2, EPD67526M/1- 0(19M)		
EQ06343001	0024K1811-6(CO)		
CT94903001	EPD116422A/2(C O)		
C387673001	3-1201713-5, EPD67422ACK02 77		
C882553001	5-1201459-2, EPD98738L		
CT98843001	EPD115851A		
A952043001	7-1201155-8, EPD100628A/1- 1L(CO)		
D700743001	1201288-3, EPD100153A		
CT94913001	EPD107550G/1- N(CO)		
1385423001	7-1199572-3, EPD95224Q/1- 9(CO)		
5487033001	7-1194318-3, EPD40295Q		
CD58403001	EPD108173A, 6- 1899370-3		
CQ36033001	EPD105273ACK0 298/1		
CQ61083001	2530A0P14- 1L(CO)		
CD70953001	7526A1318- 0CK0094, 2- 1899429-3		
CD50983001	EPD107869A/1(C O), 8-1899336-0		

8621853001	1-1196716-0, EPD49551R/1-1L		
CQ31603001	EPD113283A		
4689953001	1193515-3, EPD80972A		
5435193001	1194263-5, EPD63892B		
A914083001	EPD104312A/1- 1L(CO)		
E016023001	5-1201904-0, 7526A1311-9(CO)		
9214933001	7-1197149-2, EPD70875L		
C951163001	4-1201142-6, EPD94821M/1- 9(CO)		
CQ75573001	EPD67422ACK05 03/1		
2090413001	8-1191514-6, EPD39105F		
CD85043001	EPD31475QCK02 06/1, 5-1899482-1		
9521353001	3-1197373-4, EPD79935Q		
EQ05253001	100-OHM-2SJR- 24-1L(CO)		
7227173001	5-1195650-6, EPD40890G		
CT95423001	EPD115891A		
9013253001	7522A1311-0(S), 8-1197005-3		
8241703001	8-1200285-9, EPD35077ACK02 77		
CQ11903001	EPD117498A/1- 9(CO)		
8713013001	1-1196781-9, EPD40218Q		
C060573001	9-1201422-2, EPD96295Q/1- 9(CO)		
A502873001	4-1200884-7, EPD60608C/1- 9(CO)		
5391813001	1194231-8, 9524A1P11- 1L(CO)		

CT36443001	EPD113282A, 9-1899562-4		
CT67153001	EPD104313B/1-1L(CO)		
CT92783001	EPD116377A		
9536653001	4-1197384-6, EPD60608B		
CQ04193001	EPD109318Q/1-9(M2)		
CQ70173001	EPD118341B/1-6(CO)		
CQ95403001	EPD121056A		
2665283001	5-1199910-0, EPD66569Q/1-1L(CO)		
1269273001	6-1190922-9, EPD69568B/1-9(CO)		
4400693001	3-1193307-4, 5026A1317-0(500)		
CQ72093001	EPD62444QCK06 21/1		
2005083001	9-1191452-7, 5020A1P11-1L		
CQ76833001	EPD118745ACK0 202/4		
CD48543001	EPD106418A, 7-1899324-1		
C949883001	1201342-1, EPD98739L/1-9(CO)		
CQ29933001	5020A1311-0(M3)CK2240		
8845683001	9-1197946-6, EPD94100A		
CQ72333001	EPD121286A		
0444653001	7-1190341-7, EPD20499Q/1-1L(CO)		
4407883001	4-1193314-2, 5030A1318-9		
7746533001	3-1196032-9, EPD38445Q		
A706343001	EPD104311A/1-1L(CO)		



A485693001	8-1201347-8, EPD98750A/1- 1L(CO)		
CQ93163001	EPD116816ACK0 206/4		
EQ05153001	EPD122871A/3- 1/9(CO)		
9412793001	2-1197288-3, EPD86166R/1- 9(CO)		
6502253001	9-1195134-3, 9530A1317- 90(CO)		
1718593001	1-1191250-2, 5020A3311- 92(CO)		
E947903001	6-1200929-3, EPD99111ACK03 39		
CQ76773001	7528F5814- 0CK0193		
2904013001	7-1192201-1, EPD37229A		
CQ33343001	EPD118336A		
CD75183001	EPD104280A/2(C O), 6-1899443-4		
5629373001	8-1194447-2, EPD30885B		
7495013001	4-1195845-6, EPD67892L		
CQ98113001	EPD115373ACK1 100		
A948053001	1-1201294-7, EPD95289L		
CQ99473001	CLFH179CK1200		
2485113002	6-1191822-7, 7522A1811-0		
CD76933001	EPD105601A/1- 6(CO), 1899449-4		
EQ05113001	100-OHM-2SJR- 24-2(CO)		
490097W005	4-1193666-5, 9530E1014-0		
CQ61873001	EPD120656A/2(C O)		
CQ99573001	EPD101753BCK0 446		

490097-000	3-1193666-8, 9530E1014-0		
D935083001	2-1200338-6, EPD93086RCK02 26		
6225033001	4-1194920-7, EPD74283A/3- 0(M)		
CT73953001	EPD114354A/1- 0(4M)		
EQ10193001	EPD35767QCK06 47		
798383-000	2530A0614-9, 6- 1196175-6		
D362073001	3-1201348-7, 7524A1811-0(2M)		
CQ19293001	EPD118014A/1- 9(CO)		
CD43043001	2024A0111-9, 6- 1899298-3		
8335203001	9-1199205-3, EPD95412Q		
CQ80713001	EPD91157LCK06 24		
CQ95323001	EPD121045A		
3711143001	3-1198306-5, 9530E1P14- 1L(CO)		
7436423001	8-1195801-0, EPD28251A		
E940393001	8-1201288-3, CLFH- 178CK0135		
CQ42043001	EPD119030A/1- 1L		
CD14963001	EPD105951A/1- 9(CO), 3-1899157- 0		
CQ67783001	EPD120650A/1- 5(CO)		
EQ00193001	7528A1818-0(M)		
CT54343001	EPD113433A		
CQ83703001	EPD116265A/1- 0(CO)		
CT95963001	EPD116546A/1- 9(CO)		

1723693001	8-1191253-3, EPD32856A/2(M)		
CQ85873001	EPD121857BCK0 193		
8103513001	2-1196297-6, EPD32183C		
CD37073001	5024C1P11- 9(CO), 2-1899261- 5		
3L08643001	2-1193011-9, EPD2029F		
CQ73033001	EPD121355A		
1231943001	8-1198298-7, EPD7032B/1- 1L6(CO)		
2008513002	0020D0P11-9, 7- 1191455-3		
6148333001	1194860-2, EPD63054C		
5942233001	1194698-7, EPD33307Q		
C597663001	EPD104319A/1- 9(CO)		
CD93063001	EPD110996L, 1899511-4		
CD93483001	120-OHM-2SJR- 24-1L(CO), 3- 1899512-3		
CD76883001	EPD105568A, 9- 1899448-8		
1324513001	6-1190962-8, EPD44031S/2- 1L(CO)		
CD46983001	5026C3P14- N(CO), 6- 1899316-1		
CQ83783001	EPD118179A/1- 95(CO)		
1005653001	4-1190736-1, 9526A1P11-1L		
CD18353001	EPD106112BCK0 162, 8-1899171-5		
D534643001	EPD104313A/1- 9(CO)		
CD14533001	EPD86888C, 8- 1899155-4		

9212493001	1197148-5, EPD4673G		
CQ77013001	EPD117756ACK0 298/1		
CQ41953001	EPD119030A/5(C O)		
CT89503001	EPD116118A/1- 9(CO)		
CT68403001	EPD114276A		
0672243001	7-1199555-4, EPD95224Q(CO)		
E172733001	7526A1P11- 9(CO), 3-1200600- 3		
419187-000	2-1197969-1, 7524A1P11-9(FS)		
5582983001	7-1198928-8, EPD78640LCK01 21/4		
CQ11933001	EPD117497A/2(C O)		
4408083001	5-1193314-6, 9530A1318-9		
CQ98703001	EPD122536A		
5517793001	4-1194361-6, 7820G0P11-9(CO)		
7991153001	7524A1P11- 9(CO), 4-1196178- 9		
3808053001	4-1192847-7, EPD8851F/3- 94(CO)		
CQ93043001	EPD108750ACK0 308		
D226323001	3-1201761-9, EPD101186A/1- 1L(CO)		
6814113001	1195358-2, EPD71192Q		
739261-000	5-1195770-1, EPD60301B		
2001483001	1191450-4, 5026A1P11-1L		
A597283001	EPD104316A/1- 1L(CO)		
6445033001	1-1195091-2, EPD40399Q		

CQ12803001	EPD114879A		
A121953001	1-1201508-5, EPD101626A		
CQ52733001	EPD118745ACK0 202/3		
5995093001	4-1194739-2, EPD32396B		
440808-000	5-1193314-5, 9530A1318-9		
5888793001	9-1194659-3, 9526A1311-0		
CT69773001	EPD114767A		
5105623001	1199515-1, 9530A1P17-9(CO)		
C955393001	6-1200919-1, EPD99442B		
CT89483001	EPD116119A		
8866133001	1-1196898-5, EPD69568B/1- 1L(CO)		
440499W002	5-1193311-6, 5030A1314-0		
0404813001	5-1190309-5, EPD26332A		
C677853001	4-1200754-5, EPD42233A/1- 0(CO)		
CD48483001	EPD100582BCK0 076, 5-1899324-5		
F229553001	7-1201320-8, 7516A1P11-9(CO)		
2001443001	9-1191449-3, 5026A1P17-1L		
8877113001	6-1196906-0, EPD69568A/2		
7928773001	2524E0P11- 1L(CO), 5- 1196139-7		
D023093001	4-1201142-9, EPD94822M/1- 9(CO)		
6474633001	1-1195112-1, EPD25640A		
CD17513001	EPD105273A, 9- 1899165-4		
EQ06313001	0024K1811-1(CO)		

D209823001	7820G0111-9(2M), 1200717-1		
1371113001	9-1190993-8, EPD40890H		
2949713001	7-1192234-7, 5024A1811-0(CO)		
CT94883001	EPD116422A/1-9(CO)		
CQ72733001	EPD121326A		
CT69683001	EPD114764A/2(CO)		
CD93803001	6-1899514-5, EPD111034A/1-9(CO)		
6353413001	8-1195023-1, EPD6035A/1-1L(CO)		
CT95993001	EPD116546A/3(CO)		
CQ41863001	EPD116255A/1-6(CO)		
CD56153001	EPD108038A/1-1L/9(CO), 5-1899362-5		
3323353001	1192511-5, EPD44306A/1		
CT75883001	EPD115267A		
2009413001	0024A0P11-9, 7-1191456-8		
E444373001	EPD104309A/1-9(CO)		
CT67193001	EPD104317C/2(CO)		
D335453001	1200369-7, EPD97000A		
9287123001	6-1201141-0, EPD94822L/1-9(CO)		
334657-000	1197969-1, 7524A1311-0(FS)		
CT66913001	5030A1318-0(CO)		
0677213001	3-1190510-6, EPD25986B/1-1L(CO)		
CQ56163001	EPD116267A/1-3(CO)		

EQ03443001	EPD122537ACK1 100		
CQ64063001	EPD111051ACK0 298/2		
2246673001	9-1191654-9, EPD31475A-OBS		
E849293001	8-1201929-8, 0024A0311-9(M)		
440788W004	4-1193314-6, 5030A1318-9		
CT89473001	EPD116118A		
EQ10143001	EPD122871ACK0 654/1		
A885873001	EPD104346A/1- 9(CO)		
F084573001	5-1201509-2, EPD101632A		
CQ58883001	EPD105273ACK0 298/3		
8902233001	8-1196925-2, EPD26169D		
C572543001	6-1202060-7, 9530A1114-9(3M)		
CQ74593001	EPD118341C/1- 4(CO)		
CD56463001	120-OHM-2SJR- 20-9(CO), 1899363-1		
CQ74553001	EPD118341C/1- 0(CO)		
2485113001	6-1191822-6, 7522A1811-0		
0903973001	1-1197921-3, EPD91568Q/1- 9(CO)		
440101W003	1-1193308-2, 9530A1318-0		
4400863001	6-1193307-6, 5028A1318-0(500)		
3529793001	2530A1318- 9(CO), 4-1192651- 6		
7462343001	9-1197924-4, 7530E1114-0(CO)		
CQ77123001	EPD121137ACK0 547/2		

7628933001	5-1195940-4, EPD26995Q		
440838-000	8-1193314-4, 5018D3311-0		
CD69793001	CLFH-178-0(CO), 2-1899423-3		
CT02393001	CLFH-179-0(7M), 1-1899549-2		
CT75483001	EPD115224A/1- 9(CO)		
4418063001	8-1193321-9, 5024A1311-0(M)		
CD84243001	EPD63976A/1- 9(CO), 3-1899479- 5		
D323943001	1200775-1, EPD98957B/1- 1L(CO)		
4401013001	1-1193308-1, 9530A1318-0		
CD93913001	EPD111033A/1- 1L(CO), 7- 1899514-8		
CQ98433001	EPD116846A		
CQ19253001	EPD109382ACK0 298/1		
CQ83833001	EPD118179A/3(C O)		
CQ95103001	EPD122259A		
1338463001	8-1190972-2, EPD24920A		
EQ07213001	EPD123088A		
C929223001	1-1200878-3, EPD98516BCK03 39		
CT75423001	EPD114761B		
CT82833001	EPD96718CCK02 54		
5095313001	7-1194005-5, EPD22545D		
CT36383001	EPD113286A/1(C O), 8-1899562-0		
CD31503001	EPD106743A/4(C O), 7-1899236-5		
CQ73793001	EPD121177A/1-9		



1490333001	6-1191077-0, EPD46419Q/1- 9(CO)		
4458243001	9-1193350-7, 5012A3P11-9		
CQ95873001	EPD122360A		
1305073001	9-1190947-2, 7518A1P11- 1L(CO)		
CQ72753001	EPD121328A		
CQ34083001	EPD117756ACK0 298		
4044043001	6-1199211-6, EPD95412Q/1- 9(CO)		
CD00373001	EPD104250A, 9- 1899089-7		
A578233001	3-1200752-0, EPD98957B		
9206533001	7528A1P17- 1L(CO), 7- 1197143-6		
CQ90183001	EPD77622MCK02 13		
CQ82483001	EPD121857ACK0 193		
D349783001	9-1201148-5, EPD95079A/1- 9(M)		
EQ06263001	EPD119554A		
200121W002	6-1191449-2, 5019D3P18-1L		
5666293001	5-1194474-9, CLFH179(S50)		
A328983001	5-1200812-8, EPD99292A/1- 1L/9(CO)		
420106-002	1193165-4, 5020A3311-0		
5920593001	5012A3P11- 9(CO), 7-1194682- 6		
CQ17973001	EPD117888A/1(C O)		
CQ52003001	EPD119924A		
CT67183001	EPD104317C		

CQ06963001	EPD116448A		
CD48133001	0024A0311-9(2M), 1-1899323-3		
3991533001	5-1192994-7, 5022A1P11-9(CO)		
8530253001	6-1196649-6, EPD25986C/1-1L(CO)		
CQ06613001	EPD117381ACK0236		
A728483001	6-1200524-9, EPD96002A/1-6(CO)		
CD60493001	EPD108181A, 8-1899379-0		
4145573001	9-1193124-8, EPD65700F/1(CO)		
CQ41823001	EPD116262B/1-9(CO)		
EQ02393001	EPD122640A/1-1L(CO)		
CQ83823001	EPD118179A/2(CO)		
CT73963001	EPD114354A		
C611643001	5-1201504-4, 5018A1311-0(CO)		
CQ73433001	EPD121380A		
CD53483001	EPD107992A, 1-1899349-0		
CT67213001	EPD104317C/1-9(CO)		
EQ02413001	EPD122640A/2(CO)		
CQ07233001	EPD105670ACK0440/1		
5812693001	2020E0811-0		
2000103002	0022D0P11-1L, 5-1191448-0		
D186573001	6-1202050-7, EPD101744B/1-1L(CO)		
D256123001	0024A0311-0(3M), 9-1201023-9		

CD99383001	0024K1811-0(6M), 9-1899535-6		
5354893001	3-1194204-8, EPD72947A/2(CO)		
7995633001	6-1196181-8, EPD60480L/1(CO)		
6658953001	4-1195246-6, EPD63054C/1-6		
4191873001	2-1193158-0, 7524A1P11-9(FS)		
CQ96463001	EPD122430A		
CD16843001	EPD104312B/1-9(CO), 8-1899162-1		
CT71493001	EPD114556A/1(CO)		
CQ31953001	EPD115269A		
5788673001	7-1197892-1, EPD71607A/2(CO)		
CQ91643001	0024K1811-0(M4)(FS)		
E823283001	EPD104315A/1-9(CO)		
4435763001	4-1201422-5, EPD96295Q/2-1L/9(CO)		
CQ17413001	EPD117867A/1(CO)		
A365153001	8-1200826-5, EPD98487C		
CQ78733001	EPD121587A		
CQ95393001	EPD121055A		
C179693001	5-1202050-1, EPD101755B/1-1L(CO)		
0160993001	1190126-1, EPD65055ACK0078		
2904013002	7-1192201-2, EPD37229A		
5309393001	9-1194169-7, CLFH178		
CQ91673001	0024K1811-0(M3)		

9926933001	6-1197678-1, CLFH400(S50)		
CQ48103001	5012A3811- 0CK0016		
3438753001	2-1192590-6, 5020A1311- 02(CO)		
CQ17913001	EPD117603ACK0 308		
CQ04113001	EPD109318Q/1- 9(M2)(FS)		
0683833001	2-1190515-1, EPD87667A/4-0		
2063573001	1191496-7, EPD60651B		
1372693001	6-1190995-2, EPD90041A/1- 9(CO)		
CT73173001	EPD114823A		
A457833001	3-1201747-3, EPD98865Q/1- 1L(CO)		
CQ67773001	EPD120650A/1- 3(CO)		
C345453001	EPD104312A/2(M )		
4400103002	3-1193306-9, 5024A1314-0		
CQ43813001	EPD109382ACK0 298/3		
4405693001	3-1193312-2, 5026A1311-0		
2115953001	8-1191532-6, 7518A1811-0(CO)		
6735993001	9-1195298-4, EPD67887L		
2389813001	6-1191756-4, EPD37557D		
CQ67823001	EPD120650A/3(C O)		
4405623001	2-1193312-2, 5018A1311-0		
0644013001	6-1190486-1, EPD76441L/2- 9(CO)		

2519953001	6-1191846-2, EPD2028E/1- 1L(CO)		
9637263001	5-1197946-9, EPD93791A		
5425973001	1-1194254-1, EPD24187D/1(CO )		
CQ12553001	EPD117622A		
EQ05203001	EPD122871A/3- 2/6(CO)		
D349043001	9-1200858-0, EPD96598A/3(CO )		
9059213001	8-1197038-7, EPD77622L/2(CO )		
9560673001	7518A1811-0, 1197402-8		
A215413001	EPD104448A/2(C O), 5-1899067-0		
7552683001	6-1198297-7, EPD7032B/1- 1L2(CO)		
CQ44483001	EPD60947QCK05 03		
440640W002	1193313-5, 9530A1317-9		
A965863001	1200988-8, EPD99292B		
4185973001	3-1193154-1, EPD44031S/1(CO )		
CT67303001	EPD4673H(S82M)		
CD15613001	EPD86888C/2- 1L/9(M), 8- 1899160-5		
CD75203001	EPD104280A/1- 1L(CO), 6- 1899443-6		
1437783001	5-1191039-6, EPD29057A		
CQ77113001	EPD121138ACK0 547/2		
2958893001	7-1192241-7, 5020A1P11-9		
EQ01253001	EPD122713A		

3966373001	4-1192975-0, EPD47366Q		
CQ58443001	EPD115373A		
CQ60883001	EPD116262A/2(C O)		
CT78693001	EPD115223A/1- 9(CO)		
CQ87513001	EPD116265A- 0CK0547/2		
CQ72083001	EPD62444QCK06 21		
6205903001	5030A3-317-0, 8- 1194903-6		
6012523001	2-1199954-6, EPD2028E/1- 1L0(CO)		
6300693001	9-1194986-3, EPD33017Q(CO)		
F271513001	EPD96117A/1(CO ) , 8-1200501-6		
9615153001	8-1197438-1, EPD20662B/4- 2(CO)		
CT75233001	EPD114938A		
5189543001	7-1194072-7, EPD4673G/1(CO)		
F705083001	5-1201791-3, EPD101039L/1- 1L(CO)		
4900973001	3-1193666-9, 9530E1014-0		
1049743001	5-1199206-4, EPD37229ACK00 30		
4418253001	3-1201344-1, 0022D0311- 95(CO)		
D649603001	7-1200884-5, EPD60608C/1- 1L(CO)		
D541233001	1200338-4, EPD98008L/1- 9(CO)		
CT62683001	EPD96718C		
6676093001	9-1195257-9, EPD76441L/2- 1L(CO)		

440077W005	5-1193307-5, 7524A1311-0		
F045423001	EPD99114A/1- 1L/9(CO), 9- 1200811-5		
CQ95313001	EPD121042A		
2670533001	4-1191971-1, EPD8851F/3- 9(CO)		
CQ77573001	EPD94392BCK02 06/5		
CQ07133001	EPD116448A/1(M )		
CD76293001	6-1899446-3, EPD109318Q/1- 9(M)		
A365403001	7-1201018-2, EPD60608D/1- 1L(CO)		
CQ22603001	EPD109382ACK0 298/2		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.