



# Product Change Notification

Current Date: 19-Sep-2023

## TE Connectivity

**Product Change Notification:** PCN-23-186195

**PCN Date:** 18-SEP-23

**Customer:** TTI, Inc. ( 1305175 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:** (Text limited to 120 characters)

TAT-125 and SCL Mil Spec Hold and new direct replacement Non-MIL Spec parts availability

**Description of Changes**

Dear Customer, Please be advised all TAT-125 and SCL Part Numbers (PN) with Mil Spec designation are on hold due to requalification requirements. Requalification from NAVAIR is indefinite and can be prolonged. In order to provide our valued customers with direct technical replacements that can be produced and shipped immediately, we have created NON-MIL Spec parts to directly replace existing MIL Spec parts. For customers and end-users that do not formally require the Mil Spec designation this will be the fastest option to receive product. These new PNs are exact technical copies of existing PNs, the only difference is they do not have the MIL Spec designation, and as such, there will be NO MIL Spec designation on the packaging of these new PNs. Call To Action: 1. Please review attached Excel file for a FROM-TO replacement guide. This file lists one-for-one replacements, NON-MIL Spec PN replacements for Mil Spec PNs on hold (unable to ship). 2. If a NON-Mil Spec replacement is acceptable, please work with customer care to convert current orders over to the new PNs For any additional questions or concerns please contact your local Customer Care Professional.

**Other attachments:**

[PCN -Non-MIL Spec. parts Availability](#)

[Non-MIL spec parts info.](#)

**Reason for Changes:**

Please be advised all TAT-125 and SCL Part Numbers (PN) with Mil Spec designation are on hold due to requalification requirements. Requalification from NAVAIR is indefinite and can be prolonged.

**PCN Attributes:**

<b>Product Category:</b>	<b>Kind of Change:</b>
Heat Shrink Tubing	Specification
<b>Change Feature:</b>	<b>Potential Customer Impact:</b>
Product Specification	No Customer Impact
<b>Remarks:</b>	

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Ship Date of Changed Items</b> (Changed Parts Only):
	19-SEP-2023
<b>Last Ship Date of Changed Items</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments
<b>Effectivity Date:</b>	<b>Date of First Samples:</b>

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">NB25822001</a>	NO			SCL-1/8-0-STK			
<a href="#">NB25842001</a>	NO			SCL-3/8-0-STK			
<a href="#">NB25862001</a>	NO			SCL-3/16-0-STK			
<a href="#">NB25962001</a>	NO			SCL-1/4-0-STK			



# Product Change Notification

Current Date: 19-Sep-2023

## TE Connectivity

**Product Change Notification:** PCN-23-186195

**PCN Date:** 18-SEP-23

**Customer:** TTI, Inc. ( 3057778 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:** (Text limited to 120 characters)

TAT-125 and SCL Mil Spec Hold and new direct replacement Non-MIL Spec parts availability

**Description of Changes**

Dear Customer, Please be advised all TAT-125 and SCL Part Numbers (PN) with Mil Spec designation are on hold due to requalification requirements. Requalification from NAVAIR is indefinite and can be prolonged. In order to provide our valued customers with direct technical replacements that can be produced and shipped immediately, we have created NON-MIL Spec parts to directly replace existing MIL Spec parts. For customers and end-users that do not formally require the Mil Spec designation this will be the fastest option to receive product. These new PNs are exact technical copies of existing PNs, the only difference is they do not have the MIL Spec designation, and as such, there will be NO MIL Spec designation on the packaging of these new PNs. Call To Action: 1. Please review attached Excel file for a FROM-TO replacement guide. This file lists one-for-one replacements, NON-MIL Spec PN replacements for Mil Spec PNs on hold (unable to ship). 2. If a NON-Mil Spec replacement is acceptable, please work with customer care to convert current orders over to the new PNs For any additional questions or concerns please contact your local Customer Care Professional.

**Other attachments:**

[PCN -Non-MIL Spec. parts Availability](#)

[Non-MIL spec parts info.](#)

**Reason for Changes:**

Please be advised all TAT-125 and SCL Part Numbers (PN) with Mil Spec designation are on hold due to requalification requirements. Requalification from NAVAIR is indefinite and can be prolonged.

**PCN Attributes:**

<b>Product Category:</b>	<b>Kind of Change:</b>
Heat Shrink Tubing	Specification
<b>Change Feature:</b>	<b>Potential Customer Impact:</b>
Product Specification	No Customer Impact
<b>Remarks:</b>	

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Ship Date of Changed Items</b> (Changed Parts Only):
	19-SEP-2023
<b>Last Ship Date of Changed Items</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments
<b>Effectivity Date:</b>	<b>Date of First Samples:</b>

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">NB25822001</a>	NO		RAYNB25822001	SCL-1/8-0-STK			
<a href="#">NB25842001</a>	NO		RAYNB25842001	SCL-3/8-0-STK			
<a href="#">NB25862001</a>	NO		RAYNB25862001	SCL-3/16-0-STK			
<a href="#">NB25962001</a>	NO		RAYNB25962001	SCL-1/4-0-STK			



Type of Notification	TAT-125 and SCL Mil Spec Hold and new direct replacement Non-MIL Spec parts availability
----------------------	--

Issue Date	Notification No.
13SEP2023	XX-XXX

<b>Description of Change</b>
<p>Dear Customer,</p> <p>Please be advised all <b>TAT-125 and SCL Part Numbers (PN)</b> with Mil Spec designation are on hold due to requalification requirements. Requalification from NAVAIR is indefinite and can be prolonged.</p> <p>In order to provide our valued customers with direct technical replacements that can be produced and shipped immediately, we have created <b>NON-MIL Spec</b> parts to directly replace existing <b>MIL Spec</b> parts. For customers and end-users that do not formally require the Mil Spec designation this will be the fastest option to receive product.</p> <p>These new PNs are exact technical copies of existing PNs, the only difference is they <b>do not have the MIL Spec</b> designation, and as such, there will be <b>NO MIL Spec</b> designation on the packaging of these new PNs.</p> <p><b>Call To Action:</b></p> <ol style="list-style-type: none"><li>1. Please review attached Excel file for a FROM-TO replacement guide. This file lists one-for-one replacements, <b>NON-MIL Spec PN</b> replacements for <b>Mil Spec PNs</b> on hold (unable to ship).</li><li>2. If a NON-Mil Spec replacement is acceptable, please work with customer care to convert current orders over to the new PNs</li></ol> <p>For any additional questions or concerns please contact your local Customer Care Professional.</p>

Coury, Matt	Heat Shrink Product Management
-------------	--------------------------------

Part No	Part description	MIL Spec no. from CPR	New Non-MIL spec Part No.	New Non-MIL spec. Part description
NB25882001	SCL-1/2-0-STK	M23053/4-105-0	NB46232001	SCL-1/2-0-STK-CS34568
NB25912001	SCL-1/2-2-STK	M23053/4-105-2	NB46132001	SCL-1/2-2-STK-CS34568
NB25962001	SCL-1/4-0-STK	M23053/4-103-0	NB46242001	SCL-1/4-0-STK-CS34568
NB25992001	SCL-1/4-2-STK	M23053/4-103-2	NB46112001	SCL-1/4-2-STK-CS34568
NB25822001	SCL-1/8-0-STK	M23053/4-101-0	NB46072001	SCL-1/8-0-STK-CS34568
NB26072001	SCL-1/8-2-STK	M23053/4-101-2	NB46082001	SCL-1/8-2-STK-CS34568
NB25862001	SCL-3/16-0-STK	M23053/4-102-0	NB46092001	SCL-3/16-0-STK-CS34568
NB25902001	SCL-3/16-2-STK	M23053/4-102-2	NB46102001	SCL-3/16-2-STK-CS34568
NB25922001	SCL-3/4-0-STK	M23053/4-106-0	NB46152001	SCL-3/4-0-STK-CS34568
NB25752001	SCL-3/4-2-STK	M23053/4-106-2	NB46142001	SCL-3/4-2-STK-CS34568
NB25842001	SCL-3/8-0-STK	M23053/4-104-0	NB46282001	SCL-3/8-0-STK-CS34568
NB25802001	SCL-3/8-2-STK	M23053/4-104-2	NB46122001	SCL-3/8-2-STK-CS34568
NB13922001	TAT-125-1/2-2-STK	M23053/4-203-2	NB46312001	TAT-125-1/2-2-STK-CS34568
NB24082001	TAT-125-1/2-9-STK	M23053/4-203-9	NB46322001	TAT-125-1/2-9-STK-CS34568
NB13934001	TAT-125-1/4-0-SP	M23053/4-201-0	NB46334001	TAT-125-1/4-0-SP-CS34568
NB24132001	TAT-125-1/4-9-STK	M23053/4-201-9	NB46342001	TAT-125-1/4-9-STK-CS34568
NB17632001	TAT-125-1-1/2-0-STK	M23053/4-206-0	NB46352001	TAT-125-1-1/2-0-STK-CS34568
NB24402001	TAT-125-1-1/2-9-STK	M23053/4-206-9	NB46362001	TAT-125-1-1/2-9-STK-CS34568
NB24182001	TAT-125-1-6-STK	M23053/4-205-6	NB46372001	TAT-125-1-6-STK-CS34568
NB24192001	TAT-125-1-9-STK	M23053/4-205-9	NB46382001	TAT-125-1-9-STK-CS34568
NB35662001	TAT-125-3/4-1-STK	M23053/4-204-1	NB46392001	TAT-125-3/4-1-STK-CS34568
NB14092001	TAT-125-3/4-5-STK	M23053/4-204-5	NB46402001	TAT-125-3/4-5-STK-CS34568
NB24272001	TAT-125-3/4-6-STK	M23053/4-204-6	NB46412001	TAT-125-3/4-6-STK-CS34568
NB24282001	TAT-125-3/4-9-STK	M23053/4-204-9	NB46422001	TAT-125-3/4-9-STK-CS34568
NB24314001	TAT-125-3/8-0-SP	M23053/4-202-0	NB46434001	TAT-125-3/8-0-SP-CS34568
NB24322001	TAT-125-3/8-0-STK	M23053/4-202-0	NB46442001	TAT-125-3/8-0-STK-CS34568
NB24362001	TAT-125-3/8-2-STK	M23053/4-202-2	NB46452001	TAT-125-3/8-2-STK-CS34568