



13-Nov-2014

PCN #:E-14-016951

Subject:1mm FH BTB connector with matte Tin-lead plating

Description of Change: The drawings for the listed part numbers have been modified for [clarification.To](#) change soldering area plating Matte Tin-lead 0.00381Min to bright Tin-lead 0.002Min.

Reason: Product Improvement. TE prior supplier will not support TE 1mm FH BTB connector producing, so 1MM FH line will be transfered into TE internal China plant to make sure product quality. But TE plant will only provide the bright Tin-lead 0.002Min, it will not influence function.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:31-Dec-2014

Implementation Date:31-Dec-2014

Product Affected

120534-1

120531-1

120525-1

1-120521-1

120521-1

146893-1

120533-1

120521-2

146896-2

146888-1

120528-1

120527-2

Product Affected

120603-2

120527-1

(Alias Part Numbers:

"1328973")

120526-1

120524-1

120523-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.