



Product Change Notification

Current Date: 21-Sep-2015

TE Connectivity

Product Change Notification: P-15-012075

PCN Date: 17-SEP-15

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
PIDG STRATO-THERM Terminals

Description of Changes
Manufacturing location change. CORRECTION TO PCN P-15-011691. Following Part Numbers will be transferred from our TE Connectivity Lickdale PA manufacturing location to our TE Connectivity Landisville PA manufacturing location.

Reason for Changes:				
Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.				
Estimated Dates:				
<table border="1"><tr><td>Last Order Date (Obsolete Parts Only):</td><td>First Date To Ship (Changed Parts Only):</td></tr><tr><td></td><td>15-JAN-2016</td></tr></table>	Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):		15-JAN-2016
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):			
	15-JAN-2016			

Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-JUN-2016

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-332433-0	NO						
50831	NO						
50831-1	NO						
50832	NO						
50832-1	NO		B0808005-006N				
50845	NO						
50845-1	NO						
50845-2	NO		5917427-2				
50846	NO						
50848	NO						

Customer: TTI Inc.(1305175)

Location: Maisach-Gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
50831-1	NO		TYC50831-1				
50845-2	NO		5917427-2				

Customer: TTI Inc(168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
50831	NO						
50832	NO						
50832-1	NO		B0808005-006N				
50845-1	NO						
50845-2	NO		5917427-2				
50848	NO						

Customer: TTI Electronics Asia Pte Ltd.(2771300)

Location: SINGAPORE

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-332433-0	NO						

Customer: TTI Inc(1281288)

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
50831	NO						
50832	NO						
50832-1	NO		B0808005-006N				

50845	NO						
50845-1	NO						
50845-2	NO		5917427-2				
50846	NO						
50848	NO						

Customer: TTI Inc.(3057778)

Location: Olching

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
50831-1	NO		TYC50831-1				