

10-Mar-2016 **PCN #:**P-16-012701

Subject: capacity Tooling

Description of Change: UPDATE TO PCN# P16012575 & PCN# P16012523. Due to the localization of new capacity mold to support customer demands in North and South America, we hereby inform you of a change of Distribution Center to ship the below listed TE Connectivity Part Numbers. This will take effect immediately. Your TE Customer Care Representative will contact you to review any special arrangements required and to make any appropriate adjustments to your DUNS/Vendor Codes/Supplier Codes for the new Distribution Center

Reason: Customer Request.New capacity mold is located in our TE Greensboro, NC plant. To provide faster shipment of parts to our, parts will be shipped from our Greensboro, NC Distribution Center. Refer to PCN# P15011946 regarding new capacity mold tool.

Impact of Change: form - fit - function

Key Dates:

Contact By Date:01-Apr-2016

Implementation Date:01-Apr-2016

Product Affected

828904-2

828922-2

828904-1

(Alias Part Numbers:

"CF0547-000"

"AMP-0-0828904-1")

828922-1

(Alias Part Numbers:



The change described in the PCN can be withdrawn, without notice, for any

or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the change of the cha

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.