



01-Apr-2016

PCN #:P-16-012826

**Subject:**DEUTSCH DRC, DT, DTM, DRCP, DTF, STRIKE Header  
Receptacles

**Description of Change:** Manufacturing location change. The Industrial & Commercial Transportation (hereinafter referred to as ICT) business unit of TEC is moving stamping tools and plating operations from one TEC approved supplier in the USA to another TEC approved supplier in the USA. TEC ICT will do its due diligence by requiring a PPAP from the supplier. This supplier has been used extensively in the past by TEC business unit with excellent performance.

**Reason:** Dear Customer, we inform you of this move of tools and processes as part of our aggressive continuous improvement efforts on delivery. The transfer is executed by following a TEC internal strict transfer procedure, which mitigates quality risk while increasing our ability to supply your products on time. The new manufacturing location is governed under a certified quality management system according to the standard automotive requirements. An internal release based on our specifications will be executed before any parts are delivered. PPAP packages by product family will be offered upon customer request.

**Impact of Change:**Manufacturing location change

**Key Dates:**

**Contact By Date:**01-Aug-2016

**Implementation Date:**01-Aug-2016

**Product Affected**

DTF15-12PC

(Alias Part Numbers:

"ZPF000000000130565")

DT15-4P-G003

**Product Affected**

(Alias Part Numbers:

"ZPF000000000130326")

DTM1312PA12PBR008

(Alias Part Numbers:

"1899781-5"

"DTM13-12PA-12PB-R008")

DTM15-12PA

(Alias Part Numbers:

"ZPF000000000130591")

DT15-12PB-G003

(Alias Part Numbers:

"ZPF000000000130734")

DTM13-12PC-R008

DTF15-12PD

(Alias Part Numbers:

"ZPF000000000130566")

DT15-12PB-B016

(Alias Part Numbers:

"ZPF000000000130733")

DT15-08PA-G003

(Alias Part Numbers:

"ZPF000000000130482")

DT13-12PD

(Alias Part Numbers:

"ZPF000000000130725")

DRC20-75P0102

DT15-4P

(Alias Part Numbers:

"ZPF000000000133626"

"ZPF000000000130325")

DRC20-50P05

(Alias Part Numbers:

"ZPF000000000131355")

DT13-08PB

(Alias Part Numbers:

"ZPF000000000130476")

DTM13-12PA-R008

(Alias Part Numbers:

"ZPF000000000139426")

DT15-08PC

**Product Affected**

(Alias Part Numbers:  
"ZPF000000000130484")

DT15-12PA

(Alias Part Numbers:  
"ZPF000000000130728"  
"ZPF000000000133623")

DT15-12PD-G003

SRK15-MDF-32A-001

DTM13-12PA-NP02

DTM15-12PD

(Alias Part Numbers:  
"ZPF000000000130594")

DTM13-12PA12PBR008

(Alias Part Numbers:  
"5-1899805-8")

DT13-12PB-B016

(Alias Part Numbers:  
"ZPF000000000130720")

1034-005-0205

(Alias Part Numbers:  
"1034-005-0205-B")

DTM13-12PA

(Alias Part Numbers:  
"ZPF000000000130584")

DTM1312PC12PDR008

(Alias Part Numbers:  
"3-1899781-6"  
"DTM13-12PC-12PD-R008")

DT15-12PA-B016

(Alias Part Numbers:  
"ZPF000000000130729")

DRC20-50P08

(Alias Part Numbers:  
"ZPF000000000131358")

DTM15-12PB

(Alias Part Numbers:  
"ZPF000000000130592")

DRCP25-86PBB-GC05

DT13-12PC-B016

(Alias Part Numbers:

**Product Affected**

"ZPF000000000130723")

DRC22-50P05

DRC20-60P05

DRC23-24PA-A010

DRC20-50P01

(Alias Part Numbers:

"ZPF000000000131351")

DT15-12PB

(Alias Part Numbers:

"ZPF000000000130732"

"ZPF000000000133624")

DTM1312PC12PDGR01

(Alias Part Numbers:

"DTM13-12PC-12PD-GR01")

DT15-12PC

(Alias Part Numbers:

"ZPF000000000130736")

DRC22-50P07

DT13-08PC

(Alias Part Numbers:

"ZPF000000000130478")

DT13-2P

(Alias Part Numbers:

"ZPF000000000130187")

DRC20-76P0102

DT13-20PAA-E004

(Alias Part Numbers:

"ZPF000000000130899")

46926-1

DRC23-40PC-N012

DRC22-50P04

DTM1312PA12PBGR01

(Alias Part Numbers:

"DTM13-12PA-12PB-GR01")

DRCP25-126PBB-GC03

SRK15-MDE-32A-001

94202103

(Alias Part Numbers:

"094202103")

DRC23-40PB-N010

**Product Affected**

DRC20-50P06

(Alias Part Numbers:  
"ZPF000000000131356")

DRC20-50P02

(Alias Part Numbers:  
"ZPF000000000131352")

DT13-08PB-G003

(Alias Part Numbers:  
"ZPF000000000130477")

DT15-2P-A009

DT13-6P

(Alias Part Numbers:  
"ZPF000000000130369")

DRCP25-86PBB-GC03

DRC23-40PB-N012

SRK15-MDD-32A-001

DT13-08PD

(Alias Part Numbers:  
"ZPF000000000130480")

DRC20-60P06

DT15-12PD-B016

(Alias Part Numbers:  
"ZPF000000000130740")

DRC23-24PB

(Alias Part Numbers:  
"ZPF000000000131124")

DT15-6P

(Alias Part Numbers:  
"ZPF000000000130371")

DTM13-08PA-R004

(Alias Part Numbers:  
"ZPF000000000130406")

1034-006-0405

(Alias Part Numbers:  
"1034-006-0405-B")

DTM13-12PB-R008

(Alias Part Numbers:  
"ZPF000000000130588")

247-520

DRC23-24PB-A010

**Product Affected**

DT13-4P-G003

(Alias Part Numbers:  
"ZPF000000000130324")

DRC22-50P01

(Alias Part Numbers:  
"ZPF000000000131361")

DT15-12PD

(Alias Part Numbers:  
"ZPF000000000130739")

DT15-6P-GP01

(Alias Part Numbers:  
"ZPF000000000130373")

DTM04-2P-P007

(Alias Part Numbers:  
"ZPF000000000130138")

SRK13-MDA-32A-001

DRC23-40PC

(Alias Part Numbers:  
"ZPF000000000131314")

DT13-12PB-G003

(Alias Part Numbers:  
"ZPF000000000130721")

DRC23-80P

(Alias Part Numbers:  
"ZPF000000000131418")

DRC20-50P09

(Alias Part Numbers:  
"ZPF000000000131359")

DTF15-12PC-G003

DRC23-40PB

(Alias Part Numbers:  
"ZPF000000000131313")

DRC23-40PA-G004

(Alias Part Numbers:  
"ZPF000000000131311")

DTM15-12PC

(Alias Part Numbers:  
"ZPF000000000130593")

DT13-08PA

(Alias Part Numbers:

**Product Affected**  
"ZPF000000000130474")  
DT15-12PC-G003  
(Alias Part Numbers:  
"ZPF000000000130738")  
DRC23-64PAA  
(Alias Part Numbers:  
"ZPF000000000131389")  
DT15-3P-R009  
DT13-12PA-B016  
(Alias Part Numbers:  
"ZPF000000000130717")  
DRC23-40PA  
(Alias Part Numbers:  
"ZPF000000000131310")  
DRC23-40PA-N012  
(Alias Part Numbers:  
"ZPF000000000131312")  
DTF15-12PA-G003  
(Alias Part Numbers:  
"ZPF000000000130563")  
DT13-12PB  
(Alias Part Numbers:  
"ZPF000000000130719")  
DTF15-12PB  
(Alias Part Numbers:  
"ZPF000000000130564")  
DRC23-40PD  
(Alias Part Numbers:  
"ZPF000000000131315")  
DTMF15-48P  
(Alias Part Numbers:  
"ZPF000000000131348")  
DTMF15-48P-B026  
DRC22-50P02  
DTM13-12PB  
(Alias Part Numbers:  
"ZPF000000000130586")  
DT13-6P-G003  
(Alias Part Numbers:  
"ZPF000000000130370")

**Product Affected**

DTF15-12PD-G003

DTM13-12PC

(Alias Part Numbers:

"ZPF000000000130589")

DTM13-12PA12PCR008

DT15-08PA

(Alias Part Numbers:

"ZPF000000000130481")

DT15-08PD

(Alias Part Numbers:

"ZPF000000000130485")

DRC22-50P03

DT15-6P-G003

(Alias Part Numbers:

"ZPF000000000130372")

DT15-2P-P010

(Alias Part Numbers:

"ZPF000000000130189")

DT13-4P

(Alias Part Numbers:

"ZPF000000000130323")

DRC23-24PA

(Alias Part Numbers:

"ZPF000000000131123")

SRK15-MDC-32A-001

DT13-12PD-B016

(Alias Part Numbers:

"ZPF000000000130726")

DRCP25-86PAA-G003

(Alias Part Numbers:

"1-1899819-0")

DRCP25-86PCC-GC05

DT13-12PC

(Alias Part Numbers:

"ZPF000000000130722")

DRCP25-126PAA-G003

DT15-12PA-G003

(Alias Part Numbers:

"ZPF000000000130730")

DRC20-50P04



**Product Affected**

(Alias Part Numbers:  
"ZPF000000000131354")

DT13-12PA

(Alias Part Numbers:  
"ZPF000000000130716")

DT15-12PA-B028  
DTM13-12PC12PDGR01  
DTM13-12PA-GR01

(Alias Part Numbers:  
"ZPF000000000130585")

DRCP25-86PCC-GC03  
DTF15-12PA

(Alias Part Numbers:  
"ZPF000000000130562")

DTM13-12PD-R008  
DTF15-12PB-G003  
DRC20-60P07

SRK15-MDA-32A-001  
SRK15-MDB-32A-001  
DT15-12PC-B016

(Alias Part Numbers:  
"ZPF000000000130737")

DTM1312PA12PCR008

(Alias Part Numbers:  
"DTM13-12PA-12PC-R008")

DRC23-64PAA-N010

(Alias Part Numbers:  
"ZPF000000000131390")

DRCP25-86PAA-G005  
DT15-12PB-B028  
DT15-08PB

(Alias Part Numbers:  
"ZPF000000000130483")

DTM13-12PD

(Alias Part Numbers:  
"ZPF000000000130590")

DTM1312PC12PBR008

(Alias Part Numbers:  
"DTM13-12PC-12PB-R008")

DT15-2P

**Product Affected**

(Alias Part Numbers:

"ZPF000000000130188"

"ZPF000000000133625")

DT13-12PA-G003

(Alias Part Numbers:

"ZPF000000000130718")

DRC20-50P07

(Alias Part Numbers:

"ZPF000000000131357")

DRC20-50P03

(Alias Part Numbers:

"ZPF000000000131353")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.