



Product Change Notification

Current Date: 30-May-2016

TE Connectivity

Product Change Notification: P-15-011969

PCN Date: 26-AUG-15

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

PIDG, DIAMOND GRIP, STRATO-THERM and various SOLISTRAND and PLASTI GRIP tape applied terminals.

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from our Lickdale PA TE Connectivity manufacturing location to Landisville PA TE Connectivity manufacturing location.

Reason for Changes:

Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 29-FEB-2016 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | 30-JUN-2016 |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 2-326889-1 | NO | | | | | |
| 2-327748-1 | NO | | | | | |
| 2-327934-2 | NO | | | | | |
| 2-327938-1 | NO | | | | | |
| 2-327946-4 | NO | | | | | |
| 2-327950-1 | NO | | | | | |
| 2-327952-2 | NO | | | | | |
| 2-327956-1 | NO | | | | | |
| 2-327958-1 | NO | | | | | |
| 2-327958-4 | NO | | | | | |
| 2-327960-1 | NO | | | | | |
| 2-327960-2 | NO | | | | | |
| 2-327964-4 | NO | | | | | |
| 2-327968-1 | NO | | | | | |
| 2-32835-2 | NO | | | | | |
| 2-328657-1 | NO | | | | | |
| 2-328975-1 | NO | | | | | |
| 2-328975-2 | NO | | | | | |
| 2-328975-3 | NO | | | | | |
| 2-328976-1 | NO | | | | | |
| 2-328976-2 | NO | | | | | |
| 2-328996-1 | NO | | | | | |
| 2-328998-1 | NO | | | | | |
| 2-328999-1 | NO | | | | | |
| 2-32994-1 | NO | | | | | |
| 2-330648-1 | NO | | | | | |
| 2-33156-1 | NO | | | | | |
| 2-33456-1 | NO | | | | | |
| 2-33457-2 | NO | | "401771357" | | | |
| 2-33458-3 | NO | | | | | |
| 2-33459-6 | NO | | | | | |

| | | | | | |
|---------------------------|----|--|----------------------|--|--|
| 2-33476-1 | NO | | | | |
| 2-33722-1 | NO | | | | |
| 2-34080-1 | NO | | | | |
| 2-34103-1 | NO | | | | |
| 2-34104-6 | NO | | | | |
| 2-34105-2 | NO | | | | |
| 2-34107-2 | NO | | | | |
| 2-34108-2 | NO | | | | |
| 2-34109-2 | NO | | | | |
| 2-34110-3 | NO | | | | |
| 2-34111-3 | NO | | | | |
| 2-34112-2 | NO | | | | |
| 2-34113-2 | NO | | | | |
| 2-34114-2 | NO | | "402755094" | | |
| 2-34115-2 | NO | | | | |
| 2-34117-2 | NO | | | | |
| 2-34118-2 | NO | | | | |
| 2-34119-1 | NO | | | | |
| 2-34120-1 | NO | | | | |
| 2-34121-1 | NO | | | | |
| 2-34122-1 | NO | | | | |
| 2-34123-1 | NO | | "405109166" | | |
| 2-34124-1 | NO | | | | |
| 2-34125-6 | NO | | | | |
| 2-34126-2 | NO | | | | |
| 2-34266-1 | NO | | | | |
| 2-34541-1 | NO | | "405223678" | | |
| 2-34567-1 | NO | | | | |
| 2-34805-1 | NO | | | | |
| 2-34806-2 | NO | | | | |
| 2-34806-3 | NO | | | | |
| 2-34974-1 | NO | | | | |
| 2-35106-1 | NO | | | | |
| 2-35107-1 | NO | | | | |
| 2-35108-1 | NO | | "1098560" | | |
| 2-35109-1 | NO | | "1140297", "1139542" | | |
| 2-35110-1 | NO | | "403665755" | | |
| 2-35111-1 | NO | | | | |
| 2-35112-2 | NO | | | | |
| 2-35129-1 | NO | | | | |
| 2-35135-2 | NO | | | | |
| 2-35149-1 | NO | | | | |
| 2-35152-1 | NO | | | | |
| 2-35273-2 | NO | | "1293791" | | |
| 2-35345-1 | NO | | | | |
| 2-35346-1 | NO | | | | |
| 2-35476-1 | NO | | | | |
| 2-35494-2 | NO | | | | |
| 2-35495-2 | NO | | | | |
| 2-35559-1 | NO | | | | |
| 2-35634-1 | NO | | | | |
| 2-35684-1 | NO | | | | |
| 2-35771-1 | NO | | | | |
| 2-35772-1 | NO | | | | |
| 2-35775-1 | NO | | | | |
| 2-36149-2 | NO | | | | |
| 2-36149-3 | NO | | | | |
| 2-36149-4 | NO | | | | |
| 2-36149-5 | NO | | | | |
| 2-36150-1 | NO | | | | |
| 2-36151-2 | NO | | | | |
| 2-36152-1 | NO | | "405813072" | | |
| 2-36153-2 | NO | | | | |
| 2-36153-3 | NO | | | | |
| 2-36153-4 | NO | | | | |
| 2-36153-5 | NO | | | | |
| 2-36153-6 | NO | | | | |

| | | | | | |
|----------------------------|----|--|--|--|--|
| 2-36153-9 | NO | | | | |
| 2-36154-2 | NO | | "405853706" | | |
| 2-36157-2 | NO | | | | |
| 2-36158-1 | NO | | | | |
| 2-36160-1 | NO | | | | |
| 2-36161-2 | NO | | "402624795" | | |
| 2-36161-3 | NO | | | | |
| 2-36161-4 | NO | | | | |
| 2-36161-5 | NO | | | | |
| 2-36161-6 | NO | | | | |
| 2-36195-3 | NO | | | | |
| 2-36451-1 | NO | | | | |
| 2-36880-1 | NO | | | | |
| 2-36954-2 | NO | | | | |
| 2-53983-1 | NO | | | | |
| 2-55825-1 | NO | | | | |
| 2-696200-2 | NO | | | | |
| 30926 | NO | | | | |
| 30927 | NO | | | | |
| 30928 | NO | | | | |
| 30993 | NO | | | | |
| 30996 | NO | | | | |
| 30997 | NO | | | | |
| 31094 | NO | | | | |
| 31096 | NO | | | | |
| 31159 | NO | | | | |
| 31160 | NO | | | | |
| 31161 | NO | | | | |
| 31176 | NO | | | | |
| 31251 | NO | | | | |
| 31252 | NO | | | | |
| 31256 | NO | | | | |
| 31269 | NO | | | | |
| 31270 | NO | | | | |
| 31393 | NO | | | | |
| 31396 | NO | | | | |
| 31397 | NO | | | | |
| 31397-1 | NO | | | | |
| 31398 | NO | | | | |
| 31515 | NO | | | | |
| 31516 | NO | | | | |
| 31518 | NO | | | | |
| 31589-1 | NO | | | | |
| 31679 | NO | | "4-00520-1730" | | |
| 31762 | NO | | | | |
| 31763 | NO | | | | |
| 31770 | NO | | | | |
| 31771 | NO | | | | |
| 31772 | NO | | | | |
| 31777 | NO | | | | |
| 31828 | NO | | | | |
| 31880 | NO | | | | |
| 31884 | NO | | | | |
| 31886 | NO | | "319586-000", "AMPS-0-0031886-0" | | |
| 31887 | NO | | "1969001P006" | | |
| 31888 | NO | | | | |
| 31890 | NO | | "A28230-000", "AMPS-0-0031890-0", "6089315700", "6089 3 157-00" | | |
| 31891 | NO | | | | |
| 31894 | NO | | "679058-000", "AMPS-0-0031894-0", "6089315703" | | |
| 31895 | NO | | "C58079-000", "AMPS-0-0031895-0" | | |
| 31897 | NO | | "A84499-000", "AMPS-0-0031897-0" | | |
| 31903 | NO | | | | |
| 31906 | NO | | | | |
| 31942 | NO | | | | |
| 31943 | NO | | | | |

| | | | | | |
|------------------------|----|--|---|--|--|
| 31945 | NO | | | | |
| 320209 | NO | | | | |
| 320306 | NO | | | | |
| 320359 | NO | | | | |
| 320381 | NO | | | | |
| 32050 | NO | | | | |
| 32051 | NO | | | | |
| 32053 | NO | | "126360-000", "AMPS-0-0032053-0", "6089313700" | | |
| 32054 | NO | | "589454-000", "AMPS-0-0032054-0" | | |
| 320551 | NO | | "F14692-001", "AMP-0-0320551-0", "500-095- 0002", "2-14492-8160" | | |
| 320552 | NO | | | | |
| 320553 | NO | | "CN5244-000", "AMP-0-0320553-0", "668-1003- 01", "2-14492-4160" | | |
| 320554 | NO | | "F92535-000", "AMPS-0-0320554-0" | | |
| 320555 | NO | | | | |
| 32056 | NO | | | | |
| 320560 | NO | | "C01931-000", "AMP-0-0320560-0", "2-14492- 8140" | | |
| 320561 | NO | | "CF0318-000", "AMP-0-0320561-0", "500-095- 0000", "2-14492-6140" | | |
| 320563 | NO | | "D12388-000", "AMPS-0-0320563-0" | | |
| 320564 | NO | | "A69728-000", "AMPS-0-0320564-0" | | |
| 320565 | NO | | "AMPS-0-0320565-0", "F51439-000", "0- 0320565-0" | | |
| 320566 | NO | | | | |
| 320567 | NO | | "500-095-1042", "2-14492-6100" | | |
| 320568 | NO | | "F51639-001" | | |
| 320569 | NO | | "A22724-000", "AMPS-0-0320569-0" | | |
| 32057 | NO | | | | |
| 320571 | NO | | "CN5242-000", "AMP-0-0320571-0", "2-14492- 3160" | | |
| 320572 | NO | | "EF5287-000", "AMP-0-0320572-0" | | |
| 320573 | NO | | | | |
| 320574 | NO | | "A62994-000", "AMP-0-0320574-0", "2-14492- 1140" | | |
| 320575 | NO | | | | |
| 320576 | NO | | | | |
| 320577 | NO | | "D24803-000", "HUB-RINGTERM-12-10-3/8SD" | | |
| 32058 | NO | | | | |
| 32059 | NO | | "A35266-000", "AMP-0-0032059-0" | | |
| 32060 | NO | | "AMPS-0-0032060-0", "D11529-000" | | |
| 320619 | NO | | "AMPS-0-0320619-0", "C41604-000", "4-00520- 1990" | | |
| 320620 | NO | | | | |
| 320627 | NO | | | | |
| 320629 | NO | | | | |
| 320630 | NO | | "668-1023-04" | | |
| 320631 | NO | | | | |
| 320634 | NO | | "500-095-3014", "2-14492-6130" | | |
| 320773 | NO | | | | |
| 320861 | NO | | | | |
| 320862 | NO | | "AMPS-0-0320862-0", "F94449-000" | | |
| 320863 | NO | | | | |
| 320882 | NO | | "E70689-000", "AMPS-0-0320882-0", "500-060- 3904", "1216304" | | |
| 321013 | NO | | | | |
| 321015 | NO | | | | |
| 321017 | NO | | | | |
| 321019 | NO | | | | |
| 321035 | NO | | | | |
| 321045 | NO | | "AMPS-0-0321045-0", "E13157-000" | | |
| 321233 | NO | | "A05484-000", "AMPS-0-0321233-0", "2-30733- 0040" | | |
| 321283 | NO | | | | |
| 321501 | NO | | | | |
| 321522 | NO | | | | |

| | | | | | |
|--------------------------|----|--|---|--|--|
| 32161 | NO | | | | |
| 321611 | NO | | | | |
| 321617 | NO | | | | |
| 321620 | NO | | | | |
| 321621 | NO | | | | |
| 321808 | NO | | | | |
| 321817 | NO | | | | |
| 32188 | NO | | | | |
| 321887 | NO | | | | |
| 321887-1 | NO | | | | |
| 32189 | NO | | | | |
| 321892 | NO | | | | |
| 321892-1 | NO | | | | |
| 321893 | NO | | | | |
| 321894 | NO | | | | |
| 321897 | NO | | | | |
| 321897-1 | NO | | | | |
| 321898 | NO | | | | |
| 321898-1 | NO | | | | |
| 32190 | NO | | | | |
| 322001 | NO | | | | |
| 322320 | NO | | | | |
| 322325 | NO | | | | |
| 322332 | NO | | | | |
| 322336 | NO | | | | |
| 322337 | NO | | | | |
| 322338 | NO | | | | |
| 322341 | NO | | | | |
| 322344 | NO | | | | |
| 322346 | NO | | | | |
| 322363 | NO | | | | |
| 322363-1 | NO | | | | |
| 322364 | NO | | | | |
| 322365 | NO | | | | |
| 322366 | NO | | | | |
| 322367 | NO | | | | |
| 322371 | NO | | | | |
| 322373 | NO | | | | |
| 322374 | NO | | | | |
| 322374-1 | NO | | | | |
| 322375 | NO | | | | |
| 322376 | NO | | "E99597-000", "AMP-0-0322376-0" | | |
| 322426 | NO | | | | |
| 322454-1 | NO | | | | |
| 322724 | NO | | | | |
| 322777 | NO | | "402706162" | | |
| 322823 | NO | | | | |
| 322825 | NO | | | | |
| 322873 | NO | | | | |
| 322985 | NO | | "AMPS-0-0322985-0", "D51511-000", "1394881" | | |
| 323008 | NO | | "668-1003-02" | | |
| 323011 | NO | | | | |
| 323039 | NO | | | | |
| 323066 | NO | | | | |
| 323067 | NO | | | | |
| 323068 | NO | | | | |
| 323069 | NO | | | | |
| 323069-1 | NO | | | | |
| 323151 | NO | | | | |
| 323151-1 | NO | | | | |
| 323152 | NO | | | | |
| 323152-1 | NO | | | | |
| 323152-2 | NO | | | | |
| 323153 | NO | | | | |
| 323153-1 | NO | | | | |
| 323153-2 | NO | | | | |
| 323154 | NO | | | | |

| | | | | | | |
|--------------------------|----|--|--|--|--|--|
| 323158 | NO | | | | | |
| 323160 | NO | | | | | |
| 323161 | NO | | | | | |
| 323199 | NO | | | | | |
| 323199-1 | NO | | | | | |
| 323676 | NO | | | | | |
| 323682 | NO | | | | | |
| 323699 | NO | | | | | |
| 323748 | NO | | | | | |
| 323749 | NO | | | | | |
| 323750 | NO | | | | | |
| 323751 | NO | | | | | |
| 323752 | NO | | | | | |