



Product Change Notification

Current Date: 31-Aug-2015

TE Connectivity

Product Change Notification: P-15-011970

PCN Date: 26-AUG-15

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

PIDG, DIAMOND GRIP, STRATO-THERM and various SOLISTRAND and PLASTI GRIP tape applied terminals.

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from our Lickdale PA TE Connectivity manufacturing location to our Landisville PA TE Connectivity manufacturing location.

Reason for Changes:

Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

29-FEB-2016

Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-JUN-2016

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3-31089-6	NO						
323758	NO						
323763	NO						
323784	NO						
323912	NO		11455816, BACT12AC-43				
323913	NO						
323914	NO		BACT12AC-44	"2-14492-4220"			
323915	NO		BACT12AC-45	"1189457", "4-16211-4022", "1101161"			
323916	NO		BACT12AC-46	"2-14492-8220"			
324015	NO						
324075	NO		BACT12AC-47	"1134503"			
324086	NO						
324158	NO			"F77176-000", "AMPS-0-0324158-0"			
324159	NO		BACT12AC-52	"D97987-000", "AMPS-0-0324159-0"			
32446	NO						
32448	NO						
324533	NO						
324543	NO						
32456	NO						
324567	NO						
324608	NO						

324615	NO					
324915	NO					
324918	NO			"E22648-000", "AMPS-0-0324918-0"		
32498	NO			"798370-000", "AMP-0-0032498-0"		
324993	NO					
32510	NO					
325197	NO					
32561	NO					
32562	NO			"AMP-0-0032562-0", "D64996-000", "4-15237-0000", "2-30733-0010"		
32588	NO			"AMPS-0-0032588-0", "D90904-000"		
32589	NO			"338160-000", "AMPS-0-0032589-0"		
326859	NO					
326861	NO					
326875	NO			"4-00520-2060"		
326886-1	NO					
326889	NO					
327717	NO					
327743	NO			"2-14492-3140", "1100134"		
327944	NO					
327948	NO					
328281	NO			"668-1016-02", "2-30733-0000"		
32835	NO					
32836	NO			"D40566-000", "AMPS-0-0032836-0"		
32837	NO					
328394	NO			"4-27051-2333"		
328657	NO					
32883	NO			"4-16211-9894", "2-14492-1100"		
328849	NO		BACT12AC-55	"D96600-000", "AMPS-0-0328849-0"		

328975	NO		BACT12AC-51			
328976	NO					
328996	NO		S1367-2-4			
328998	NO		BACT12AC-09	"D74476-000", "AMPS-0-0328998-0"		
328999	NO					
329697	NO					
329951	NO					
330648	NO		82340-109221-1			
330896	NO					
331467	NO		BACT12AC-58			
34080	NO			"500-095-0148", "4-16211-4014"		
342061	NO			"846100-000", "AMPS-0-0342061-0"		
342062	NO					
342063	NO			"767361-000", "AMPS-0-0342063-0"		
342064	NO					
342066	NO					
34294	NO					
34541	NO			"A52622-000", "AMPS-0-0034541-0", "668-1005-02", "1362238"		
34805	NO					
34806	NO			"AMP-0-0034806-0", "C46815-000"		
34810	NO			"AMP-0-0034810-0", "D14886-000"		
34974	NO					
35106	NO					
35107	NO					
35108	NO			"AMPS-0-0035108-0", "C57639-000", "500-060-1422", "2-14492-8100"		
35109	NO			"AMPS-0-0035109-0", "F67095-000"		
35110	NO			"AMPS-0-0035110-0", "E36230-		

				000", "2-14492-3100"			
35111	NO			"211624-000", "AMPS-0-0035111-0"			
35112	NO			"D94238-000", "AMPS-0-0035112-0"			
35148	NO			"E38772-000", "AMPS-0-0035148-0"			
35149	NO		699-4472-084A	"AMPS-0-0035149-0", "C04253-000", "4-00520-2000"			
35150	NO						
35151	NO			"C58906-000", "AMPS-0-0035151-0"			
35273	NO						
35274	NO						
35316	NO						
35345	NO						
35346	NO						
35362	NO						
35363	NO			"AMPS-0-0035363-0", "F41472-000"			
35364	NO						
35481	NO						
35559	NO			"AMP-0-0035559-0", "E20814-000"			
35605	NO						
35634	NO						
35762	NO						
36149	NO		BACT12AC-1	"2-42937-0285"			
36150	NO			"C24355-000", "AMPS-0-0036150-0"			
36151	NO		699-4472-082A, S1367-1-6	"CJ0960-001", "AMP-0-0036151-0", "500-095-0001", "2-14492-6160"			
36152	NO			"AMPS-0-0036152-0", "F40776-000", "11021"			
36153	NO		BACT12AC-3, S1367-1-10	"E15470-000", "AMP-0-0036153-0", "2-14492-1160"			
36154	NO			"AMPS-0-0036154-0", "D27582-			

				000", "110209", "4-00520-2110", "1-14647-0030"			
36157	NO						
36158	NO		S1367-2-6	"668-1041-02"			
36160	NO		S1367-2-10	"AMP-0-0036160-0", "E00855-000"			
36161	NO		BACT12AC-12, S1367-3-10	"AMP-0-0036161-0", "E87226-000"			
36203	NO						
50881	NO			"A09418-000", "AMPS-0-0050881-0"			
50881-2	NO						
51863	NO		BACT12AC-2, BACT12AC2	"4-16211-9784"			
51863-1	NO		BACT12AC-2, BACT12AC-2A				
51863-2	NO						
51863-3	NO						
51863-4	NO						
51864	NO		BACT12AC-7				
51864-1	NO		011-004181-002, BACT12AC-53				
51864-2	NO		126300-29, BACT12AC-8				
51864-3	NO						
51864-4	NO						
51864-5	NO						
51864-6	NO						
51864-7	NO						
51864-8	NO						
51864-9	NO						
51874	NO			"1044642"			

52077	NO						
52189	NO						
52273	NO						
52273-1	NO						
52273-2	NO						
52274	NO						
52274-1	NO						
52307	NO						
52369	NO			"1356397"			
52403	NO						
52409-1	NO						
52410	NO						
52410-1	NO						
52421-3	NO						
52430-2	NO						
52730-1	NO						
52922	NO			"F34670-000", "AMPS-0-0052922-0"			
52924	NO						
52924-1	NO						
52925	NO			"E66977-000", "AMPS-0-0052925-0"			
52927-1	NO						
52928	NO			"C98444-000", "AMPS-0-0052928-0"			
52928-1	NO						
52929	NO			"AMPS-0-0052929-0", "D04859-000", "2-42933-5341"			
52929-1	NO						
52929-3	NO						
52930	NO			"AMPS-0-0052930-0", "D67548-000"			
52930-1	NO						

52930-3	NO					
52931-1	NO					
52933	NO			"E12039-000", "AMP-0-0052933-0"		
52934	NO			"D45431-000", "AMPS-0-0052934-0"		
52934-1	NO					
52935	NO			"AMPS-0-0052935-0", "E94617-000"		
52935-1	NO					
52935-2	NO					
52935-3	NO					
52936-1	NO					
52936-2	NO					
52936-3	NO					
52937-1	NO					
52941	NO			"AMPS-0-0052941-0", "E40828-000"		

Customer: TTI Inc.(1305175)

Location: Maisach-Gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
323784	NO		TYC323784				
323912	NO		BACT12AC-43, 11455816, TYC323912				
323915	NO		BACT12AC-45, TYC323915	"1189457", "4-16211-4022", "1101161"			
323916	NO		TYC323916, BACT12AC-46	"2-14492-8220"			
324158	NO			"F77176-000", "AMPS-0-0324158-			

				0"			
32456	NO						
324567	NO						
32562	NO		TYC32562	"AMP-0-0032562-0", "D64996-000", "4-15237-0000", "2-30733-0010"			
326861	NO		TYC326861				
327948	NO		TYC327948				
328281	NO		TYC328281	"668-1016-02", "2-30733-0000"			
32835	NO						
32836	NO		TYC32836	"D40566-000", "AMPS-0-0032836-0"			
328394	NO		TYC328394	"4-27051-2333"			
328849	NO		BACT12AC-55	"D96600-000", "AMPS-0-0328849-0"			
328998	NO		BACT12AC-09, TYC328998	"D74476-000", "AMPS-0-0328998-0"			
330648	NO		82340-109221-1, TYC330648				
331467	NO		BACT12AC-58, TYC331467				
342061	NO		TYC342061	"846100-000", "AMPS-0-0342061-0"			
342062	NO		TYC342062				
342063	NO		TYC342063	"767361-000", "AMPS-0-0342063-0"			
342064	NO		TYC342064				
342066	NO		TYC342066				
34806	NO		TYC34806	"AMP-0-0034806-0", "C46815-000"			

35106	NO						
35109	NO		TYC35109	"AMPS-0-0035109-0", "F67095-000"			
35111	NO		TYC35111	"211624-000", "AMPS-0-0035111-0"			
35151	NO		TYC35151	"C58906-000", "AMPS-0-0035151-0"			
35273	NO		TYC35273				
35274	NO		TYC35274				
35316	NO		TYC35316				
35346	NO						
35559	NO		TYC35559	"AMP-0-0035559-0", "E20814-000"			
36150	NO		TYC36150	"C24355-000", "AMPS-0-0036150-0"			
36160	NO		S1367-2-10, TYC36160	"AMP-0-0036160-0", "E00855-000"			
51863-1	NO		TYC51863-1, BACT12AC-2, BACT12AC-2A				
51863-2	NO						
51863-3	NO		TYC51863-3				
51864-4	NO		TYC51864-4				
51864-9	NO						
52077	NO						
52273	NO						
52274	NO		TYC52274				
52410	NO		TYC52410				
52924	NO		TYC52924				
52928	NO		TYC52928	"C98444-000", "AMPS-0-			

				0052928-0"			
52929	NO		TYC52929	"AMPS-0-0052929-0", "D04859-000", "2-42933-5341"			
52930	NO		TYC52930	"AMPS-0-0052930-0", "D67548-000"			
52934	NO		TYC52934	"D45431-000", "AMPS-0-0052934-0"			
52935	NO		TYC52935	"AMPS-0-0052935-0", "E94617-000"			
52941	NO		TYC52941	"AMPS-0-0052941-0", "E40828-000"			

Customer: TTI Inc(168830)

Location: Fort Worth

Agreement Number: TTI003

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3-31089-6	NO						
323758	NO						
323763	NO						
323912	NO		BACT12AC-43, 11455816				
323913	NO						
323914	NO		BACT12AC-44	"2-14492-4220"			
323915	NO		BACT12AC-45	"1189457", "4-16211-4022", "1101161"			
323916	NO		BACT12AC-46	"2-14492-8220"			
324015	NO						

324075	NO		BACT12AC-47	"1134503"			
324086	NO						
324158	NO			"F77176-000", "AMPS-0-0324158-0"			
324159	NO		BACT12AC-52	"D97987-000", "AMPS-0-0324159-0"			
32446	NO						
32448	NO						
324533	NO						
324543	NO						
324608	NO						
324615	NO						
324915	NO						
324918	NO			"E22648-000", "AMPS-0-0324918-0"			
32498	NO			"798370-000", "AMP-0-0032498-0"			
324993	NO						
32510	NO						
325197	NO						
32561	NO						
32589	NO			"338160-000", "AMPS-0-0032589-0"			
326861	NO						
326875	NO			"4-00520-2060"			
326886-1	NO						
327717	NO						
327743	NO			"2-14492-3140", "1100134"			
327944	NO						
32835	NO						
32836	NO			"D40566-000", "AMPS-0-0032836-0"			
32837	NO						
328394	NO			"4-27051-2333"			
328657	NO						

32883	NO			"4-16211-9894", "2-14492-1100"			
328849	NO		BACT12AC-55	"D96600-000", "AMPS-0-0328849-0"			
328975	NO		BACT12AC-51				
328976	NO						
328996	NO		S1367-2-4				
328999	NO						
329697	NO						
329951	NO						
330648	NO		82340-109221-1				
330896	NO						
34080	NO			"500-095-0148", "4-16211-4014"			
34294	NO						
34541	NO			"A52622-000", "AMPS-0-0034541-0", "668-1005-02", "1362238"			
34805	NO						
34974	NO						
35107	NO						
35108	NO			"AMPS-0-0035108-0", "C57639-000", "500-060-1422", "2-14492-8100"			
35109	NO			"AMPS-0-0035109-0", "F67095-000"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
35111	NO			"211624-000", "AMPS-0-0035111-0"			
35112	NO			"D94238-000", "AMPS-0-0035112-0"			
35149	NO		699-4472-084A	"AMPS-0-0035149-0", "C04253-000", "4-00520-2000"			
35151	NO			"C58906-000", "AMPS-0-0035151-0"			
35273	NO						
35316	NO						

35345	NO						
35362	NO						
35363	NO				"AMPS-0-0035363-0", "F41472-000"		
35364	NO						
35481	NO						
35559	NO				"AMP-0-0035559-0", "E20814-000"		
35762	NO						
36149	NO		BACT12AC-1		"2-42937-0285"		
36150	NO				"C24355-000", "AMPS-0-0036150-0"		
36151	NO		699-4472-082A, S1367-1-6		"CJ0960-001", "AMP-0-0036151-0", "500-095-0001", "2-14492-6160"		
36152	NO				"AMPS-0-0036152-0", "F40776-000", "11021"		
36153	NO		S1367-1-10, BACT12AC-3		"E15470-000", "AMP-0-0036153-0", "2-14492-1160"		
36154	NO				"AMPS-0-0036154-0", "D27582-000", "110209", "4-00520-2110", "1-14647- 0030"		
36158	NO		S1367-2-6		"668-1041-02"		
36160	NO		S1367-2-10		"AMP-0-0036160-0", "E00855-000"		
36161	NO		S1367-3-10, BACT12AC-12		"AMP-0-0036161-0", "E87226-000"		
50881	NO				"A09418-000", "AMPS-0-0050881-0"		
50881-2	NO						
51863	NO		BACT12AC2, BACT12AC-2		"4-16211-9784"		
51863-1	NO		BACT12AC-2, BACT12AC-2A				
51863-2	NO						
51863-3	NO						

51863-4	NO						
51864	NO		BACT12AC-7				
51864-1	NO		BACT12AC-53, 011-004181-002				
51864-2	NO		126300-29, BACT12AC-8				
51864-3	NO						
51864-4	NO						
51864-5	NO						
51864-6	NO						
51864-7	NO						
51864-8	NO						
51864-9	NO						
52077	NO						
52189	NO						
52273	NO						
52273-1	NO						
52273-2	NO						
52369	NO			"1356397"			
52403	NO						
52409-1	NO						
52410-1	NO						
52421-3	NO						
52730-1	NO						
52922	NO			"F34670-000", "AMPS-0-0052922-0"			
52924	NO						
52924-1	NO						
52925	NO			"E66977-000", "AMPS-0-0052925-0"			
52927-1	NO						

52928-1	NO						
52929	NO			"AMPS-0-0052929-0", "D04859-000", "2-42933-5341"			
52929-1	NO						
52929-3	NO						
52930-1	NO						
52930-3	NO						
52931-1	NO						
52934-1	NO						
52935-1	NO						
52935-2	NO						
52935-3	NO						
52936-1	NO						
52936-2	NO						
52936-3	NO						
52937-1	NO						

Customer: TTI Electronics Asia Pte Ltd.(2771300)

Location: SINGAPORE

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
323915	NO		BACT12AC-45	"1189457", "4-16211-4022", "1101161"			
326859	NO						
35108	NO			"AMPS-0-0035108-0", "C57639-000", "500-060-1422", "2-14492-8100"			
35151	NO			"C58906-000", "AMPS-0-0035151-0"			
36153	NO		S1367-1-10,	"E15470-000", "AMP-0-0036153-0", "2-			

			BACT12AC-3	14492-1160"			
36154	NO			"AMPS-0-0036154-0", "D27582-000", "110209", "4-00520-2110", "1-14647- 0030"			
52929-1	NO						
52935	NO			"AMPS-0-0052935-0", "E94617-000"			
52936-1	NO						

Customer: TTI (MC)(2922321)

Location: Pointe-Claire

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
35149	NO		699-4472-084A	"AMPS-0-0035149-0", "C04253- 000", "4-00520-2000"			

Customer: Shanghai TTI ELelectronics Co Ltd(1405773)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
323758	NO						
35109	NO			"AMPS-0-0035109-0", "F67095-000"			
36161	NO		S1367-3-10, BACT12AC-12	"AMP-0-0036161-0", "E87226-000"			

Customer: TTI Electronics Asia Pte Ltd.(2771300)

Location: SINGAPORE

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
323915	NO		BACT12AC-45	"1189457", "4-16211-4022", "1101161"			
326859	NO						
35108	NO			"AMPS-0-0035108-0", "C57639-000", "500-060-1422", "2-14492-8100"			
35151	NO			"C58906-000", "AMPS-0-0035151-0"			
36153	NO		S1367-1-10, BACT12AC-3	"E15470-000", "AMP-0-0036153-0", "2-14492-1160"			
36154	NO			"AMPS-0-0036154-0", "D27582-000", "110209", "4-00520-2110", "1-14647-0030"			
52929-1	NO						
52935	NO			"AMPS-0-0052935-0", "E94617-000"			
52936-1	NO						

Customer: TTI(3003903)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
328996	NO		S1367-2-4				

34806	NO			"AMP-0-0034806-0", "C46815-000"			
52077	NO						
52941	NO			"AMPS-0-0052941-0", "E40828-000"			

Customer: Shanghai TTI Electronics Co Ltd(2850040)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
323758	NO						
35109	NO			"AMPS-0-0035109-0", "F67095-000"			
36161	NO			"AMP-0-0036161-0", "E87226-000"			

Customer: TTI Electronics Asia Pte Ltd.(2771300)

Location: SINGAPORE

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
323915	NO		BACT12AC-45	"1189457", "4-16211-4022", "1101161"			
326859	NO						
35108	NO			"AMPS-0-0035108-0", "C57639-000", "500-060-1422", "2-14492-8100"			

35151	NO			"C58906-000", "AMPS-0-0035151-0"			
36153	NO		S1367-1-10, BACT12AC-3	"E15470-000", "AMP-0-0036153-0", "2-14492-1160"			
36154	NO			"AMPS-0-0036154-0", "D27582-000", "110209", "4-00520-2110", "1-14647-0030"			
52929-1	NO						
52935	NO			"AMPS-0-0052935-0", "E94617-000"			
52936-1	NO						

Customer: TTI Electronics Asia Pte Ltd(3063486)

Location: Taipei

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
52273-1	NO						

Customer: TTI Inc(1281288)

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3-31089-6	NO						
323758	NO						
323763	NO						
323912	NO		BACT12AC-43,				

			11455816			
323913	NO					
323914	NO		BACT12AC-44	"2-14492-4220"		
323915	NO		BACT12AC-45	"1189457", "4-16211-4022", "1101161"		
323916	NO		BACT12AC-46	"2-14492-8220"		
324015	NO					
324075	NO		BACT12AC-47	"1134503"		
324086	NO					
324158	NO			"F77176-000", "AMPS-0-0324158-0"		
324159	NO		BACT12AC-52	"D97987-000", "AMPS-0-0324159-0"		
32446	NO					
32448	NO					
324533	NO					
324543	NO					
324608	NO					
324615	NO					
324915	NO					
324918	NO			"E22648-000", "AMPS-0-0324918-0"		
32498	NO			"798370-000", "AMP-0-0032498-0"		
324993	NO					
32510	NO					
325197	NO					
32561	NO					
32588	NO			"AMPS-0-0032588-0", "D90904-000"		
32589	NO			"338160-000", "AMPS-0-0032589-0"		
326861	NO					
326875	NO			"4-00520-2060"		
326886-1	NO					

326889	NO						
327717	NO						
327743	NO			"2-14492-3140", "1100134"			
327944	NO						
32835	NO						
32836	NO			"D40566-000", "AMPS-0-0032836-0"			
32837	NO						
328394	NO			"4-27051-2333"			
328657	NO						
32883	NO			"4-16211-9894", "2-14492-1100"			
328849	NO		BACT12AC-55	"D96600-000", "AMPS-0-0328849-0"			
328975	NO		BACT12AC-51				
328976	NO						
328996	NO		S1367-2-4				
328999	NO						
329697	NO						
329951	NO						
330648	NO		82340-109221-1				
330896	NO						
34080	NO			"500-095-0148", "4-16211-4014"			
34294	NO						
34541	NO			"A52622-000", "AMPS-0-0034541-0", "668-1005-02", "1362238"			
34805	NO						
34810	NO			"AMP-0-0034810-0", "D14886-000"			
34974	NO						
35106	NO						
35107	NO						
35108	NO			"AMPS-0-0035108-0", "C57639-000",			

				"500-060-1422", "2-14492-8100"			
35109	NO			"AMPS-0-0035109-0", "F67095-000"			
35110	NO			"AMPS-0-0035110-0", "E36230-000", "2-14492-3100"			
35111	NO			"211624-000", "AMPS-0-0035111-0"			
35112	NO			"D94238-000", "AMPS-0-0035112-0"			
35148	NO			"E38772-000", "AMPS-0-0035148-0"			
35149	NO		699-4472-084A	"AMPS-0-0035149-0", "C04253-000", "4-00520-2000"			
35150	NO						
35151	NO			"C58906-000", "AMPS-0-0035151-0"			
35273	NO						
35316	NO						
35345	NO						
35362	NO						
35363	NO			"AMPS-0-0035363-0", "F41472-000"			
35364	NO						
35481	NO						
35559	NO			"AMP-0-0035559-0", "E20814-000"			
35605	NO						
35634	NO						
35762	NO						
36149	NO		BACT12AC-1	"2-42937-0285"			
36150	NO			"C24355-000", "AMPS-0-0036150-0"			
36151	NO		699-4472-082A, S1367-1-6	"CJ0960-001", "AMP-0-0036151-0", "500-095-0001", "2-14492-6160"			
36152	NO			"AMPS-0-0036152-0", "F40776-000", "11021"			
36153	NO		S1367-1-10,	"E15470-000", "AMP-0-0036153-0",			

			BACT12AC-3	"2-14492-1160"			
36154	NO			"AMPS-0-0036154-0", "D27582-000", "110209", "4-00520-2110", "1-14647- 0030"			
36157	NO						
36158	NO		S1367-2-6	"668-1041-02"			
36160	NO		S1367-2-10	"AMP-0-0036160-0", "E00855-000"			
36161	NO		S1367-3-10, BACT12AC-12	"AMP-0-0036161-0", "E87226-000"			
36203	NO						
50881	NO			"A09418-000", "AMPS-0-0050881-0"			
50881-2	NO						
51863	NO		BACT12AC2, BACT12AC-2	"4-16211-9784"			
51863-1	NO		BACT12AC-2, BACT12AC-2A				
51863-2	NO						
51863-3	NO						
51863-4	NO						
51864	NO		BACT12AC-7				
51864-1	NO		BACT12AC-53, 011- 004181-002				
51864-2	NO		126300-29, BACT12AC-8				
51864-3	NO						
51864-4	NO						
51864-5	NO						
51864-6	NO						
51864-7	NO						
51864-8	NO						

51864-9	NO						
51874	NO			"1044642"			
52077	NO						
52189	NO						
52273	NO						
52273-1	NO						
52273-2	NO						
52274-1	NO						
52307	NO						
52369	NO			"1356397"			
52403	NO						
52409-1	NO						
52410-1	NO						
52421-3	NO						
52430-2	NO						
52730-1	NO						
52922	NO			"F34670-000", "AMPS-0-0052922-0"			
52924	NO						
52924-1	NO						
52925	NO			"E66977-000", "AMPS-0-0052925-0"			
52927-1	NO						
52928-1	NO						
52929	NO			"AMPS-0-0052929-0", "D04859-000", "2-42933-5341"			
52929-1	NO						
52929-3	NO						
52930-1	NO						
52930-3	NO						
52931-1	NO						

52933	NO			"E12039-000", "AMP-0-0052933-0"			
52934-1	NO						
52935-1	NO						
52935-2	NO						
52935-3	NO						
52936-1	NO						
52936-2	NO						
52936-3	NO						
52937-1	NO						

Customer: TTI Inc.(3057778)

Location: Olching

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
323784	NO		TYC323784				
323915	NO		TYC323915	"1189457", "4-16211-4022", "1101161"			
323916	NO		TYC323916	"2-14492-8220"			
32456	NO						
32562	NO		TYC32562	"AMP-0-0032562-0", "D64996-000", "4-15237-0000", "2-30733-0010"			
326861	NO		TYC326861				
327948	NO		TYC327948				
32836	NO		TYC32836	"D40566-000", "AMPS-0-0032836-0"			
328998	NO		TYC328998	"D74476-000", "AMPS-0-0328998-0"			
330648	NO		TYC330648				
331467	NO		TYC331467				

342064	NO		TYC342064			
34806	NO		TYC34806	"AMP-0-0034806-0", "C46815-000"		
35106	NO					
35109	NO		TYC35109	"AMPS-0-0035109-0", "F67095-000"		
35111	NO		TYC35111	"211624-000", "AMPS-0-0035111-0"		
35151	NO		TYC35151	"C58906-000", "AMPS-0-0035151-0"		
35273	NO		TYC35273			
35274	NO		TYC35274			
35316	NO		TYC35316			
35559	NO		TYC35559	"AMP-0-0035559-0", "E20814-000"		
36150	NO		TYC36150	"C24355-000", "AMPS-0-0036150-0"		
36160	NO		TYC36160	"AMP-0-0036160-0", "E00855-000"		
51863-1	NO		TYC51863-1			
51863-2	NO					
51864-4	NO		TYC51864-4			
52273	NO					
52929	NO		TYC52929	"AMPS-0-0052929-0", "D04859-000", "2-42933-5341"		
52930	NO		TYC52930	"AMPS-0-0052930-0", "D67548-000"		
52935	NO		TYC52935	"AMPS-0-0052935-0", "E94617-000"		

Customer: TTI Electronics Asia Pte Ltd.(1407161)

Location: HONG KONG

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
323915	NO			"1189457", "4-16211-4022", "1101161"			
326859	NO						

35108	NO			"AMPS-0-0035108-0", "C57639-000", "500-060-1422", "2-14492-8100"			
35151	NO			"C58906-000", "AMPS-0-0035151-0"			
36154	NO			"AMPS-0-0036154-0", "D27582-000", "110209", "4-00520-2110", "1-14647- 0030"			
52273-1	NO						
52929-1	NO						
52935	NO			"AMPS-0-0052935-0", "E94617-000"			

Customer: TTI Inc(2922318)

Location: Tustin

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
327717	NO						

Customer: Shanghai TTI ELelectronics Co Ltd(3064990)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
323758	NO						
35109	NO			"AMPS-0-0035109-0", "F67095-000"			

