



Product Change Notification

Current Date: 11-Jul-2016

TE Connectivity

Product Change Notification: P-15-012194

PCN Date: 02-NOV-15

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing Location Change of Menlo Park Tubing Products

Description of Changes

This notification is to inform our customers that TE Connectivity is closing our Menlo Park facility in USA and moving the production to our Trutnov facility in Czech Republic and our Shanghai facility in China. Both receiving facilities are already established Heat Shrinkable Tubing (Tubing or Products) manufacturing sites with Trutnov facility manufacturing Tubing since 2008 and Shanghai facility - since 1996. This manufacturing and Products transfer will start in 2016 with the targeted final closure date of Menlo Park location by the end of 2019. TE reserves the right to provide TE qualified Products from any of the new locations during this transfer period. Customers may still receive Products from Menlo Park location after this closure due to stock we will manufacture to allow this transfer to happen without affecting our customer base. TE will continue with internal qualification and testing of all Products after they are received at the new locations.

Reason for Changes:

If you require a PPAP or specific testing please inform us within 90 days of receiving this notification so we can coordinate the documentation and support your requirements. After this 90 day period we will take no reply as you are satisfied with TE internal qualification and testing. For any questions or concerns please contact your Customer Care Professional.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-JAN-2016
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0065672002	NO		4-1190050-9, TAT-125-1-9-STK			
007871P001	NO		1190061-2, FP21-2-X-48IN			
008339J001	NO		6-1190064-3, V4-6.0-0-SP-SM			
0158874001	NO		3-1190124-9, FPO-1-1/2-0-SP			
018645J002	NO		7-1190145-2, HIX-VW1-1-1/2-0-SP-SM			
0200294003	NO		2-1190156-0, MIL-LT-1/8-5-SP			
029101-000	NO		1197923-5, MIL-LT-1-1/2-9-SP-CS7223			
0331174003	NO		8-1190256-6, MIL-LT-3/64-1-SP			
0345014001	NO		1-1190267-4, MIL-LT-3/8-5-SP			
034565-000	NO		5-1190267-6, VERSAFIT-1/2-9-FSP			
034831-000	NO		5-1190269-3, RT-218-1/4-9-SP-CS6396			
038095-000	NO		4-1190294-8, ES2000-NO.4-A1-0-47MM			
042787J001	NO		2-1190328-1, V4-1.5-0-SP-SM			
043300-000	NO		5-1197931-1, RNF-100-3/8-CL-SP-CS7465			
0464234003	NO		5-1190356-7, MIL-LT-3/32-0-SP			
046571J001	NO		7-1190357-5, V2-18.0-0-FSP-SM			
051339-000	NO		3-1190393-4, RNF-100-NO.336-BK-40MM			
051417-000	NO		8-1190393-4, RNF-100-3/4-GN-FSP			
051893-000	NO		2-1190397-9, GPS-3/16-0-STK			
0586872002	NO		2-1190445-1, MIL-LT-3/16-0-STK			
0615334002	NO		5-1190465-4, MIL-LT-1/2-0-SP			
063725P011	NO		5-1190481-1, ES2000-NO.2-B9-0-50MM			
063725P012	NO		5-1190481-2, ES2000-NO.2-B9-0-65MM			
063725P013	NO		5-1190481-3, ES2000-NO.2-B9-0-75MM			
063725P014	NO		5-1190481-4, ES2000-NO.2-B9-0-1200MM			
063725P016	NO		5-1190481-6, ES2000-NO.2-B9-0-60MM			
063725P017	NO		5-1190481-7, ES2000-NO.2-B9-0-40MM			
063725P018	NO		5-1190481-8, ES2000-NO.2-B9-0-30MM			
063725P021	NO		6-1190481-0, ES2000-NO.2-B9-0-27MM			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
063725P022	NO		6-1190481-1,,ES2000-2-4FOOT, ES2000-NO.2-B9-0-STK			
063725P025	NO		6-1190481-3, ES2000-NO.2-B9-0-20MM			
063725P028	NO		6-1190481-5, ES2000-NO.2-B9-0-25MM			
063725P029	NO		6-1190481-6, ES2000-NO.2-B9-0-95MM			
063725P030	NO		6-1190481-7, ES2000-NO.2-B9-0-80MM			
063725P031	NO		6-1190481-8, ES2000-NO.2-B9-0-150MM			
063725P034	NO		7-1190481-1, ES2000-NO.2-B9-0-35MM			
063725P035	NO		7-1190481-2, ES2000-NO.2-B9-0-70MM			
063725P036	NO		7-1190481-3, ES2000-NO.2-B9-0-90MM			
063725P041	NO		7-1190481-4, ES2000-NO.2-B9-0-305MM			
063725P046	NO		7-1190481-7, ES2000-NO.2-B9-0-100MM			
063725P049	NO		8-1190481-0, ES2000-NO.2-A1-0-STK			
063725P078	NO		1190482-7, ES2000-NO.2-B9-0-38MM			
063725P079	NO		1190482-8, ES2000-NO.2-B9-0-45MM			
063725P080	NO		1190482-9, ES2000-NO.2-B9-0-33MM			
063725P081	NO		1-1190482-0, ES2000-NO.2-A1-0-27MM			
063725P082	NO		1-1190482-1, ES2000-NO2B9-0-65MMCS7519			
066584-000	NO		2-1199628-3, SGXFFR-04-0-33IN/NM			
067168N002	NO		"4-1190506-6"			
0679904002	NO		3-1190512-6, CGPE-105-3/4-X-SP			
0737652001	NO		9-1190551-7, FPO-3/32-2-STK			
073906-000	NO		9-1199125-2, RNF-100-1.1MM-CL-STK			
080467-000	NO		2-1190597-4, FPO-3/4-0-FSP			
080551-000	NO		8-1190597-4, LMX3500-SAS-1112-8			
080824-000	NO		9-1199211-4, FPO-5/8-0-SP			
0831074003	NO		7-1190614-9, MIL-LT-1-1/2-0-SP			
0831074007	NO		8-1190614-0, MIL-LT-PP-1-1/2-0			
087410-000	NO		6-1197977-8, RNF-100-NO.93-CL-SPCS7677			
095353-000	NO		1190699-2, SRPT-1/2-0-STK			
095506-000	NO		9-1198884-1, CDW-1/8-0-SP			
0994512003	NO		8-1190728-3, MIL-LT-1-4-STK			
1022134003	NO		1190748-4, VERSAFIT-1/8-8-SP			
103687J002	NO		6-1190758-1, VERSAFIT-2-0-SP-SM			
104417-000	NO		8-1190763-1, LMX3500-SAS-710-8			
107499-000	NO		3-1190785-9, SRPT-3/64-0-STK			
113729-000	NO		5-1190829-2, RNF-100-3/32-WH-SP-CS5533			
117168-000	NO		9-1199152-3, SRPT-1/16-0-SP			
117405-000	NO		9-1190854-1, SRPT-1/4-0-STK			
122604-000	NO		6-1197971-2, V2-3.0-9-SP			
124815-000	NO		4-1190907-1, TC-CAPS-4001-9-CS7596			
1287114003	NO		9-1190934-6, VERSAFIT-3/16-3-SP			
130253-000	NO		1-1197866-6, VERSAFIT-5/8-6-FSP			
1308412002	NO		2-1190951-1, FPO-3/16-6-STK			
1308414001	NO		2-1190951-2, FPO-3/16-6-SP			
1366094002	NO		3-1190990-9, NETM1000-10-0-SP			
137963J001	NO		6-1191000-7, V2-1.5-0-SP-SM			
146419-000	NO		3-1191058-4, DWP-125-3/8-0-5P12.0			
149071-000	NO		9-1191077-7, ATUM-16/4-0-1.5IN			
150467-000	NO		9-1191087-6, VFP-OX-1/4-0-SP			
150648-000	NO		4-1198927-6, TAK-CAPS-3/16-N-CS5373			
151125H001	NO		6-1191092-2, VFP-21-3/4-0-STK-SM			
1518474002	NO		7-1191097-6, RNF-150-3/8-9-SP			
152125-000	NO		5-1191099-6, RNF-100-1-CL-FSP			
152981-000	NO		3-1191105-8, AP2000-107R-0-264MM			
162041-001	NO		3-1197915-2, SST-16-13/226/NM			
1622254001	NO		3-1191171-2, VERSAFIT-1/4-0-BULK-SP			
1637114002	NO		4-1191181-6, RNF-150-1/16-0-SP			
171727-000	NO		1-1191249-4, RT-3-NO.1A-0-1IN			
1735404003	NO		3-1191262-0, VERSAFIT-3/32-5-SP			
1738254001	NO		3-1191264-9, RT-220-1/4-0-SP			
182083-000	NO		2-1191323-8, VERSAFIT-1-0-FSP			
1826414002	NO		9-1191326-9, MIL-LT-1/4-6-SP			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
185816-000	NO		3-1198889-4, CDW-1-1/2-0-SP			
188534-000	NO		6-1201211-0, V2-0.8-0-SP-SM			
190545-000	NO		8-1197858-0, FTS-680-X-SP-CS7656			
190979-000	NO		3-1191385-1, VERSAFIT-1/8-0-70MM			
1918614002	NO		6-1191391-1, RNF-150-1/8-9-SP			
193197P002	NO		4-1191401-5, ES1000-NO.1-C1-X-55MM			
193197P003	NO		4-1191401-6, ES1000-NO.1-C1-X-65MM			
193197P004	NO		4-1191401-7, ES1000-NO.1-C1-X-STK			
193197P005	NO		4-1191401-8, ES1000-NO.1-A1-X-STK			
193197P007	NO		5-1191401-0, ES1000-NO.1-C1-X-20MM			
193197P008	NO		5-1191401-1, ES1000-NO.1-C1-X-50MM			
193197P010	NO		5-1191401-3, ES1000-NO.1-C1-X-25MM			
193197P011	NO		5-1191401-4, ES1000-NO.1-C1-X-30MM			
193197P021	NO		6-1191401-4, ES1000-NO.1-C1-X-100MM			
193197P022	NO		6-1191401-5, ES1000-NO.1-C1-X-45MM			
193197P023	NO		6-1191401-6, ES1000-NO.1-C1-X-35MM			
193197P024	NO		6-1191401-7, ES1000-NO.1-C1-X-40MM			
194899M005	NO		8-1191413-8, MIL-LT-3/4-2-SP			
194899P004	NO		8-1191413-9, MIL-LT-3/4-A1-2-25MM			
1994974001	NO		2-1191445-0, VFP-1/4-2-SP			
2-603325-4	NO		"791403J002", "VFP-21-3/16-0-SP-SM"			
2023834001	NO		2-1191467-7, MIL-LT-1/4-1-SP			
205635N006	NO		3-1191490-8, ES-CAP-NO.3-B8-0-40MM			
2088854002	NO		8-1191513-3, FPO-3/32-5-SP			
215589J002	NO		1-1191557-9, VFP-21-3/32-0-SP-SM			
215687-000	NO		9-1191557-4, SRPT-3/4-0-STK			
219157B001	NO		1191617-5, RNF-100-0.150-CL			
219599H001	NO		3-1191620-9, VFP-21-1/4-0-STK-SM			
227807N002	NO		9-1191676-5, SST-30-15/FR/97			
229873P003	NO		5-1191689-0, VFP-21-1/2-9-48IN-SM			
233617-000	NO		9-1191715-5, MIL-LT-1-0-FSP			
235265J001	NO		6-1191730-1, V2-27.0-0-FSP-SM			
2434444003	NO		4-1191786-5, VERSAFIT-1-1/2-2-SP			
245783N001	NO		1191803-8, RNF-100-3/16-BK-SP-CS5004			
248969-000	NO		9-1191825-1, RT-375-0X-2.0-X			
257084-000	NO		3-1199500-4, RNF-100-1/8-BK-STK-CS7224			
260219-001	NO		8-1191903-9, SST-48-27/FR/RED/97			
260219N002	NO		9-1191903-0, SST-48-27/FR/RED/97			
261214-000	NO		RW-175-1/4-X-1.25IN			
263347-000	NO		4-1191938-0, MIL-LT-3/8-5-FSP			
268181-000	NO		2-1191979-5, MIL-LT-1/2-4-FSP			
269647-000	NO		1-1191990-6, ES-CAP-HW-NO.3-M8-0-45MM			
2748174003	NO		5-1192035-7, VERSAFIT-3/32-6-SP			
288681-000	NO		3-1192189-7, FPO-3-2-SP			
289987-000	NO		6-1192198-2, RNF-100-1/4-BK-STK-CS5004			
291555-000	NO		1-1192211-0, VFP-2-2-SP			
2949076002	NO		3-1192234-1, CGPE-HW-12-A1-0-10.3MM			
2949076003	NO		3-1192234-2, CGPE-HW-12-A1-0-15MM			
2954754002	NO		6-1192238-8, FPO-3/16-9-SP			
295547-000	NO		2-1192239-2, RNF-100-1/2-RD-SP-CS5006			
2965654002	NO		6-1192246-6, FPO-1-9-SP			
298481-000	NO		1-1192260-7, ES2000-NR.1-C1-0-50MM			
3-603328-2	NO		"572089M002", "FP21-1/2-0-SP"			
305063-000	NO		1192310-3, GPA-1-1/2-0-STK			
307621-000	NO		3-1192330-0, SRPT-1/16-X-STK			
3093412001	NO		7-1192342-4, SSP-1/4-0-STK			
3137792002	NO		4-1192373-2, RT-375-1-X-STK			
3137796014	NO		5-1192373-1, RT-375-1-X-65MM			
316673-000	NO		5-1192399-9, CDW-1/4-0-STK			
334095-000	NO		1-1192524-8, CDW-12/3-0-STK			
335135-000	NO		7-1192531-1, FPO-1/2-0-SP-BULK			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3367752001	NO		8-1192542-1, FPO-1/16-2-STK			
3371890001	NO		7-1192545-8, ES-CAP-NO.1-C1-0-30MM			
3371890003	NO		7-1192545-9, ES-CAP-NO.1-C1-0-35MM			
3371890005	NO		8-1192545-0, ES-CAP-NO.1-C1-0-40MM			
348503-001	NO		4-1192622-3, SST-9-27/FR/RED/97			
351005-000	NO		RW-175-0.462-X-STK-CS7612			
3634084003	NO		1192725-4, VERSAFIT-1-1/2-4-SP			
364171-000	NO		5-1192730-5, ES1000-NO.2-B9-X-100MM			
367639-000	NO		9-1192755-5, VERSAFIT-3/8-0-FSP-SM			
370827-000	NO		8-1192777-9, SSP-3/8-0-SP			
372286-000	NO		1-1198890-4, CDW-12/3-0-SP			
377740-000	NO		3-1199646-7, TAT-125-3-0-4IN-TFIT-SFMR			
380737-000	NO		1192847-3, SGSST-27FR-2-51IN			
383877-000	NO		5-1192879-4, LMX3000-25/8-K1-0-55MM			
3844752002	NO		1-1192885-3, MIL-LT-1/2-9-STK			
3844754003	NO		1-1192885-5, MIL-LT-1/2-9-SP			
388994-000	NO		9-1198229-3, SSP-3/4-2-STK			
390358-000	NO		1448665-1, V2-5.0-0-SP			
391765-000	NO		1192940-3, SRPT-3/8-0-STK			
3926434004	NO		1192946-4, TAT-125-HW-450-X-SP			
396017-000	NO		6-1192970-6, VFP-3/4-9-FSP			
4065014002	NO		1-1193067-0, VERSAFIT-1-1/4-4-SP			
4086290001	NO		3-1193082-6, SAS-200-500-1048-1X-2K/2			
408675-000	NO		7-1193082-0, RNF-100-1-RD-SP-CS7465			
4114612001	NO		1-1193103-6, RNF-100-NO.333-CL-STK			
4182070001	NO		6-1193151-4, SAS-200-075-1017-1X			
4183674002	NO		7-1193152-8, VFP-3/4-2-SP			
4243952001	NO		3-1193195-3, FPO-1/2-5-STK			
4326652003	NO		1193254-7, MIL-LT-3/8-2-STK			
432665P004	NO		1-1193254-0, MIL-LT-3/8-A1-2-25MM			
434136-000	NO		4-1199365-8, ATUM-6/2-0-1.5IN			
437929-000	NO		5-1193291-7, MIL-LT-1/2-2-FSP			
438687-000	NO		1-1193297-0, VERSAFIT-1-1/4-8-SP			
4393894001	NO		1193302-4, FPO-1/16-5-SP			
440452-000	NO		7-1199181-4, RT-3-NO.1-0-2.25IN			
4429524009	NO		6-1193329-9, DWP-125-1/8-0-SP			
4453654002	NO		3-1193347-6, VERSAFIT-3/16-7-SP			
446253-000	NO		1-1193354-2, RNF-100-3/4-CL-FSP			
446921-000	NO		8-1193358-6, V2-4.0-0-SP			
449582-000	NO		VERSAFIT-MINI-SPL-3/4-BK, 8-1200740-7			
455001-000	NO		1448667-1, MIL-LT-1/2-0-FSP			
457079J001	NO		2-1193430-1, V4-3.5-0-SP-SM			
459730-000	NO		1-1199022-2, RNF-100-3/64-WH-SP-CS5004			
461137-000	NO		"8-1193458-5"			
461957-000	NO		9-1193464-8, FPO-3-6-SP			
4625674002	NO		2-1193469-4, FPO-3/16-2-SP			
467625-000	NO		1193505-8, RNF-100-1-YO-FSP			
4685294002	NO		4-1193511-9, CGPE-105-1/8-4-SP			
473507-000	NO		5-1193547-4, LMX3500-SAS-510-8			
474591-000	NO		4-1193555-9, AP2000-108-0-177MM			
4807466011	NO		8-1193598-0, TAT-NYLON-NO.2-6X-1.025IN			
4824214003	NO		9-1193610-6, VERSAFIT-3/64-6-SP			
4846272001	NO		4-1193626-8, FPO-1/8-4-STK			
4903754007	NO		2-1193668-8, RT-375-1/2-X-SP			
4909974001	NO		8-1193672-9, RT-220-3/64-9-SP			
492201-000	NO		3-1193681-7			
4944904001	NO		1193698-3, CGPE-105-1/16-0-SP			
499347-000	NO		9-1193732-8, GPA-2-0-STK			
502001L020	NO		7-1193752-7, RP-4800-NO.1-0-STK-CS6925			
502001M021	NO		8-1193752-1, RP-4800-NO.1-0-SP-CS6351			
502002M017	NO		1-1193753-5, RP-4800-NO.2-0-SP-CS5200			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
502002M030	NO		1-1193753-6, RP-4800-NO.2-OSPCS7381			
5020054016	NO		5-1193753-7, RP-4800-NO.4-0-SP			
5020102005	NO		7-1193753-6, RP-4800-NO.10-0-STK			
502010M006	NO		8-1193753-2, RP-4800-NO.10-0-SP-CS6493			
5020114003	NO		8-1193753-7, RP-4800-NO.9-0-SP			
502679N002	NO		7-1193779-8, SAS-090-1-1048-1X-CS6667			
502679N003	NO		7-1193779-9, SAS-090-1-1048-1X-CS7329			
502680N003	NO		8-1193779-4, SAS-115-1-1048-1X-CS6667			
5027712004	NO		2-1193782-3, RP-4800-NO.11-0-STK			
5028214001	NO		9-1193783-6, RP-4800-NO.5-0-SP			
504528-000	NO		2-1199983-6, SGHRHF-250FR-0-23IN			
5052874030	NO		8-1193822-0, RNF-100-3/64-BU-SP			
5052894108	NO		1642242-2, RNF-100-1/16-BK-SP			
5052902037	NO		7-1193824-4, RNF-100-1/16-RD-STK			
505294M309	NO		3-1193828-4, RNF-100-3/32-BKSPCS5004			
505294M310	NO		3-1193828-5, RNF-100-3/32-BKSPCS7210			
5052952040	NO		1-1193829-1, RNF-100-3/32-RD-STK			
5052994173	NO		3-1193833-0,,RNF-100-1/8-0, RNF-100-1/8-BK-SP			
5053002039	NO		1193835-9, RNF-100-1/8-RD-STK			
505301M083	NO		3-1193836-7, RNF-100-1/8-YO-SP-CS5529			
5053022046	NO		8-1193836-1, RNF-100-1/8-BU-STK			
5053024047	NO		8-1193836-7,,RNF-100-1/8-6, RNF-100-1/8-BU-SP			
5053046188	NO		8-1193839-5, RNF-100-3/16-BK-0.5IN			
5053062083	NO		8-1193841-5, RNF-100-3/16-YO-STK			
5053102059	NO		4-1193848-0, RNF-100-1/4-RD-STK			
5053124054	NO		8-1193850-2, RNF-100-1/4-BU-SP			
505313M224	NO		3-1193852-8, RNF-100-1/4-WHSPCS5004			
505313M225	NO		3-1193852-9, RNF-100-1/4-WH-SP-CS7465			
505314L546	NO		9-1193854-8, RNF-100-3/8-BK-STKCS5004			
5053162199	NO		4-1193858-1, RNF-100-3/8-YO-STK			
5053182074	NO		9-1193860-3, RNF-100-3/8-WH-STK			
505318M076	NO		5-1193861-2, RNF-100-3/8-WH-SP-CS5321			
505319M260	NO		9-1193863-3, RNF-100-1/2-BK-SP-CS6162			
505319P402	NO		1193865-7, RNF-100-1/2-A1-BK-40MM			
505319P406	NO		1193865-9, RNF-100-1/2-BK-30MM			
505319P416	NO		1-1193865-1, RNF-100-1/2-A1-BK-120MM			
505320L078	NO		7-1193865-1, RNF-100-1/2-RD-STK-CS5318			
5053234078	NO		1-1193868-4, RNF-100-1/2-WH-SP			
5053244180	NO		4-1193869-0,,RNF-100-3/4-OSP, RNF-100-3/4-BK-SP			
505324M353	NO		7-1193870-6, RNF-100-3/4-BK-SP-CS5004			
5053252050	NO		8-1193871-6, RNF-100-3/4-RD-STK			
505326L134	NO		3-1193873-3, RNF-100-3/4-YO-STK-CS5529			
505329M158	NO		5-1193877-7, RNF-100-1-BK-SP-CS5529			
505334L190	NO		3-1193883-5, RNF-100-1-1/2-BKSTKCS5004			
5053352027	NO		6-1193883-8, RNF-100-1-1/2-RD-STK			
5053404021	NO		4-1193886-9, RNF-100-2-RD-SP			
5053434037	NO		3-1193887-0, RNF-100-2-WH-SP			
5053444034	NO		6-1193887-4, RNF-100-3-BK-SP			
505344L030	NO		1193888-2, RNF-100-3-BK-STK-CS7224			
5053492029	NO		1-1193889-0, RNF-100-4-BK-STK			
505349M027	NO		4-1193889-2, RNF-100-4-BK-SP-CS5529			
5053992015	NO		2-1193892-8, RNF-100-1/16-OR-STK			
5053994016	NO		3-1193892-1, RNF-100-1/16-OR-SP			
5054022018	NO		7-1193892-4, RNF-100-3/32-BN-STK			
5054032019	NO		9-1193892-1, RNF-100-3/32-OR-STK			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5054082014	NO		6-1193893-6, RNF-100-1/8-VT-STK			
5054104024	NO		1193894-6, RNF-100-3/16-BN-SP			
5054112017	NO		2-1193894-0, RNF-100-3/16-OR-STK			
5054134024	NO		5-1193894-6, RNF-100-1/4-BN-SP			
5054184014	NO		5-1193895-2, RNF-100-3/8-VT-SP			
5054224013	NO		2-1193896-1, RNF-100-1/2-VT-SP			
5054252011	NO		6-1193896-6, RNF-100-3/4-OR-STK			
5054294013	NO		2-1193897-9, RNF-100-1-VT-SP			
5054314013	NO		5-1193897-4, RNF-100-1-1/2-BN-SP			
505441M037	NO		8-1193898-0, RNF-100-1/4-GN-SP- CS5006			
505443M027	NO		6-1193899-9, RNF-100-3/8-GN-SP- CS5321			
5054532024	NO		2-1193900-4, RNF-100-1/16-GN-STK			
5054534025	NO		3-1193900-0, RNF-100-1/16-GN-SP			
5054554027	NO		5-1193900-5, RNF-100-1/2-GN-SP			
5055182014	NO		6-1193901-6, RNF-100-3/64-GN-STK			
5058682024	NO		5-1193905-0, VERSAFIT-3/32-0-STK			
5058726037	NO		6-1193906-3, VERSAFIT-3/16-0-1IN			
505872P034	NO		8-1193906-7, VERSAFIT-3/16-0-0.9375IN			
5058762031	NO		7-1193907-1, VERSAFIT-3/8-0-STK			
5058834003	NO		9-1193908-0, RNF-100-5-WH-SP			
5070014034	NO		1642707-1, RNF-100-3/64-CL-SP			
507002L038	NO		9-1193959-0, RNF-100-1/16-CL- STKCS6128			
5070032071	NO		1193960-3, RNF-100-3/32-CL-STK			
5070034072	NO		1-1193960-3, RNF-100-3/32-CL-SP			
507003M074	NO		8-1193960-5, RNF-100-3/32-CL-SP- CS5533			
507005B054	NO		9-1193962-5, RNF-100-3/16-CL			
5070074081	NO		2-1193964-9, RNF-100-3/8-CL-SP			
5070104071	NO		9-1193967-0,,RNF-100-1-X, RNF-100-1- CL-SP			
5070112068	NO		7-1193968-1, RNF-100-1-1/2-CL-STK			
507011L073	NO		4-1193969-3, RNF-100-1-1/2CLSTK- CS7250			
5070124025	NO		6-1193969-8, RNF-100-2-CL-SP			
507012M030	NO		9-1193969-8, RNF-100-2-CL-SP-CS7312			
507013L017	NO		2-1193970-9, RNF-100-3-CL-STK-CS7250			
5070144011	NO		4-1193970-2, RNF-100-4-CL-SP			
5072032002	NO		1-1193972-3, RNF-100-5-CL-STK			
507538-000	NO		1198905-4, V4-9.0-0-SP-SM			
5076682002	NO		1448810-3, DWP-125-3/4-0-STK			
508083P005	NO		3-1193994-7, VERSAFIT-NO.32-0-1.25IN			
508083P006	NO		3-1193994-8, VERSAFIT-NO.32-0-1IN			
508212-000	NO		1201714-1, HTCP-3/16-X-SP			
509329-000	NO		3-1194004-7, FPO-3/8-0-FSP			
5113132001	NO		1-1194019-9, FPO-3/8-X-STK			
514979-000	NO		1-1194045-5, DWP-125-1/4-0-5P12.0			
5200246028	NO		8-1194082-3, CRN-1/16-0-10MM			
5200266045	NO		7-1194083-9, CRN-3/8-0-2.5IN			
5200266053	NO		8-1194083-5, CRN-3/8-0-60MM			
5200266061	NO		1899222-8, CRN-3/8-0-80MM			
520029D010	NO		3-1194084-0, CRN-3/32-0-EXP			
520038D009	NO		9-1194084-8, CRN-1/8-0-EXP			
5200534015	NO		4-1194085-4, CRN-3/64-0-SP			
5202004018	NO		2-1194088-3, RT-3-NO.4-0-SP			
521277-000	NO		2-1194097-0, ATUM-16/4-0-STK-CS7335			
5241734002	NO		6-1194117-2, NETM1000-5-0-SP			
5250022017	NO		1-1194124-8, CRN-1/16-X-STK			
5250032015	NO		6-1194124-6, CRN-3/32-X-STK			
5250052007	NO		5-1194125-7, CRN-3/16-X-STK			
5250074017	NO		1194126-9, CRN-3/8-X-SP			
5260030007	NO		6-1194133-2, TC-CAPS-4005-8			
526003N006	NO		6-1194133-3, TC-CAPS-4005-8-CS5504			
526003N008	NO		6-1194133-4, TC-CAPS-4005-8CS5369			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
526003N009	NO		6-1194133-5, TC-CAPS-4005-8CS5414			
526003N010	NO		6-1194133-6, TC-CAPS-4005-8CS5655			
526003N011	NO		6-1194133-7, TC-CAPS-4005-8CS6994			
528976-000	NO		6-1198877-7, CDW-3/8-0-SP			
530219P009	NO		4-1194164-8, RNF-150-1/4-0-1.25IN			
5319594003	NO		3-1194177-0, MIL-LT-1/8-2-SP			
537019-000	NO		1194215-6, RNF-100-1/8-BK-30MM			
537057-000	NO		3-1194215-4, GPA-3/16-0-SP			
5402992002	NO		3-1194238-3, MIL-LT-3/32-9-STK			
540299M004	NO		3-1194238-7, MIL-LT-3/32-9-SP-CS7312			
543633P040	NO		2-1194264-6, SCT-NO.1-C2-0-50MM			
543633P050	NO		3-1194264-6, SCT-NO.1-E6-0-27MM			
543633P051	NO		3-1194264-7, SCT-NO.1-E6-0-50MM			
543633P052	NO		3-1194264-8, SCT-NO.1-E6-0-65MM			
543633P053	NO		3-1194264-9, SCT-NO.1-E6-0-75MM			
543633P055	NO		4-1194264-1, SCT-NO.1-E6-0-1200MM			
543633P059	NO		4-1194264-5, SCT-NO.1-B5-0-65MM			
543633P062	NO		4-1194264-8, SCT-NO.1-E6-0-25MM			
543633P064	NO		5-1194264-0, SCT-NO.1-E6-0-STK			
543633P070	NO		5-1194264-3, SCT-NO.1-E6-0-305MM			
543633P076	NO		5-1194264-7, SCT-NO.1-E6-0-101MM			
543633P079	NO		6-1194264-0, SCT-NO.1-E6-0-40MM			
543633P080	NO		6-1194264-1, SCT-NO.1-E6-0-20MM			
543633P081	NO		6-1194264-2, SCT-NO.1-E6-0-35MM			
543633P085	NO		6-1194264-6, SCT-NO.1-E6-0-45MM			
5450024026	NO		RW-175-1/16-X-SP			
5450032030	NO					
545003L063	NO		RW-175-3/32-X-STK-CS5772			
545003L146	NO		RW-175-3/32-X-STKCS5994			
545004D087	NO		4-1194279-3, RW-175-1/8-X-EXP			
5450052028	NO		RW-175-3/16-X-STK			
545005L164	NO		RW-175-3/16-X-STKCS5020			
545005P160	NO		RW-175-3/16-A1-X-30MM			
545008D031	NO		3-1194285-2, RW-175-1/2-X-EXP			
5450092014	NO		RW-175-3/4-X-STK			
545009D022	NO		2-1194286-3, RW-175-3/4-X-EXP			
5450552007	NO		RW-175-1-1/2-X-STK			
5450562001	NO		RW-175-2-X-STK			
5450842003	NO		RW-175-1/4-0-STK			
5451242007	NO		8-1194288-0, RT-218-3/64-9-STK			
545126M003	NO		9-1194288-8, RT-218-1/8-9-SP-CS6355			
5451314004	NO		1194289-8, RT-218-3/16-9-SP			
545132L002	NO		1-1194289-5, RT-218-1/4-9-STK-CS5971			
5451344004	NO		2-1194289-6, RT-218-1/2-9-SP			
545145-000	NO		5-1194289-2, RNF-100-1.154-CL-SPCS7628			
5451512002	NO		RW-175-3/16-0-STK			
5453724003	NO		1-1194292-7, RT-218-1/16-9-SP			
5454242002	NO		RW-175-1-0-STK			
548283-000	NO		6-1194315-6, RNF-100-1/8-WH-SP-CS5004			
550001D025	NO		6-1194327-7, SCL-1/8-1-EXP			
550002D016	NO		1194328-6, SCL-3/16-8-EXP			
5500112001	NO		2-1194330-2, SCL-3/8-9-STK			
550019P065	NO		1-1194331-4, SCL-3/8-A1-0-40MM			
550024P007	NO		3-1194331-7, SCL-1/8-A1-2-75MM			
550031L034	NO		4-1194333-3, SCL-1/2-0-STK-CS6401			
5500692005	NO		1324239-2, TAT-125-1/4-0-STK			
550071L018	NO		2-1194336-7, TAT-125-1/2-0-STK-CS6171			
550071L043	NO		2-1194336-8, TAT-125-1/2-0-STK-CS5451			
5500732014	NO		7-1194336-1, TAT-125-1-0-STK			
550073L021	NO		9-1194336-0, TAT-125-1-0-STK-CS7350			
550073L036	NO		9-1194336-2, TAT-125-1-0-STKCS5451			
550074L013	NO		1-1194337-5, TAT-125-1-1/2-0-STKCS6931			
550074L024	NO					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
			1-1194337-7, TAT-125-1-1/2-0-STKCS5451			
5500762006	NO		4-1194337-1, TAT-125-3-0-STK			
5500962003	NO		3-1194338-0, TAT-125-1/8-0-STK			
5500984015	NO		4-1194338-2, TAT-125-3/16-0-SP			
550105L021	NO		5-1194339-8, SCL-3/4-0-STK-CS5279			
550105P049	NO		6-1194339-5, SCL-3/4-A1-0-40MM			
550105P050	NO		6-1194339-6, SCL-3/4-A1-0-65MM			
550105P052	NO		6-1194339-7, SCL-3/4-A1-0-30MM			
550106D021	NO		1-1194340-7, SCL-1-0			
5501092019	NO		3-1194340-1,, SCL-1/4-0-STK			
5510060002	NO		7-1194354-6, PD-CAP-1/2-0			
5510060004	NO		7-1194354-8, PD-CAP-1/2-NOIR			
5510690002	NO		2-1194356-7, TAK-CAPS-1/8-N			
5510700002	NO		3-1194356-1, TAK-CAPS-3/16-N			
5515694001	NO		1448271-1,,UT12347-901, MIL-LT-NO.2-0-SP			
557224-000	NO		RW-175-3/32-X-STK-CS7403			
560393-000	NO		8-1194423-2, VERSAFIT-1/2-5-FSP			
5628512001	NO		1-1194447-5, FPO-1/16-4-STK			
5634732043	NO		4-1194451-4, ATUM-12/3-0-STK-CS7408			
573413-000	NO		9-1194551-0, CDW-24/6-0-STK			
575075J001	NO		1-1194564-2, V-28.0-0-FSP-SM			
576143P001	NO		2-1194571-4, FP21-1/2-9-STK			
5762674002	NO		1-1194572-1, RNF-150-1/8-0-SP			
5765954007	NO		3-1194574-8, RT-375-3/8-X-SP			
582275-000	NO		8-1194612-8, FPO-3/8-4-FSP			
5842292002	NO		6-1194626-7, MIL-LT-1/4-2-STK			
584229P008	NO		7-1194626-6, MIL-LT-1/4-A1-2-25MM			
5944092002	NO		3-1194699-2, FPO-2-0-STK			
5944094001	NO		3-1194699-3, FPO-2-0-SP			
5967494002	NO		7-1194719-2, FPO-3/64-2-SP			
596815-000	NO		2-1194720-3, VFP-3/4-4-FSP			
597098-002	NO		HRNF-125-10/97/NM			
598025-000	NO		6-1194728-1, VERSAFIT-1/8-0-0.75IN			
601587-000	NO		5-1194762-8, GPS-1-0-STK			
602185P002	NO		1194767-8, VFP-21-1/16-9-48IN-SM			
602739-000	NO		9-1194770-3, RNF-100-2-BK-SP-CS7443			
603316-3	NO		"098017-000", "DWP-125-1/8-0-10P12.0"			
603316-4	NO		"442952P014", "DWP-125-1/8-0-STK"			
603317-4	NO		"507668P010", "DWP-125-3/4-0-STK"			
603322-1	NO		"594727P008", "VFP-21-1/16-0-STK-SM"			
603322-3	NO		"594727J002", "VFP-21-1/16-0-SP-SM"			
603323-1	NO		"215589P008", "VFP-21-3/32-0-48IN-SM"			
603323-5	NO					
603323-6	NO					
603349-1	NO		"737104-000", "FP21-1-X-48IN"			
6054654001	NO		5-1194790-9, FPO-3/64-8-SP			
605803M017	NO		1-1194793-1, MIL-LT-3/8-0-SP-CS7312			
605803P011	NO		1-1194793-4, MIL-LT-3/8-A1-0-25MM			
605803P013	NO		1-1194793-6, MIL-LT-3/8-A1-0-45MM			
608027-000	NO		5-1194809-3, ATUM-52/13-0-SP-CS6877			
613615P030	NO		2-1194851-5, FLT-NO.1-C2-0-50MM			
613615P033	NO		2-1194851-8, FLT-NO.1-C5-0-50MM			
613615P035	NO		3-1194851-0, FLT-NO.1-C6-0-50MM			
618235-000	NO		RW-175-1/16-X-STK-CS5994			
620667-000	NO		4-1194904-3, GPS-1/2-0-STK			
6264044003	NO		3-1194961-1, VERSAFIT-3/4-2-SP			
636501-000	NO		RW-175-3/64-X-STK-CS5020			
638855N002	NO		6-1195049-4, SST-6-03/226			
639508J001	NO		7-1195054-6, VERSAFIT-3/64-2-SP-SM			
641576-000	NO		5-1200215-3, RNF-100-1/2-BK-440MM			
641805-000	NO		4-1195072-2, ATUM-32/8-0-STK-CS7335			
642293-000	NO		1195076-9, SCL-1/4-2-STK			
6465212003	NO		114517-01,1448193-1, DWP-125-1/2-0-STK			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
654193-000	NO		6-1195161-8, RNF-100-1-RD-FSP			
6597692001	NO		6-1195200-5, MIL-LT-3/32-2-STK			
663673-000	NO		6-1195230-4, FPO-3/4-2-FSP			
6641114002	NO		7-1195233-8, TAT-125-HW-375-X-SP			
664303M001	NO		1195235-3, FP21-1-0-SP			
664851-000	NO		8-1195238-3, GPA-1/2-0-STK			
665491-000	NO		4-1195243-7, VFP-1-6-SP			
6774974002	NO		7-1195326-9, CGPE-105-3/32-0-SP			
6790932001	NO		2-1195338-5, FPO-3/8-6-STK			
681506-000	NO		4-1197886-0, V4-2.5-9-SP-SM			
683027-000	NO		5-1197886-2, ES1000-NO.2-B9-X-COIL			
687401J001	NO		2-1195398-4, V2-28.0-0-FSP-SM			
688375N001	NO		1195407-7, SAS-160-1-1124-8D-CS5420			
689829J002	NO		1195417-9, VFP-21-2-0-SP-SM			
691648-000	NO		4-1197962-9, TC-CAPS-4001-9-CS7475			
700954-000	NO		6-1199106-3, FPO-1/2-1-SP			
702470L027	NO		4-1195512-8, ATUM-52/13-0-STK-CS6877			
7028556008	NO		2-1195515-8, RT-375-1/16-X-10MM			
703145-001	NO		"3-1195517-5"			
704619-000	NO		1195527-4, VERSAFIT-3/16-9-SP-CS7532			
716209T001	NO		8-1195603-0			
7191294002	NO		8-1195624-7, VERSAFIT-1-1/2-7-SP			
722022-000	NO		6-1199502-5, RT-3-NO.1-0-COIL			
728737-000	NO		2-1195694-9, MIL-LT-3/8-9-FSP			
729259-001	NO		"8-1195697-0"			
7348194001	NO		9-1195738-8, RT-220-1/8-9-SP			
737004-000	NO		8-1197987-4, RNF-100-1-CL-FSP-CS7312			
738807-000	NO		3-1195767-3, AP2000-108-0-272MM			
7449274003	NO		9-1195810-1, MIL-LT-3/64-4-SP			
748922-000	NO		1-1199184-8, RP-4800-NO.3-9-SP			
753817-000	NO		5-1195876-4, LMX3500-30/10-0-30MM			
753972-000	NO		5-1199192-9, RP-4800-NO.10-0-STKCS7710			
755533-000	NO		8-1195888-8, VERSAFIT-1/2-6-FSP			
756061-000	NO		4-1195892-8, RNF-100-1-BU-FSP			
7580146023	NO		5-1195906-5, DWP-125-3/8-0-1.5IN			
760779N002	NO		6-1195925-8, SST-48-13/226			
761263-000	NO		1-1195929-3, SCL-3/16-0-BULK-COIL			
761895-000	NO		4-1195933-8, GPA-3-0-STK			
7629592001	NO		1195941-1, FPO-1/4-9-STK			
768955-000	NO		9-1195991-6, CDW-16/4-0-STK			
774257-000	NO		5-1196029-3, RNF-100-3/8-GN-FSP			
778153-000	NO		9-1196056-8, VERSAFIT-3/4-0-FSP-SM			
778961N002	NO		8-1196062-3, SAS-250-1-1124-8D-CS5420			
7824712001	NO		5-1196077-3, FPO-1/16-9-STK			
7903976003	NO		4-1196122-1, LMX3500-25/8-0-30MM			
792673-000	NO		1-1196138-8, VERSAFIT-1-2-FSP			
8003012003	NO		2-1196188-2, MIL-LT-3/16-2-STK			
801464P075	NO		1196197-6, ATUM-16/4-0-40MM			
805411-000	NO		4-1196225-9, AP2000-108-0-108MM			
819639M001	NO		4-1196387-7, FP21-1-1/2-0-SP			
821380-000	NO		1-1199204-6, V2-7.0-4-40MM			
828255-000	NO		2-1196468-2, ES2000-NR.2-B9-0-50MM			
8430574002	NO		5-1196576-4, FPO-3-0-SP			
8453334002	NO		5-1196594-2, FPO-3/32-9-SP			
8509970001	NO		9-1196634-7, SAS-115-1-1017-1X			
8515104003	NO		9-1196638-1, VERSAFIT-1-1/2-6-SP			
853963H003	NO		2-1196657-7, HIX-VW1-1/8-0-STK-SM			
859782-000	NO		5-1201231-0, QS1500-NO.2-F6-0-60MM			
866121-000	NO		3-1196744-0, ES1000-NO.1-C1-X-80MM			
8694194003	NO		7-1196767-6, MIL-LT-3/64-0-SP			
8699472002	NO		6-1196771-1, MIL-LT-2-0-STK			
8726032002	NO		1-1196790-4, RT-375-3/4-X-STK			
8777354001	NO		1-1196826-2, VFP-1/4-9-SP			
878771M002	NO		1-1196841-2, FP21-1/16-0-SP			
880523-000	NO		RW-175-3/16-X-SP-CS5405			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
881723J001	NO		7-1196863-4, V2-14.0-0-FSP-SM			
881901B001	NO		2-1196865-5, RNF-100-0.160-CL			
883974D004	NO		1196880-8, ATUM-4/1-0-EXP			
888685J001	NO		5-1196913-8, VERSAFIT-1-9-SP-SM			
893778-000	NO		1-1200436-7, HSP2000-NO.4-N9-0-STK			
8938892001	NO		2-1196952-1, FPO-2-X-STK			
894449-000	NO		2-1196956-2, SGNFSST-30-0-28IN/NM/NX			
895231P008	NO		5-1196961-1, SCT-NO.0-E8-0-STK			
8954932001	NO		3-1196963-6, FPO-3/32-0-STK			
8974852001	NO		1-1196977-3, FPO-1/8-X-STK			
899745-000	NO		RW-175-1/4-X-STK-CS6053			
8998592002	NO		8-1196994-1, MIL-LT-3/32-3-STK			
9004894003	NO		RW-175-030-X-SP			
909677-000	NO		9-1197065-3, AP2000-107-0-130MM			
9170152001	NO		1-1197118-5, DWP-125-2-0-STK			
917015P002	NO		1-1197118-7, DWP-125-2-0-48IN			
9184154003	NO		1448444-4, MIL-LT-3/4-0-SP			
922030-001	NO		1-1197154-6, SST-27-20/FR/RED/97			
923757-000	NO		2-1197166-6, VFP-1-4-FSP			
9243974002	NO		6-1197170-7, NETM2000-12-0-SP			
9261394001	NO		1197183-5, FPO-1/4-6-SP			
929251-000	NO		4-1197204-5, DWP-125-1/2-0-3P12.0			
929859J001	NO		7-1197208-7, V4-9.0-0-FSP-SM			
933846-000	NO		1199858-4, HSP2000-NO.2-N7-0-150MM			
934669P014	NO		3-1197242-7, DWP-125-1-0-40MM			
940387-000	NO		9-1197281-2, VERSAFIT-3X-3/8-0-1IN			
947874-000	NO		1-1197962-1, VERSAFIT-1/16-N4-0-SP			
9496376003	NO		3-1197346-6, LMX3500-52/18-0-40MM			
951101-000	NO		1-1197355-8, RNF-100-3/16-RD-SP-CS7554			
9550856026	NO		5-1197394-0, TAK-SLEEVE-NO.1-X-1IN			
9550856027	NO		5-1197394-1, TAK-SLEEVE-NO.1-X-3IN			
955297-000	NO		9-1197395-7, RNF-100-3/16-WH-SP-CS7554			
9668274002	NO		8-1197475-3, VERSAFIT-1-1/2-0-SP			
967231N002	NO		1197479-2, SST-48-27/226			
9717172001	NO		1-1197511-4, FPO-2-4-STK			
973459N002	NO		"7-1197523-7"			
975745-000	NO		1-1197540-4, SRPT-3/16-X-STK			
977872-000	NO		9-1199626-3, SGNFSST-03-0-33IN/NM			
985463-000	NO		1197613-4, FPO-1-1/4-X-STK			
9867312001	NO		2-1197621-8, FPO-2-6-STK			
9904532001	NO		7-1197658-5, FPO-3/32-X-STK			
992245-000	NO		RW-175-1/4-X-STK-CS5772			
992407-000	NO		1-1197676-3, FPO-3/8-5-FSP			
999221-000	NO		3-1197725-2, RNF-100-1/4-GN-SP-CS7387			
9996214002	NO		1-1197728-7, FPO-1/2-9-SP			
A04375-000	NO		2-1201147-4, ES1000-KIT3-REFILL			
A04704-000	NO		9-1202115-0, FL2500-NO.3-J1-0-35MM			
A12807-000	NO		1200902-3, VERSAFIT-3X-3/8-7-RSP			
A21213-000	NO		5-1201860-8, FL2500-NO.4-J2-0-40MM			
A24264-000	NO		VERSAFIT-3/16-0-40MM			
A24404-000	NO		1202128-2, V2-2.0-0-SP			
A26491-000	NO		6-1201784-7, V2-2.5-1-SP-SM			
A28445-000	NO		8-1202111-1, VERSAFIT-3/4-0-1.181IN			
A40858-000	NO		5-1201680-6, V4-4.0-6-SP-SM			
A48215-000	NO		RW-175-1/2-X-STK-CS7435			
A52739-000	NO		5-1200082-7, VERSAFIT-3/4-0-FSP-CS7646			
A61809-000	NO		8-1201874-8, AP2000-106-0-70MM			
A64673-000	NO		3-1201906-5, V2-1.0-8-SP-SM			
A66551-000	NO		1200741-5, RNF-100-MINI-SPL-1/16-BK			
A75248-000	NO		8-1200532-1, SCL-1/8-1-STK-CS7387			
A75427-000	NO		1-1200919-7, VERSAFIT-3/8-0-50MM			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
A82691-000	NO		6-1200721-2, VERSAFIT-3/8-KT2-REFILL			
A85565-000	NO		3-1201906-7, V2-1.0-2-SP-SM			
A85745-000	NO		1-1201441-7, V4-0.6-0-SP			
A85761-000	NO		1-1201251-2, TAT-125-1/2-0-STK-CS7350			
A85870-000	NO		3-1201461-2, ES1000-NO.4-F3-X-30MM			
A87326-000	NO		8-1202161-4, RNF-100-3-BK-STK-CS7250			
A95354-000	NO		8-1199983-5, SGHRHF-175FR-0-23IN			
A98179-000	NO		3-1201562-7, VERSAFIT-1/4-9-2IN			
A99658-000	NO		1-1202112-3, RNF-100-3/16-RD-1IN			
BM9156-000	NO		MIL-LT-1/2-5-FSP-CS7210			
C02828-000	NO		8-1201509-8, VERSAFIT-5/8-3-SP			
C11031-000	NO		9-1201869-2, V2-3.5-5-SP-SM			
C13345-000	NO		6-1201690-4, MIL-LT-1/2-4-FSP-CS7223			
C17600-000	NO		2-1200741-5, VERSAFIT-MINI-SPL-1/8-BK			
C20744-000	NO		5-1201707-8, ES1000-NO.2-B9-X-45MM			
C21606-000	NO		5-1200701-1, RNF-100-3/16-WH-STKCS5592			
C27598-000	NO		7-1201782-3, FL2500-NO.4-J2-0-30MM			
C27689-000	NO		2-1200812-2, FL2500-NO.3-C7-0-50MM			
C29958-000	NO		4-1201794-8, VERSAFIT-1/16-1LT-SP			
C30357-000	NO		7-1199656-0, RNF-100-1/2-BK-FSP-CS5004			
C33328-000	NO		3-1201906-9, V2-1.5-5-SP-SM			
C33628-000	NO		1-1201459-9, AP2000-106-0-1823MM			
C37332-000	NO		2-1201432-7, RT-218-3/32-9-SP-CS6396			
C41287-000	NO		3-1200436-9, RNF-100-3/16-BK-0.875IN			
C42951-000	NO		RW-175-0.660-X-25MM			
C44297-000	NO		9-1200573-1			
C70122-000	NO		1201753-5, RP-4800-NO.3-0-SP-CS7710			
C87605-000	NO		8-1200721-3, VERSAFIT-1/4-KT2-REFILL			
C96329-000	NO		4-1201906-3, V2-6.0-4-SP-SM			
CA0767-000	NO		DWP-125-1-0-2IN			
CA3276-000	NO		CRN-3/8-0-50MM			
CA3626-000	NO		VERSAFIT-3/16-0-2.078IN			
CA4282-000	NO		"RW-175-3/16-X-STK-CS5772"			
CA8174-000	NO		5-1899136-1, RT-220-1/16-9-SP			
CA8791-000	NO		ES2000-NO.4-B7-0-203MM			
CB0934-000	NO		"FL2500-NO.4-J2-0-55MM", "2-1899832-2"			
CB1869-000	NO		RNF-100-1/2-BK-4.5IN			
CB5000-000	NO					
CB5001-000	NO		"2-1899832-6"			
CB5015-000	NO		1899279-5, BSTS-07X4			
CB5021-000	NO					
CB5024-000	NO		"3-1195009-9"			
CB5032-000	NO		"6-1899832-1"			
CB5033-000	NO		"2-1196945-9"			
CB5035-000	NO		"BSTS-13X25FR/NM", "6-1899832-3"			
CB5037-000	NO		"8-1899832-1"			
CB5045-000	NO		"8-1899832-6"			
CB5053-000	NO		"BSTS-17X4/CL", "8-1899832-8"			
CB5059-000	NO		"8-1899832-9"			
CB5087-000	NO		9-1899207-4, HF-07FRX4			
CB5091-000	NO		"1-1899833-5"			
CB5096-000	NO		"1-1899833-7"			
CB5116-000	NO					
CB5118-000	NO					
CB5121-000	NO					
CB5123-000	NO					
CB5129-000	NO		"HRHF-250FR-10/97"			
CB5133-000	NO					
CB5146-000	NO					
CB5153-000	NO					
CB5163-000	NO					
CB5164-000	NO					
CB5168-000	NO					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB5173-000	NO					
CB5178-000	NO					
CB5179-000	NO					
CB5184-000	NO					
CB5187-000	NO					
CB5189-000	NO					
CB5190-000	NO					
CB5191-000	NO		"SGNFSST-03-0-33IN/NM"			
CB5193-000	NO					
CB5194-000	NO					
CB5195-000	NO					
CB5196-000	NO		"SGNFSST-04-2-33IN/NM"			
CB5199-000	NO					
CB5202-000	NO					
CB5204-000	NO					
CB5205-000	NO					
CB5208-000	NO					
CB5210-000	NO					
CB5214-000	NO					
CB5219-000	NO					
CB5221-000	NO		"SGNFSST-30-2-51IN/NM"			
CB5226-000	NO					
CB5246-000	NO		"SGSST-11FR-4-51IN/NM"			
CB5258-000	NO					
CB5284-000	NO					
CB5288-000	NO					
CB5289-000	NO		5-1899230-3, SST-12-17/FR/97			
CB5317-000	NO					
CB5329-000	NO					
CB5330-000	NO					
CB5336-000	NO					
CB5337-000	NO					
CB5342-000	NO					
CB5349-000	NO					
CB5351-000	NO					
CB5354-000	NO					
CB5355-000	NO					
CB5363-000	NO					
CB5372-000	NO		"SST-48-15/97"			
CB5387-000	NO					
CB5412-000	NO					
CB5418-000	NO					
CB5422-000	NO					
CB5425-000	NO					
CB5426-000	NO					
CB5434-000	NO		"2-1899833-7"			
CB5626-000	NO		FL2500-NO.1-18-0-25MM			
CB8769-000	NO		"VERSAFIT-3/8R-0-60IN"			
CC4714-000	NO					
CF2744-000	NO					
CF2745-000	NO					
CF3733-000	NO					
CF3962-000	NO					
CF4690-000	NO		RNF-100-1/2-BK-1.5IN			
CF6152-000	NO					
CF7706-000	NO		5-1899235-7, HRHF-200FR-10/97/NM			
CH25686001	NO		CRN-3/8-0-170MM, 6-1899585-8			
CH35622001	NO		2-1899614-3, CRN-1/2-0-MS-STK			
CJ3835-000	NO		"SGSST-17FR-2-51IN/NM"			
CJ3944-000	NO		"SSTS-2-58"			
CJ3948-000	NO		"SSTS-3-58-NV"			
CJ3950-000	NO					
CJ4564-000	NO		"VERSAFIT-1-0-STK-CS5438"			
CJ5292-000	NO		"FL2500-NO.0-17-0-40MM", "4-1899833-8"			
CJ9434-000	NO		"SST-48-15/FR/YLW/97"			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CJ9638-000	NO		"VERSAFIT-1/16-0-0.32IN"			
CL0860-000	NO		"ES-CAP-NO.5-H1-X-35MM"			
CL1264-000	NO					
CL2370-000	NO		"DWP-125-0.450-0-55MM"			
CL3457-000	NO		"VERSAFIT-3/16-0-1.5IN-SM"			
CL4285-000	NO		"RNF-100-3/32-BK-STK-CS5529"			
CL4406-000	NO		"QS1500-NO.4-F8-0-200MM"			
CL7083-000	NO		"RW-175-1/8-X-STK-CS7212"			
CL7864-000	NO		"RNF-100-1/2-RD-FSP-CS5004"			
CL9347-000	NO		"ATUM-8/2-0-STK-CS7335"			
CM0278-000	NO		"CRN-3/8-0-100MM"			
CM1082-000	NO		"RW-175-0.625-X-STK"			
CM1473-000	NO		"VERSAFIT-3X-3/8-0-SP-CS5920"			
CM1712-000	NO		"RP-4800-NO.1-9-STK-CS8762"			
CM2111-000	NO		"ATUM-24/8-0-3.5IN", "1899833-9"			
CM2696-000	NO		"DWP-125-3/8-0-1.25IN"			
CM3867-000	NO		"ES2000-NO.4-A1-0-48MM"			
CM4449-000	NO		"1-1899417-2", "DWP-125-1/8-0-10MM"			
CM8507-000	NO					
CM8714-000	NO					
CM9488-000	NO					
CM9611-000	NO		RNF-100-1/16-BK-110MM			
CM9713-000	NO					
CN0387-000	NO					
CN2133-000	NO					
CN2235-000	NO					
CN2275-000	NO		HRHF-250CL-10-CS8980			
CN3422-000	NO					
CN3423-000	NO					
CN3523-000	NO					
CN3839-000	NO		SCL-3/8-2-STK-CS7387			
CN5309-000	NO		RNF-100-3/16-BK-50MM			
CN7178-000	NO					
CN7827-000	NO		VERSAFIT-3/32-9-SP-CS5438			
CN8371-000	NO		RNF-100-3/8-WH-SP-CS5004			
CN8527-000	NO					
CP0295-000	NO		6-1899833-7, RNF-100-1/4-BK-4IN			
CP0425-000	NO					
CP0902-000	NO					
CP0963-000	NO		FL2500-NO.1-I8-0-280MM			
CP2329-000	NO					
CP2435-000	NO		AP2000-15-0-104MM			
CP3361-000	NO		DWP-125-1/4-0-0.30IN-T.031			
CP3634-000	NO					
CP3790-000	NO					
CP3791-000	NO					
CP3796-000	NO					
CP3797-000	NO					
CP3798-000	NO					
CP4349-000	NO					
CP4797-000	NO		SCT-NO.4-E2-0-95MM			
CP9374-000	NO					
CP9849-000	NO					
CR0243-000	NO					
CR0658-000	NO		9-1899566-9, ATUM-12/3-0-24IN			
CR0799-000	NO					
CR1576-000	NO		TAT-125-1/2-0-1.25IN			
CR2073-000	NO					
CR2206-000	NO		"8-1899572-8", "ES2000-NO.1-C1-0-27MM-SH"			
CR2448-000	NO					
CR2746-000	NO					
CR3609-000	NO					
CR3611-000	NO					
CR3613-000	NO					
CR3823-000	NO		HRSR-125FR-18/NM			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CR8169-000	NO					
CR8359-000	NO					
CR9723-000	NO					
CS0778-000	NO					
CS0993-000	NO					
CS2514-000	NO		"SCT-NO.1-E6-0-10MM", "6-1899831-1"			
CS6783-000	NO					
CS7065-000	NO					
CS8789-000	NO					
CS8792-000	NO		HF-04FRX4/NM			
CS9310-000	NO					
CS9722-000	NO					
CS9986-000	NO		"9-1899641-7"			
CU0518-000	NO					
CU1635-000	NO					
CU1958-000	NO		RW-175-1/2-X-STK-CS5405			
CU2818-000	NO		ES2000-NO.2-B9-0-130MM			
CU3264-000	NO					
CU3549-000	NO		RNF-100-3/16-BK-60MM			
CU4597-000	NO		9-1899652-2, ES1000-NO.4-B7-X-70MM			
CU5165-000	NO		HRHF-300FR-11/97			
CU6276-000	NO		RNF-100-1/4-BK-38MM			
CU6473-000	NO		TAT-125-1-1/2-2-STK			
CU9961-000	NO					
CV3261-000	NO					
CV3266-000	NO		RW-175-3/32-0-SP			
CV3269-000	NO					
CV3271-000	NO					
CV3280-000	NO					
CV3285-000	NO					
CV3286-000	NO					
CV3288-000	NO					
CV3289-000	NO					
CV3290-000	NO					
CV3296-000	NO					
CV3299-000	NO		RW-175-3/64-X-STK			
CV3305-000	NO					
CV3309-000	NO					
CV3311-000	NO					
CV3321-000	NO					
CV3329-000	NO					
CV3333-000	NO					
CV3336-000	NO					
CV3338-000	NO					
CV3344-000	NO		RW-175-0.300-X-STK			
CV3351-000	NO					
CV3358-000	NO					
CV3359-000	NO					
CV3364-000	NO					
CV3375-000	NO					
CV3380-000	NO					
CV3386-000	NO					
CV3390-000	NO					
CV3396-000	NO					
CV3398-000	NO					
CV3404-000	NO					
CV3406-000	NO					
CV3408-000	NO					
CV3410-000	NO					
CV3415-000	NO					
CV3426-000	NO					
CV3433-000	NO		RW-175-1/8-X-1IN			
CV3434-000	NO					
CV3443-000	NO					
CV3444-000	NO					
CV3452-000	NO					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CV4190-000	NO					
CV4191-000	NO					
CV4198-000	NO					
CV4204-000	NO					
CV4210-000	NO					
CV4212-000	NO					
CV4214-000	NO					
CV4219-000	NO					
CV4357-000	NO		HT-200-1/8-X-SP			
CV4359-000	NO		HT-200-1/4-X-SP			
CV4363-000	NO		HT-200-1-X-SP			
CV6463-000	NO					
CV6464-000	NO					
CV6676-000	NO		RNF-100-1/2-BK-640MM			
CV7318-000	NO		VERSAFIT-1/4-4-1IN			
CW0407-000	NO		DWP-125-1-0-100MM			
CW2773-000	NO					
CW2834-000	NO					
CW3316-000	NO		2-1899776-3, ES1000-NO.3-B8-X-48MM			
CW4865-000	NO		RNF-100-1/2-RD-40MM			
CW6497-000	NO		VERSAFIT-3/8-0-95MM			
CW7197-000	NO					
CW7383-000	NO		SCL-3/4-2-6IN			
CW8843-000	NO		DWP-125-3/16-0-0.938IN			
CX0355-000	NO					
CX0817-000	NO		"RNF-100-3/32-BK-3IN", "7-1899832-0"			
CX0819-000	NO		"RNF-100-3/16-BK-3IN", "6-1899832-7"			
CX0828-000	NO		"RNF-100-1/16-BK-4IN", "5-1899832-3"			
CX0829-000	NO		"RNF-100-3/32-BK-4IN", "5-1899832-2"			
CX0830-000	NO		"RNF-100-1/8-BK-4IN", "5-1899832-1"			
CX0833-000	NO		"RNF-100-3/8-BK-4IN", "3-1899832-9"			
CX1665-000	NO		FL2500-NO.2-I9-0-40MM			
CX1883-000	NO					
CX2365-000	NO		"RNF-100-1/4-WH-SP-CS7674", "4-1899832-0"			
CX4688-000	NO					
CX5930-000	NO					
CX6025-000	NO					
CX6765-000	NO					
CX7481-000	NO		ES1000-NO.2-B9-X-32MM, 5-1899719-4			
CX7757-000	NO					
CX8434-000	NO		"1-1194385-7"			
CX8815-000	NO					
CY0589-000	NO		RNF-100-0.874-PGY-SP			
CY2584-000	NO					
CY2585-000	NO					
CY2826-000	NO					
CY4648-000	NO					
CY6704-000	NO					
CY6790-000	NO		CRN-3/64-0-MS-SP			
CY6792-000	NO		"CRN-1/16-0-MS-STK", "4-1899832-6"			
CY7414-000	NO		SCT-NO.3-E3-0-20MM			
CY8295-000	NO					
CY8415-000	NO					
CY9277-000	NO		RNF-100-3/16-BK-40MM			
CY9637-000	NO		TAT-125-1-6-STK			
CZ0181-000	NO		SCT-NO.5-Z4-0-STK			
CZ0223-000	NO					
CZ0224-000	NO					
CZ0538-000	NO					
CZ0539-000	NO					
CZ1014-000	NO		"DWP-125-1/2-2-60MM", "3-1899832-4"			
CZ2165-000	NO		CRN-3/64-0-MS-125MM			
CZ2993-000	NO		RP-4800-NO.3-2-STK			
CZ6033-000	NO		SST-3-11/FR/97			
CZ6253-000	NO					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CZ6522-000	NO		BSTS-11-CL-7.25IN			
CZ7155-000	NO					
CZ8200-000	NO		VERSAFIT-3/4-0-2.25IN			
CZ9706-000	NO		TAK-SLEEVE-1/8-X-BULK-SP			
D04950-000	NO		3-1200816-9, ES2000-NO.1-C1-0-38MM			
D06744-000	NO		3-1200967-4, SGSST-AMP950-6-04FR-33IN			
D13064-000	NO		1199658-7, V2-5.0-4-40MM			
D14887-000	NO		2-1200478-7, RNF-100-3/16-BK-SP-CS7387			
D21933-000	NO		3-1201854-0, V2-4.0-3-SP-SM			
D27408-000	NO		9-1200979-5, ES1000-HW-NO.3-M8-X-45MM			
D27573-000	NO		1200590-5, VERSAFIT-3/8-KT1-REFILL			
D28520-000	NO		V2-4.0-1-SP-SM			
D32701-000	NO		4-1201906-7, V2-8.0-6-SP-SM			
D38564-000	NO		7-1202000-9, V2-15.0-9-FSP-SM			
D41363-000	NO		4-1201792-6, V2-18.0-2-FSP-SM			
D48425-000	NO		7-1202052-3, RNF-100-NO.342-CL-STK			
D49340-000	NO		RW-175-3/4-X-STK-CS5654			
D50412-000	NO		8-1199628-9, SGSST-03FR-0-33IN/NM			
D55991-000	NO		3-1201923-1, RNF-100-3/16-BK-SP-CS7807			
D57591-000	NO		5-1200741-1, VERSAFIT-MINI-SPL-3/8-BK			
D58196-000	NO		9-1202115-6, FL2500-NO.2-I9-0-50MM			
D60073-000	NO		9-1202128-0, V2-6.0-0-SP			
D61513-000	NO		3-1200680-7, SGBSTS-17X20FR			
D61513-001	NO		4-1200690-9			
D68311-000	NO		9-1202026-1, RNF-100-1/4-BK-SP-CS7797			
D70463-000	NO		2-1199839-0, ES1000-NO.2B9X125MMCS7721			
D92011-000	NO		9-1202099-4, RNF-100-3/16-CL-1.6IN			
D93622-000	NO		4-1201775-4, V2-10.0-8-FSP-SM			
E07303-000	NO		3-1200881-6, SCL-3/8-0-STK-CS5279			
E11083-000	NO		1-1200396-4, HPFL-1/4-0-SP			
E11218-000	NO		6-1201550-3, HTCP-3/4-X-SP			
E16234-000	NO		6-1200741-6, DWP-125-3/4-2-150MM			
E18325-000	NO		6-1201431-3, V4-4.0-2-SP-SM			
E18900-000	NO		8-1201784-3, V2-8.0-8-FSP-SM			
E20277-000	NO		5-1201906-5, V2-14.0-4-SP-SM			
E21086-000	NO		8-1200998-3, HPFL-3X-1-0-SP-CS6660			
E25409-000	NO		9-1201751-1, VERSAFIT-3/8-0-525MM			
E37108-000	NO		3-1201663-5, HTCP-1/4-X-SP			
E42951-000	NO		1-1201753-8, RP-4800-NO.8-0-SP-CS7710			
E45033-000	NO		1-1201261-8, FPO-4X-NO.10-0-SP			
E46480-000	NO		2-1201828-0, V4-25.0-0-FSP-SM			
E54544-000	NO		1202071-1, TC-CAPS-4005-8-CS7815			
E54656-000	NO		9-1200589-6, RT-218-1/16-9-SP-CS7747			
E60872-000	NO		8-1201039-7, ES2000-NO.3-B8-0-70MM			
E62069-000	NO		8-1200527-7, TAT-125-3/4-0-STK-CS7373			
E62580-000	NO		9-1201895-6, TAT-125-3/4-0-2.5IN			
E72106-000	NO		1448193-8, DWP-125-1/2-0-80MM			
E77532-000	NO		9-1201775-8, VERSAFIT-3/8-0-292MM			
E80582-000	NO		6-1201191-4, TAT-125-3/4-0-STK-CS7350			
E82142-000	NO		2-1200874-1, HSP2000-NO.4-N9-0-150MM			
E83921-000	NO		3-1201698-9, HTCP-1/8-X-SP			
E92029-000	NO		1200589-3, RT-218-3/8-9-SP-CS7747			
E94267-000	NO		4-1202129-0, V2-12.0-0-FSP			
E95708-000	NO		8-1199962-6, RNF-100-3/8-BK-STK-CS7728			
EF4019-000	NO					
EF5319-000	NO					
EF9828-000	NO					
EG0480-000	NO					
EG1346-000	NO		VERSAFIT-1/4-2-1IN			

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EG1637-000	NO					
EG3301-000	NO		"5-1899836-5"			
EG3753-000	NO					
EG3754-000	NO					
EG3757-000	NO					
EG3762-000	NO					
EG4286-000	NO					
EG4289-000	NO					
EG4295-000	NO					
EG4905-000	NO		SST-48-03/FR/97/RED			
EG5520-000	NO					
EG5525-000	NO					
EG5526-000	NO					
EG6814-000	NO					
EG7797-000	NO		DWP-125-3/4-0-55MM			
EG9829-000	NO		ES2000-NO.2-B9-0-127MM			
EG9837-000	NO		ES2000-NO.3-B8-0-132MM			
EG9839-000	NO		ES2000-NO.4-B7-0-85MM			
EH1364-000	NO					
F03430-000	NO		5-1201739-8, RT-218-3/32-9-STK-CS5971			
F07939-000	NO		4-1201692-0, V2-4.0-5-SP-SM			
F14541-000	NO		3-1200984-3, ES-CAP-HW-NO.3-X-45MM-ST			
F15041-000	NO		2-1201426-4, V2-4.0-2-SP-SM			
F21924-000	NO		110065,,1448193-7, DWP-125-1/2-0-70MM			
F26770-000	NO		3-1201758-8, V2-10.0-5-FSP-SM			
F26811-000	NO		5-1201666-6, RNF-100-1/2-BK-690MM			
F34451-000	NO		1-1201234-6, FPO-4X-NO.2-0-SP			
F34465-000	NO		5-1200761-4, FL2500-NO.2-I9-0-30MM			
F34470-000	NO		2-1200527-9, SCL-3/4-4-STK-CS7387			
F34682-000	NO		8-1201755-5, RNF-100-3/4-WH-STK-CS5592			
F34921-000	NO		3-1201367-9, RNF-150-3/16-0-20MM			
F37063-000	NO		1-1200590-3, VERSAFIT-1/4-KT1-REFILL			
F41454-000	NO		7-1201147-5, DWP-125-1/2-KIT3-REFILL			
F66231-000	NO		6-1202129-5, V2-16.0-0-FSP			
F66623-000	NO		7-1201149-2, DWP-125-1-KIT3-REFILL			
F78253-000	NO		7-1201407-4, V2-5.0-9-SP-SM			
F84496-000	NO		1200968-7, TPEN-NR7-0-STK-CS7760			
F99253-000	NO		RNF-100-1/2-BK-3IN			