



07-Jul-2016

PCN #:P-16-013275

Subject:Manufacturing Location Change for IDENT made at Menlo Park

Description of Change: Manufacturing location change. Following Part Numbers will be transferred from Menlo Park to Redwood City.

Reason: This notification is to inform our customers that TE Connectivity is closing our facility in Menlo Park California, USA and moving the production of ADM Elastomeric Tubing and IDENT to our Redwood City California, USA facility. The sites are only 4 miles apart and the current manufacturing operations will remain the same after the migration. This includes the same workforce, materials, and equipment. The transfer will start in October 2016 with the targeted completion in 2018. TE reserves the right to provide TE qualified products from either site both during and after the transfer period, on stocked items. To ensure a successful and seamless transition, TE will perform validation testing at Redwood City as the production migrates. Please note that some of these products are currently made in TE locations other than Menlo Park. This notification does not apply to you if you currently receive these products from a manufacturing site other than Menlo Park.

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:17-Oct-2016

Implementation Date:17-Oct-2016

Product Affected

CB7762-000

(Alias Part Numbers:

"RPS-1K-6-250/2.0-S3-9")

9062290001

Product Affected

(Alias Part Numbers:

"8-1197040-8"

"RPS-8-4/2.0-S1-9")

CL0169-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-2-CS8766")

0618750001

(Alias Part Numbers:

"1190468-4"

"HT-SCE-1/2-2.0-S1-0")

405309-000

(Alias Part Numbers:

"8-1193058-4"

"D-SCE-1K-12-50-S1-9")

CB5752-000

(Alias Part Numbers:

"HT-SCE-1/8-2.0-0-PB-CS7783")

EC6652-000

6195170001

(Alias Part Numbers:

"1-1194894-6"

"HT-SCE-3/8-2.0-S1-9")

9337110001

(Alias Part Numbers:

"8-1197235-7"

"HT-SCE-1/2-2.0-0")

CL5871-000

(Alias Part Numbers:

"HT-SCE-1K-3/4-0-PB-CS7783")

816855-000

(Alias Part Numbers:

"6-1196365-3"

"RPS-1K-22-18/2.0-S2-4")

2773310001

(Alias Part Numbers:

"7-1192053-8"

"HT-SCE-1/2-2.0-S1-9")

C93166-000

(Alias Part Numbers:

"2-1202096-9"

Product Affected

"HT-SCE-1-2.0-0-CS7783")

9061490001

(Alias Part Numbers:

"3-1197040-2"

"RPS-2.5K-22-18/2.0-S1-9")

402961-000

(Alias Part Numbers:

"9-1193041-1"

"HT-SCE-1/4-2.0-9-CS7537")

CM3939-000

(Alias Part Numbers:

"D-SCE-4.8-3-SP-CS8766")

EH3342-000

4602050003

(Alias Part Numbers:

"9-1193451-3"

"RPS-1-400/2.0-9")

A26898-000

(Alias Part Numbers:

"3-1201660-0"

"HT-SCE-1K-3/16-S1-9CS0013")

CW7931-000

7191070001

(Alias Part Numbers:

"7-1195624-3"

"RPS-2.5K-18-12/2.0-9")

CZ6693-000

A37217-000

(Alias Part Numbers:

"9-1201241-8"

"D-SCE-18-50-S1-4-CS34034")

CJ9824-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-S1-3-CS8766")

CW7935-000

197667-000

(Alias Part Numbers:

"7-1191432-2"

"D-SCE-1.5K-9.5-50-S1-4")

1661090001

Product Affected

(Alias Part Numbers:

"1-1191199-4"

"RPS-1K-18-12/2.0-4")

CU6339-000

034635-000

(Alias Part Numbers:

"1190268-8"

"D-SCE-38-50-4")

D10921-000

(Alias Part Numbers:

"9-1200432-7"

"RPS-1K-10-2/2.0-S3-9")

1229590001

(Alias Part Numbers:

"5-1190894-1"

"RPS-16-10/2.0-9")

3258170003

(Alias Part Numbers:

"5-1192465-2"

"RPS-400-1000/2.0-4")

327501-000

(Alias Part Numbers:

"7-1192477-2"

"HT-SCE-1/2-9-CS-34034")

456421-000

(Alias Part Numbers:

"6-1193425-2"

"D-SCE-12-50-9-CS34034")

6264570001

(Alias Part Numbers:

"6-1194961-5"

"RPS-1K-18-12/2.0-S2-9")

3142550001

(Alias Part Numbers:

"7-1192378-9"

"D-SCE-6.4-50-S1-4")

A44566-000

(Alias Part Numbers:

"7-1201773-2"

"D-SCE-3.2-50-9")

Product Affected

768263-000

(Alias Part Numbers:

"8-1195986-0"

"D-SCE-25-50-4")

CM6785-000

7443890001

(Alias Part Numbers:

"2-1195807-5"

"RPS-1K-18-12/2.0-S1-4")

475683-000

(Alias Part Numbers:

"8-1193562-9"

"D-SCE-1K-38-50-9")

CN3359-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-7-CS8766")

4716110001

(Alias Part Numbers:

"6-1193533-7"

"HT-SCE-1-2.0-4")

7674850001

(Alias Part Numbers:

"9-1195980-4"

"RPS-1K-8-4/2.0-9")

5266190001

(Alias Part Numbers:

"3-1194138-3"

"D-SCE-1K-3.2-50-4")

473305N002

(Alias Part Numbers:

"1-1193546-0"

"HT-SCE-3/8-2.0-0-CS7210")

EG2714-000

EC6669-000

(Alias Part Numbers:

"2-1899791-4"

"UV-SCE-1K-3/16-2.0-9")

CY6870-000

EC6685-000

(Alias Part Numbers:

Product Affected

"3-1899791-4"

"UV-SCE-1K-3/4-2.0-9")

CA2944-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-4-CS7834")

CU6337-000

8779670001

(Alias Part Numbers:

"6-1196827-3"

"RPS-18-12/2.0-4")

240205-000

(Alias Part Numbers:

"1-1191765-8"

"D-SCE-2.4-50-4")

8374950001

(Alias Part Numbers:

"6-1196536-5"

"RPS-1K-22-18/2.0-S1-9")

6096530001

(Alias Part Numbers:

"1194821-9"

"RPS-1K-10-2/2.0-S1-4")

3247530001

(Alias Part Numbers:

"8-1192457-0"

"RPS-5K-22-18/2.0-9")

2398990001

(Alias Part Numbers:

"2-1191763-4"

"HT-SCE-1-2.0-0")

0561490001

(Alias Part Numbers:

"8-1190427-4"

"RPS-18-12/2.0-9")

CZ1591-000

CV7178-000

872083-000

(Alias Part Numbers:

"6-1196786-9"

"D-SCE-1K-25-50-4")

Product Affected

4117110001

(Alias Part Numbers:

"1193105-3"

"HT-SCE-1/2-2.0-9")

8716810001

(Alias Part Numbers:

"5-1196783-4"

"HT-SCE-3/8-2.0-9")

C62527-000

(Alias Part Numbers:

"6-1200715-8"

"RPS-1K-6-250/2.0-S2-9")

1400610001

(Alias Part Numbers:

"5-1191015-5"

"HT-SCE-1/4-2.0-S1-9")

4625470001

(Alias Part Numbers:

"1-1193469-1"

"RPS-18-12/2.0-S3-9")

CJ9803-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-S1-3-CS8766")

CY2403-000

EC6623-000

(Alias Part Numbers:

"1-1899791-0"

"UV-SCE-3/32-2.0-4")

CJ9808-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-3-CS8766")

4689010001

(Alias Part Numbers:

"2-1193514-6"

"RPS-2.5K-16-10/2.0-S3-9")

4893150001

(Alias Part Numbers:

"9-1193660-6"

"RPS-18-12/2.0-S1-4")

C74367-000

Product Affected

(Alias Part Numbers:

"9-1201324-2"

"HT-SCE-1K-1-1/2-2.0-S1-9")

5492670001

(Alias Part Numbers:

"3-1194322-4"

"D-SCE-9.5-50-S1-4")

CY6888-000

D78438-000

(Alias Part Numbers:

"8-1202036-5"

"RPS-1-400/2.0-4-CS-0016")

132365-000

(Alias Part Numbers:

"9-1190961-4"

"D-SCE-1K-4.8-50-9")

CZ6689-000

CJ9813-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-S1-7-CS8766")

704905-000

(Alias Part Numbers:

"9-1195528-5"

"D-SCE-4.8-50-9")

D29596-000

(Alias Part Numbers:

"8-1201335-0"

"NBC-SCE-1K-1/8-2.0-9")

991361-000

(Alias Part Numbers:

"1-1197667-2"

"HT-SCE-5K-1/8-2.0-9")

8306110001

(Alias Part Numbers:

"7-1196485-8"

"HT-SCE-1/4-2.0-9")

9809850001

(Alias Part Numbers:

"4-1197580-3"

"D-SCE-1K-25-50-S1-4")

Product Affected

CJ0268-000

(Alias Part Numbers:

"HT-SCE-1-2.0-9-CS8745")

CJ0266-000

(Alias Part Numbers:

"HT-SCE-1/2-2.0-9-CS8745")

CV5624-000

CN3357-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-5-CS8766")

CM1954-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-3-CS7834")

CV5579-000

2209350001

(Alias Part Numbers:

"8-1191628-1"

"HT-SCE-1K-3/4-2.0-9")

CN0251-000

A13973-000

(Alias Part Numbers:

"7-1200621-7"

"HT-SCE-1K-3/16-2.0-0")

CJ9805-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-S1-9-CS8766")

393177-000

(Alias Part Numbers:

"1192950-7"

"NBC-SCE-1/4-2.0-9")

949459-000

(Alias Part Numbers:

"8-1197344-4"

"D-SCE-1K-38-50-4")

6134370001

(Alias Part Numbers:

"4-1194849-3"

"RPS-22-18/2.0-9")

CW7933-000

CS4472-000

Product Affected

CY8610-000

(Alias Part Numbers:

"HT-SCE-1K-1/8-2.0-2L")

EH2941-000

CJ9830-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-9-CS8766")

CB8207-000

(Alias Part Numbers:

"HT-SCE-1/8-2.0-4"

"1-1899348-6")

EC6648-000

(Alias Part Numbers:

"1-1899791-5"

"UV-SCE-3/4-2.0-4")

EF3680-000

C58463-000

(Alias Part Numbers:

"7-1201324-3"

"HT-SCE-1K-1-2.0-S1-9")

847879-000

(Alias Part Numbers:

"6-1196612-8"

"NBC-SCE-1/8-2.0-9")

A32214-000

(Alias Part Numbers:

"3-1201372-9"

"RPS-1K-10-2/2.0-S2-9")

EC6684-000

(Alias Part Numbers:

"3-1899791-3"

"UV-SCE-1K-3/4-2.0-4")

EC6680-000

(Alias Part Numbers:

"3-1899791-1"

"UV-SCE-1K-1/2-2.0-4")

CY8612-000

(Alias Part Numbers:

"HT-SCE-1K-3/16-2.0-2L")

397277-000

Product Affected

(Alias Part Numbers:

"6-1192979-1"

"HT-SCE-1K-3/16-2.0-9")

CA1544-000

(Alias Part Numbers:

"HT-SCE-1K-3/16-2.0-4")

CW8842-000

CL8567-000

(Alias Part Numbers:

"D-SCE-1K-12-50-9-CS7834")

CY8611-000

(Alias Part Numbers:

"HT-SCE-1K-3/8-2.0-2L")

4282090001

(Alias Part Numbers:

"5-1193221-9"

"HT-SCE-5K-3/32-2.0-9")

CM2498-000

(Alias Part Numbers:

"D-SCE-5K-6.4-50-9-CS8766")

9105556001

(Alias Part Numbers:

"4-1197072-3"

"TMS-CCUV-SLEEVE-8-X-65MM")

D60603-000

(Alias Part Numbers:

"4-1201568-2"

"HT-SCE-5K-1/8-S1-9-CS0013")

9850216001

(Alias Part Numbers:

"4-1197609-8"

"TMS-CCUV-SLEEVE-1-X-65MM")

D53079-000

(Alias Part Numbers:

"8-1199632-5"

"HT-SCE-1K-3/16-2.0-S1-9")

166642-000

(Alias Part Numbers:

"4-1200205-7"

"D-SCE-1K-6.4-50-6")

Product Affected

700137-000

(Alias Part Numbers:

"1-1195496-6"

"D-SCE-12-50-S1-9-CS34034")

CM1215-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-9-CS7834")

CJ9816-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-S1-9-CS8766")

F15138-000

(Alias Part Numbers:

"1201336-9"

"NBC-SCE-1K-3/8-2.0-9")

CJ9815-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-9-CS8766")

CV5575-000

CN4146-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-4-CS8776")

CN0084-000

EG4272-000

5902770001

(Alias Part Numbers:

"8-1194669-4"

"RPS-1K-22-18/2.0-S1-4")

CN3364-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-5-CS8766")

129501-000

(Alias Part Numbers:

"6-1197916-1"

"D-SCE-1K-38-50-S1-4")

EC6637-000

(Alias Part Numbers:

"1-1899791-2"

"UV-SCE-1/4-2.0-9")

A72327-000

(Alias Part Numbers:

Product Affected

"6-1201695-9"

"HT-SCE-1K-3/32-2.0-S3-9")

E11133-000

(Alias Part Numbers:

"6-1201761-7"

"D-SCE-2.4-50-9")

CJ9818-000

(Alias Part Numbers:

"D-SCE-1K-4.8-50-S1-3-CS8766")

CU6342-000

449993-000

(Alias Part Numbers:

"9-1193379-9"

"D-SCE-1K-25-50-9")

EC6689-000

(Alias Part Numbers:

"3-1899791-6"

"UV-SCE-1K-1-2.0-9")

CU6343-000

CJ9809-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-S1-3-CS8766")

9510670003

(Alias Part Numbers:

"8-1197354-8"

"RPS-400-1000/2.0-9")

8880530001

(Alias Part Numbers:

"1-1196909-2"

"HT-SCE-1/8-2.0-S1-9")

EC6692-000

(Alias Part Numbers:

"3-1899791-7"

"UV-SCE-1K-1-1/2-2.0-4")

2557290003

(Alias Part Numbers:

"7-1191871-9"

"RPS-1-400/2.0-4")

3045950001

(Alias Part Numbers:

Product Affected

"6-1192306-9"

"D-SCE-38-50-S1-4")

CC9106-000

(Alias Part Numbers:

"5-1899464-8"

"TMS-90-SCE-1/2-6")

C10583-000

(Alias Part Numbers:

"7-1202127-4"

"HT-SCE-3/4-2.0-9CS7783")

C06740-000

(Alias Part Numbers:

"2-1202036-9"

"RPS-1-400/2.0-9-CS-0016")

8542570001

(Alias Part Numbers:

"2-1196659-7"

"RPS-6-250/2.0-S1-9")

CJ9828-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-S1-7-CS8766")

188139-000

(Alias Part Numbers:

"5-1191365-7"

"D-SCE-18-50-S1-2L-CS34034")

CB6010-000

(Alias Part Numbers:

"HT-SCE-3/8-2.0-0-PB-CS7783")

C48947-000

(Alias Part Numbers:

"7-1201660-5"

"HT-SCE-1K-3/8-9-CS0013")

CU1243-000

1910650001

(Alias Part Numbers:

"9-1191385-7"

"RPS-22-18/2.0-S3-9")

CS5527-000

A05476-000

(Alias Part Numbers:

Product Affected

"9-1200611-0"

"D-SCE-6.4-50-S1-2LCS34034")

4529710001

(Alias Part Numbers:

"1193401-4"

"HT-SCE-1/2-2.0-4")

2012570001

(Alias Part Numbers:

"1191459-2"

"HT-SCE-1K-1/8-2.0-S1-9")

9251810001

(Alias Part Numbers:

"3-1197176-8"

"RPS-1K-16-10/2.0-S2-9")

CJ9819-000

(Alias Part Numbers:

"D-SCE-1K-4.8-50-9-CS8766")

CM6575-000

9122770001

(Alias Part Numbers:

"5-1197084-8"

"RPS-1K-16-10/2.0-S3-9")

5299850001

(Alias Part Numbers:

"8-1194161-6"

"HT-SCE-1-1/2-2.0-0")

CN3361-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-0-CS8766")

9166110001

(Alias Part Numbers:

"3-1197115-6"

"HT-SCE-1/4-2.0-S1-0")

8153950001

(Alias Part Numbers:

"8-1196354-9"

"D-SCE-18-50-4")

0620070001

(Alias Part Numbers:

"1-1190469-3"

Product Affected

"HT-SCE-3/16-2.0-0")

9498050001

(Alias Part Numbers:

"9-1197346-0"

"D-SCE-2.5K-4.8-50-4")

2439450001

(Alias Part Numbers:

"6-1191789-1"

"RPS-1K-22-18/2.0-9")

CZ6695-000

9353250001

(Alias Part Numbers:

"2-1197247-2"

"RPS-16-10/2.0-4")

889613-000

(Alias Part Numbers:

"1196921-7"

"NBC-SCE-3/8-2.0-9")

8560610001

(Alias Part Numbers:

"4-1196672-1"

"RPS-22-18/2.0-S1-4")

CC9103-000

(Alias Part Numbers:

"5-1899464-5"

"TMS-90-SCE-1/2-3")

CJ0270-000

(Alias Part Numbers:

"HT-SCE-1/8-2.0-9-CS8745")

5572350001

(Alias Part Numbers:

"5-1194395-9"

"D-SCE-1K-6.4-50-4")

4039050001

(Alias Part Numbers:

"1193049-5"

"RPS-2.5K-22-18/2.0-S3-9")

550819-000

(Alias Part Numbers:

"1-1194348-2"

Product Affected

"HT-SCE-1K-1-2.0-9")

CA6194-000

(Alias Part Numbers:

"HT-SCE-1K-3/16-2.0-6")

CW7936-000

CC9104-000

(Alias Part Numbers:

"5-1899464-6"

"TMS-90-SCE-1/2-4")

CU6344-000

CV5437-000

CW8057-000

CN3358-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-6-CS8766")

CJ9800-000

(Alias Part Numbers:

"D-SCE-1K-12-50-9-CS8766")

3554750001

(Alias Part Numbers:

"8-1192668-6"

"HT-SCE-3/16-2.0-S1-9")

EC6664-000

(Alias Part Numbers:

"2-1899791-0"

"UV-SCE-1K-1/8-2.0-4")

CM2496-000

(Alias Part Numbers:

"D-SCE-5K-4.8-50-9-CS8766")

0229410001

(Alias Part Numbers:

"5-1190177-4"

"RPS-1K-1-400/2.0-9")

CJ9804-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-9-CS8766")

056675-000

(Alias Part Numbers:

"7-1197852-3"

"TMS-CCUV-SLV-6-65MMCS7633")

Product Affected

1827990001

(Alias Part Numbers:

"1191328-9"

"HT-SCE-3/4-2.0-0")

372389-000

(Alias Part Numbers:

"2-1192789-1"

"D-SCE-1K-12-50-4")

4108170001

(Alias Part Numbers:

"3-1193098-7"

"HT-SCE-1/8-2.0-9")

7079550001

(Alias Part Numbers:

"3-1195549-2"

"RPS-2.5K-16-10/2.0-S1-9")

434811-000

(Alias Part Numbers:

"7-1193269-2"

"TMS-CCUV-SLV-5-65MMCS7633")

EC6640-000

(Alias Part Numbers:

"1-1899791-3"

"UV-SCE-3/8-2.0-4")

EC6677-000

(Alias Part Numbers:

"3-1899791-0"

"UV-SCE-1K-3/8-2.0-9")

CA2946-000

(Alias Part Numbers:

"D-SCE-1K-12-50-4-CS7834"

"1-1899740-8")

CC9105-000

(Alias Part Numbers:

"5-1899464-7"

"TMS-90-SCE-1/2-5")

4288010001

(Alias Part Numbers:

"6-1193225-5"

"RPS-10-2/2.0-S1-9")

Product Affected

EC6660-000

(Alias Part Numbers:

"1-1899791-8"

"UV-SCE-1K-3/32-2.0-4")

CJ9821-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-S1-1-CS8766")

3340610001

(Alias Part Numbers:

"9-1192523-5"

"D-SCE-1K-9.5-50-S1-4")

2571170001

(Alias Part Numbers:

"6-1191881-6"

"RPS-16-10/2.0-S1-4")

EC6644-000

F60500-000

(Alias Part Numbers:

"8-1201773-8"

"D-SCE-6.4-50-9")

8296870003

(Alias Part Numbers:

"1-1196479-8"

"RPS-10-2/2.0-9")

CJ0272-000

(Alias Part Numbers:

"HT-SCE-3/8-2.0-9-CS8745")

2498710001

(Alias Part Numbers:

"6-1191832-8"

"RPS-18-12/2.0-S1-9")

CM1951-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-1-CS7834")

1197370001

(Alias Part Numbers:

"1-1190871-8"

"RPS-16-10/2.0-S3-9")

CN9427-000

(Alias Part Numbers:

Product Affected

"D-SCE-12-50-9-CS8766")

517445-000

(Alias Part Numbers:

"6-1194062-1"

"D-SCE-5K-3.2-50-S1-9")

CJ9802-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-3-CS8766")

5101310001

(Alias Part Numbers:

"1194010-2"

"RPS-2.5K-18-12/2.0-S3-9")

5711630001

(Alias Part Numbers:

"8-1194529-0"

"HT-SCE-1K-1/4-2.0-9")

CA2945-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-6-CS7834")

762261-000

(Alias Part Numbers:

"1195936-4"

"D-SCE-1K-18-50-4")

CF6346-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-9-CS7834")

CY8609-000

(Alias Part Numbers:

"HT-SCE-1K-1/4-2.0-2L")

5502830001

(Alias Part Numbers:

"5-1194342-6"

"RPS-1K-16-10/2.0-9")

CM1948-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-7-CS7834")

E24471-000

(Alias Part Numbers:

"6-1201515-8"

"D-SCE-38-50-S1-8-CS34034")

Product Affected

CJ9812-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-S1-6-CS8766")

CL8045-000

(Alias Part Numbers:

"HT-SCE-1K-3/8-2.0-9-CS7740")

105715-000

(Alias Part Numbers:

"5-1190772-7"

"D-SCE-1K-18-50-9")

8947570001

(Alias Part Numbers:

"4-1196958-0"

"HT-SCE-1-2.0-9")

CM3557-000

(Alias Part Numbers:

"HT-SCE-3/8-2.0-9-PB-CS7783")

CV4994-000

8737350001

(Alias Part Numbers:

"5-1196798-2"

"RPS-1K-22-18/2.0-4")

A35215-000

(Alias Part Numbers:

"3-1200501-3"

"D-SCE-1K-3.2-50-S1-9")

052983-000

(Alias Part Numbers:

"8-1197852-6"

"TMS-CCUV-SLV-8-65MMCS7633")

5516930001

(Alias Part Numbers:

"8-1194360-1"

"RPS-1K-6-250/2.0-9")

CW9197-000

1806950001

(Alias Part Numbers:

"6-1191313-5"

"RPS-2.5K-16-10/2.0-9")

A90285-000

Product Affected

(Alias Part Numbers:

"4-1200363-3"

"HT-SCE-3/8-2.0-9-CS7742")

0236090001

(Alias Part Numbers:

"8-1190182-6"

"HT-SCE-3/32-2.0-0")

CL6827-000

(Alias Part Numbers:

"HT-SCE-1/2-2.0-9-PB-CS7783")

CC9145-000

(Alias Part Numbers:

"9-1899464-7"

"TMS-90-SCE-3/16-3")

CM1947-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-6-CS7834")

CW7932-000

066334-000

(Alias Part Numbers:

"3-1199549-1"

"HT-SCE-2.5K-1/4-2.0-9")

E54968-000

(Alias Part Numbers:

"3-1201258-5"

"RPS-1K-1-400/2.0-S3-4")

CV7180-000

102197-000

(Alias Part Numbers:

"9-1190747-1"

"D-SCE-38-50-9-CS34034")

CU6341-000

4486176001

(Alias Part Numbers:

"7-1193370-5"

"TMS-CCUV-SLEEVE-5-X-65MM")

CJ9811-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-S1-5-CS8766")

CL9689-000

Product Affected

(Alias Part Numbers:

"D-SCE-4.8-50-S1-9-CS8766")

2571070001

(Alias Part Numbers:

"5-1191881-8"

"RPS-1K-1-400/2.0-4")

8375990001

(Alias Part Numbers:

"4-1196537-7"

"RPS-1K-10-2/2.0-4")

3045010001

(Alias Part Numbers:

"1192306-4"

"RPS-1K-6-250/2.0-S1-9")

D33741-000

(Alias Part Numbers:

"D-SCE-1K-12-50-6-CS7834")

F53327-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-S1-9"

"1200398-9")

9352370001

(Alias Part Numbers:

"5-1197246-7"

"HT-SCE-1/8-2.0-0")

885477-000

(Alias Part Numbers:

"3-1196890-4"

"D-SCE-4.8-50-S1-9-CS34034")

CM3700-000

(Alias Part Numbers:

"HT-SCE-1/8-2.0-9-PB-CS7783")

057323-000

(Alias Part Numbers:

"7-1190435-0"

"D-SCE-3.2-S1-2L-CS34034")

CN3367-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-8-CS8766")

121727-000

Product Affected

(Alias Part Numbers:

"1190886-5"

"HT-SCE-1K-3/8-2.0-9")

CW2837-000

CN3745-000

CN0093-000

EH2939-000

0226070001

(Alias Part Numbers:

"1190175-3"

"RPS-22-18/2.0-S2-4")

7278870001

(Alias Part Numbers:

"1-1195688-7"

"RPS-1K-18-12/2.0-9")

A27893-000

(Alias Part Numbers:

"8-1200621-1"

"HT-SCE-1K-1/8-2.0-0")

E90935-000

(Alias Part Numbers:

"9-1201895-7"

"HT-SCE-3/16-2.0-4")

970388-000

(Alias Part Numbers:

"9-1197953-3"

"D-SCE-25-4-SP")

A66062-000

(Alias Part Numbers:

"7-1201751-8"

"HT-SCE-2.5K-1/4-9-CS7740")

CW7937-000

CA7153-000

(Alias Part Numbers:

"HT-SCE-1K-3/8-2.0-6")

EC6673-000

(Alias Part Numbers:

"2-1899791-7"

"UV-SCE-1K-1/4-2.0-9")

3308470001

Product Affected

(Alias Part Numbers:

"5-1192499-3"

"RPS-18-12/2.0-S2-9")

CN6946-000

(Alias Part Numbers:

"D-SCE-1K-18-50-9-CS8766")

CJ0267-000

(Alias Part Numbers:

"HT-SCE-3/4-2.0-9-CS8745")

CV5577-000

E52724-000

(Alias Part Numbers:

"1-1201711-2"

"D-SCE-1K-38-50-S1-9")

CP8472-000

(Alias Part Numbers:

"HT-SCE-1K-1/4-2.0-S1-4")

CJ6200-000

(Alias Part Numbers:

"HTTMS-3/8-1.50-9-CS2515")

EC6661-000

(Alias Part Numbers:

"1-1899791-9"

"UV-SCE-1K-3/32-2.0-9")

E44758-000

(Alias Part Numbers:

"6-1201189-5"

"D-SCE-4.8-50-S1-9")

A63405-000

(Alias Part Numbers:

"1201244-4"

"RPS-1K-1-400/2.0-S1-4")

C03232-000

(Alias Part Numbers:

"8-1201403-8"

"D-SCE-12-50-9")

CJ9833-000

(Alias Part Numbers:

"D-SCE-1K-9.5-50-S1-9-CS8766")

CN4020-000

Product Affected

CM1944-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-1-CS7834")

CL5872-000

(Alias Part Numbers:

"HT-SCE-1K-1-0-PB-CS7783")

CV7175-000

373463-000

(Alias Part Numbers:

"3-1192797-6"

"RPS-1K-8-4/2.0-S1-4")

F21848-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-9"

"9-1200397-9")

CU6941-000

8545196001

(Alias Part Numbers:

"1196661-2"

"TMS-CCUV-SLEEVE-7-X-65MM")

8315576001

(Alias Part Numbers:

"1196493-6"

"TMS-CCUV-SLEEVE-6-X-65MM")

310711-000

(Alias Part Numbers:

"1-1192352-5"

"NBC-SCE-1-2.0-9")

CL9654-000

(Alias Part Numbers:

"D-SCE-2.4-50-8-CS8766")

5879530001

(Alias Part Numbers:

"7-1194652-3"

"RPS-400-1000/2.0-S1-9")

CM1125-000

(Alias Part Numbers:

"HT-SCE-3/32-2.0-0-PB-CS7783")

2902090001

(Alias Part Numbers:

Product Affected

"4-1192200-3"

"HT-SCE-1K-3/32-2.0-9")

EC6633-000

(Alias Part Numbers:

"1-1899791-1"

"UV-SCE-1/8-2.0-9")

1328690001

(Alias Part Numbers:

"3-1190965-2"

"RPS-1K-400-1000/2.0-4")

5748250001

(Alias Part Numbers:

"1-1194562-3"

"RPS-2.5K-18-12/2.0-4")

CL9690-000

(Alias Part Numbers:

"D-SCE-6.4-50-9-CS8766")

CB4071-000

477958-000

(Alias Part Numbers:

"6-1199621-8"

"HT-SCE-3/8-2.0-4")

278005-000

(Alias Part Numbers:

"5-1192058-4"

"D-SCE-5K-2.4-50-S1-9")

9117310001

(Alias Part Numbers:

"7-1197080-7"

"D-SCE-6.4-50-4")

CY6871-000

CX5929-000

084257-000

(Alias Part Numbers:

"7-1190622-2"

"HT-SCE-1-1/2-2.0-2L")

CX1053-000

(Alias Part Numbers:

"WM-SCE-48.2-9"

"5-1899822-7")

Product Affected

CN0087-000

CM1950-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-8-CS7834")

A14233-000

(Alias Part Numbers:

"HT-SCE-1/4-2.0-9-CS7783")

CV5431-000

EC6665-000

(Alias Part Numbers:

"2-1899791-1"

"UV-SCE-1K-1/8-2.0-9")

4419990001

(Alias Part Numbers:

"1-1193323-3"

"D-SCE-1K-3.2-50-S2-4")

7033790003

(Alias Part Numbers:

"3-1195518-9"

"RPS-10-2/2.0-4")

9410990001

(Alias Part Numbers:

"9-1197286-5"

"HT-SCE-3/4-2.0-9")

3206430001

(Alias Part Numbers:

"9-1192430-4"

"HT-SCE-3/16-2.0-9")

8420630001

(Alias Part Numbers:

"9-1196568-0"

"HT-SCE-1-1/2-2.0-9")

CP8473-000

(Alias Part Numbers:

"HT-SCE-1K-3/8-2.0-S1-4")

531520-000

(Alias Part Numbers:

"1-1199616-5"

"HT-SCE-1K-1-1/2-2.0-9")

CC3801-000

Product Affected

(Alias Part Numbers:

"RPS-1K-400-1000/2.0-S1-4"

"1899274-5")

CM1946-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-5-CS7834")

3490750001

(Alias Part Numbers:

"5-1192626-2"

"D-SCE-1K-4.8-50-4")

CZ0626-000

CZ6696-000

CJ9329-000

(Alias Part Numbers:

"HT-SCE-1-2.0-9-CS7742")

CX1386-000

D08632-000

(Alias Part Numbers:

"7-1201335-7"

"NBC-SCE-1K-1/4-2.0-9")

7710110001

(Alias Part Numbers:

"5-1196006-7"

"D-SCE-9.5-50-4")

740569-000

(Alias Part Numbers:

"4-1195780-4"

"D-SCE-1K-18-50-S1-9")

663453-000

(Alias Part Numbers:

"1195229-2"

"D-SCE-1K-9.5-50-9")

7514950001

(Alias Part Numbers:

"8-1195859-1"

"RPS-1K-8-4/2.0-S2-9")

6355850001

(Alias Part Numbers:

"6-1195025-6"

"HT-SCE-1/4-2.0-0")

Product Affected

EG8020-000

CU4088-000

779141-000

(Alias Part Numbers:

"9-1196063-1"

"D-SCE-6.4-50-S1-9-CS34034")

772259-000

(Alias Part Numbers:

"4-1196015-2"

"D-SCE-2.5K-4.8-50-S1-4")

CJ9822-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-S1-2-CS8766")

CN9426-000

(Alias Part Numbers:

"D-SCE-18-50-9-CS8766")

2321830001

(Alias Part Numbers:

"6-1191705-7"

"RPS-22-18/2.0-S2-9")

EC6672-000

(Alias Part Numbers:

"2-1899791-6"

"UV-SCE-1K-1/4-2.0-4")

CY8608-000

(Alias Part Numbers:

"HT-SCE-1K-1/2-2.0-2L")

CB6013-000

(Alias Part Numbers:

"HT-SCE-1-1/2-2.0-0-PB-CS7783")

CJ9814-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-S1-8-CS8766")

8478290001

(Alias Part Numbers:

"3-1196612-8"

"RPS-1K-10-2/2.0-9")

CJ9831-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-S1-9-CS8766")

Product Affected

544030-000

(Alias Part Numbers:

"1199518-2"

"HT-SCE-1K-1-2.0-0")

9934510001

(Alias Part Numbers:

"6-1197684-9"

"HT-SCE-1K-1/8-2.0-9")

CU6345-000

C05675-000

(Alias Part Numbers:

"5-1201660-9"

"HT-SCE-1K-1/4-9-CS0013")

6036230001

(Alias Part Numbers:

"1194777-5"

"HT-SCE-1K-1/2-2.0-9")

CN0086-000

147547-000

(Alias Part Numbers:

"3-1191066-9"

"D-SCE-1K-2.4-50-4")

1056030001

(Alias Part Numbers:

"8-1190771-5"

"D-SCE-1K-3.2-50-S1-4")

131854-000

(Alias Part Numbers:

"6-1199206-0"

"HT-SCE-1K-3/4-2.0-0")

5178430001

(Alias Part Numbers:

"2-1194065-8"

"RPS-1K-6-250/2.0-4")

9711150001

(Alias Part Numbers:

"7-1197506-5"

"RPS-2.5K-16-10/2.0-4")

CL5870-000

(Alias Part Numbers:

Product Affected

"HT-SCE-1K-1/2-0-PB-CS7783")

EC6656-000

(Alias Part Numbers:

"1-1899791-7"

"UV-SCE-1-1/2-2.0-4")

1845630001

(Alias Part Numbers:

"1191340-2"

"RPS-6-250/2.0-9")

CM1956-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-7-CS7834")

7218310001

(Alias Part Numbers:

"1-1195644-2"

"RPS-2.5K-18-12/2.0-S1-9")

CL9663-000

(Alias Part Numbers:

"D-SCE-2.4-50-S1-9-CS8766")

F645930001

(Alias Part Numbers:

"5-1201170-4"

"D-SCE-12-50-S1-9")

CV5434-000

CN0089-000

CN3360-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-8-CS8766")

CR1081-000

2355930001

(Alias Part Numbers:

"1191733-8"

"HT-SCE-3/32-2.0-S1-9")

CJ9827-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-S1-6-CS8766")

2866050001

(Alias Part Numbers:

"7-1192170-8"

"RPS-22-18/2.0-4")

Product Affected

EH3354-000

EH3345-000

CJ0265-000

(Alias Part Numbers:

"HT-SCE-1/4-2.0-9-CS8745")

5519236001

(Alias Part Numbers:

"4-1194362-1"

"TMS-CCUV-SLEEVE-3-X-65MM")

D14966-000

(Alias Part Numbers:

"D-SCE-2.4-50-S1-9"

"7-1200629-7")

707112-000

(Alias Part Numbers:

"8-1199190-0"

"D-SCE-1K-6.4-50-S1-9")

3818630001

(Alias Part Numbers:

"8-1192854-8"

"RPS-1-400/2.0-S1-9")

073937-000

(Alias Part Numbers:

"5-1190553-2"

"D-SCE-2.5K-6.4-50-S1-4")

300147-000

(Alias Part Numbers:

"1-1197862-2"

"D-SCE-5K-3.2-50-9")

8187210001

(Alias Part Numbers:

"6-1196380-4"

"RPS-1-400/2.0-S1-4")

CR5572-000

CN0085-000

6655690001

(Alias Part Numbers:

"1-1195244-2"

"RPS-1K-16-10/2.0-S1-4")

CY6889-000

Product Affected

CA7155-000

(Alias Part Numbers:

"HT-SCE-1K-1-1/2-2.0-6")

CN3354-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-1-CS8766")

EH3347-000

A943930001

(Alias Part Numbers:

"2-1201168-2"

"D-SCE-3.2-50-S1-9")

CJ9810-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-S1-4-CS8766")

3994950001

(Alias Part Numbers:

"8-1192997-3"

"RPS-1K-18-12/2.0-S3-9")

919385-000

(Alias Part Numbers:

"4-1197134-5"

"D-SCE-1K-9.5-50-4")

6409110001

(Alias Part Numbers:

"1195066-5"

"RPS-1K-22-18/2.0-S3-9")

CM1942-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-2-CS7834")

210261-000

(Alias Part Numbers:

"6-1191523-7"

"HT-SCE-1K-3/8-2.0-0")

EC1921-000

(Alias Part Numbers:

"1-1899658-9"

"D-SCE-1K-38-50-5")

769356-000

(Alias Part Numbers:

"8-1199205-4"

Product Affected

"HT-SCE-1K-1/4-2.0-0")

CN3356-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-4-CS8766")

949687-000

(Alias Part Numbers:

"5-1197346-1"

"D-SCE-2.4-50-S1-9-CS34034")

EC6649-000

CN0091-000

CB2412-000

(Alias Part Numbers:

"HT-SCE-1/2-2.0-0-PB-CS7783")

EC6688-000

(Alias Part Numbers:

"3-1899791-5"

"UV-SCE-1K-1-2.0-4")

CJ9817-000

(Alias Part Numbers:

"D-SCE-1K-4.8-50-3-CS8766")

213293-000

(Alias Part Numbers:

"6-1191541-5"

"D-SCE-5K-2.4-50-S1-4")

EH3337-000

0704570001

(Alias Part Numbers:

"9-1190529-6"

"RPS-16-10/2.0-S2-9")

CX5220-000

EC6668-000

(Alias Part Numbers:

"2-1899791-3"

"UV-SCE-1K-3/16-2.0-4")

3555830001

(Alias Part Numbers:

"5-1192669-0"

"RPS-8-4/2.0-4")

EC6653-000

(Alias Part Numbers:

Product Affected

"1-1899791-6"

"UV-SCE-1-2.0-9")

CL9687-000

(Alias Part Numbers:

"D-SCE-3.2-50-S1-9-CS8766")

CW6167-000

CC9170-000

(Alias Part Numbers:

"2-1899465-3"

"TMS-90-SCE-3/32-9")

7822250001

(Alias Part Numbers:

"7-1196075-5"

"RPS-22-18/2.0-S1-9")

412575-000

(Alias Part Numbers:

"5-1193111-1"

"D-SCE-1K-9.5-50-S1-9")

CC9102-000

(Alias Part Numbers:

"5-1899464-4"

"TMS-90-SCE-1/2-2")

7343816001

(Alias Part Numbers:

"5-1195735-4"

"TMS-CCUV-SLEEVE-2-X-65MM")

CV7176-000

CN0250-000

CZ9391-000

D97082-000

(Alias Part Numbers:

"1-1201709-9"

"RPS-1K-22-18/2.0-S3-SS-9")

EC6693-000

(Alias Part Numbers:

"3-1899791-8"

"UV-SCE-1K-1-1/2-2.0-9")

CJ9832-000

(Alias Part Numbers:

"D-SCE-1K-9.5-50-9-CS8766")

Product Affected

CP3919-000

7395470001

(Alias Part Numbers:

"5-1195772-6"

"RPS-1K-400-1000/2.0-9")

F37136-000

(Alias Part Numbers:

"1200589-2"

"HT-SCE-3/4-2.0-4")

F23293-000

(Alias Part Numbers:

"1-1199633-0"

"HT-SCE-1K-3/8-2.0-S1-9")

EC6681-000

(Alias Part Numbers:

"3-1899791-2"

"UV-SCE-1K-1/2-2.0-9")

1089350001

(Alias Part Numbers:

"8-1190795-2"

"RPS-6-250/2.0-4")

322537-000

(Alias Part Numbers:

"6-1192441-9"

"D-SCE-9.5-50-9")

257233-000

(Alias Part Numbers:

"5-1191882-4"

"D-SCE-38-50-S1-9-CS34034")

3325350001

(Alias Part Numbers:

"5-1192512-1"

"RPS-1K-22-18/2.0-S2-9")

CN3366-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-7-CS8766")

C91356-000

(Alias Part Numbers:

"1-1201325-6"

"HT-SCE-1K-1/4-2.0-S1-9")

Product Affected

EG9960-000

6310810001

(Alias Part Numbers:

"1194994-1"

"D-SCE-1K-4.8-50-S1-4")

CA7865-000

(Alias Part Numbers:

"HT-SCE-1K-1/8-2.0-6")

CJ9823-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-3-CS8766")

0714370001

(Alias Part Numbers:

"4-1190536-7"

"RPS-2.5K-22-18/2.0-9")

F94420-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-9"

"6-1200417-4")

CW7938-000

424992-000

(Alias Part Numbers:

"8-1198130-9"

"D-SCE-18-50-9")

6797570001

(Alias Part Numbers:

"9-1195343-0"

"RPS-1K-10-2/2.0-S1-9")

EH3344-000

651686-000

(Alias Part Numbers:

"6-1199425-3"

"HT-SCE-3/4-2.0-2L")

0497070001

(Alias Part Numbers:

"8-1190380-0"

"HT-SCE-1K-1/2-2.0-0")

4389470001

(Alias Part Numbers:

"7-1193298-3"

Product Affected

"RPS-1-400/2.0-S2-4")

0137310001

(Alias Part Numbers:

"7-1190107-7"

"RPS-16-10/2.0-S1-9")

CA7154-000

(Alias Part Numbers:

"HT-SCE-1K-1/2-2.0-6")

EC6645-000

(Alias Part Numbers:

"1-1899791-4"

"UV-SCE-1/2-2.0-9")

EC6676-000

(Alias Part Numbers:

"2-1899791-9"

"UV-SCE-1K-3/8-2.0-4")

726169-000

(Alias Part Numbers:

"2-1195675-6"

"D-SCE-2.5K-4.8-50-S1-9")

9791650001

(Alias Part Numbers:

"3-1197564-7"

"D-SCE-1K-6.4-50-S1-4")

CA5939-000

(Alias Part Numbers:

"HT-SCE-1K-1/4-2.0-6")

CM1955-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-5-CS7834")

CV5435-000

584589-000

(Alias Part Numbers:

"3-1194629-0"

"D-SCE-4.8-50-9-CS34034")

CJ9820-000

(Alias Part Numbers:

"D-SCE-1K-4.8-50-S1-9-CS8766")

1801410001

(Alias Part Numbers:

Product Affected

"6-1191309-0"

"RPS-1K-8-4/2.0-4")

646331-000

(Alias Part Numbers:

"2-1195104-4"

"D-SCE-1K-12-50-S1-4")

CJ9825-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-S1-4-CS8766")

4775630001

(Alias Part Numbers:

"6-1193576-7"

"D-SCE-4.8-50-4")

CU6338-000

3979470001

(Alias Part Numbers:

"4-1192984-3"

"RPS-8-4/2.0-9")

6891450001

(Alias Part Numbers:

"3-1195412-2"

"RPS-1K-18-12/2.0-S1-9")

CM1952-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-2-CS7834")

733963-000

(Alias Part Numbers:

"2-1195732-8"

"HT-SCE-1/8-2.0-S3-9")

E39054-000

(Alias Part Numbers:

"3-1201661-6"

"HT-SCE-5K-3/32-S1-9CS0013")

4483750001

(Alias Part Numbers:

"1-1193369-1"

"RPS-8-4/2.0-S1-4")

319356-000

(Alias Part Numbers:

"1-1201189-8"

Product Affected

"D-SCE-6.4-50-S1-9")

3234330001

(Alias Part Numbers:

"1192448-4"

"RPS-1K-16-10/2.0-4")

CC9182-000

(Alias Part Numbers:

"3-1899465-5"

"TMS-90-SCE-3/8-4")

CB2410-000

(Alias Part Numbers:

"HT-SCE-3/4-2.0-0-PB-CS7783")

EH6454-000

(Alias Part Numbers:

"D-SCE-38-50-S2-4")

1755170001

(Alias Part Numbers:

"2-1191276-1"

"D-SCE-3.2-50-4")

816090-000

(Alias Part Numbers:

"1198091-5"

"D-SCE-1K-25-50-S1-9")

123033-000

(Alias Part Numbers:

"1190895-3"

"D-SCE-18-50-S1-9-CS34034")

4589050001

(Alias Part Numbers:

"6-1193442-2"

"RPS-1K-8-4/2.0-S1-9")

A13476-000

(Alias Part Numbers:

"7-1201278-2"

"D-SCE-9.5-50-S1-9")

E62181-000

(Alias Part Numbers:

"D-SCE-1K-4.8-50-S1-9"

"9-1200500-3")

371901-000

Product Affected

(Alias Part Numbers:

"8-1192785-7"

"D-SCE-2.5K-4.8-50-9")

4733050001

(Alias Part Numbers:

"1193546-9"

"HT-SCE-3/8-2.0-0")

4431550001

(Alias Part Numbers:

"1-1193331-4"

"HT-SCE-1K-3/32-2.0-0")

848672-001

(Alias Part Numbers:

"2-1201189-7"

"D-SCE-18-50-S1-9")

C32829-000

(Alias Part Numbers:

"6-1201416-8"

"RPS-1K-18-12/2.0-SS-S3-9")

4147230001

(Alias Part Numbers:

"1193126-7"

"HT-SCE-1K-1/8-2.0-4")

CM6784-000

EC6657-000

E54960-000

(Alias Part Numbers:

"2-1202111-1"

"HT-SCE-1/4-2.0-0-CS7783")

5476270001

(Alias Part Numbers:

"1-1194311-2"

"HT-SCE-3/32-2.0-9")

A36937-000

(Alias Part Numbers:

"7-1200419-9"

"D-SCE-1K-3.2-50-9")

CM1957-000

(Alias Part Numbers:

"D-SCE-1K-6.4-50-8-CS7834")

Product Affected

8304950001

(Alias Part Numbers:

"1196485-1"

"RPS-18-12/2.0-S3-4")

5530290001

(Alias Part Numbers:

"6-1194370-1"

"D-SCE-3.2-50-S1-4")

CR5571-000

CA7152-000

(Alias Part Numbers:

"HT-SCE-1K-1-2.0-6")

CW6776-000

CM8510-000

CP8471-000

(Alias Part Numbers:

"HT-SCE-1K-1-1/2-2.0-S1-4")

CJ9807-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-S1-2-CS8766")

CM3301-000

(Alias Part Numbers:

"HT-SCE-1-2.0-9-CS7822")

698197-000

(Alias Part Numbers:

"6-1195479-0"

"D-SCE-9.5-50-S1-9-CS34034")

105285-000

(Alias Part Numbers:

"7-1190769-1"

"D-SCE-18-50-9-CS34034")

041344-000

(Alias Part Numbers:

"3-1197955-7"

"D-SCE-38-4-SP")

129488-000

(Alias Part Numbers:

"1197955-3"

"D-SCE-18-4-SP")

CJ9826-000

Product Affected

(Alias Part Numbers:

"D-SCE-1K-2.4-50-S1-5-CS8766")

3851810001

(Alias Part Numbers:

"2-1192890-6"

"RPS-1K-16-10/2.0-S1-9")

CW7934-000

902767-000

(Alias Part Numbers:

"8-1197015-0"

"D-SCE-25-50-S1-4")

CU6340-000

CJ0269-000

(Alias Part Numbers:

"HT-SCE-1-1/2-2.0-9-CS8745")

317639-000

(Alias Part Numbers:

"5-1192406-0"

"D-SCE-1K-12-50-9")

474467-000

(Alias Part Numbers:

"5-1193554-7"

"HT-SCE-2.5K-3/16-2.0-9")

EC1723-000

(Alias Part Numbers:

"1-1899658-2"

"D-SCE-1K-2.4-50-5")

CJ9829-000

(Alias Part Numbers:

"D-SCE-1K-2.4-50-S1-8-CS8766")

CY8613-000

(Alias Part Numbers:

"HT-SCE-1K-3/32-2.0-2L")

CJ9806-000

(Alias Part Numbers:

"D-SCE-1K-3.2-50-S1-1-CS8766")

1464630001

(Alias Part Numbers:

"6-1191058-6"

"HT-SCE-1/4-2.0-4")

Product Affected

CZ5517-000

CL5868-000

(Alias Part Numbers:

"HT-SCE-2.5K-1/4-0-PB-CS7783")

223121-000

(Alias Part Numbers:

"1191644-4"

"D-SCE-3.2-50-9-CS34034")

6209416001

(Alias Part Numbers:

"3-1194906-6"

"TMS-CCUV-SLEEVE-4-X-65MM")

EC6636-000

EK1387-000

588371-000

(Alias Part Numbers:

"7-1194655-7"

"D-SCE-5K-3.2-50-S1-4")

334551N002

(Alias Part Numbers:

"2-1192527-1"

"HT-SCE-3/16-2-S2-0-CS7210")

CF3724-000

(Alias Part Numbers:

"HT-SCE-3/32-2.0-9-CS8745")

EC6641-000

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.