



06-Jul-2016

PCN #:P-16-013263

Subject:Manufacturing Location Change for ADM Elastomeric Tubing made at Menlo Park

Description of Change: Manufacturing location change. Following Part Numbers will be transferred from Menlo Park to Redwood City.

Reason: This notification is to inform our customers that TE Connectivity is closing our Menlo Park, California, USA facility and moving the production of ADM Elastomeric Tubing and IDENT to our Redwood City, California, USA facility. The sites are only 4 miles apart and the current manufacturing operations will remain the same after the migration, including same workforce, same materials, and same equipment. The transfer will start in October 2016 with the targeted completion in 2018. TE reserves the right to provide TE qualified products from either site during this transfer period, and after the transfer period on stocked items. To ensure a successful and seamless transition, TE will perform validation testing at Redwood City as the production migrates. Please note that some of these products are currently made in TE locations other than Menlo Park; this notification does not apply to you if you currently receive these products from a manufacturing site other than Menlo Park.

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:17-Oct-2016

Implementation Date:17-Oct-2016

Product Affected

F69019-000

(Alias Part Numbers:

"1-1201739-3"

"RT-780-1/4-0-SP")

Product Affected

CS1968-000

5770534002

(Alias Part Numbers:

"8-1194577-0"

"RT555-1-1/2-0-SP")

EF6041-000

(Alias Part Numbers:

"DR-25-3/4-0-100FT/CSP")

637942-000

(Alias Part Numbers:

"8-1197947-3"

"HCTE-0437-0-SP-CS7063")

622902M013

(Alias Part Numbers:

"6-1194923-1"

"NTFR-1-1/4-0-SP-CS7056")

CM3561-000

(Alias Part Numbers:

"RT-790-3/8-0-SP")

920203-000

(Alias Part Numbers:

"3-1197812-6"

"RHSTTN125-1-1/4-0-SP")

5550044008

(Alias Part Numbers:

"2-1194378-5"

"NT-5/8-0-SP")

516542M009

(Alias Part Numbers:

"4-1194056-7"

"NTFR-5/8-0SPCS6705")

E67526-000

(Alias Part Numbers:

"RT-780-2-0-SP")

CU5621-000

622902M010

(Alias Part Numbers:

"5-1194923-9"

"NTFR-1-1/4-0SPCS6680")

978536-000

Product Affected

(Alias Part Numbers:

"2-1199428-1"

"HCTE-0281-0-SP-CS7711")

325833M001

(Alias Part Numbers:

"6-1192465-5"

"NTFR-3/16-0-BULK-SP")

CX4398-000

661411M008

(Alias Part Numbers:

"1195214-8"

"NTFR-3/8-0SPCS5962")

3043434002

(Alias Part Numbers:

"8-1192304-3"

"NTFR-7/8-0-SP")

D22288-000

(Alias Part Numbers:

"8-1200701-9"

"NT-5/8-0-SP-CS6361")

558056M001

(Alias Part Numbers:

"8-1194405-4"

"VPB-1/4-0-SP-CS7180")

590790-000

(Alias Part Numbers:

"6-1197948-6"

"HCTE-0500-0-SP-CS7063")

CU6568-000

EF3778-000

(Alias Part Numbers:

"DR-25-1/2-0-300FT/CSP")

863737M001

(Alias Part Numbers:

"5-1196726-3"

"NTFR-1/4-0-BULK-SP")

CB7845-000

(Alias Part Numbers:

"RW-200-2-0-SP")

CL0550-000

Product Affected

(Alias Part Numbers:

"RT555-3/4-0-MDBGSP-CS8768")

CJ0106-000

(Alias Part Numbers:

"RT555-NO.38-0-120MM-CS8752")

390531-000

(Alias Part Numbers:

"2-1192932-1"

"NTFR-1-3/4-0-SP-CS6243")

7973394008

(Alias Part Numbers:

"6-1196169-0"

"NTFR-1-1/2-0SPCS7029")

555002M015

(Alias Part Numbers:

"1194378-2"

"NT-3/8-0-SP-CS6327")

D23071-000

(Alias Part Numbers:

"7-1199962-3"

"VPB-1/2-0-SP-CS7733")

1102734002

(Alias Part Numbers:

"3-1190805-6"

"MTZH-1/2-F9-0-SP")

1743354001

(Alias Part Numbers:

"9-1191267-9"

"DR-25-3/8-0-CS-115105")

324700-000

(Alias Part Numbers:

"9-1199112-3"

"DR-25-3-0-CSP-65FT")

CJ6133-000

(Alias Part Numbers:

"9-1899298-8"

"RT-790-1/4-0-SP")

274615-000

(Alias Part Numbers:

"1-1192034-3"

Product Affected

"NTFR-1-1/2-0-SP-22.5/1")

560376M001

(Alias Part Numbers:

"5-1194423-8"

"NTFR-1/8-0-SP-CS5962")

CX6567-000

856168-000

(Alias Part Numbers:

"5-1198090-9"

"RHSTTN88-7/8-0-SP")

CB9682-000

(Alias Part Numbers:

"RW-200-7/8-0-SP-CS5430")

CB9685-000

(Alias Part Numbers:

"RW-200-3/8-0-SP-CS5430")

622902M014

(Alias Part Numbers:

"6-1194923-2"

"NTFR-1-1/4-0-SP-CS5445")

CM6832-000

D36937-000

(Alias Part Numbers:

"7-1201831-0"

"HCTE-0625-0-SP-CS7679")

5660034007

(Alias Part Numbers:

"7-1194469-8")

462571M013

(Alias Part Numbers:

"3-1193469-8"

"NTFR-3/4-0-SP-CS7029")

661411M009

(Alias Part Numbers:

"1195214-9"

"NTFR-3/8-0SPCS5982")

F30249-000

(Alias Part Numbers:

"RT555-NO.1-0-SP")

5550124002

Product Affected

(Alias Part Numbers:

"3-1194379-2"

"NT-3-0-SP")

5580624004

(Alias Part Numbers:

"3-1194406-6"

"VPB-1-1/2-0SPCS5444")

CN9063-000

(Alias Part Numbers:

"VPB-1-1/4-0-SP-CS7733")

E34118-000

(Alias Part Numbers:

"7-1201249-2"

"DR-25-3-0-CSP-44FT")

CA3362-000

(Alias Part Numbers:

"VPB-1-0-SP-CS7733")

0997794004

(Alias Part Numbers:

"1-1190731-5"

"DR-25-NO.9-0-SP")

932299-000

(Alias Part Numbers:

"4-1197226-4"

"RT555-3/4-0-SP-CS7501")

CS1828-000

5660024001

(Alias Part Numbers:

"6-1194469-7"

"SFR-3/8-0-SP")

EF6039-000

(Alias Part Numbers:

"DR-25-1-1/2-0-50FT/CSP")

CW2591-000

526595M014

(Alias Part Numbers:

"1-1194138-7"

"NTFR-1-0-SP-CS5445")

5550274001

(Alias Part Numbers:

Product Affected

"5-1194379-2"

"NT-3/16-0-SP")

503359-000

(Alias Part Numbers:

"6-1193788-6"

"DR-25-NO.11-0-SP")

F47966-000

(Alias Part Numbers:

"9-1201727-1"

"NTFR-1/8-0-SP-CS7340")

5660404001

(Alias Part Numbers:

"4-1194470-3"

"SFR-1/8-0-SP")

CR8971-000

CZ4427-000

(Alias Part Numbers:

"RT-780-2-3-SP")

603262M001

(Alias Part Numbers:

"5-1194774-7"

"NTFR-2-0-SP-CS5982")

CW2770-000

173689-000

(Alias Part Numbers:

"3-1191263-9"

"NTFR-1/2-0-SP-CS6889")

069783M006

(Alias Part Numbers:

"1-1190525-3"

"NTFR-1/2-0SPCS5633")

C21127-000

(Alias Part Numbers:

"1202151-8"

"RT-780-1/2-0-SP")

CS9584-000

(Alias Part Numbers:

"SFR -NO.2-0-STK")

321555M005

(Alias Part Numbers:

Product Affected

"8-1192436-2"

"NTFR-1-3/4-0-SP-CS5445")

456575-000

(Alias Part Numbers:

"7-1193426-0"

"NTFR-5/8-0-SP-CS7340")

5660084001

(Alias Part Numbers:

"1194470-5"

"SFR-1-1/4-0-SP")

341925M015

(Alias Part Numbers:

"1-1192578-8"

"NTFR-1/4-0SPCS7229")

C28227-000

(Alias Part Numbers:

"4-1201241-6"

"RT555-5/8-0-44MM")

7391174004

(Alias Part Numbers:

"5-1195769-1"

"HCTE-0437-0-SP")

5660074001

(Alias Part Numbers:

"9-1194469-8"

"SFR-1-0-SP")

566016M005

(Alias Part Numbers:

"2-1194470-3")

028710-000

(Alias Part Numbers:

"8-1199945-6"

"DR-25-1/4-0-NM-SP")

526595M006

(Alias Part Numbers:

"1-1194138-0"

"NTFR-1-0SPCS5633")

293788-000

(Alias Part Numbers:

"1197949-7"

Product Affected

"HCTE-1000-0-SP-CS7063")

5660054001

(Alias Part Numbers:

"8-1194469-7"

"SFR-3/4-0-SP")

D15047-000

(Alias Part Numbers:

"5-1201833-2"

"NTFR-3/16-0-SP-CS6889")

025321-000

(Alias Part Numbers:

"1-1197854-6"

"RHSTTN38-3/8-0-SP")

797339M007

(Alias Part Numbers:

"6-1196169-6"

"NTFR-1-1/2-0SPCS6889")

E26016-000

(Alias Part Numbers:

"3-1200621-3"

"NT-MIL-3/16-0-SP")

558056M006

(Alias Part Numbers:

"8-1194405-6"

"VPB-1/4-0-SP-CS7127")

531751N001

(Alias Part Numbers:

"7-1194175-1"

"S1255-02-3/4X100FT-CS5442")

174477-000

(Alias Part Numbers:

"4-1197847-0"

"RHSTTN100-1-0-SP")

506635-000

(Alias Part Numbers:

"4-1193930-8"

"S1255-02-3/4X100FT-CS5370")

160353-000

(Alias Part Numbers:

"9-1191157-9"

Product Affected

"RT555-1-1/4-0-SP-CS7501")

007840-000

(Alias Part Numbers:

"1-1197949-7"

"HCTE-0375-0-SP-CS7063")

462571M008

(Alias Part Numbers:

"3-1193469-4"

"NTFR-3/4-0SPCS6243")

CX4407-000

CS2402-000

CX4401-000

5580594002

(Alias Part Numbers:

"1194406-4"

"VPB-3/4-0-SP")

566007M004

(Alias Part Numbers:

"1194470-2"

"SFR-1-0-SP-CS7099")

6032624006

(Alias Part Numbers:

"5-1194774-6"

"NTFR-2-0SPCS7029")

622902M009

(Alias Part Numbers:

"5-1194923-8"

"NTFR-1-1/4-0SPCS6243")

CV6035-000

(Alias Part Numbers:

"DR-25-1/2-0-730FT/CSP")

622330-000

(Alias Part Numbers:

"9-1198105-7"

"RHSTTN200-2-0-SP")

558061M009

(Alias Part Numbers:

"3-1194406-0"

"VPB-1-1/4-0SPCS7127")

555006M008

Product Affected

(Alias Part Numbers:

"6-1194378-2"

"NT-7/8-0-SP-CS5002")

560376M004

(Alias Part Numbers:

"5-1194423-9"

"NTFR-1/8-0SPCS5683")

D11555-000

(Alias Part Numbers:

"4-1200708-2"

"NT-MIL-2-0-SP")

5580574002

(Alias Part Numbers:

"8-1194405-9"

"VPB-3/8-0-SP")

4010894001

(Alias Part Numbers:

"5-1193028-9"

"VPB-2-1/2-0-SP")

5039266080

(Alias Part Numbers:

"9-1193798-4"

"DR-25-3/8-0-30MM")

F12355-000

(Alias Part Numbers:

"1-1201850-3"

"RT555-3/16-0-0.75IN")

5491534002

(Alias Part Numbers:

"5-1194321-7"

"NT-9/32-0-SP")

CX4399-000

503927M050

(Alias Part Numbers:

"9-1193799-9"

"DR-25-1/4-0-SP-CS7054")

C96433-000

(Alias Part Numbers:

"1200621-6"

"NT-MIL-1/4-0-SP")

Product Affected

6638954006

(Alias Part Numbers:

"2-1195232-1"

"HCTE-0500-0SPCS7301")

341925M009

(Alias Part Numbers:

"1-1192578-3"

"NTFR-1/4-0SPCS5962")

5660014001

(Alias Part Numbers:

"5-1194469-9"

"SFR-1/4-0-SP")

859869-000

(Alias Part Numbers:

"1-1197815-7"

"NTFR-3/8-0-SP-CS6327")

CP9373-000

(Alias Part Numbers:

"NT-MIL-3/8-0-CSP-500/1")

437165-000

(Alias Part Numbers:

"1193286-5"

"RT555-1/2-0-SP-CS7501")

1273314002

(Alias Part Numbers:

"8-1190925-2"

"MTZH-1-F9-0-SP")

341925M012

(Alias Part Numbers:

"1-1192578-6"

"NTFR-1/4-0SPCS6705")

516542M008

(Alias Part Numbers:

"4-1194056-6"

"NTFR-5/8-0SPCS6243")

CB9686-000

(Alias Part Numbers:

"RW-200-3/4-0-SP-CS5430")

CS2176-000

069783M009

Product Affected

(Alias Part Numbers:

"1-1190525-6"

"NTRF-1/2-0SPCS5984")

D36200-000

(Alias Part Numbers:

"9-1201969-2"

"RT-770-1-1/4-0-SP")

790235-000

(Alias Part Numbers:

"2-1196121-7"

"HTET-1/8-0-SP")

5580664002

(Alias Part Numbers:

"6-1194406-5"

"VPB-7/8-0-SP")

560376M005

(Alias Part Numbers:

"6-1194423-0"

"NTRF-1/8-0SPCS5984")

5294944004

(Alias Part Numbers:

"4-1194158-2"

"VPB-3/16-0SPCS5444")

558061M001

(Alias Part Numbers:

"2-1194406-9"

"VPB-1-1/4-0-SP-CS5821")

661411M010

(Alias Part Numbers:

"1-1195214-0"

"NTRF-3/8-0SPCS5984")

8918194004

(Alias Part Numbers:

"2-1196937-9"

"HCTE-0750-0-SP")

566006M005

(Alias Part Numbers:

"9-1194469-5")

1618474004

(Alias Part Numbers:

Product Affected

"6-1191168-9"

"HCTE-0625-0-SP")

CY2335-000

661411M001

(Alias Part Numbers:

"1195214-5"

"NTFR-3/8-0-SP-CS7340")

069783P014

(Alias Part Numbers:

"2-1190525-1"

"NTFR-1/2-0-350MM")

CJ6131-000

(Alias Part Numbers:

"9-1899298-7"

"RT-790-3/16-0-SP")

278276-000

(Alias Part Numbers:

"4-1200504-6"

"NTFR-3-0-SP-CS6705")

CB9561-000

(Alias Part Numbers:

"RW-200-1/4-0-SP-CS5430")

CF9054-000

(Alias Part Numbers:

"RW-200-1/8-0-SPMDBG-CS8751")

9053514002

(Alias Part Numbers:

"9-1197034-0"

"MTZH-1/8-F9-0-SP")

341925M013

(Alias Part Numbers:

"1-1192578-7"

"NTFR-1/4-0SPCS7029")

CX2390-000

1208484001

(Alias Part Numbers:

"9-1190878-7"

"NTFR-3/16-0-SP")

F41960-000

(Alias Part Numbers:

Product Affected

"1-1200684-2"

"NT-MIL-1-1/4-0-SP")

069783M013

(Alias Part Numbers:

"1-1190525-9"

"NTFR-1/2-0SPCS7229")

5550064009

(Alias Part Numbers:

"5-1194378-5"

"NT-7/8-0-SP")

462571M001

(Alias Part Numbers:

"3-1193469-1"

"NTFR-3/4-0-SP-CS5633")

141748-000

(Alias Part Numbers:

"7-1199216-8"

"S1048-TAPE-1X100FT-CS8431")

555008M008

(Alias Part Numbers:

"9-1194378-2"

"NT-1-1/4-0-SP-CS6069")

CJ2315-000

(Alias Part Numbers:

"RW-200-1/4-0-SP-CS7761")

5660014007

(Alias Part Numbers:

"6-1194469-3")

D86198-000

(Alias Part Numbers:

"2-1201165-0"

"NT-MIL-3-0-SP")

663895M003

(Alias Part Numbers:

"2-1195232-3"

"HCTE-0500-0-SP-CS7098")

558065M001

(Alias Part Numbers:

"6-1194406-0"

"VPB-5/8-0-SP-CS7278")

Product Affected

712134-000

(Alias Part Numbers:

"2-1199962-3"

"VPB-5/8-0-SP-CS7733")

341925M008

(Alias Part Numbers:

"1-1192578-2"

"NTFR-1/4-0SPCS5683")

828837T001

(Alias Part Numbers:

"3-1196472-6")

A97393-000

(Alias Part Numbers:

"RT-770-2-0-SP")

341925M016

(Alias Part Numbers:

"1-1192578-9"

"NTFR-1/4-0-SP-CS7340")

560376M007

(Alias Part Numbers:

"6-1194423-2"

"NTFR-1/8-0SPCS6705")

5550104002

(Alias Part Numbers:

"1-1194379-1"

"NT-1-3/4-0-SP")

5265954012

(Alias Part Numbers:

"1194138-6"

"NTFR-1-0SPCS7029")

304343M007

(Alias Part Numbers:

"8-1192304-9"

"NTFR-7/8-0SPCS5962")

CN8530-000

(Alias Part Numbers:

"RW-200-2-0-SP-CS7646")

2270594002

(Alias Part Numbers:

"7-1191671-7"

Product Affected

"HCTE-1625-0-SP")

CJ7935-000

(Alias Part Numbers:

"NT-MIL-NO.2-0-40IN")

C46223-000

(Alias Part Numbers:

"1-1202151-0"

"RT-780-1-0-SP")

5580604002

(Alias Part Numbers:

"1-1194406-5"

"VPB-1-0-SP")

5049814002

(Alias Part Numbers:

"1193814-9"

"MTZH-3/8-F9-0-SP")

555009M009

(Alias Part Numbers:

"1194379-6"

"NT-1-1/2-0-SP-CS6293")

5603764002

(Alias Part Numbers:

"5-1194423-7"

"NTFR-1/8-0-SP")

304343M012

(Alias Part Numbers:

"9-1192304-3"

"NTFR-7/8-0-SP-CS5445")

661411M012

(Alias Part Numbers:

"1-1195214-2"

"NTFR-3/8-0SPCS6705")

C23948-000

(Alias Part Numbers:

"RT-770-1/8-0-SP")

555003J014

(Alias Part Numbers:

"1-1194378-7"

"NT-1/2-0-SP-SM")

CL3456-000

Product Affected

(Alias Part Numbers:

"RW-200-1/4-0-SP-CS8773")

321555M001

(Alias Part Numbers:

"8-1192436-1"

"NTFR-1-3/4-0-SP-CS6889")

0697834016

(Alias Part Numbers:

"1-1190525-0"

"NTFR-1/2-0-SP-CS7340")

890060-000

(Alias Part Numbers:

"2-1196924-8"

"S1017-1.0X50")

D64130-000

(Alias Part Numbers:

"6-1200708-8"

"NT-MIL-1-0-SP")

C32412-000

(Alias Part Numbers:

"9-1200620-2"

"NT-MIL-1/2-0-SP")

CB3609-000

(Alias Part Numbers:

"S1048-TAPE-1X100FT-CS8731")

523858-000

(Alias Part Numbers:

"3-1198293-5"

"VPB-3-0-SP-CS5444")

5580624002

(Alias Part Numbers:

"3-1194406-5"

"VPB-1-1/2-0-SP")

797339M010

(Alias Part Numbers:

"6-1196169-7"

"NTFR-1-1/2-0-SP-CS5633")

CX5038-000

950643-000

(Alias Part Numbers:

Product Affected

"8-1197351-2"

"NTFR-1/4-0-SP-CS6069")

790377-000

(Alias Part Numbers:

"5-1197818-1"

"NTFR-1/4-0-SP-CS7387")

CU5619-000

558057M001

(Alias Part Numbers:

"9-1194405-1"

"VPB-3/8-0-SP-CS5821")

6032624002

(Alias Part Numbers:

"5-1194774-5"

"NTFR-2-0-SP")

0378234004

(Alias Part Numbers:

"1-1190292-6"

"HCTE-0875-0-SP")

069783M010

(Alias Part Numbers:

"1-1190525-7"

"NTFR-1/2-0SPCS6243")

656421M001

(Alias Part Numbers:

"9-1195176-9"

"NTFR-5/8-0-BULK-SP")

5039324007

(Alias Part Numbers:

"4-1193802-9"

"DR-25-1/8-0-SP"

"DR-25-1/8-0-SP"

"DR-25-1/8-0-SP-")

8623434002

(Alias Part Numbers:

"1-1196717-9"

"RT555-5/8-0-SP")

288042-000

(Alias Part Numbers:

"9-1197907-6"

Product Affected

"RHSTTN63-5/8-0-SP")

5580574004

(Alias Part Numbers:

"9-1194405-0"

"VPB-3/8-0SPCS5444")

CF9052-000

(Alias Part Numbers:

"RW-200-1/4-0-SPMDBG-CS8751")

966311-000

(Alias Part Numbers:

"3-1197472-2"

"NTFR-3/16-0-SP-CS7560")

5580654002

(Alias Part Numbers:

"5-1194406-6"

"VPB-5/8-0-SP")

CM6649-000

CB7764-000

(Alias Part Numbers:

"1-1899240-0"

"RW-200-1/8-0-SP")

0999094004

(Alias Part Numbers:

"1-1190732-2"

"HCTE-0375-0-SP")

C12594-000

(Alias Part Numbers:

"2-1201063-2"

"S1124-0.75X100FT-CS8562")

555001M007

(Alias Part Numbers:

"8-1194377-3"

"NT-1/4-0-SP-CS6826")

5660164003

(Alias Part Numbers:

"2-1194470-2"

"SFR-3/16-0-SP")

CB9689-000

(Alias Part Numbers:

"RW-200-1-1/4-0-SP-CS5430")

Product Affected

526595M008

(Alias Part Numbers:

"1-1194138-2"

"NTFR-1-0SPCS5982")

568493-000

(Alias Part Numbers:

"2-1194514-7"

"HTET-1-0-SP")

304343M006

(Alias Part Numbers:

"8-1192304-8"

"NTFR-7/8-0SPCS5683")

6229024012

(Alias Part Numbers:

"5-1194923-2"

"NTFR-1-1/4-0SPCS7029")

D27671-000

(Alias Part Numbers:

"RT-770-1-1/2-0-SP")

797339M005

(Alias Part Numbers:

"6-1196169-4"

"NTFR-1-1/2-0SPCS5962")

555001M014

(Alias Part Numbers:

"8-1194377-5"

"NT-1/4-0-SP-CS5480")

CN2041-000

797339M006

(Alias Part Numbers:

"6-1196169-5"

"NTFR-1-1/2-0SPCS6243")

120848M002

(Alias Part Numbers:

"1190879-1"

"NTFR-3/16-0-SP-CS7340")

CZ6860-000

(Alias Part Numbers:

"NTFR-1/2-0-SP-ESL")

661411M007

Product Affected

(Alias Part Numbers:

"1195214-7"

"NTFR-3/8-0SPCS5683")

035250-000

(Alias Part Numbers:

"5-1200171-1"

"S1048-TAPE-1X100FT-CS8469")

C39270-000

(Alias Part Numbers:

"3-1201921-1"

"RT-770-5/8-0-SP")

526595M007

(Alias Part Numbers:

"1-1194138-1"

"NTFR-1-0SPCS5962")

120848M006

(Alias Part Numbers:

"1190879-2"

"NTFR-3/16-0SPCS5683")

CB7841-000

(Alias Part Numbers:

"RW-200-3/4-0-SP"

"2-1899203-8")

3693074002

(Alias Part Numbers:

"4-1192767-4"

"RT555-1/2-0-SP")

0697834012

(Alias Part Numbers:

"1190525-9"

"NTFR-1/2-0SPCS7029")

304343M009

(Alias Part Numbers:

"9-1192304-1"

"NTFR-7/8-0SPCS6680")

F35905-000

(Alias Part Numbers:

"3-1200710-2"

"NT-MIL-1-1/2-0-SP")

CU4872-000

Product Affected

(Alias Part Numbers:

"NT-5/8-0-SP-CS5002")

F48748-000

(Alias Part Numbers:

"1201739-3"

"RT-780-3/8-0-SP")

3419254014

(Alias Part Numbers:

"1192578-7"

"NTFR-1/4-0SPCS7029")

CS1970-000

5039254029

(Alias Part Numbers:

"4-1193797-0"

"DR-25-3/4-0-SP"

"DR-25-3/4-0-SP")

CB9688-000

(Alias Part Numbers:

"RW-200-3/16-0-SP-CS5430")

341925M002

(Alias Part Numbers:

"1192578-9"

"NTFR-1/4-0-SP-CS6680")

C69150-000

(Alias Part Numbers:

"4-1201849-5"

"RT555-3/16-0-0.5IN")

531751-000

(Alias Part Numbers:

"7-1194175-0"

"S1255-02-3/4X100FT")

F44172-000

(Alias Part Numbers:

"9-1201892-8"

"NT-MIL-1/2-0-40IN")

CN9176-000

(Alias Part Numbers:

"VPB-1-1/2-0-SP-CS7733")

341768-000

(Alias Part Numbers:

Product Affected

"2-1197948-8"

"HCTE-1500-0-SP-CS7063")

5660174002

(Alias Part Numbers:

"2-1194470-6"

"SFR-1-3/4-0-SP")

536185M001

(Alias Part Numbers:

"1-1194209-8"

"NTFR-1/2-0-BULK-SP")

E83605-000

(Alias Part Numbers:

"4-1200621-8"

"NT-MIL-5/8-0-SP")

CM6650-000

C97747-000

(Alias Part Numbers:

"1200621-7"

"NT-MIL-1-0-BULK-SP")

CX4402-000

CB9684-000

(Alias Part Numbers:

"RW-200-5/8-0-SP-CS5430")

555029M001

(Alias Part Numbers:

"6-1194379-0"

"NT-1/8-0-SP-CS6826")

574039T001

(Alias Part Numbers:

"6-1194556-4")

F97757-000

(Alias Part Numbers:

"RT-780-1/8-0-SP")

157433-000

(Alias Part Numbers:

"6-1191137-0"

"HCTE-0750-0-SP-CS7575")

CX4404-000

343255-000

(Alias Part Numbers:

Product Affected

"1192586-7"

"S1017-1.0X50-CS6886")

CF6497-000

(Alias Part Numbers:

"S1255-02-3/4X100FT-CS8041")

CP2525-000

(Alias Part Numbers:

"RT-780-3/4-3-SP")

E33151-000

(Alias Part Numbers:

"9-1200147-8"

"NTFR-1/2-0-CONT-160/1-SP")

954615-000

(Alias Part Numbers:

"1197391-8"

"S1255-02-3/4X100FT-CS5561")

329858-000

(Alias Part Numbers:

"1-1201053-2"

"DR-25-1/2-0-350MM")

CN2042-000

CP4650-000

(Alias Part Numbers:

"RT-780-1-1/4-3-SP")

C35095-000

(Alias Part Numbers:

"9-1200620-3"

"NT-MIL-7/8-0-SP")

341925M010

(Alias Part Numbers:

"1-1192578-4"

"NTFR-1/4-0SPCS5984")

D56022-000

(Alias Part Numbers:

"5-1201738-1"

"RT-770-1/2-0-SP")

0181534002

(Alias Part Numbers:

"8-1190141-0"

"RT555-3/8-0-SP")

Product Affected

603262M005

(Alias Part Numbers:

"5-1194774-9"

"NTRF-2-0SPCS6705")

102010-000

(Alias Part Numbers:

"4-1198774-6"

"HCTE-0750-0-SP-CS7679")

5660044001

(Alias Part Numbers:

"8-1194469-2"

"SFR-5/8-0-SP")

5039234011

(Alias Part Numbers:

"5-1193795-6"

"DR-25-1-1/2-0-SP"

"DR-25-1-1/2-0-SP")

A45792-000

(Alias Part Numbers:

"1201242-4"

"RT555-1-0-50MM")

F25351-000

(Alias Part Numbers:

"7-1201432-1"

"NTRF-1/8-0-SP-CS7387")

4438994002

(Alias Part Numbers:

"1-1193336-2"

"RT555-3/16-0-SP")

2416954003

(Alias Part Numbers:

"6-1191775-4"

"MTZH-1-1/2-F9-0-SP-CS7427")

CX2203-000

(Alias Part Numbers:

"RT555-1/2-0-70MM")

F70260-000

(Alias Part Numbers:

"RT-780-1-1/4-0-SP")

F38290-000

Product Affected

(Alias Part Numbers:

"9-1201738-8"

"RT-780-5/8-0-SP")

408771-000

(Alias Part Numbers:

"3-1193083-9"

"VPB-1-1/4-0-SP-CS7012")

CW9389-000

489945-000

(Alias Part Numbers:

"2-1193665-9"

"VPB-1/4-0-SP-CS7278")

C21039-000

(Alias Part Numbers:

"1201738-9"

"RT-770-1/4-0-SP")

114001-000

(Alias Part Numbers:

"4-1190831-0"

"NTFR-3/4-0-SP-CS6880")

526595M013

(Alias Part Numbers:

"1-1194138-6"

"NTFR-1-0-SP-CS7340")

661411M015

(Alias Part Numbers:

"1-1195214-4"

"NTFR-3/8-0-SP-CS5445")

CB7765-000

(Alias Part Numbers:

"RW-200-3/8-0-SP"

"2-1899203-9")

5580644001

(Alias Part Numbers:

"4-1194406-9"

"VPB-3-0-SP")

CS1972-000

462571M014

(Alias Part Numbers:

"3-1193469-9"

Product Affected

"NTRF-3/4-0-SP-CS5445")

1219394001

(Alias Part Numbers:

"6-1190887-8"

"NT-1-1/2-0-CONT-SP")

CL0544-000

(Alias Part Numbers:

"RT555-1/8-0-MDBGSP-CS8768")

422825-000

(Alias Part Numbers:

"1-1193184-9"

"RT555-1/4-0-SP-CS7501")

057873-000

(Alias Part Numbers:

"5-1190439-0"

"NTRF-7/8-0-SP-CS6889")

3821734002

(Alias Part Numbers:

"6-1192857-2"

"RT555-3/4-0-SP")

E54361-000

(Alias Part Numbers:

"2-1201261-4"

"FET-1/2-0-SP")

069783M011

(Alias Part Numbers:

"1-1190525-8"

"NTRF-1/2-0SPCS6705")

918755P003

(Alias Part Numbers:

"2-1197130-8"

"RT555-1/4-0-1IN")

E42130-000

(Alias Part Numbers:

"3-1200621-9"

"NT-MIL-3/8-0-BULK-SP")

D33057-000

(Alias Part Numbers:

"9-1200147-3"

"NTRF-5/8-0-CONT-105/1-SP")

Product Affected

5265954002

(Alias Part Numbers:

"1194138-5"

"NTFR-1-0-SP")

239061-000

(Alias Part Numbers:

"1-1197909-9"

"NTFR-2-0-SP-CS6243")

CS2177-000

CX4405-000

F90576-000

(Alias Part Numbers:

"7-1201239-6"

"RT555-3/8-0-25MM")

CB7838-000

(Alias Part Numbers:

"RW-200-1/4-0-SP"

"RW-200-1/4-0-SP"

"6-1899771-0")

CP0582-000

F12102-000

(Alias Part Numbers:

"5-1201832-0"

"HCTE-0500-0-SP-CS7679")

0697834002

(Alias Part Numbers:

"1190525-7"

"NTFR-1/2-0-SP")

8418254001

(Alias Part Numbers:

"2-1196567-4"

"NTFR-NO.1-0-SP")

560376M006

(Alias Part Numbers:

"6-1194423-1"

"NTFR-1/8-0SPCS6243")

CS8105-000

658683-000

(Alias Part Numbers:

"8-1195192-4"

Product Affected

"NTRF-3/16-0-SP-CS5445")

C34634-000

(Alias Part Numbers:

"1-1201999-7"

"RT555-3/8-0-120MM")

D51558-000

(Alias Part Numbers:

"5-1200708-8"

"NT-MIL-3/4-0-SP")

5165424010

(Alias Part Numbers:

"3-1194056-9"

"NTRF-5/8-0SPCS7029")

5550054021

(Alias Part Numbers:

"4-1194378-4"

"NT-3/4-0-SP-CS5002")

CL0549-000

(Alias Part Numbers:

"RT555-5/8-0-MDBGSP-CS8768")

5550134002

(Alias Part Numbers:

"4-1194379-1"

"NT-4-0-SP")

532953-000

(Alias Part Numbers:

"9-1197859-8"

"NT-1/4-0-SP-CS6361")

EG4263-000

D25800-000

(Alias Part Numbers:

"1-1202151-3"

"RT-780-3/4-0-SP")

5147664004

(Alias Part Numbers:

"4-1194043-7"

"NTRF-3-0SPCS7029")

558059M001

(Alias Part Numbers:

"1194406-8"

Product Affected

"VPB-3/4-0-SP-CS7127")

315149-000

(Alias Part Numbers:

"7-1192384-6"

"RT555-5/8-0-SP-CS7501")

967461-000

(Alias Part Numbers:

"1197873-9"

"RHSTTN25-1/4-0-SP")

526595M001

(Alias Part Numbers:

"1194138-8"

"NTRF-1-0-SP")

0092794001

(Alias Part Numbers:

"1190072-6"

"DR-25-3/4-0-CS-115107")

CX5037-000

161415T001

(Alias Part Numbers:

"5-1191165-6")

773045M003

(Alias Part Numbers:

"6-1196020-1"

"HCTE-1250-0-SP-CS7063")

F24044-000

(Alias Part Numbers:

"2-1200710-9"

"NT-MIL-3/8-0-SP")

EG3252-000

(Alias Part Numbers:

"RW-200-3/32-0-SP")

555007M008

(Alias Part Numbers:

"7-1194378-7"

"NT-1-0-SP-CS7364")

5294944002

(Alias Part Numbers:

"4-1194158-1"

"VPB-3/16-0-SP")

Product Affected

6614114002

(Alias Part Numbers:

"9-1195213-9"

"NTFR-3/8-0-SP")

3832174001

(Alias Part Numbers:

"5-1192872-2"

"DR-25-1-0-CS-115108")

526595M011

(Alias Part Numbers:

"1-1194138-5"

"NTFR-1-0SPCS6705")

5580594010

(Alias Part Numbers:

"1194406-5"

"VPB-3/4-0SPCS5444")

CU5618-000

661411M011

(Alias Part Numbers:

"1-1195214-1"

"NTFR-3/8-0SPCS6243")

D03893-000

(Alias Part Numbers:

"1201256-7"

"DR-25-3-0-CSP-50FT")

5147664002

(Alias Part Numbers:

"4-1194043-6"

"NTFR-3-0-SP")

E97372-000

(Alias Part Numbers:

"1200710-9"

"NT-MIL-1-3/4-0-SP")

890113-000

(Alias Part Numbers:

"9-1196924-2"

"S1048-TAPE-1X100-FT")

622902M007

(Alias Part Numbers:

"5-1194923-6"

Product Affected

"NTFR-1-1/4-0SPCS5633")

F52847-000

(Alias Part Numbers:

"1201739-6"

"RT-770-3/8-0-SP")

5039294018

(Alias Part Numbers:

"1-1193800-2"

"DR-25-3/16-0-SP")

CP6531-000

(Alias Part Numbers:

"NTFR-5/8-0-CSP-165/2")

A65435-000

(Alias Part Numbers:

"9-1200621-1"

"NT-MIL-1/8-0-SP")

998210-000

(Alias Part Numbers:

"3-1197950-3"

"HCTE-2000-0-SP-CS7063")

6614114013

(Alias Part Numbers:

"1195214-1"

"NTFR-3/8-0SPCS7029")

CW8430-000

(Alias Part Numbers:

"RT555-1/4-0-0.375IN")

797339M011

(Alias Part Numbers:

"6-1196169-8"

"NTFR-1-1/2-0-SP-CS5445")

CF9840-000

(Alias Part Numbers:

"RW-200-1/2-0-SPMDBG-CS8751")

516542M011

(Alias Part Numbers:

"4-1194056-8"

"NTFR-5/8-0-SP-CS6680")

3419254003

(Alias Part Numbers:

Product Affected

"1192578-6"

"NTFR-1/4-0-SP")

4625714010

(Alias Part Numbers:

"2-1193469-8"

"NTFR-3/4-0SPCS7029")

304343M010

(Alias Part Numbers:

"9-1192304-2"

"NTFR-7/8-0SPCS6705")

120848M008

(Alias Part Numbers:

"1190879-4"

"NTFR-3/16-0-SP-CS5982")

5550024014

(Alias Part Numbers:

"9-1194377-2"

"NT-3/8-0-SP")

558060M009

(Alias Part Numbers:

"2-1194406-0"

"VPB-1-0SPCS7127")

CS1969-000

CW4651-000

CL7866-000

(Alias Part Numbers:

"NTFR-7/8-0-SP-CS7387")

661411M006

(Alias Part Numbers:

"1195214-6"

"NTFR-3/8-0SPCS5633")

5580564002

(Alias Part Numbers:

"8-1194405-2"

"VPB-1/4-0-SP")

566001M004

(Alias Part Numbers:

"6-1194469-4"

"SFR-1/4-0-SP-CS5007")

3679754004

Product Affected

(Alias Part Numbers:

"4-1192758-1"

"HCTE-1000-0-SP")

5550294002

(Alias Part Numbers:

"5-1194379-7"

"NT-1/8-0-SP")

5580654008

(Alias Part Numbers:

"5-1194406-7"

"VPB-5/8-0SPCS5444")

CP2523-000

(Alias Part Numbers:

"RT-780-1/2-3-SP")

558063M001

(Alias Part Numbers:

"4-1194406-4"

"VPB-2-0-SP-CS7007")

5039364006

(Alias Part Numbers:

"1-1193803-2"

"DR-25-3-0-SP")

5580634002

(Alias Part Numbers:

"4-1194406-0"

"VPB-2-0-SP")

069783M001

(Alias Part Numbers:

"1-1190525-2"

"NTFR-1/2-0-SP-CS6492")

6269314002

(Alias Part Numbers:

"9-1194964-7"

"RT555-1/16-0-SP")

890103N001

(Alias Part Numbers:

"7-1196924-8"

"S1124-0.75X100FT-CS5382")

116035-000

(Alias Part Numbers:

Product Affected

"1-1197850-8"

"NTFR-3/4-0-SP-CS6680")

CP2527-000

(Alias Part Numbers:

"RT-780-3/8-3-SP")

0638514002

(Alias Part Numbers:

"9-1190482-8"

"HCTE-0312-0-SP")

CS1971-000

6229024003

(Alias Part Numbers:

"5-1194923-1"

"NTFR-1-1/4-0-SP")

CB9560-000

(Alias Part Numbers:

"RW-200-1/2-0-SP-CS5430")

555004M016

(Alias Part Numbers:

"3-1194378-4"

"NT-5/8-0SPCS7387")

813221M001

(Alias Part Numbers:

"9-1196326-3"

"NTFR-3/4-0-BULK-SP")

CU5620-000

5491534003

(Alias Part Numbers:

"5-1194321-8"

"NT-9/32-0-ASP")

758777-000

(Alias Part Numbers:

"1195912-3"

"HCTE-1000-0-SP-CS7630")

566004M003

(Alias Part Numbers:

"8-1194469-4"

"SFR-5/8-0-SP-CS7099")

516542M012

(Alias Part Numbers:

Product Affected

"4-1194056-9"

"NTFR-5/8-0-SP-CS5445")

526595M009

(Alias Part Numbers:

"1-1194138-3"

"NTFR-1-0SPCS6243")

CN2588-000

CL8585-000

(Alias Part Numbers:

"RW-200-1/4-0-SP-CS8778")

4625714002

(Alias Part Numbers:

"2-1193469-7"

"NTFR-3/4-0-SP")

069783M008

(Alias Part Numbers:

"1-1190525-5"

"NTFR-1/2-0SPCS5962")

CL0548-000

(Alias Part Numbers:

"RT555-1/2-0-MDBGSP-CS8768")

503927M100

(Alias Part Numbers:

"1193800-1"

"DR-25-1/4-0SPCS6938")

084145-000

(Alias Part Numbers:

"8-1190621-4"

"NTFR-3/4-0-CSP-165/1")

873085-000

(Alias Part Numbers:

"3-1197878-3"

"NTFR-1/4-0-SP-CS6889")

CX5039-000

874246-000

(Alias Part Numbers:

"1197925-6"

"RHSTTN50-1/2-0-SP")

3043434011

(Alias Part Numbers:

Product Affected

"8-1192304-4"

"NTFR-7/8-0SPCS7029")

CL0960-000

(Alias Part Numbers:

"RT555-1-0-MDBGSP-CS8768")

5550094010

(Alias Part Numbers:

"9-1194378-9"

"NT-1-1/2-0-SP")

558060M001

(Alias Part Numbers:

"1-1194406-9"

"VPB-1-0-SP-CS7278")

182455M001

(Alias Part Numbers:

"7-1191325-8"

"NTFR-7/8-0-BULK-SP")

4596494001

(Alias Part Numbers:

"7-1193447-4"

"NTFR-3-0-CONT-65/1-SP")

555004M007

(Alias Part Numbers:

"3-1194378-3"

"NT-5/8-0-SP-CS6826")

8946734002

(Alias Part Numbers:

"7-1196957-5"

"VPB-1/8-0-SP")

4010894004

(Alias Part Numbers:

"6-1193028-0"

"VPB-2-1/2-0SPCS5444")

CM9025-000

5580564004

(Alias Part Numbers:

"8-1194405-3"

"VPB-1/4-0SPCS5444")

9965874002

(Alias Part Numbers:

Product Affected

"1-1197706-9"

"RT555-1-0-SP")

CM8713-000

514766M001

(Alias Part Numbers:

"4-1194043-8"

"NTFR-3-0-SP")

CS5319-000

558062M001

(Alias Part Numbers:

"3-1194406-7"

"VPB-1-1/2-0-SP-CS7180")

665458-000

(Alias Part Numbers:

"3-1199834-2"

"NT-NO.495-0-ASP")

589414-000

(Alias Part Numbers:

"9-1199836-4"

"RHSTTN175-1-3/4-0-SP")

341925M017

(Alias Part Numbers:

"2-1192578-0"

"NTFR-1/4-0-SP-CS5445")

037823M003

(Alias Part Numbers:

"1-1190292-8"

"HCTE-0875-0-SP-CS7063")

CP2529-000

(Alias Part Numbers:

"RT-780-5/8-3-SP")

CL0545-000

(Alias Part Numbers:

"RT555-3/16-0-MDBGSP-CS8768")

566003M004

(Alias Part Numbers:

"7-1194469-9"

"SFR-1/2-0-SP-CS5007")

E10575-000

(Alias Part Numbers:

Product Affected

"8-1201185-0"

"S1124-0.75X100FT-CS8609")

3000294002

(Alias Part Numbers:

"6-1192272-5"

"MTZH-1/4-F9-0-SP")

CN6613-000

CU5622-000

099909M003

(Alias Part Numbers:

"1-1190732-7"

"HCTE-0375-0-SP-CS7397")

815493-000

(Alias Part Numbers:

"5-1196355-5"

"RT555-1-1/2-0-SP-CS7501")

986394-000

(Alias Part Numbers:

"6-1199646-2")

433901-000

(Alias Part Numbers:

"9-1197901-0"

"RHSTTN300-3-0-SP")

558066M001

(Alias Part Numbers:

"6-1194406-7"

"VPB-7/8-0-SP-CS7278")

069129-000

(Alias Part Numbers:

"6-1190520-2"

"RT555-3/8-0-SP-CS7501")

868685-000

(Alias Part Numbers:

"6-1196762-9"

"NTFR-1-3/4-0-CSP-50/1")

5580614002

(Alias Part Numbers:

"2-1194406-5"

"VPB-1-1/4-0-SP")

CP2533-000

Product Affected

(Alias Part Numbers:
"RT-780-1-1/2-3-SP")
890103-000

(Alias Part Numbers:
"7-1196924-4"
"S1124-TAPE-0.75X100-FT")
5580664004

(Alias Part Numbers:
"6-1194406-6"
"VPB-7/8-0SPCS5444")
797339M001

(Alias Part Numbers:
"6-1196169-3"
"NTFR-1-1/2-0-SP-CS6492")
CF1592-000

(Alias Part Numbers:
"VPB-1/2-0-SP-CS7012")
6614114016

(Alias Part Numbers:
"1195214-2"
"NTFR-3/8-0-SP-CS7387")
CW6821-000

341925M007
(Alias Part Numbers:
"1-1192578-1"
"NTFR-1/4-0SPCS5633")

891819M003
(Alias Part Numbers:
"3-1196937-0"
"HCTE-0750-0-SP-CS7063")

510381T001
(Alias Part Numbers:
"7-1194011-2")
120848M007

(Alias Part Numbers:
"1190879-3"
"NTFR-3/16-0SPCS6680")
069783M007

(Alias Part Numbers:
"1-1190525-4"

Product Affected

"NTFR-1/2-0SPCS5683")

042565M001

(Alias Part Numbers:

"3-1190326-4"

"NTFR-3/8-0-BULK-SP")

227059M003

(Alias Part Numbers:

"7-1191671-9"

"HCTE-1625-0-SP-CS7063")

CZ6618-000

(Alias Part Numbers:

"NTFR-3/8-0-SP-ESL")

5550074007

(Alias Part Numbers:

"6-1194378-8"

"NT-1-0-SP")

304343M005

(Alias Part Numbers:

"8-1192304-7"

"NTFR-7/8-0SPCS5633")

7730454002

555008M015

(Alias Part Numbers:

"9-1194378-3"

"NT-1-1/4-0SPCS6361")

A71386-000

(Alias Part Numbers:

"3-1200479-1"

"FET-1-1/2-0-SP")

946233-000

(Alias Part Numbers:

"6-1197322-4"

"RT555-1-0-SP-CS7501")

425670-000

(Alias Part Numbers:

"5-1198293-9"

"NTFR-1-3/4-0-SP-CS6327")

555002M025

(Alias Part Numbers:

"1194378-3"

Product Affected

"NT-3/8-0-SP-CS5338")

6638954004

(Alias Part Numbers:

"2-1195232-0"

"HCTE-0500-0-SP")

666474-000

(Alias Part Numbers:

"6-1199428-4"

"RT555-3/16-0-1IN")

7788694001

(Alias Part Numbers:

"9-1196061-9"

"DR-25-1/2-0-CS-115106")

982105-000

(Alias Part Numbers:

"1197588-4"

"HCTE-1000-0-SP-CS7575")

161847M003

(Alias Part Numbers:

"7-1191168-0"

"HCTE-0625-0-SP-CS7063")

3215554002

(Alias Part Numbers:

"7-1192436-9"

"NTFR-1-3/4-0-SP")

558009B023

(Alias Part Numbers:

"2-1198877-0")

462571M009

(Alias Part Numbers:

"3-1193469-5"

"NTFR-3/4-0SPCS6705")

CB7840-000

(Alias Part Numbers:

"RW-200-5/8-0-SP"

"2-1899203-4")

558008B023

(Alias Part Numbers:

"1-1198877-9")

5165424002

Product Affected

(Alias Part Numbers:

"3-1194056-8"

"NTFR-5/8-0-SP")

069783M015

(Alias Part Numbers:

"2-1190525-0"

"NTFR-1/2-0-SP-CS5445")

CW5416-000

CB7837-000

(Alias Part Numbers:

"1-1899445-4"

"RW-200-3/16-0-SP")

359385-000

(Alias Part Numbers:

"2-1192696-5"

"NTFR-1/8-0-SP-CS5633")

622902M008

(Alias Part Numbers:

"5-1194923-7"

"NTFR-1-1/4-0SPCS5962")

CB9691-000

(Alias Part Numbers:

"RW-200-1-0-SP-CS5430")

D42165-000

(Alias Part Numbers:

"8-1201773-1"

"RT555-3/8-0-1.5IN")

CB9692-000

(Alias Part Numbers:

"RW-200-1/8-0-SP-CS5430")

5039274019

(Alias Part Numbers:

"4-1193799-3"

"DR-25-1/4-0-SP"

"DR-25-1/4-0-SP")

A09251-000

(Alias Part Numbers:

"9-1201929-8"

"RT-770-3/4-0-SP")

CB7766-000

Product Affected

(Alias Part Numbers:

"6-1899816-0"

"RW-200-1-0-SP")

5550114002

(Alias Part Numbers:

"2-1194379-2"

"NT-2-0-SP")

682889-000

(Alias Part Numbers:

"3-1195367-4"

"S1017-1.0X50-CS8192")

CB7839-000

(Alias Part Numbers:

"RW-200-1/2-0-SP"

"7-1899210-2")

516542M001

(Alias Part Numbers:

"4-1194056-2"

"NTFR-5/8-0-SP-CS5633")

394517-000

(Alias Part Numbers:

"6-1197837-6"

"RHSTTN150-1-1/2-0-SP")

CW5415-000

555003M012

(Alias Part Numbers:

"1-1194378-8"

"NT-1/2-0-SP-CS6293")

7973394002

(Alias Part Numbers:

"5-1196169-9"

"NTFR-1-1/2-0-SP")

CF9053-000

(Alias Part Numbers:

"RW-200-3/16-0-SPMDBG-CS8751")

E31316-000

(Alias Part Numbers:

"7-1201738-6"

"RT-770-1-0-SP")

A84440-000

Product Affected

(Alias Part Numbers:

"8-1201253-9"

"NPL-3/8-0-SP")

622902M011

(Alias Part Numbers:

"6-1194923-0"

"NTFR-1-1/4-0SPCS6705")

210048-000

(Alias Part Numbers:

"6-1197950-9"

"HCTE-1750-0-SP-CS7063")

5580634008

(Alias Part Numbers:

"4-1194406-1"

"VPB-2-0SPCS5444")

462571M006

(Alias Part Numbers:

"3-1193469-2"

"NTFR-3/4-0SPCS5962")

CJ4328-000

(Alias Part Numbers:

"NTFR-5/8-0-SP-CS6889")

676494-000

(Alias Part Numbers:

"5-1197951-8"

"NTFR-7/8-0-SP-CS7340")

CP6356-000

(Alias Part Numbers:

"SET-1/8-0-SP")

D72576-000

(Alias Part Numbers:

"3-1201716-5"

"SET-1/2-0-SP")

CU3843-000

5039314011

(Alias Part Numbers:

"1193802-5"

"DR-25-2-0-SP")

9693274004

(Alias Part Numbers:

Product Affected

"1-1197494-4"

"HCTE-1750-0-SP")

980971-000

(Alias Part Numbers:

"3-1197580-4"

"RT555-1-0-SP-MU50FT")

CB1491-000

(Alias Part Numbers:

"HCTE-0437-0-2.3IN")

555009M014

(Alias Part Numbers:

"1194379-7"

"NT-1-1/2-0SPCS6361")

517233M003

(Alias Part Numbers:

"1-1194061-6"

"HCTE-0281-0-SP-CS7063")

7662514004

(Alias Part Numbers:

"9-1195971-1"

"HCTE-1500-0-SP")

C20427-000

(Alias Part Numbers:

"RT-770-3/16-0-SP")

5580614008

(Alias Part Numbers:

"2-1194406-6"

"VPB-1-1/4-0SPCS5444")

5660114004

(Alias Part Numbers:

"1-1194470-6"

"SFR-2-0-SP")

CX5036-000

304343M008

(Alias Part Numbers:

"9-1192304-0"

"NTFR-7/8-0SPCS6243")

6427934002

(Alias Part Numbers:

"3-1195079-9"

Product Affected

"MTZH-2-F9-0-SP")

603262M007

(Alias Part Numbers:

"6-1194774-0"

"NTFR-2-0-SP-CS5683")

C53028-000

(Alias Part Numbers:

"2-1201754-3"

"S1017-1.0X50-CS8674")

526595M010

(Alias Part Numbers:

"1-1194138-4"

"NTFR-1-0SPCS6680")

CA5245-000

(Alias Part Numbers:

"NT-1-1/4-0-SP-CS5002")

5660064004

(Alias Part Numbers:

"9-1194469-4"

"SFR-7/8-0-SP")

566005M004

(Alias Part Numbers:

"9-1194469-0"

"SFR-3/4-0-SP-CS6336")

1635014002

(Alias Part Numbers:

"1191180-7"

"RT555-1-1/4-0-SP")

9466874002

(Alias Part Numbers:

"8-1197325-0"

"MTZH-3/16-F9-0-SP")

462571M012

(Alias Part Numbers:

"3-1193469-7"

"NTFR-3/4-0-SP-CS7340")

CB1490-000

(Alias Part Numbers:

"NT-MIL-1/4-0-CSP-300/1")

304343M001

Product Affected

(Alias Part Numbers:

"8-1192304-6"

"NTFR-7/8-0-SP-CS6223")

F04555-000

(Alias Part Numbers:

"1-1200442-1"

"NTFR-1-3/4-0-SP-CS5633")

CF9055-000

(Alias Part Numbers:

"RW-200-3/8-0-SPMDBG-CS8751")

6790994004

(Alias Part Numbers:

"4-1195338-0"

"HCTE-0187-0-SP")

603262M004

(Alias Part Numbers:

"5-1194774-8"

"NTFR-2-0SPCS5962")

1719534002

(Alias Part Numbers:

"8-1191250-0"

"RT555-2-0-SP")

9187554002

(Alias Part Numbers:

"2-1197130-7"

"RT555-1/4-0-SP")

5039264026

(Alias Part Numbers:

"4-1193798-8"

"DR-25-3/8-0-SP"

"DR-25-3/8-0-SP")

CR7068-000

(Alias Part Numbers:

"NTFR-1/2-0-ASP")

5580584008

(Alias Part Numbers:

"9-1194405-5"

"VPB-1/2-0SPCS5444")

137502-000

(Alias Part Numbers:

Product Affected

"3-1198870-0"

"NT-1/2-0-SP-CS5002")

682009M001

(Alias Part Numbers:

"1-1195361-0"

"NTFR-1/8-0-BULK-SP")

492049-000

(Alias Part Numbers:

"5-1197865-9"

"NTFR-3/4-0-SP-CS6889")

462571M007

(Alias Part Numbers:

"3-1193469-3"

"NTFR-3/4-0SPCS5984")

CB7842-000

(Alias Part Numbers:

"RW-200-7/8-0-SP")

382173P003

(Alias Part Numbers:

"6-1192857-3"

"RT555-3/4-0-60MM")

CX1049-000

CB9690-000

(Alias Part Numbers:

"RW-200-1-1/2-0-SP-CS5430")

558058M001

(Alias Part Numbers:

"9-1194405-8"

"VPB-1/2-0-SP-CS7007")

143283-000

(Alias Part Numbers:

"9-1191036-0"

"RT555-2-0-SP-CS7501")

CM9747-000

CZ6861-000

(Alias Part Numbers:

"NTFR-1/4-0-SP-ESL")

CB9659-000

(Alias Part Numbers:

"RW-200-1/8-0-6IN")

Product Affected

890113N002

(Alias Part Numbers:

"9-1196924-5"

"S1048-TAPE-1X100FT-CS8323")

D67481-000

(Alias Part Numbers:

"2-1200621-0"

"NT-MIL-3/4-0-BULK-SP")

368401-000

(Alias Part Numbers:

"6-1197838-4"

"RHSTTN75-3/4-0-SP")

5550054014

(Alias Part Numbers:

"4-1194378-0"

"NT-3/4-0-SP")

514766M005

(Alias Part Numbers:

"4-1194043-9"

"NTFR-3-0-SP-CS5445")

5580584002

(Alias Part Numbers:

"9-1194405-4"

"VPB-1/2-0-SP")

D11869-000

(Alias Part Numbers:

"8-1201240-8"

"RT555-5/8-0-38MM")

341925M011

(Alias Part Numbers:

"1-1192578-5"

"NTFR-1/4-0SPCS6243")

555001M013

(Alias Part Numbers:

"8-1194377-4"

"NT-1/4-0SPCS5002")

CL0547-000

(Alias Part Numbers:

"RT555-3/8-0-MDBGSP-CS8768")

CR0976-000

Product Affected

7536494002

(Alias Part Numbers:

"5-1195875-0"

"RT555-1/8-0-SP")

516542M007

(Alias Part Numbers:

"4-1194056-5"

"NTFR-5/8-0SPCS5962")

2025294002

(Alias Part Numbers:

"3-1191468-2"

"MTZH-3/4-F9-0-SP")

CB9687-000

(Alias Part Numbers:

"RW-200-3/4-0-SP-CS5003")

462571M011

(Alias Part Numbers:

"3-1193469-6"

"NTFR-3/4-0SPCS7382")

070736-000

(Alias Part Numbers:

"4-1199112-9"

"NTFR-2-0-SP-CS6889")

EF6040-000

(Alias Part Numbers:

"DR-25-1-0-100FT/CSP")

555013M005

(Alias Part Numbers:

"4-1194379-3"

"NT-4-0-SP-CS7029")

5660094006

(Alias Part Numbers:

"1-1194470-2"

"SFR-1-1/2-0-SP")

516542M006

(Alias Part Numbers:

"4-1194056-4"

"NTFR-5/8-0SPCS5683")

603262M008

(Alias Part Numbers:

Product Affected

"6-1194774-1"

"NTFR-2-0-SP-CS5445")

D08165-000

(Alias Part Numbers:

"1-1201660-6"

"SET-3/8-0-SP")

769249-000

(Alias Part Numbers:

"2-1195994-5"

"NTFR-1-0-SP-CS6889")

F01946-000

(Alias Part Numbers:

"8-1201078-9"

"NT-MIL-4-0-SP")

5172334004

(Alias Part Numbers:

"1-1194061-5"

"HCTE-0281-0-SP")

F37937-000

(Alias Part Numbers:

"5-1201239-3"

"RT555-3/4-0-44MM")

5039244037

(Alias Part Numbers:

"3-1193796-5"

"DR-25-1-0-SP")

3215554004

(Alias Part Numbers:

"8-1192436-0"

"NTFR-1-3/4-0SPCS7029")

2416954002

(Alias Part Numbers:

"6-1191775-3"

"MTZH-1-1/2-F9-0-SP")

CX4408-000

CV5539-000

(Alias Part Numbers:

"NT-MIL-4-0-SP-ESL")

F67816-000

(Alias Part Numbers:

Product Affected

"RT-780-3/16-0-SP")

CW4997-000

(Alias Part Numbers:

"S1048-TAPE-1/2X100-FT")

CS8104-000

875253-000

(Alias Part Numbers:

"7-1196808-1"

"SFR-3/8-0-SP-CS7536")

5550034011

(Alias Part Numbers:

"1-1194378-1"

"NT-1/2-0-SP")

CL0546-000

(Alias Part Numbers:

"RT555-1/4-0-MDBGSP-CS8768")

5580604008

(Alias Part Numbers:

"1-1194406-6"

"VPB-1-0SPCS5444")

CX9423-000

(Alias Part Numbers:

"DR-25-3/8-0-200FT/CSP")

558056M005

(Alias Part Numbers:

"8-1194405-5"

"VPB-1/4-0SPCS5821")

CS2401-000

CA7301-000

(Alias Part Numbers:

"DR-25-3/4-0-80M/CSP")

5660034001

(Alias Part Numbers:

"7-1194469-4"

"SFR-1/2-0-SP")

503930M066

(Alias Part Numbers:

"8-1193801-4"

"DR-25-1/2-0-SP-CS7143")

763701-000

Product Affected

(Alias Part Numbers:

"1195946-8"

"VPB-3/4-0-SP-CS7278")

5039304024

(Alias Part Numbers:

"7-1193800-4"

"DR-25-1/2-0-SP"

"DR-25-1/2-0-SP")

CB7843-000

(Alias Part Numbers:

"RW-200-1-1/4-0-SP")

EJ0999-000

(Alias Part Numbers:

"DR-25-2-0-75FT/CSP")

CP2531-000

(Alias Part Numbers:

"RT-780-1-3-SP")

0459334001

(Alias Part Numbers:

"1190353-5"

"FIT-600-3-BK-SP")

CA0981-000

(Alias Part Numbers:

"VPB-1/4-0-SP-CS7012")

689919M001

(Alias Part Numbers:

"7-1195417-8"

"NTFR-1-0-BULK-SP")

560376M008

(Alias Part Numbers:

"6-1194423-3"

"NTFR-1/8-0-SP-CS5445")

915157-000

(Alias Part Numbers:

"8-1197104-2"

"NTFR-3/8-0-SP-CS6889")

CB7844-000

(Alias Part Numbers:

"RW-200-1-1/2-0-SP")

CW4999-000

Product Affected

(Alias Part Numbers:

"S1048-TAPE-3/4X100-FT")

5550084009

(Alias Part Numbers:

"8-1194378-3"

"NT-1-1/4-0-SP")

5039256141

(Alias Part Numbers:

"1-1193798-6"

"DR-25-3/4-0-2IN")

4438994003

(Alias Part Numbers:

"1-1193336-3"

"RT555-3/16-0-SP-CS7501")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.