



07-Jul-2016

PCN #:P-16-013266

Subject:SUPERSEAL 1.5 SERIES 1P PLUG ASSY

Description of Change: For following component part number we have built a new tool:282056-1,282056-2,1-282056-2.

Reason: Customer Request.Dear Customer, we hereby inform you about a tool replacement of a molding tool for the above mentioned part-Number. As a result of our continuous strive for quality improvements of our production, we hereby inform you upfront about a new tool, which is under construction In order to meet all specification requirements to replace the current one, which is worn out.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:14-Oct-2016

Implementation Date:14-Oct-2016

Product Affected

1-282079-2

282079-2

2-282079-2

282079-3

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.