

01-Aug-2016 **PCN** #:P-16-013368

Subject: Terminals and Splices, SOLISTRAND, PLASTI-GRIP, PIDG

**Description of Change:** Manufacturing location change. Following Part Numbers produced in Japan will be transferred from Outside Vendor in Japan to Kauffman Road plant in TE US. With this change, some of parts will have the change on packing quantities as shown in attached pdf file. This notification does not have influence on the Part Numbers that has been produced in US already.

**Reason:** Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality and form-fit-function of the concerned products. The new manufacturing location has been already certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Impact of Change: Manufacturing location change

**Key Dates:** 

Contact By Date:01-Oct-2016

**Implementation Date:**01-Oct-2016

## **Product Affected**

32447 34137 (Alias Part Numbers: "F21569-000" "AMPS-0-0034137-0") 34120

## **Product Affected**

(Alias Part Numbers:

"1027271")

32448

34117

31906

36467

34159

(Alias Part Numbers:

"C57951-000"

"AMPS-0-0034159-0")

32442

130171

(Alias Part Numbers:

"E99746-000")

36151

(Alias Part Numbers:

"CJ0960-001"

"AMP-0-0036151-0"

"500-095-0001"

"2-14492-6160")

170530-1

321020

31818

(Alias Part Numbers:

"768360-000"

"AMPS-0-0031818-0")

34067

32957

34105

(Alias Part Numbers:

"CA8889-000"

"AMPS-0-0034105-0")

34131

320560

(Alias Part Numbers:

"C01931-000"

"AMP-0-0320560-0"

"2-14492-8140")

34158

(Alias Part Numbers:

## **Product Affected**

- "841140-000"
- "AMPS-0-0034158-0"
- "2-42938-5296"
- "2-42938-5263")
- 35432
- 34070
- (Alias Part Numbers:
- "268412-000"
- "AMPS-0-0034070-0")
- 130090
- 170535-1
- 31900
- 32996
- 32958
- 321019
- 130094
- (Alias Part Numbers:
- "257080-000"
- "AMPS-0-0130094-0"
- "6089315706")
- 170532-1
- 34104
- 32959
- 130167
- 32543
- 31903
- 31899
- 34157
- (Alias Part Numbers:
- "E14197-000"
- "AMPS-0-0034157-0")
- 32562
- (Alias Part Numbers:
- "AMP-0-0032562-0"
- "D64996-000"
- "4-15237-0000"
- "2-30733-0010")
- 171519-2
- 34852
- (Alias Part Numbers:

## **Product Affected**

"F26552-000"

"AMPS-0-0034852-0")

34130

34133

160011

321021

32441

320574

(Alias Part Numbers:

"A62994-000"

"AMP-0-0320574-0"

"2-14492-1140")

171519-1

31904

321017

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.