



04-Aug-2016

PCN #:P-16-013411

Subject:Raychem Adapters

Description of Change: You are receiving this notice because you may have purchased one or more of the affected parts from TE Connectivity or one of our distribution channel partners. This notice is to inform you that TE Connectivity is moving the connector accessories operation from the plant in Redwood City, California, U.S.A. to the TE plant located in Hermosillo, Mexico. This move involves relocation of final packaging of two or more finished components that are produced at our various plant locations and/or suppliers. There are no changes in the current plant or supplier locations of the components being packaged. This move does not have any impact on form, fit or function.

Reason: Dear Customer, we hereby inform you about a transfer of tools and/or processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a tool which produces a finished TE-product. A PPAP Level 1 will be available if it concerns a component of a TE-product, where the production location of the finished TE-product remains unchanged. If you require such a PPAP, please notify the responsible TE Sales Contact within 14 calendar days after receipt of this PCN

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:04-Aug-2016

Implementation Date:04-Aug-2016

Product Affected

930997-000

(Alias Part Numbers:

"208M724-19B12"

"6-1197216-4")

EF9603-000

(Alias Part Numbers:

"BNX40AC90-2014AX-CS9062")

559713-000

(Alias Part Numbers:

"6-1194417-7"

"TXR54AB00-1606AI")

529883-000

(Alias Part Numbers:

"2-1194161-1"

"TXR40AC45-1208AI")

E31231-000

(Alias Part Numbers:

"7-1201928-5"

"203M014-19B06")

129513-000

(Alias Part Numbers:

"6-1190940-0"

"TXR15AB00-1618AI")

138979-000

(Alias Part Numbers:

"8-1191007-9"

"TXR40AB90-1414AI")

404783-000

(Alias Part Numbers:

"1193055-9"

"TXR61AB90-1608AI")

EG1388-000

(Alias Part Numbers:

"STXR40AZ00-0814BI")

CW0972-000

(Alias Part Numbers:

"TXR41AZ90-1812BI")

EF9598-000

(Alias Part Numbers:

"BNX40AC00-1812AX-CS9062")

Product Affected

478499-000

(Alias Part Numbers:

"218M616-19A"

"9-1193582-1")

CW7117-000

(Alias Part Numbers:

"BNX40AC90-1006AX-CS9062")

F91992-000

(Alias Part Numbers:

"208M814-19C10"

"4-1200494-8")

D92945-000

(Alias Part Numbers:

"5-1201353-6"

"TXR18AB90-2416AI")

CL0081-000

(Alias Part Numbers:

"HEX40-AC-90-15-A5-3"

"1-1899317-6")

EG0971-000

527781-000

(Alias Part Numbers:

"3-1194146-9"

"HEX40-AC-00-15-A5-1")

938453-000

(Alias Part Numbers:

"1197270-5"

"TXR41AB90-2010AI")

D13563-000

(Alias Part Numbers:

"7-1201139-8"

"PNX41AB00-1412")

244081N002

(Alias Part Numbers:

"6-1191790-5"

"CSGA-B")

850863-000

(Alias Part Numbers:

"9-1196633-0"

"TXR40AB90-1407BI")

Product Affected

355995-000

(Alias Part Numbers:

"3-1192672-2"

"TXR54AC00-1608AIF")

192941-000

(Alias Part Numbers:

"5-1191399-7"

"TX40AB90-2412")

122913-000

(Alias Part Numbers:

"1-1190894-7"

"TXR40AB90-1610BI")

027963-000

(Alias Part Numbers:

"4-1190216-7"

"TXR41AC90-1008AI")

003547-000

(Alias Part Numbers:

"8-1190026-5"

"TXR54AC45-0804AI")

CV5200-000

(Alias Part Numbers:

"BNX54SJ00-2216AX-CS9062")

BM9778-000

(Alias Part Numbers:

"TXR40AB90-2004BI")

990207-000

(Alias Part Numbers:

"1-1197657-1"

"TXR40AB00-1408BI")

EG2225-000

838913-000

(Alias Part Numbers:

"7-1196546-1"

"TXR40AB00-2014BI")

CM6240-000

(Alias Part Numbers:

"HEX40-AC-45-21-A9-1")

542967-000

(Alias Part Numbers:

Product Affected

"201M114-62J"

"1-1194259-0")

CH2258-000

(Alias Part Numbers:

"9-1899574-7"

"KTKK-5012")

268423-000

(Alias Part Numbers:

"1191981-4"

"TXR54AC00-1008AI")

345101-000

(Alias Part Numbers:

"3-1192598-8"

"TXR40SC00-1408AI")

EF9615-000

(Alias Part Numbers:

"BNX54SC90-1208AX-CS9062")

185735-000

(Alias Part Numbers:

"9-1191348-2"

"TXR40AB90-0804AI2")

081649-000

(Alias Part Numbers:

"8-1190605-2"

"TXR40AB90-2414BI")

CX9973-000

(Alias Part Numbers:

"BNX40AC00-1005AX-CS9062")

CJ3461-000

(Alias Part Numbers:

"TXR40SJ90-2406AI")

894623-000

(Alias Part Numbers:

"3-1196957-9"

"TXR47AB00-2408AI")

728345-000

(Alias Part Numbers:

"3-1195691-0"

"TXR54AB90-1208AIH")

E56611-000

Product Affected

(Alias Part Numbers:

"5-1201480-4"

"TXR66SJ90-3624BI")

424446-000

(Alias Part Numbers:

"3-1199024-2"

"TXR54AC90-6118AI")

425565-000

(Alias Part Numbers:

"4-1193203-0"

"TTRD-14-14-04-CAI-F")

089897-000

(Alias Part Numbers:

"5-1190659-0"

"TXR41AB00-2405AI")

E66042-000

(Alias Part Numbers:

"6-1201189-7"

"203M012-19C03-CS5567")

529801-000

(Alias Part Numbers:

"5-1194160-5"

"202M708-19G")

514093-000

(Alias Part Numbers:

"8-1194038-3"

"STXR40AB00-1212BI")

A82757-000

(Alias Part Numbers:

"1199635-1"

"TXR66AB00-2008AI")

CZ6513-000

(Alias Part Numbers:

"TXR54AB45-2210AIL")

882777-000

(Alias Part Numbers:

"1-1196871-7"

"TXR21AB00-1818AI")

CW7086-000

(Alias Part Numbers:

Product Affected

"TXR40AZ00-2210BI")

756497-000

(Alias Part Numbers:

"203M022-19B16-12"

"4-1195895-9")

596895-000

(Alias Part Numbers:

"8-1194720-4"

"TXR40AB00-2412AI")

487367-000

(Alias Part Numbers:

"7-1193646-3"

"TXR40AC00-2008AI")

947403-000

(Alias Part Numbers:

"6-1197330-8"

"TXR18AB45-2808BI")

807412-000

(Alias Part Numbers:

"8-1196255-3"

"203M610-19A")

687777S002

(Alias Part Numbers:

"203M116-19A10-CS5352"

"2-1195402-6")

057748-000

(Alias Part Numbers:

"3-1198138-3"

"TXR21AB90-2012AI")

533821-000

(Alias Part Numbers:

"7-1194190-3"

"TXR21AB00-0804AI")

965703-000

(Alias Part Numbers:

"208M716-19B08"

"4-1197468-8")

740625-000

(Alias Part Numbers:

"8-1195780-0"

Product Affected

"TXR40SJ00-1208AI")

360033-000

(Alias Part Numbers:

"2-1192701-9"

"TXR40AB00-2018AI")

004845-000

(Alias Part Numbers:

"1190037-3"

"209M410-19B")

255687-000

(Alias Part Numbers:

"5-1197843-2"

"TXR41AB90-1007AI")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.