



23-Aug-2016

PCN #:E-16-010987

Subject:284617-1 PIN/TAB HEADER ASSY. 154 POSITIONS

Description of Change: add little shoulders on the 2.8mm TAB contacts (lengths 48,1mm; 57,15mm)

Reason: Product Improvement. In order to optimize the stitching process we would need little shoulders on the 2.8mm TAB contacts (lengths 48,1mm; 57,15mm)

Impact of Change:form - fit - function

Key Dates:

Contact By Date:30-Oct-2016

Implementation Date:30-Oct-2016

Product Affected

284617-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE

Connectivity Sales Representative

[Copyright](#) TE Connectivity Corporation