



20-Sep-2016

PCN #:E-16-013335

Subject:8 pos. Housing for Junior-Timer Contact

Description of Change: Serial tool is worn out; A new tool is available which is producing two other codings of this series. To get PN 927366/368 on the new tool the area of injection needs to be enlarged because the nozzle is positioned directly on the part. The change does not affect the function of the connector, because injection area is not in contact with counterpart.

Reason: Manufacturing / Process Requirements. Internal Requirement

Impact of Change:form - fit - function

Key Dates:

Contact By Date:22-Jan-2017

Implementation Date:22-Jan-2017

Product Affected

927368-1

(Alias Part Numbers:

"F92568-000"

"AMPS-0-0927368-1")

927366-1

(Alias Part Numbers:

"E30629-000"

"AMPS-0-0927366-1")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.