



Product Change Notification

Current Date: 26-Sep-2016

TE Connectivity

Product Change Notification: P-16-013591

PCN Date: 21-SEP-16

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Add a new production line

Description of Changes
Add a new production line in TE NEPZ.
Other attachments:
ECR

Reason for Changes:	
Product improvement.Current production capacity can't meet customer's demand.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	15-DEC-2016

Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	15-FEB-2017

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282080-1	NO			"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			
282080-1	NO			"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			
282080-1	NO			"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			
282080-1	NO			"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			
282080-1	NO			"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			
282080-1	NO			"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			

Customer: TTI Inc.(1305175)

Location: Maisach-Gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282080-1	NO		TYC282080-1	"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			

Customer: TTI Inc(168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282080-1	NO			"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			

Customer: TTI Electronics Asia Pte Ltd.(2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282080-1	NO			"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			

Customer: Tti Inc(3065242)

Location: Maisach-Gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282080-1	NO			"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			

Customer: TTI Inc(1281288)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282080-1	NO			"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			

Customer: TTI Inc.(3057778)

Location: Olching

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282080-1	NO		TYC282080-1	"CM8390-000", "AMP-0-0282080-1", "2-42939-6211"			