



22-Dec-2016

PCN #:P-16-013990

Subject:AMP MCP 2.8 CONTACT

Description of Change: TE Connectivity Brazil would like to inform about a Tooling transfer of the DIE 11-20305. the Following Part Numbers produced at this tool: 1-968849-1 1-968849-2 1-968849-3 1-1355833-1 1-1355877-1 1-968851-1 1-968851-2 1-968851-3 1-968880-1 1-968880-3 1-1355876-1 will be transferred from TE EMEA to TE Brazil.

Reason: Dear Customer, we hereby inform you about a transfer of one DIE that produce the MCP Terminals listed at this PCN. This tool was brought to Brazil to better meet customer demands and improve our delivery. The new manufacturing location operates under a certified quality management system in accordance with standard concerned automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. will be submit a PPAP before the Start of the Production for All customers

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:31-Mar-2017

Implementation Date:31-Mar-2017

Product Affected

1-968851-1

1-968851-2

1-1355876-1

1-968849-1

1-968880-3

1-968880-1

(Alias Part Numbers:

Product Affected

"1-0968880-1")

1-968849-3

1-968849-2

1-1355833-1

1-968851-3

1-1355877-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.