



06-Jan-2017

PCN #:E-16-017879

Subject:PD5, PD10 and K41 Relay Labels

Description of Change: Label update - logo and cage code The drawings for the listed part numbers have been modified to correct following; Before:
After:

Reason: Document Clarification. Create series label with latest logo and mfg cage code

Impact of Change:form - fit - function

Key Dates:

Contact By Date:31-Jan-2017

Implementation Date:31-Jan-2017

Product Affected

1-1618256-3

(Alias Part Numbers:

"PD10B335")

2-1618256-1

(Alias Part Numbers:

"PD5AB57")

1-1618256-1

(Alias Part Numbers:

"PD10AC57")

2-1618256-5

(Alias Part Numbers:

"PD5C335")

3-1618013-9

(Alias Part Numbers:

Product Affected

"PD5B335")

4-1618239-0

(Alias Part Numbers:

"K41B834")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.