



05-Jan-2017

PCN #:P-17-014025

**Subject:**Product produced at TE Hermosillo, MX

**Description of Change:** TE Connectivity (TE) is moving manufacturing location of the products listed below from TE Hermosillo to TE Guangdong. Please contact your TE Sales Engineer with questions. The specific part numbers are detailed below.

**Reason:** After an extensive analysis of our TE business unit operations, we are announcing a plan to simplify our manufacturing footprint. As a result of this plan, product produced at our TE Rock Hill, SC OR Hermosillo, MX facilities will be relocated to other TE Connectivity locations (North America and China) by the end of November 2017. Additionally, we will relocate some product produced at our TE Dongguan China facility for our North American market to our Hermosillo, MX facility by the end of November 2017.

**Impact of Change:**Manufacturing location change

**Key Dates:**

**Contact By Date:**02-Oct-2017

**Implementation Date:**02-Oct-2017

**Product Affected**

1-5750913-2

747514-1

5-749865-1

5787082-5

745211-8

5749084-5

786556-5

1-747529-3

## **Product Affected**

5749621-5

1-749656-2

5787962-1

5749069-2

5749621-1

5749111-7

1-747545-1

5749110-2

745485-1

5787190-8

5786554-5

747559-1

745489-3

749611-8

2180279-9

5749084-9

747562-2

5749085-9

747562-4

5786556-5

747562-6

5787962-2

787055-1

1-747529-1

5787942-9

749698-2

5749070-9

747545-1

747561-7

745490-2

745215-7

747562-5

(Alias Part Numbers:

"A83650-000"

"AMP-0-0747562-5")

786554-1

5749069-9

5-750450-1

787081-4

1-786156-0

## **Product Affected**

747562-9  
749871-1  
786930-5  
1-786163-9  
749699-4  
5-749865-2  
747529-6  
747562-8  
747511-1  
5749621-7  
1-745492-9  
749861-2  
747545-6  
749697-6  
5749621-3  
786156-5  
786155-7  
749861-1  
786865-5  
5796055-3  
5787170-9  
5750913-2  
747546-2  
786554-9  
749109-1  
5786555-5  
1-5750913-7  
5787362-5  
6-786862-5  
5786155-5  
5-749877-5  
1-745494-7  
745205-7  
745487-3  
5-749864-2  
747529-4  
745484-1  
786554-7  
749069-1  
747512-3

## **Product Affected**

5-749866-1

1-747530-4

1-747514-1

749865-1

786163-7

1-745492-7

749698-3

5787775-1

5786860-7

5787169-9

5787082-3

5-749611-9

5787190-5

747544-1

749109-7

745484-3

5749069-4

5786555-9

1761028-1

749109-6

1761028-3

1-749656-1

1-745495-8

(Alias Part Numbers:

"D32547-000"

"AMP-1-0745495-8"

"4-16211-7546")

5787394-8

745486-3

5787082-2

747530-3

747514-9

5749699-5

747514-2

5750913-5

749866-1

6888135-1

5787131-3

(Alias Part Numbers:

"010-5593-00")

## **Product Affected**

787081-5

1-747545-0

1-745496-9

1-745497-7

745483-4

786930-1

747529-2

747530-2

5-749879-9

5749111-3

1-786156-6

786555-7

745207-7

1-786156-5

1-747529-2

747545-8

749861-3

745201-7

6489232-1

1-786156-1

749864-1

745488-3

5787395-5

1-749611-2

749069-2

1-745491-7

(Alias Part Numbers:

"E48286-000"

"AMP-1-0745491-7")

747530-9

5749111-8

(Alias Part Numbers:

"010-7020-00")

749109-3

786156-7

749868-3

5749111-1

786156-2

5749210-7

745486-4

## **Product Affected**

787004-3

747561-8

747530-4

749697-2

5749621-9

5-750722-7

747561-4

1-745495-9

1-786156-4

747530-7

5750927-5

787081-2

1-745203-1

747527-2

1-5749111-0

747529-9

1-745496-7

(Alias Part Numbers:

"C29226-000"

"AMP-1-0745496-7")

5796055-1

747530-6

1-747545-3

5-749864-1

1-747513-0

1-786156-3

786156-1

1-745493-5

(Alias Part Numbers:

"E46905-000"

"AMP-1-0745493-5")

745489-1

1-747562-2

1-786163-5

747529-5

(Alias Part Numbers:

"AMP-0-0747529-5"

"F03518-000")

5-786862-5

5786557-7

## **Product Affected**

1-745492-8

(Alias Part Numbers:

"A18649-000"

"AMP-1-0745492-8")

1-747562-1

5-749861-2

747529-7

745209-8

1-747530-3

5-749879-5

5749721-5

5787083-5

5787170-4

1375631-1

786930-4

747513-2

747546-4

1-747514-0

747529-1

6658751-1

1-745494-5

(Alias Part Numbers:

"D82690-000"

"AMP-1-0745494-5"

"2-42932-9181")

747530-1

747545-5

(Alias Part Numbers:

"AMP-0-0747545-5"

"D37262-000")

1761028-6

5749069-1

1-745493-4

(Alias Part Numbers:

"E42316-000"

"AMP-1-0745493-4"

"2-42932-9171")

5796055-2

1-745498-5

(Alias Part Numbers:

**Product Affected**

"D38794-000"

"AMP-1-0745498-5")

5749069-5

1888608-1

5787083-7

749069-9

747546-7

747514-8

1-745496-8

747513-1

747546-8

747546-1

5787169-7

747546-9

1-747513-1

5749699-8

(Alias Part Numbers:

"010-4965-01")

5787928-7

1-745491-6

1-786863-7

2-745495-0

747513-7

5749069-7

5786555-7

747514-3

5749110-1

747544-3

747527-1

1-745497-6

1-745491-8

5786162-9

747562-7

749863-1

5786554-2

1-747546-0

5796055-4

749868-4

5787170-5

747545-4



## **Product Affected**

745485-3

5787394-7

786930-2

5787170-7

2-745496-0

1-747546-2

747514-5

(Alias Part Numbers:

"AMP-0-0747514-5"

"D98211-000")

5-749861-3

1-747529-4

747545-2

2-745492-0

(Alias Part Numbers:

"C71485-000"

"AMP-2-0745492-0")

5786554-1

786156-9

786554-2

749865-2

5787973-2

1-5750913-9

747559-3

1-747561-0

5787266-5

786555-5

5-749872-7

6364289-1

750832-1

6-786863-7

786555-9

747513-4

747528-2

747514-6

747543-3

747559-2

1-5786557-1

1-786156-2

5749070-7

## **Product Affected**

747559-4

1-1218901-4

749698-1

5787137-1

747513-3

749697-9

1-745493-6

1-787171-6

747514-4

747514-7

787228-2

5-749877-7

5749621-2

6761055-1

787081-7

5787362-7

747561-6

747561-9

5787973-1

1-747529-0

747543-1

1-747530-0

1-745495-7

786155-5

5787190-7

1761028-2

749110-2

787081-9

745490-3

745203-9

1-786163-7

2007241-1

745211-9

5787131-2

(Alias Part Numbers:

"010-5849-00")

1-786554-0

5749085-5

1761028-5

747512-1

## **Product Affected**

1-745491-9

745490-1

749697-3

745490-4

747513-8

5749109-7

747545-9

747545-3

747546-3

1-5786554-0

749109-2

747530-5

(Alias Part Numbers:

"AMP-0-0747530-5"

"E43355-000")

3-787081-6

5749721-7

745488-1

5787362-9

5749621-4

5787394-2

5787082-9

5749111-4

745487-1

5749070-5

787228-1

5787394-5

1-745494-6

5786136-5

5-749873-1

1-787081-5

749863-2

745209-7

(Alias Part Numbers:

"4-16211-7283")

749069-8

749866-2

5749210-5

749867-5

747513-9

## **Product Affected**

5-749866-2

747511-2

5786557-9

5786554-7

747562-1

1-747530-1

5-749611-5

6-749656-0

786557-7

5787190-1

745483-1

5-749877-9

1-747562-0

1761028-4

747546-6

1-5750913-5

786554-5

1-745498-6

5749111-6

749870-2

747560-1

747560-2

786930-6

5750458-5

5750913-7

747530-8

1-745494-8

747529-3

749109-5

1-747530-2

747528-1

747546-5

(Alias Part Numbers:

"AMP-0-0747546-5"

"C11327-000")

5749699-7

5750961-1

1-747545-2

786163-5

749698-5

## **Product Affected**

5-749872-1

5796048-1

6364491-1

786930-3

1-747561-1

5749621-8

1-749621-6

5787642-1

745201-9

5786155-7

5787082-7

749869-2

5-750640-1

747561-1

6364306-1

749872-1

5786554-9

1-747546-1

747529-8

745211-7

1-1218901-2

5749109-3

787136-1

5749069-8

5-749878-7

1-745497-5

(Alias Part Numbers:

"C21157-000"

"AMP-1-0745497-5")

749069-7

5749109-5

5787131-1

1-787081-7

5749721-3

5749109-6

787055-2

5-749861-4

1-745498-7

787081-3

5-749861-1

## **Product Affected**

749069-5

749873-1

1-787082-8

1-787082-7

1658751-1

1-786557-1

786557-5

1489232-1

749611-9

749611-5

749611-1

749085-9

749085-5

786136-5

750458-5

749721-7

749721-5

749721-3

749070-9

749070-7

749070-5

750961-1

749084-9

749084-5

787394-5

787394-2

787362-9

787362-7

787362-5

787266-5

787190-8

1-750913-9

1-750913-7

750913-2

749621-8

749621-7

(Alias Part Numbers:  
"010-1487-00")

749621-2

(Alias Part Numbers:

**Product Affected**

"A07943-000"

"AMP-0-0749621-2")

749111-8

749111-6

749111-1

749879-9

749879-5

749878-7

1-786862-5

786862-5

750640-1

749877-9

749877-7

749877-5

749656-7

749656-5

787190-7

787190-5

(Alias Part Numbers:

"1027979")

787190-1

787171-9

787171-7

787171-5

787171-4

787171-2

787170-9

787170-7

787170-5

787170-4

787169-9

787169-7

787083-7

787083-5

787082-9

(Alias Part Numbers:

"6422325400")

787082-7

787082-5

787082-3

**Product Affected**

787082-2

1364973-2

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any



or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.