

11-Jan-2017 **PCN** #:P-17-014050

**Subject:**Change manufacturing location of Multigig Daughter Card connector such as: Tier 1, Tier 2, RT2 and RT2-R

**Description of Change:** Manufacturing location change. Following Part Numbers will be transferred from outside supplier to TE Connectivity manufacturing location in Mt.Joy, Pennsylvania

Reason: The TE Connectivity MultiGig product family offers several product offerings to support various products to support high speed signals in the VPX embedded computing architecture segment. The product offering has been widely adopted into the Military/Aerospace market place. The growth of the product offering as well as the anticipated forecasted growth in the market place require TE to migrate the manufacturing of the product offering into an internal TE manufacturing facility to better support our customer base. The manufacturing of the MultiGig product daughter card product offering will be relocated to our TE Connectivity manufacturing location in Mt.Joy,PA. This transition will occur on/or about March 31th,2017. The new manufacturing location is under a certified quality management system. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, performance, ability to supply and form-fit-function of the concerned products.

Impact of Change: Manufacturing location change

**Key Dates:** 

Contact By Date: 17-Apr-2017

**Implementation Date:** 17-Apr-2017

## **Product Affected**

1410205-3

1410206-2

1410206-3

## **Product Affected**

- 1410187-1
- 1410975-2
- 1410215-3
- 1410132-3
- 1410478-1
- 2102772-2
- 1410479-2
- 1410416-1
- 2102773-2
- 1410189-1
- 1410207-2
- 1410190-3
- 1410170 3
- 1410414-2
- 1410139-2
- 1410414-1
- 1410190-2
- 1410326-3
- 1410303-2
- 1410970-4
- 1410971-2
- 1410132-1
- 1410205-1
- 1410189-5
- 1410217-3
- 1410188-1
- 1410228-4
- 1410137-1
- 1410975-3
- 2102772-1
- 1410232-4
- . . . . . . . .
- 1410421-4
- 1410971-4
- 1410232-3
- 2102771-2
- 1410196-1
- 1410195-1
- 1410970-3
- 1410188-2
- 1410137-2
- 1410191-3

## **Product Affected**

- 2102771-1
- 1410189-3
- 1410187-4
- 1410125-3
- 1410479-1
- 1410971-3
- 1410138-2
- 1410421-1
- 1410191-1
- 1410416-3
- 1410228-2
- 1+10220-2
- 1410207-3
- 1410414-5
- 2102773-1
- 1410217-1
- 1410190-1
- 1410303-1
- 1410187-3
- 1410365-3
- 1410414-4
- 1410187-5
- 1410421-3
- 1410188-4
- 1410205-2
- 1410968-4
- 1410139-1
- 1410147-2
- 1410326-4
- 1410970-2
- 1410421-2
- 1410190-4
- 1410191-4
- 1410187-2
- 1410189-4
- 1410215-1
- 1410997-2
- 1410205-4
- 1410188-3
- 1410972-3
- 1410415-2

## **Product Affected**

- 1410975-4
- 1410189-2
- 1410207-1
- 1410191-2
- 1410367-3
- 1410368-3
- 1410232-1
- 1410997-1
- 1410478-2
- 1410125-1
- 1410972-4
- 1410138-1
- 1410147-1
- 1410207-4
- 1410415-1
- 1410968-2
- 1410968-3

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.