



Product Change Notification

Current Date: 30-Jan-2017

TE Connectivity

Product Change Notification: P-17-014092

PCN Date: 26-JAN-17

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Raychem W&C Distribution Location Change Notification

Description of Changes
Dear Valued Customer, This letter is to provide formal advance notification that Raychem Wire and Cable products will be relocating our distribution facility located in Ontario, CA USA to Fremont, CA USA. There will be no AS9102 FAI s or PPAP s needed or made for this warehouse address change.

Reason for Changes:								
Part status change. TE Connectivity Raychem is committed to providing all customers with high quality products. If further information is required regarding this notification, please contact your local TE Connectivity account manager. We thank you for continued support of TE Connectivity's brand of products.								
Estimated Dates:								
<table border="1"><tr><td>Last Order Date (Obsolete Parts Only):</td><td>First Date To Ship (Changed Parts Only):</td></tr><tr><td></td><td>05-FEB-2017</td></tr><tr><td>Last Ship Date (Obsolete Parts Only):</td><td>Last Date for Mixed Shipments: (Changed Parts Only):</td></tr><tr><td></td><td>No Mixed Shipments</td></tr></table>	Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):		05-FEB-2017	Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):		No Mixed Shipments
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):							
	05-FEB-2017							
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):							
	No Mixed Shipments							

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
006453-000	NO			"5-1190049-4", "FLTWC0311-16-0"			
0160793001	NO			"8-1190125-3", "99M0111-22-2L"			
1007553001	NO			"7-1190737-7", "100G0111-0.25-9"			
216027-008	NO			"9-1191562-9", "55A0111-26-9", "55A0111-26-9"			
2820803007	NO			"9-1192101-1", "44A0111-28-0"			
4064593002	NO			"8-1202025-3", "FLDWC0311-18-4"			
6390053001	NO			"7-1195050-5", "99M0111-24-6"			
6994543001	NO			"100G0121-0.40-0/9", "1-1197929-1"			
733809-000	NO			"1-1195731-7", "FLTWC0311-18-0"			
9395153002	NO			"7-1200693-8", "FLHTC0311-26-1"			
C302613002	NO			"3-1899266-3", "FLDWC0311-18-5"			
CD45243001	NO			"100E0111-0.75-9", "9-1899308-5"			
CR5130-000	NO			"44A0311-12-3"			
CY6750-000	NO			"2022E0421-0"			

EJ0751-000	NO			"10603-0000-0-L050"			
EK4596-000	NO						
EK4600-000	NO			"FLDWC6004-18-1"			

Customer: TTI Inc.(1305175)

Location: Maisach-Gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0160793001	NO		RAY0160793001	"8-1190125-3", "99M0111-22-2L"			
1007553001	NO		RAY1007553001	"7-1190737-7", "100G0111-0.25-9"			
2820803007	NO		RAY2820803007	"9-1192101-1", "44A0111-28-0"			
4064593002	NO		TYCFLDWC0311-18-4, RAY4064593002	"8-1202025-3", "FLDWC0311-18-4"			
6390053001	NO		RAY6390053001	"7-1195050-5", "99M0111-24-6"			
6994543001	NO		RAY6994543001	"100G0121-0.40-0/9", "1-1197929-1"			
733809-000	NO		TYCFLTWC0311-18-0, RAY733809-000, TYC733809-000	"1-1195731-7", "FLTWC0311-18-0"			
9395153002	NO		RAY9395153002	"7-1200693-8", "FLHTC0311-26-1"			
C302613002	NO		TYCFLDWC0311-18-5, RAYC302613002	"3-1899266-3", "FLDWC0311-18-5"			

CD45243001	NO		RAYCD45243001	"100E0111-0.75-9", "9-1899308-5"			
EK4596-000	NO						
EK4600-000	NO			"FLDWC6004-18-1"			

Customer: TTI Inc(168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
216027-008	NO			"9-1191562-9", "55A0111-26-9", "55A0111-26-9"			
CR5130-000	NO			"44A0311-12-3"			
CY6750-000	NO			"2022E0421-0"			
EJ0751-000	NO			"10603-0000-0-L050"			

Customer: TTI Electronics Asia Pte Ltd.(2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
006453-000	NO			"5-1190049-4", "FLTWC0311-16-0"			

733809-000	NO			"1-1195731-7", "FLTWC0311-18-0"			
----------------------------	----	--	--	------------------------------------	--	--	--

Customer: TTI Inc(1281288)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
216027-008	NO			"9-1191562-9", "55A0111-26-9", "55A0111-26-9"			
CR5130-000	NO			"44A0311-12-3"			
CY6750-000	NO			"2022E0421-0"			
EJ0751-000	NO			"10603-0000-0-L050"			

Customer: TTI Inc.(3057778)

Location: Olching

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0160793001	NO		RAY0160793001	"8-1190125-3", "99M0111-22-2L"			
1007553001	NO		RAY1007553001	"7-1190737-7", "100G0111-0.25-9"			

2820803007	NO		RAY2820803007	"9-1192101-1", "44A0111-28-0"			
4064593002	NO		TYCFLDWC0311-18-4, RAY4064593002	"8-1202025-3", "FLDWC0311-18-4"			
6390053001	NO		RAY6390053001	"7-1195050-5", "99M0111-24-6"			
6994543001	NO		RAY6994543001	"100G0121-0.40-0/9", "1-1197929-1"			
733809-000	NO		TYCFLTWC0311-18-0, RAY733809-000, TYC733809- 000	"1-1195731-7", "FLTWC0311-18-0"			
9395153002	NO		RAY9395153002	"7-1200693-8", "FLHTC0311-26-1"			
C302613002	NO		TYCFLDWC0311-18-5, RAYC302613002	"3-1899266-3", "FLDWC0311-18-5"			
CD45243001	NO		RAYCD45243001	"100E0111-0.75-9", "9-1899308-5"			
EK4596-000	NO						
EK4600-000	NO			"FLDWC6004-18-1"			