



Product Change Notification

Current Date: 30-Jan-2017

TE Connectivity

Product Change Notification: P-17-014099

PCN Date: 26-JAN-17

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Raychem W&C Distribution Location Change Notification

Description of Changes
Dear Valued Customer, This letter is to provide formal advance notification that Raychem Wire and Cable products will be relocating our distribution facility located in Ontario, CA USA to Fremont, CA USA. There will be no AS9102 FAI s or PPAP s needed or made for this warehouse address change.

Reason for Changes:								
Part status change.TE Connectivity Raychem is committed to providing all customers with high quality products. If further information is required regarding this notification, please contact your local TE Connectivity account manager. We thank you for continued support of TE Connectivity's brand of products.								
Estimated Dates:								
<table border="1"><tr><td>Last Order Date (Obsolete Parts Only):</td><td>First Date To Ship (Changed Parts Only):</td></tr><tr><td></td><td>05-FEB-2017</td></tr><tr><td>Last Ship Date (Obsolete Parts Only):</td><td>Last Date for Mixed Shipments: (Changed Parts Only):</td></tr><tr><td></td><td>No Mixed Shipments</td></tr></table>	Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):		05-FEB-2017	Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):		No Mixed Shipments
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):							
	05-FEB-2017							
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):							
	No Mixed Shipments							

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1153883001	NO			"100G1121-0.40-0/9-0", "1-1199091-1"			
162811-000	NO			"2-1191175-4", "FLHTC0311-22-4"			
1942633001	NO			"100G0111-2.00-0", "5-1191409-2"			
280800-000	NO			"6-1201994-3", "44/7004-22-4"			
2813803003	NO			"6-1192084-4", "44/7031-20-9"			
2831433006	NO			"5-1192132-1", "44A0111-20-2L"			
4451293001	NO			"100F0111-20", "3-1193345-7"			
4498853001	NO			"1-1197859-3", "55A9002-30-2"			
533193-000	NO			"44A9605-16-5", "1-1194186-6"			
5595313002	NO			"4-1194416-9", "55PC0811-10-9"			
6272953001	NO			"100G0111-0.40-5", "5-1194967-1"			
7402913001	NO			"2-1195778-8", "99M0111-22-0", "99M0111-22-0"			
8862813001	NO			"9-1196895-8", "FLHTC0311-26-2"			
909635-000	NO			"6-1197065-4", "FLDWC0311-12-2"			
C07826-000	NO			"8-1201892-7", "0024A0024-0"			

CB2676-000	NO			"55/P1324-26-0/9-9CS3192"			
CD74773001	NO			"100G1131-0.40-0/2/9-0", "9-1899440-1"			
CF2169-000	NO			"EPD-RWC-20322CS3092"			
CQ52233001	NO			"100E0111-0.50-9"			
EG8070-000	NO			"55A7588-22-9/96CS3429"			
EG8073-000	NO			"55A7589-26-9/96-9CS3430"			
EK4593-000	NO			"FLDWC6004-14-0"			

Customer: TTI Inc.(1305175)

Location: Maisach-Gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2813803003	NO		RAY2813803003	"6-1192084-4", "44/7031-20-9"			
2831433006	NO		RAY2831433006	"5-1192132-1", "44A0111-20-2L"			
4451293001	NO		RAY4451293001	"100F0111-20", "3-1193345-7"			
5595313002	NO			"4-1194416-9", "55PC0811-10-9"			
7402913001	NO		RAY7402913001	"2-1195778-8", "99M0111-22-0", "99M0111-22-0"			
8862813001	NO		RAY8862813001	"9-1196895-8", "FLHTC0311-26-2"			
909635-000	NO		RAY909635-000	"6-1197065-4", "FLDWC0311-12-2"			

CQ52233001	NO		RAYCQ52233001	"100E0111-0.50-9"			
EK4593-000	NO			"FLDWC6004-14-0"			

Customer: TTI Inc(168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1153883001	NO			"100G1121-0.40-0/9-0", "1-1199091-1"			
280800-000	NO			"6-1201994-3", "44/7004-22-4"			
4498853001	NO			"1-1197859-3", "55A9002-30-2"			
533193-000	NO			"44A9605-16-5", "1-1194186-6"			
6272953001	NO			"100G0111-0.40-5", "5-1194967-1"			
C07826-000	NO			"8-1201892-7", "0024A0024-0"			
CB2676-000	NO			"55/P1324-26-0/9-9CS3192"			
CD74773001	NO			"100G1131-0.40-0/2/9-0", "9-1899440-1"			
CF2169-000	NO			"EPD-RWC-20322CS3092"			
EG8070-000	NO			"55A7588-22-9/96CS3429"			
EG8073-000	NO			"55A7589-26-9/96-9CS3430"			

Customer: TTI Electronics Asia Pte Ltd.(2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
162811-000	NO			"2-1191175-4", "FLHTC0311-22-4"			

Customer: TTI Inc(1281288)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1153883001	NO			"100G1121-0.40-0/9-0", "1-1199091-1"			
1942633001	NO			"100G0111-2.00-0", "5-1191409-2"			
280800-000	NO			"6-1201994-3", "44/7004-22-4"			
4498853001	NO			"1-1197859-3", "55A9002-30-2"			
533193-000	NO			"44A9605-16-5", "1-1194186-6"			
6272953001	NO			"100G0111-0.40-5", "5-1194967-1"			
C07826-000	NO			"8-1201892-7", "0024A0024-0"			

CB2676-000	NO			"55/P1324-26-0/9-9CS3192"			
CD74773001	NO			"100G1131-0.40-0/2/9-0", "9-1899440-1"			
EG8070-000	NO			"55A7588-22-9/96CS3429"			
EG8073-000	NO			"55A7589-26-9/96-9CS3430"			

Customer: TTI Inc.(3057778)

Location: Olching

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2813803003	NO		RAY2813803003	"6-1192084-4", "44/7031-20-9"			
4451293001	NO		RAY4451293001	"100F0111-20", "3-1193345-7"			
7402913001	NO		RAY7402913001	"2-1195778-8", "99M0111-22-0", "99M0111-22-0"			
8862813001	NO		RAY8862813001	"9-1196895-8", "FLHTC0311-26-2"			
909635-000	NO		RAY909635-000	"6-1197065-4", "FLDWC0311-12-2"			
CQ52233001	NO		RAYCQ52233001	"100E0111-0.50-9"			
EK4593-000	NO			"FLDWC6004-14-0"			

