



Product Change Notification

Current Date: 30-Jan-2017

TE Connectivity

Product Change Notification: P-17-014094

PCN Date: 26-JAN-17

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Raychem W&C Distribution Location Change Notification

Description of Changes

Dear Valued Customer, This letter is to provide formal advance notification that Raychem Wire and Cable products will be relocating our distribution facility located in Ontario, CA USA to Fremont, CA USA. There will be no AS9102 FAI s or PPAP s needed or made for this warehouse address change.

Reason for Changes:

Part status change. TE Connectivity Raychem is committed to providing all customers with high quality products. If further information is required regarding this notification, please contact your local TE Connectivity account manager. We thank you for continued support of TE Connectivity's brand of products.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

05-FEB-2017

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1002413001	NO			"2-1190734-8", "100G0111-0.40-3"			
172013-000	NO			"4-1191251-1", "FLDWC0311-24-0"			
211123-000	NO			"6-1191529-3", "FLHTC0311-14-9"			
2183143002	NO			"4-1191604-9", "55A0111-28-2"			
265046-002	NO			"5-1191951-3", "81044/9-8-9"			
282206-005	NO			"8-1192107-1", "81044/12-26-9"			
3368913001	NO			"100G0111-3.00-0", "6-1192543-9"			
440900-001	NO			"4-1193315-2", "5026A1334-0"			
464196-001	NO			"7-1193480-9", "EPD6062-16-9CS1693"			
4870753002	NO			"9-1200693-3", "FLHTC0311-14-0"			
557986-000	NO			"3-1201231-2", "82A0813-6-9-F874"			
715025-000	NO			"10603-0000-0", "5-1195595-7"			
721018-000	NO			"7-1198062-3", "FLHTC0311-22-8"			

7308713001	NO			"5-1195709-7", "99M0111-22-9"			
7482063001	NO			"1198862-3", "ACW0219-1.50-2(NS)"			
7724153001	NO			"4-1196016-7", "99M0111-24-2L"			
9922713001	NO			"100G0111-0.40-0", "1-1197675-4"			
CF7347-000	NO			"7724S1LL4-9"			
CX2065-000	NO			"EPD106254A-US"			
D856933001	NO			"100G1121-3.00-0/9-0", "1200171-9"			
EG1477-000	NO			"TR300-0000-0"			
EG8690-000	NO						
EK4594-000	NO			"FLDWC6004-14-1"			

Customer: TTI Inc.(1305175)

Location: Maisach-Gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
172013-000	NO		RAY172013-000	"4-1191251-1", "FLDWC0311-24-0"			
2183143002	NO		RAY2183143002	"4-1191604-9", "55A0111-28-2"			
282206-005	NO		RAY282206-005	"8-1192107-1", "81044/12-26-9"			
3368913001	NO		RAY3368913001	"100G0111-3.00-0", "6-			

				1192543-9"			
7308713001	NO		RAY7308713001	"5-1195709-7", "99M0111-22-9"			
7482063001	NO		RAY7482063001	"1198862-3", "ACW0219- 1.50-2(NS)"			
7724153001	NO		RAY7724153001	"4-1196016-7", "99M0111-24-2L"			
9922713001	NO		RAY9922713001	"100G0111-0.40-0", "1- 1197675-4"			
D856933001	NO		RAYD856933001	"100G1121-3.00-0/9-0", "1200171-9"			
EK4594-000	NO			"FLDWC6004-14-1"			

Customer: TTI Inc(168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1002413001	NO			"2-1190734-8", "100G0111-0.40-3"			
265046-002	NO			"5-1191951-3", "81044/9- 8-9"			
440900-001	NO			"4-1193315-2", "5026A1334-0"			
464196-001	NO			"7-1193480-9", "EPD6062- 16-9CS1693"			
557986-000	NO			"3-1201231-2", "82A0813- 6-9-F874"			

715025-000	NO			"10603-0000-0", "5-1195595-7"			
9922713001	NO			"100G0111-0.40-0", "1-1197675-4"			
CF7347-000	NO			"7724S1LL4-9"			
CX2065-000	NO			"EPD106254A-US"			
EG1477-000	NO			"TR300-0000-0"			
EG8690-000	NO						

Customer: TTI Electronics Asia Pte Ltd.(1407161)

Location: Kowloon Bay

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4870753002	NO			"9-1200693-3", "FLHTC0311-14-0"			

Customer: TTI Electronics Asia Pte Ltd.(2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
211123-000	NO			"6-1191529-3", "FLHTC0311-14-9"			
4870753002	NO			"9-1200693-3", "FLHTC0311-14-0"			

721018-000	NO			"7-1198062-3", "FLHTC0311-22-8"			
----------------------------	----	--	--	------------------------------------	--	--	--

Customer: TTI Inc(1281288)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1002413001	NO			"2-1190734-8", "100G0111-0.40-3"			
265046-002	NO			"5-1191951-3", "81044/9-8-9"			
440900-001	NO			"4-1193315-2", "5026A1334-0"			
464196-001	NO			"7-1193480-9", "EPD6062-16-9CS1693"			
557986-000	NO			"3-1201231-2", "82A0813-6-9-F874"			
715025-000	NO			"10603-0000-0", "5-1195595-7"			
9922713001	NO			"100G0111-0.40-0", "1-1197675-4"			
CF7347-000	NO			"7724S1LL4-9"			
EG8690-000	NO						

Customer: TTI Inc.(3057778)

Location: Olching

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
172013-000	NO		RAY172013-000	"4-1191251-1", "FLDWC0311-24-0"			
2183143002	NO		RAY2183143002	"4-1191604-9", "55A0111-28-2"			
282206-005	NO		RAY282206-005	"8-1192107-1", "81044/12-26-9"			
3368913001	NO		RAY3368913001	"100G0111-3.00-0", "6-1192543-9"			
7308713001	NO		RAY7308713001	"5-1195709-7", "99M0111-22-9"			
7482063001	NO		RAY7482063001	"1198862-3", "ACW0219-1.50-2(NS)"			
7724153001	NO		RAY7724153001	"4-1196016-7", "99M0111-24-2L"			
9922713001	NO		RAY9922713001	"100G0111-0.40-0", "1-1197675-4"			
D856933001	NO		RAYD856933001	"100G1121-3.00-0/9-0", "1200171-9"			
EK4594-000	NO			"FLDWC6004-14-1"			