



10-Feb-2017

PCN #:E-16-018032

Subject:DEUTSCH DT plug - 8 pin

Description of Change: The Industrial and Commercial Transportation (ICT) business unit of TE Connectivity (TEC) intends to implement a change to the DT8 pin plug front seal (1010-007-0806) to improve sealing robustness. The inside width and length will decrease approximately 4% and 5%, respectively. Also, the amount of silicone phenyl fluid will reduce from 1.75% to 0.50%. PPAP package will be offered by customer request once a sufficient inventory bank is built to prevent any delay. DT8pin product drawings are not affected, however see attached for 1010-007-0806 pre-release product drawing.

Reason: Product Improvement. Dear Customer, we inform you of this change as part of our aggressive continuous improvement efforts. The change has minimal effect on form and does not affect fit or function. The change has been validated with manufacturing and laboratory testing. The change will be managed by TEC TS16949 quality procedures. An internal release based on our specifications will be executed before any parts are delivered.

IMPORTANT: This is a continual improvement so the current and previous revisions of these parts can be used interchangeably in the field. This change is being phased-in gradually and the previous revision can remain stocked until use.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:05-May-2017

Implementation Date:05-May-2017

Product Affected

DT06-08SB-P004

DT06-08SD

Product Affected

(Alias Part Numbers:
"ZPF000000000130468")

DT06-08SB

(Alias Part Numbers:
"ZPF000000000130453")

DT06-08SB-C015

(Alias Part Numbers:
"ZPF000000000130457")

DT06-08SC-C017

(Alias Part Numbers:
"ZPF000000000130465")

1010-007-0806

(Alias Part Numbers:
"ZPF000000000131814")

DT06-08SD-P004

DT06-08SA

(Alias Part Numbers:
"ZPF000000000130439"

"DT06-08SA-SC"

"DT06-08SA-S")

DT06-08SC-CE01

(Alias Part Numbers:
"ZPF000000000130462")

DT06-08SB-CE01

(Alias Part Numbers:
"ZPF000000000130454")

DT06-08SD-CE01

(Alias Part Numbers:
"ZPF000000000130469")

DT06-08SC

(Alias Part Numbers:
"ZPF000000000130461")

DT06-08SA-C015

(Alias Part Numbers:
"ZPF000000000130444")

DT06-08SA-E003

(Alias Part Numbers:
"ZPF000000000130449")

DT06-08SA-P004

DT06-08SB-C017

Product Affected

(Alias Part Numbers:

"ZPF000000000130458")

DT06-08SA-E005

(Alias Part Numbers:

"ZPF000000000130450")

DT06-08SA-C017

(Alias Part Numbers:

"ZPF000000000130445")

DT06-08SA-EP04

DT06-08SA-CE01

(Alias Part Numbers:

"ZPF000000000130440")

DT06-08SA-E008

(Alias Part Numbers:

"ZPF000000000130451")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.