



17-Mar-2017

PCN #:E-17-003782

Subject:SR4 and SR6 relay types

Description of Change: Add a second source of glue used to seal pins in base. We intend to use the new glue at least partially by September 18th, 2017 but might both glues alternatively in the future. This change is considered by TE Connectivity as a; . Location of change, see

Reason: Product Improvement. The new glue has both better performance in useability (better viscosity), is easier available from supplier and is already in use in production of other products. It has different colour (light brown instead of brow/red) but identical electrical characteristics compared to the previous one, no change of any specification or behaviour of the relay.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:18-Sep-2017

Implementation Date:18-Sep-2017

Product Affected

6-1415027-1

(Alias Part Numbers:

"SR6D4024")

9-1415018-1

(Alias Part Numbers:

"V23050-A1110-A533"

"V23050A1110A533")

1393260-9

(Alias Part Numbers:

"V23050-A1040-A542"

"V23050A1040A542")

Product Affected

4-1415543-2

(Alias Part Numbers:

"SR960017")

8-1415359-1

(Alias Part Numbers:

"V23050A1110A551X01")

6-1415053-1

(Alias Part Numbers:

"SR4M4006")

8-1415017-1

(Alias Part Numbers:

"V23050-A1005-A533"

"V23050A1005A533")

1393260-4

(Alias Part Numbers:

"V23050-A1012-A542"

"V23050A1012A542")

6-1415537-3

(Alias Part Numbers:

"SR6A6K18")

3-1415055-1

(Alias Part Numbers:

"SR4D4024")

6-1415537-9

(Alias Part Numbers:

"SR6A6K60")

9-1415055-1

(Alias Part Numbers:

"SR4D4110")

1-1415544-0

5-1415539-2

(Alias Part Numbers:

"SR6V6K24")

9-1415538-1

(Alias Part Numbers:

"SR960009")

1-1415539-0

(Alias Part Numbers:

"SR960012")

7-1415537-9

Product Affected

(Alias Part Numbers:

"SR6B6K21")

5-1415053-1

(Alias Part Numbers:

"SR4M4005")

1-1415055-1

(Alias Part Numbers:

"SR4D4018")

6-1415055-1

(Alias Part Numbers:

"SR4D4048")

1-1415544-5

3-1415353-1

(Alias Part Numbers:

"SR6M4024")

1393260-7

(Alias Part Numbers:

"V23050-A1024-A542"

"V23050A1024A542")

8-1415537-0

(Alias Part Numbers:

"SR6B6K24")

7-1415537-6

(Alias Part Numbers:

"SR6B6K12")

8-1415535-1

(Alias Part Numbers:

"SR9400003")

1-1393260-2

(Alias Part Numbers:

"V23050-A1085-A542"

"V23050A1085A542")

3-1415540-6

(Alias Part Numbers:

"SR960014")

7-1415541-9

(Alias Part Numbers:

"SR960016(SR6V6K18)")

6-1415054-1

(Alias Part Numbers:

Product Affected

"SR4M4110")

8-1415542-6

(Alias Part Numbers:

"S940-DA3-D024-00004")

3-1415542-5

(Alias Part Numbers:

"SR6V6K12")

5-1415544-4

3-1415018-1

(Alias Part Numbers:

"V23050-A1021-A533"

"V23050A1021A533")

1415539-9

(Alias Part Numbers:

"SR960011")

2-1415055-1

(Alias Part Numbers:

"SR4D4021")

6-1415537-4

(Alias Part Numbers:

"SR6A6K21")

1415055-1

(Alias Part Numbers:

"SR4D4012")

7-1415537-8

(Alias Part Numbers:

"SR6B6K18")

4-1415542-4

(Alias Part Numbers:

"SR6V6K21")

5-1415539-1

3-1415540-7

(Alias Part Numbers:

"SR900015")

8-1415053-1

(Alias Part Numbers:

"SR4M4012")

1-1415544-3

8-1415537-1

(Alias Part Numbers:

Product Affected

"SR6B6K36")

6-1415018-1

(Alias Part Numbers:

"V23050-A1048-A533"

"V23050A1048A533")

3-1415543-3

(Alias Part Numbers:

"ANDERUNG"

"SR6V6K18")

4-1415053-1

(Alias Part Numbers:

"SR4M4024")

1393260-6

(Alias Part Numbers:

"V23050-A1021-A542"

"V23050A1021A542")

1-1393260-3

(Alias Part Numbers:

"V23050-A1110-A542"

"V23050A1110A542")

1393260-1

(Alias Part Numbers:

"V23050-A1005-A542"

"V23050A1005A542")

7-1415537-2

(Alias Part Numbers:

"SR6B6K05")

7-1415053-1

(Alias Part Numbers:

"SR4M4009")

7-1415018-1

(Alias Part Numbers:

"V23050-A1060-A533"

"V23050A1060A533")

9-1415537-0

(Alias Part Numbers:

"SR6C6K12")

6-1415537-1

(Alias Part Numbers:

"SR6A6K12")

Product Affected

1415062-1

(Alias Part Numbers:

"SR6D4110")

5-1415019-1

(Alias Part Numbers:

"V23050-A1110-A551"

"V23050A1110A551")

9-1415053-1

(Alias Part Numbers:

"SR4M4018")

1415015-1

(Alias Part Numbers:

"V23050-A1024-A533"

"V23050A1024A533")

3-1415532-1

(Alias Part Numbers:

"V23050A1018A542X07")

7-1415055-1

(Alias Part Numbers:

"SR4D4060")

1415017-1

(Alias Part Numbers:

"V23050-A1024-A551"

"V23050A1024A551")

1-1415017-1

(Alias Part Numbers:

"V23050-A1012-A551"

"V23050A1012A551")

7-1415537-1

(Alias Part Numbers:

"SR6A6L10")

7-1415359-1

(Alias Part Numbers:

"V23050A1110A533X01")

5-1415055-1

(Alias Part Numbers:

"SR4D4040")

1-1393260-0

(Alias Part Numbers:

"V23050-A1048-A542"

Product Affected

"V23050A1048A542")

1-1415015-1

(Alias Part Numbers:

"V23050-A1012-A533"

"V23050A1012A533")

1415054-1

(Alias Part Numbers:

"SR4M4021")

4-1415543-3

(Alias Part Numbers:

"S940-D03-D024")

9-1415537-4

(Alias Part Numbers:

"SR6C6K24")

6-1415537-5

(Alias Part Numbers:

"SR6A6K24")

5-1415537-8

(Alias Part Numbers:

"SR6A6K05")

6-1415538-3

(Alias Part Numbers:

"SR960008")

1-1393260-1

(Alias Part Numbers:

"V23050-A1060-A542"

"V23050A1060A542")

5-1415054-1

(Alias Part Numbers:

"SR4M4085")

1-1415539-1

(Alias Part Numbers:

"SR960010")

1393260-2

(Alias Part Numbers:

"V23050-A1006-A542"

"V23050A1006A542")

7-1415054-1

(Alias Part Numbers:

"SR4D4005")

Product Affected

1393260-5

(Alias Part Numbers:

"V23050-A1018-A542"

"V23050A1018A542")

3-1415054-1

(Alias Part Numbers:

"SR4M4048")

6-1415017-1

(Alias Part Numbers:

"V23050-A1018-A551"

"V23050A1018A551")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.