



11-May-2017

PCN #:P-17-014385

Subject:Raychem Product Installation Tools

Description of Change: Manufacturing location change. Part Numbers listed will be transferred from TE Redwood City, California, USA Plant to TE AMERMEX Plant in Hermosillo, Mexico.

Reason: Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:10-Jul-2017

Implementation Date:10-Jul-2017

Product Affected

413186-000

(Alias Part Numbers:

"4-1193115-5"

"AT-1319-78-SOLDTCT-ADAPT")

993770-000

(Alias Part Numbers:

"1197687-6")

582602-000

Product Affected

(Alias Part Numbers:

"2-1194615-4"

"AA-400-32-MK3-SUPHTR-120V")

994375-000

(Alias Part Numbers:

"6-1197691-0"

"IR-550-216-FOOT-SWTCH-ASY")

979663-000

(Alias Part Numbers:

"9-1197567-4"

"AA-400-102-MINI-SOLD-TIP")

979672-000

(Alias Part Numbers:

"1197568-5"

"AA-400-103-LOW-FLOW-TIP")

173643-000

(Alias Part Numbers:

"1191263-4"

"RH-3960-1-TINEL-KIT-120V")

007510-000

(Alias Part Numbers:

"4-1198063-5"

"IR-550-238-VIEWING-WINDOW")

993917-000

(Alias Part Numbers:

"1197688-2"

"AT-1319-17-482-CNT-ADPTR")

993693-000

(Alias Part Numbers:

"2-1197686-1"

"IR-500-39-RG-9-REFLECTOR")

156553-000

(Alias Part Numbers:

"1-1191131-9"

"AA-400-136-MK3-HOSE-KIT")

491878-000

(Alias Part Numbers:

"9-1193678-0"

"HT-900A-103-REFL-RPLMT-KT")

C66438-000

Product Affected

(Alias Part Numbers:

"5-1200404-4"

"IR-550-300-MARKIII-CE")

729711-000

(Alias Part Numbers:

"9-1195700-0"

"HT-900A-114-TC-RPLMT-KIT")

994350-000

(Alias Part Numbers:

"3-1197691-2"

"IR-550-50-MARKII-HT-TOOL")

910987-000

(Alias Part Numbers:

"4-1197075-3"

"HT-900B-1-HT-TOOL-YEL-OBS")

CV4406-000

(Alias Part Numbers:

"ED-7-001-550-HOLD-FIX")

712121-000

(Alias Part Numbers:

"2-1195578-2"

"HT-920B-10-HT-TOOL-OLIVE")

837097-000

(Alias Part Numbers:

"8-1196533-8"

"HT-900B-30-HT-TOOL-OLIVE")

508744-000

(Alias Part Numbers:

"5-1193999-5")

859855-000

(Alias Part Numbers:

"9-1196699-5"

"RH-3965-1-TINEL-KIT-220V")

CP2331-000

980123-000

(Alias Part Numbers:

"1197574-1"

"HT-900A-32-HNDLE-KIT-115V")

074594-000

(Alias Part Numbers:

Product Affected

"1-1190558-4")

979646-000

(Alias Part Numbers:

"5-1197567-8"

"AA-400-94-SLD-SLV-TIP-KIT")

281917-000

(Alias Part Numbers:

"5-1192089-7"

"AA-400-200-CE-SUPRHTR")

993702-000

(Alias Part Numbers:

"2-1197686-9")

CY8483-000

444179-000

(Alias Part Numbers:

"2-1193338-4"

"AA-400-228-EL-KT-240V-CE")

238231-000

(Alias Part Numbers:

"4-1191751-0"

"AA-400-229-GUN-HSE-KIT")

CN4646-000

(Alias Part Numbers:

"AE-PNP-FIXT")

CV1032-000

(Alias Part Numbers:

"9-1899740-7"

"IR-550/ED-7-KIT")

444100-000

(Alias Part Numbers:

"5-1193337-9"

"HT-900A-100-LBT-RPLMT-KIT")

959025-000

(Alias Part Numbers:

"7-1197423-9")

993871-000

(Alias Part Numbers:

"7-1197687-1"

"AT-1319-11-12-ST-ADP-ASY")

993695-000

Product Affected

(Alias Part Numbers:

"2-1197686-3"

"IR-500-41-RG-11-REFLECTOR")

013750-000

(Alias Part Numbers:

"9-1190107-1"

"AA-400-128-MK3-EL-KIT-120")

994590-000

(Alias Part Numbers:

"3-1197693-7"

"IR-550-19-RG-6-NOSECONE")

170224-000

(Alias Part Numbers:

"9-1191238-0")

529600-000

(Alias Part Numbers:

"8-1199183-1"

"IR-550-240-REFURB-KIT")

252997-000

(Alias Part Numbers:

"3-1191851-5")

993938-000

(Alias Part Numbers:

"2-1197688-6"

"AT-1319-19-723-SLDT-ASSY")

993872-000

(Alias Part Numbers:

"7-1197687-4"

"AT-1319-12")

992008-000

(Alias Part Numbers:

"3-1197673-0")

CV4408-000

(Alias Part Numbers:

"ED-7-001-550-PCB")

CV2777-000

(Alias Part Numbers:

"ED-7-001-550")

979647-000

(Alias Part Numbers:

Product Affected

"6-1197567-4"

"AA-400-96-NED-PNT-TIP-KIT")

F91912-000

(Alias Part Numbers:

"3-1200880-5")

993877-000

(Alias Part Numbers:

"8-1197687-0"

"AT-1319-14-16-748-ST-ADP")

CN4647-000

993850-000

(Alias Part Numbers:

"5-1197687-0"

"AD-1319-9-HOLD-FIX-PACKAG")

979649-000

(Alias Part Numbers:

"7-1197567-4")

395241-000

(Alias Part Numbers:

"1-1192965-6"

"AT-1319-22-SLDRT-HLD-FIXT")

979691-000

(Alias Part Numbers:

"2-1197568-7"

"AA400-101-STAINLESS-BOOT")

303754-000

(Alias Part Numbers:

"6-1192300-5"

"HT-920B-1-HT-TOOL-YELLOW")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.