



19-Jun-2017

**PCN #:**E-17-008479

**Subject:**Applicator Components

**Description of Change:** P/N 1803480-1, correct typing error on print. P/N 1803252, correct wire barrel thickness to match wire crimper. P/N 5-1803056-2, correct typing error on print. P/N 2844939-1, change angles for manufacturing purposes. P/N 469542, updated radius to eliminate possible sharp corner in radius

**Reason:** Product Improvement.

**Impact of Change:**form - fit - function

**Key Dates:**

**Contact By Date:**21-Jul-2017

**Implementation Date:**21-Jul-2017

**Product Affected**

5-1803056-2

469542-2

469542-3

469542-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.