



07-Nov-2017

PCN #:E-17-015861

Subject:LEV100A5ANG Relay

Description of Change: The drawings for the listed part numbers have been modified to correct following; Before: Label shown 180 degrees from tubulation side. After:Label orientation on production drawing need to be located on tubulation side.

Reason: Document Clarification. Kilovac production drawing shows 180 degrees from tubulation side. All relays shipped with label on correct position - tubulation side.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:31-Jan-2018

Implementation Date:31-Jan-2018

Product Affected

9-1618389-8

(Alias Part Numbers:

"LEV100A5ANG")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.