



14-Nov-2017

PCN #:P-17-015058

Subject:AFFECTS CUSTOMER SHIPMENTS WITHIN NORTH AMERICA ONLY - Distribution Center change from Mechanicsburg, PA to El Paso, TX

Description of Change: THERE IS NO CHANGE TO MANUFACTURING LOCATION OR TO PARTS! Due to consolidation of Distribution Centers, TE is moving the material from our Pennsylvania DC in Mechanicsburg, PA to our DC in El Paso, TX. The transition to El Paso will take place during the weekend of January 20th, 2018. All products you currently receive from our Mechanicsburg, PA location will be transitioned to the new Distribution Center by Monday, January 22nd, 2018. In preparation of the January 23rd go-live, TE will be shipping January 22nd requirements on Friday January 19th, 2018. Your TE Customer Care Representative will contact you to review any special arrangements required for pick-up on Friday and to make any appropriate adjustments to your DUNS/Vendor Codes/Supplier Codes for the new DC. Current DC address: 1311 S. Market Street, Mechanicsburg, PA 17055 Current DUNS Code: 781582481 New DC address: 32 Celerity Wagon, El Paso, TX 79906 New DUNS Code: 080037706 See attached Customer Notification letter.

Reason: Customer Request.Consolidation of distribution centers.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:23-Jan-2018

Implementation Date:23-Jan-2018

Product Affected

5-928999-6

282466-1

(Alias Part Numbers:

Product Affected

"EG9735-000"

"AMP-0-0282466-1")

828801-4

2-1564559-1

1-1418448-1

(Alias Part Numbers:

"8202607143")

2-2112850-1

5-1904006-1

(Alias Part Numbers:

"0 332 019 103")

282536-1

1-1418480-1

9-1452380-9

1-1418479-1

1393315-2

(Alias Part Numbers:

"V23132A2001A200")

1-1355154-1

2177787-1

1393304-5

(Alias Part Numbers:

"V23134J 56X408")

1379217-1

1452303-2

1-1904007-1

(Alias Part Numbers:

"0 332 019 110")

1534046-1

1-1719506-3

9-1563172-9

1355390-6

9-1563173-9

1670365-1

1241978-2

282683-1

1-1418506-1

8-1393305-4

(Alias Part Numbers:

"VF4-45H11-S05")

Product Affected

345809-1

1393315-9

(Alias Part Numbers:

"V23132B2002A200")

1952075-1

1-1904045-2

(Alias Part Numbers:

"3 334 485 008"

"V23333-Z1001-A008")

7-1414985-1

1355600-4

5-1393304-6

(Alias Part Numbers:

"V23134M 52C642"

"V23134M0052C642")

5-1414968-1

(Alias Part Numbers:

"V23132B2002B200-EV-USBX")

3-1904131-7

2208004-1

2-1904022-3

(Alias Part Numbers:

"0 332 209 158")

1-1904027-1

(Alias Part Numbers:

"0 332 209 203")

1-968849-2

4-1414992-7

(Alias Part Numbers:

"V23136A0004X086-EV-CBOX")

1534167-1

967598-1

1418758-3

1719566-1

1452671-2

1544358-1

(Alias Part Numbers:

"P73100730025")

2-1414967-9

1241765-2

Product Affected

344106-1

1-699696-9

6-968973-1

1379675-1

929504-6

9-965382-2

185454-1

963216-1

6-968974-1

880811-2

(Alias Part Numbers:

"EG9729-000"

"AMP-0-0880811-2"

"51.033.00")

2208004-2

2208165-1

1-1823724-1

1-1355668-2

2208324-1

282308-1

1703014-4

928966-1

965636-1

1418884-3

1564760-1

2-962915-1

1-1414286-0

3-1904022-2

(Alias Part Numbers:

"0 332 209 150")

347887-3

929989-1

344009-1

3-1904131-0

2-967624-1

1544545-1

(Alias Part Numbers:

"P7310073010")

929971-1

1452065-1

Product Affected

1-2177053-1

929027-3

1-929270-1

282109-1

1393277-8

(Alias Part Numbers:

"V23076A1022C133")

2-1904070-2

1-962916-2

1-699695-9

1952120-1

2-1904020-4

(Alias Part Numbers:

"0 332 209 151")

2-1719686-4

1-953042-6

1-1544545-2

(Alias Part Numbers:

"P76100760608"

"TL010")

4-1718353-1

5-1419148-3

(Alias Part Numbers:

"V23073H2005A402")

965633-1

1544332-1

(Alias Part Numbers:

"P790861")

9-1414780-4

(Alias Part Numbers:

"V23134-B0052-X490")

929650-2

6-1414989-1

1-1414714-0

1-1452337-1

925590-2

(Alias Part Numbers:

"0-0925590-2")

281866-3

1-929504-1

Product Affected

929504-2

100283-1

284743-2

1-1534546-2

1393303-2

(Alias Part Numbers:

"V23134B 52X309 * B")

968137-2

1379118-1

2-1393302-2

(Alias Part Numbers:

"V23134A 52C643"

"V23134A0052C643"

"D33228-000"

"AMPS-2-1393302-2")

2-1703884-1

3-1355470-3

5-963716-2

965383-1

(Alias Part Numbers:

"0-0965383-1")

1393276-7

(Alias Part Numbers:

"V23071A1010A132")

963898-1

965901-1

1-827688-1

1-967644-2

927849-2

1432635-1

(Alias Part Numbers:

"VF4A-61F21-A01")

1-1534155-1

166500-2

1-1414699-0

1-967623-6

963904-3

1-1393277-4

(Alias Part Numbers:

"V23076A3001C132")

Product Affected

1-963616-1

1-1418497-0

172500-1

929504-3

927766-3

(Alias Part Numbers:

"AMP-0-0927766-3"

"E17312-000")

927768-9

1337352-1

1703875-1

144617-1

1-1394916-2

144479-1

1379114-3

1432279-1

(Alias Part Numbers:

"VFMA-15F41-Z07-PKG-CHR")

1-967623-5

1-1904005-4

(Alias Part Numbers:

"0 332 201 107")

7-1393278-2

(Alias Part Numbers:

"V23133A3022D142")

967354-3

2177202-8

5-1393302-8

(Alias Part Numbers:

"V23134A1052C643")

2-967059-1

1-967281-1

1544218-1

(Alias Part Numbers:

"P3010130854")

1-1414122-0

282107-1

3-1904131-5

1-1241371-1

3-1904131-6

Product Affected

493830-2

953363-1

1-967242-1

1475104-1

1-964334-1

1-1414708-0

344111-1

1-1393315-4

(Alias Part Numbers:

"V23132M M")

925575-1

1-2141324-5

7-1452671-3

1-962843-1

4-1415009-6

(Alias Part Numbers:

"V23136-L0031-X088")

825213-1

1393277-6

(Alias Part Numbers:

"V23076A1001D143")

7-1718747-6

1241634-3

1-1534546-1

1-1415006-2

1563110-1

963774-1

1703339-3

929387-1

1-968325-4

2-1355123-3

100836-1

965643-1

1-968318-1

1-967240-1

2141227-1

2-1904131-9

282956-1

827551-3

(Alias Part Numbers:

Product Affected

"CF0027-000"

"AMP-0-0827551-3")

3-1393292-8

(Alias Part Numbers:

"V23074A1002A403")

1241794-2

2-968700-1

1-1904045-6

(Alias Part Numbers:

"3 334 485 046"

"V23333-Z0001-B046")

1-968037-4

1-1414939-4

1-966718-2

1904000-1

(Alias Part Numbers:

"0 332 002 150")

6-1904059-1

(Alias Part Numbers:

"V23232-A0002-X014")

2208325-1

1-967624-1

1-964300-3

1904002-2

(Alias Part Numbers:

"0 332 002 250")

1394872-1

1544452-1

(Alias Part Numbers:

"P7010070285")

1534531-1

1-962841-2

2-963964-7

965601-2

3-1393278-7

(Alias Part Numbers:

"V23133A1022C133")

1544142-1

(Alias Part Numbers:

"P7810878266")

Product Affected

282189-1

(Alias Part Numbers:

"CF0543-000"

"AMP-0-0282189-1")

2-1904131-5

9-1414992-1

3-1904020-8

(Alias Part Numbers:

"0 332 209 159")

8-1393292-4

(Alias Part Numbers:

"V23074A1001A403")

962189-1

1-1904004-3

(Alias Part Numbers:

"0 332 011 007")

929504-5

1-1414687-0

1670364-1

953302-1

185534-1

6-1419137-4

(Alias Part Numbers:

"V23074A2001A403")

1-1991226-2

1-1414469-0

2-1904045-4

(Alias Part Numbers:

"3 334 485 041"

"V23333-Z0002-A041")

1-1904045-1

(Alias Part Numbers:

"3 334 485 007"

"V23333-Z0001-A007")

3-1703884-2

5-1393304-5

(Alias Part Numbers:

"V23134M")

929504-4

1-1414761-0

Product Affected

(Alias Part Numbers:

"V23086-C1001-A403-EV-USBX")

281934-3

(Alias Part Numbers:

"80.246.00")

1-1452347-1

828801-5

282465-1

(Alias Part Numbers:

"61.359.00")

344112-1

1411594-1

(Alias Part Numbers:

"V23540F6000Y65")

5-1393302-1

(Alias Part Numbers:

"V23134A 53C643")

1-1452058-1

1534153-1

3-968700-1

828545-1

2-1904025-6

(Alias Part Numbers:

"0 332 209 211")

1544333-1

(Alias Part Numbers:

"P790862")

1703874-1

927773-3

1-929278-2

1-1718422-1

929968-1

1-828881-1

1-967626-1

1-1719188-0

927827-1

964740-1

963598-1

1-962915-3

1-1452350-1

Product Affected

1-964294-3

7-1393273-8

(Alias Part Numbers:
"V23072C1062A303T")

1416010-1

(Alias Part Numbers:
"V23132-A2001-B200")

1355206-1

2-1904058-7

(Alias Part Numbers:
"V23700-F0002-A408")

2-1904011-2

(Alias Part Numbers:
"0 332 019 151")

1241794-6

5-1393292-8

(Alias Part Numbers:
"V23074A2001A402")

3-1393303-4

(Alias Part Numbers:
"V23134B1052C642")

2-929171-1

106462-1

2-1355668-2

1544545-3

(Alias Part Numbers:
"P7310073060")

1355526-2

1418776-1

1-1414173-0

3-1904131-3

344108-1

1379675-2

4-1393302-1

(Alias Part Numbers:
"V23134A 52X278")

1452601-1

2-1904022-4

(Alias Part Numbers:
"0 332 209 161")

Product Affected

2-963217-1

1-1904045-5

(Alias Part Numbers:

"3 334 485 045"

"V23333-Z1001-B045")

1-173630-2

2-1904025-5

(Alias Part Numbers:

"0 332 209 206")

1-1418775-1

1-967621-6

1241434-1

1393304-9

(Alias Part Numbers:

"V23134J1052D642")

2-1904058-5

(Alias Part Numbers:

"V23700-C0001-A408")

1432706-1

(Alias Part Numbers:

"VSA-0010")

6-1414921-8

4-1418506-1

7-1414967-8

(Alias Part Numbers:

"V23086-R1802-A803")

929504-1

1-929974-4

929990-1

1-962581-1

(Alias Part Numbers:

"8202611523")

1-966693-1

1-1904020-5

(Alias Part Numbers:

"0 332 209 152")

282080-2

1-1703884-3

5-1904012-1

(Alias Part Numbers:

Product Affected

"0 332 019 150")

968271-1

185792-1

(Alias Part Numbers:

"825G-37539")

1-1703884-1

6-928918-2

927766-1

144969-2

1904001-2

(Alias Part Numbers:

"0 332 002 156")

100291-1

4-1904124-3

183035-1

(Alias Part Numbers:

"CM8391-000"

"AMP-0-0183035-1"

"2-42939-6221"

"820P-36547"

"4004200209")

282404-1

(Alias Part Numbers:

"61.355.00"

"820P-36528")

1-963449-2

185226-1

963357-5

699694-1

1394026-1

1544132-2

(Alias Part Numbers:

"P7010870860")

1337706-2

4-1393298-9

(Alias Part Numbers:

"V23136M M")

953118-1

282764-1

1379118-4

Product Affected

962191-1

1-2141272-1

2-1904131-6

1-1414632-0

2-1904025-3

(Alias Part Numbers:

"0 332 209 204")

1-1355470-5

282191-1

3-1393303-7

(Alias Part Numbers:

"V23134B1053C642")

1-1393302-4

(Alias Part Numbers:

"VF7-11H11")

1393277-4

(Alias Part Numbers:

"V23076A1001C133")

9-1415001-5

(Alias Part Numbers:

"CZ1474-000")

4-1904065-7

927770-1

1-1718644-2

1-1414552-0

284617-1

964408-1

3-1418390-1

1-963215-1

344070-1

1418994-1

699686-1

1-1393302-6

(Alias Part Numbers:

"VF7-41F11-S01")

8-968973-2

2-1718643-2

5-965908-1

1-2141227-1

348794-4

Product Affected

1-964332-1

1393280-5

(Alias Part Numbers:
"V23086C1001A402")

6-1393292-3

(Alias Part Numbers:
"V23074A2002A403")

966168-4

1432800-1

(Alias Part Numbers:
"VF4A-35F21-Z05")

9-1393305-9

(Alias Part Numbers:
"VF4-65H11-S08")

8-1393305-7

(Alias Part Numbers:
"VF4-55F11-S01")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.