

04-Jan-2018 **PCN #:**E-17-018685

**Subject:**DEUTSCH DTP 4pin series grommet supplier manufacturing location change.

**Description of Change:** The Industrial and Commercial Transportation (ICT) business unit of TE Connectivity (TEC) intends to move the molding of the rear wire grommet that is used in the part number(s) listed below from the current supplier USA location to the current supplier Mexico location. We hereby reserve the right to move the tool back to the current supplier USA location as business needs require this. Final assembly of the connectors will remain in ICT-Empalme, Sonora (MX) campus. This PCN is in effect immediately and indefinitely.

**Reason:** Dear Customer, we inform you of this move of the grommet as part of our aggressive continuous improvement efforts and to meet on time product shipments. An internal release based on our specifications will be executed before any parts are delivered. Level 3 PPAP packages by part number assembly will be offered upon customer request.

**Impact of Change:** form - fit - function

**Key Dates:** 

Contact By Date:02-Feb-2018

**Implementation Date:**02-Feb-2018

## **Product Affected**

DTP04-4P-P018-948A DTP04-4P-C015 (Alias Part Numbers: "ZPF000000000130271" "DTP04-4P-C015-E")

DTP04-4P-CE02

## **Product Affected**

DTP04-4P-C017

DTP04-4P-P018

DTP06-4S-C017

DTP06-4S-E004

(Alias Part Numbers:

"ZPF00000000130280")

DTP06-4S-CE03

DTP04-4P-P018-947Y

DTP04-4P-L012

(Alias Part Numbers:

"ZPF00000000130274")

DTP04-4P-P052

(Alias Part Numbers:

"DTP04-4P-P052-LD"

"DTP04-4P-P052-LS"

"DTP04-4P-P052-L")

DTP06-4S-EE01

(Alias Part Numbers:

"ZPF00000000130281"

"DTP06-4S-EE01-RU")

DTP06-4S-C034

DTP04-4P-P018-1

DTP04-4P-P059

(Alias Part Numbers:

"DTP04-4P-P059-LD"

"DTP04-4P-P059-LS"

"DTP04-4P-P059-L")

DTP04-4P-CE01

DTP04-4P-P018-947Z

DTP04-4P-LE07

(Alias Part Numbers:

"ZPF00000000130275"

"DTP04-4P-LE07-RU")

DTP06-4S-E003

(Alias Part Numbers:

"ZPF00000000130279"

"DTP06-4S-E003-LS"

"DTP06-4S-E003-L")

**DTP06-4S** 

(Alias Part Numbers:

## **Product Affected**

"ZPF00000000130276"

"DTP06-4S-AS"

"DTP06-4S-SC")

DTP04-4P-E004

(Alias Part Numbers:

"ZPF00000000130273")

DTP06-4S-CE01

DTP04-4P-E003

(Alias Part Numbers:

"ZPF00000000130272"

"DTP04-4P-E003-MS"

"DTP04-4P-E003-M")

DTP04-4P-CE03

DTP06-4S-C015

(Alias Part Numbers:

"ZPF00000000130277"

"DTP06-4S-C015-LD"

"DTP06-4S-C015-LS"

"DTP06-4S-C015-E"

"DTP06-4S-C015-L")

DTP04-4P

(Alias Part Numbers:

"ZPF000000000130270"

"DTP04-4P-AS"

"DTP04-4P-SC"

"DTP04-4P-S")

DTP06-4S-CE02

(Alias Part Numbers:

"ZPF00000000130278")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.