



09-Mar-2018

PCN #:E-17-017633

Subject:DEUTSCH Header Receptacle Packaging.

Description of Change: Packaging Change. Change the EPS foam trays to an antistatic PCV plastic formed trays. Also change box carton to meet standard per AIAG (Automotive) type and quantity per box.

Reason: Dear customer, we are contacting you to notify you of a process change to the way the below part number(s) are packaged. These changes will conform to automotive AIAG packaging standards and will eliminate non-recyclable EPA foam. Changes you will notice are the way the product is packaged, box size and quantity. This change does not affect fit, form or function of the product. Shipment of both packaging versions may be mixed. **IMPORTANT:** This is a continual improvement process. These changes are being phased in gradually and previous packaging versions can remain stocked until use. The product drawings or application specifications are not affected.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:20-Mar-2018

Implementation Date:20-Mar-2018

Product Affected

DTM1312PA12PBR008

(Alias Part Numbers:

"1899781-5"

"DTM13-12PA-12PB-R008")

SRK13-MDD-32A-001

DRC23-40PB-N009

DRC22-50P10

Product Affected

DRC10-40P

(Alias Part Numbers:
"ZPF000000000131270")

DRC13-24PA-C023

DRC23-40PA-N007

SRK13-MDB-32A-001

DRCP25-126PAA-G003

DRC20-50P10

(Alias Part Numbers:
"ZPF000000000131360")

DTLP13-4PB-N011

DRC10-24PC

DRC20-60P08

DTM1312PC12PDR008

(Alias Part Numbers:
"3-1899781-6"
"DTM13-12PC-12PD-R008")

2321098-1

(Alias Part Numbers:
"SRK15-MDH-32A-001-G003")

DRC13-24PC-CG01

DRC22-50P05

DTM13-12PB-NP02

DRC13-40PB

(Alias Part Numbers:
"ZPF000000000131282")

DRC13-40PB-CG01

DRC20-60P05

SRK13MDD32A001G003

(Alias Part Numbers:
"SRK13-MDD-32A-001-G003")

DRC23-24PA-A010

DRC10-24PD-AG02

DRC22-50P07

DRC20-60P02

DRC22-50P04

DTM1312PA12PBGR01

(Alias Part Numbers:
"DTM13-12PA-12PB-GR01")

SRK15-MDE-32A-001

Product Affected

DTM13-12PC-NP02

DRC23-40PB-N010

DRC10-24PB

DRC20-50P02

(Alias Part Numbers:

"ZPF000000000131352")

DRC13-24PC-C023

SRK13MDA32A001G003

(Alias Part Numbers:

"SRK13-MDA-32A-001-G003")

DTLP13-4PC-N011

DRC23-40PB-N012

DRC20-60P06

DRCP25-126PBB-GC03

DRC10-24PA-A004

(Alias Part Numbers:

"ZPF000000000131084")

DT13-36PABC-R015

(Alias Part Numbers:

"5-1899792-7")

SRK13-MDH-32A-001

DRC23-24PB-A010

DRC22-50P01

(Alias Part Numbers:

"ZPF000000000131361")

DRC23-40PA-N009

SRK15MDJ32A001G003

(Alias Part Numbers:

"SRK15-MDJ-32A-001-G003")

DT13-24PAB-GR02

SRK13-MDA-32A-001

(Alias Part Numbers:

"5-1899842-7")

DT13-36PABC-GR02

SRK13-MDE-32A-001

SRK13MDF32A001G003

(Alias Part Numbers:

"SRK13-MDF-32A-001-G003")

DRC13-40PD-C023

SRK15MDD32A001G003

Product Affected

(Alias Part Numbers:

"SRK15-MDD-32A-001-G003")

DT13-12PB-B016

DRC23-40PD-N012

SRK13-MDI-32A-001

DRC13-40PB-C023

DRC23-64PAA

(Alias Part Numbers:

"ZPF000000000131389")

DRC23-40PA-N012

(Alias Part Numbers:

"ZPF000000000131312")

SRK13MDI32A001G003

(Alias Part Numbers:

"SRK13-MDI-32A-001-G003")

DT13-12PB

DTMF15-48P-B026

DRC22-50P02

DRC13-24PC-G002

SRK13-MDC-32A-001

SRK15MDI32A001G003

(Alias Part Numbers:

"SRK15-MDI-32A-001-G003")

SRK15-MDA-32A

DRC13-24PA

(Alias Part Numbers:

"ZPF000000000131097")

DRC13-24PB-G002

(Alias Part Numbers:

"ZPF000000000131101")

DRC10-24PB-A004

(Alias Part Numbers:

"ZPF000000000131085")

DRC20-60P09

SRK15-MDC-32A-001

DRC23-40PC-N009

SRK13-MDG-32A-001

SRK13-MDJ-32A-001

DRC23-24PA

(Alias Part Numbers:

Product Affected

"ZPF000000000131123")

SRK15MDE32A001G003

(Alias Part Numbers:

"SRK15-MDE-32A-001-G003")

DTM13-12PB

(Alias Part Numbers:

"ZPF000000000130586")

SRK15MDG32A001G003

(Alias Part Numbers:

"SRK15-MDG-32A-001-G003")

DTM13-12PB-R005

(Alias Part Numbers:

"ZPF000000000130587")

DRC13-24PD-G002

DT13-20PAA

DRC20-60P03

DTM13-12PD-R008

DTM13-12PD

(Alias Part Numbers:

"ZPF000000000130590")

SRK15-MDA-32A-001

DTM1312PA12PBR008H

(Alias Part Numbers:

"DTM13-12PA-12PB-R008-H")

DRC10-24PA

(Alias Part Numbers:

"ZPF000000000131083")

DRC23-24PB

(Alias Part Numbers:

"ZPF000000000131124")

DRC20-60P04

SRK15-MDI-32A-001

DTM13-12PC12PDGR01

DT13-12PD-B016

DTM13-12PC-GR01

DRC10-40P-AG02

DRC13-40PC-C023

DTM13-12PC-R008

DTM13-12PB-GR01

DT13-24PAB-R015

Product Affected

DT13-12PD

DRC13-40PD

(Alias Part Numbers:
"ZPF000000000131286")

DRC13-24PB

(Alias Part Numbers:
"ZPF000000000131100")

DRC20-50P05

(Alias Part Numbers:
"ZPF000000000131355")

DTM13-12PA-R008

(Alias Part Numbers:
"ZPF000000000139426")

DRC22-50P06

SRK15-MDF-32A-001

DTLP13-4PD-N011

DTM13-12PC-G003

DTM13-12PA-NP02

SRK13MDE32A001G003

(Alias Part Numbers:
"SRK13-MDE-32A-001-G003")

DRC10-24PD-A004

(Alias Part Numbers:
"ZPF000000000131087")

DRC13-40PA

(Alias Part Numbers:
"ZPF000000000131279")

DRC20-50P08

(Alias Part Numbers:
"ZPF000000000131358")

DRC23-40PD-N009

DRC13-24PA-G002

(Alias Part Numbers:
"ZPF000000000131099")

DRC20-50P01

(Alias Part Numbers:
"ZPF000000000131351")

SRK15MDF32A001G003

(Alias Part Numbers:
"SRK15-MDF-32A-001-G003")

Product Affected

DT13-12PB-G003

SRK13MDG32A001G003

(Alias Part Numbers:

"SRK13-MDG-32A-001-G003")

DT13-20PAA-E004

DRC23-40PC-N012

DTM13-12PC

(Alias Part Numbers:

"ZPF000000000130589")

94202103

(Alias Part Numbers:

"094202103")

DRC20-50P06

(Alias Part Numbers:

"ZPF000000000131356")

DRC13-40PB-G002

(Alias Part Numbers:

"ZPF000000000131283")

DTM1312PA12PBR008M

(Alias Part Numbers:

"DTM13-12PA-12PB-R008-MIL")

DRC13-24PB-CG01

DT13-12PA-GR02

SRK15-MDD-32A-001

DRC10-24PD

DRC13-24PD-C023

DTM13-12PD-NP02

DRC13-24PA-CG01

(Alias Part Numbers:

"ZPF000000000131098")

DRC23-24PC

DRC10-24PA-AG01

DTM13-12PB-R008

(Alias Part Numbers:

"ZPF000000000130588")

DRC10-40PA-A004

DRC10-24PC-AG02

DRC13-24PD

(Alias Part Numbers:

"ZPF000000000131103")

Product Affected

DRC13-40PD-CG01

SRK13MDJ32A001G003

(Alias Part Numbers:

"SRK13-MDJ-32A-001-G003")

DTM13-12PB-G003

DT13-12PA-B016

DRC22-50P08

DRC13-24PB-C023

DRC22-50P09

DTM13-12PA

(Alias Part Numbers:

"ZPF000000000130584")

DT13-12PC-G003

DTM13-12PA12PBR008

(Alias Part Numbers:

"5-1899805-8")

DTM13-12PA12PCR008

DRC13-40PC-G002

(Alias Part Numbers:

"ZPF000000000131285")

DRC10-24PC-A004

(Alias Part Numbers:

"ZPF000000000131086")

DRC23-80P

(Alias Part Numbers:

"ZPF000000000131418")

DRC20-50P09

(Alias Part Numbers:

"ZPF000000000131359")

DT13-12PC-B016

DRC23-24PD

SRK15MDH32A001G003

(Alias Part Numbers:

"SRK15-MDH-32A-001-G003")

SRK13MDH32A001G003

(Alias Part Numbers:

"SRK13-MDH-32A-001-G003")

DRC10-40P-A004

(Alias Part Numbers:

"ZPF000000000131271")

Product Affected

SRK13MDB32A001G003

(Alias Part Numbers:

"SRK13-MDB-32A-001-G003")

DT13-12PA-G003

DT13-48PABCD-R015

(Alias Part Numbers:

"3-1899782-1")

DRC23-40PB-N007

DRC10-40PA

DRC22-50P03

DTM13-12PD-GR01

DRC13-40PA-C023

DT13-12PD-G003

DRC23-24PC-A010

DRC10-24PA-AG02

DRC13-40PA-CG01

SRK15-MDH-32A-001

SRK15-MDG-32A-001

DRC13-40PD-G002

SRK13MDC32A001G003

(Alias Part Numbers:

"SRK13-MDC-32A-001-G003")

DTMF15-48P

(Alias Part Numbers:

"ZPF000000000131348")

SRK13-MDF-32A-001

DRC20-60P10

DRC23-40PC-N007

DRC13-40PA-G002

(Alias Part Numbers:

"ZPF000000000131281")

DT13-12PC

DRC13-40PC-CG01

DRC13-24PC

(Alias Part Numbers:

"ZPF000000000131102")

DRC23-24PD-A010

DRC20-50P04

(Alias Part Numbers:

"ZPF000000000131354")

Product Affected

DT13-12PA

DRC10-24PB-AG02

DTM13-12PA-GR01

(Alias Part Numbers:
"ZPF000000000130585")

DRC13-40PC

(Alias Part Numbers:
"ZPF000000000131284")

DTM13-12PD-G003

SRK15-MDJ-32A-001

DTM13-12PA-R005

DRC20-60P07

SRK15-MDB-32A-001

DTM13-12PA-G003

DRC23-64PAA-N010

(Alias Part Numbers:
"ZPF000000000131390")

DT13-12PA-R015

DRC23-40PD-N007

DRC13-24PD-CG01

DT13-48PABCD-GR02

DJD10-21P

DTLP13-4PA-N011

DRC20-60P01

DRC20-50P07

(Alias Part Numbers:
"ZPF000000000131357")

DRC20-50P03

(Alias Part Numbers:
"ZPF000000000131353")

DT13-12P

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.