



14-May-2018

PCN #:P-18-015820

Subject:Change of pickup location for Trutnov sourced ES2000 and ATUM parts.

Description of Change: Pickup location of ES2000 and ATUM parts will change from TE's WCDC in Ontario, CA to PADC in Mechanicsburg, PA. To be tied to PCN P-18-015354 and P-18-015360 that stated change of manufacturing location for these parts.

Reason: Product improvement.Parts listed in this change notice were previously manufactured at TE's facility at Menlo Park, CA. Since this facility is being closed, manufacturing has been moved to Trutnov, Czech Republic. Changing pickup location to PADC will shorten LT of Made to Order parts by 2 weeks, as shipments from Trutnov arrive on the East Coast of the US by ocean transit. New LT for PADC was already communicated on notifications about manufacturing location change.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:11-Jun-2018

Implementation Date:11-Jun-2018

Product Affected

NB12086001

NB11022001

NB10626001

NB11056001

NB12262001

NB12252001

NB12034001

NB10666001

Product Affected

NB08846001

NB09886001

NB09342001

NB11176001

NB10026001

NB10306001

NB10706001

NB10516001

829131P037

(Alias Part Numbers:

"9-1196474-4"

"ES2000-NO.1-C1-0-80MM")

NB09066001

NB09166001

NB10646001

NB08876001

NB11116001

NB10506001

NB09216001

NB09836001

NB09012001

NB12452001

063725P080

(Alias Part Numbers:

"1190482-9"

"ES2000-NO.2-B9-0-33MM")

NB09646001

NB10124001

829131P017

(Alias Part Numbers:

"7-1196474-6"

"ES2000-NO.1-C1-0-60MM")

NB11926001

829131P026

(Alias Part Numbers:

"8-1196474-3"

"ES2000-NO.1-C1-0-25MM")

NB11392001

NB11136001

063725P078

Product Affected

(Alias Part Numbers:

"1190482-7"

"ES2000-NO.2-B9-0-38MM")

NB09952001

(Alias Part Numbers:

"ATUM--19/6-0-STK")

NB1202-001

NB11956001

EG9829-000

(Alias Part Numbers:

"ES2000-NO.2-B9-0-127MM")

NB11906001

NB11822001

NB12422001

NB09264001

NB09776001

NB12072001

NB11476001

829131P051

(Alias Part Numbers:

"1196475-3"

"ES2000-NO.1-C1-0-40MM")

NB12362001

NB10546001

NB09896001

NB10186001

NB10152001

NB11784001

D04950-000

(Alias Part Numbers:

"3-1200816-9"

"ES2000-NO.1-C1-0-38MM")

NB10046001

NB10114001

NB10142001

NB11066001

NB12406001

NB09944001

NB10562001

NB11936001

Product Affected

NB09356001

NB10256001

NB10884001

NB09368001

(Alias Part Numbers:
"ATUM--16/4-0-1M")

NB12482001

NB11736001

NB10314001

NB11566001

NB12042001

NB10016001

826309-000

(Alias Part Numbers:
"7-1196454-4"
"ES2000-NO.1-C1-0-45MM")

NB08896001

NB11166001

NB11252001

829131P011

(Alias Part Numbers:
"7-1196474-0"
"ES2000-NO.1-C1-0-30MM")

NB12116001

829131P014

(Alias Part Numbers:
"7-1196474-3"
"ES2000-NO.1-C1-0-65MM")

NB11354001

NB10382001

NB09126001

NB09986001

NB10476001

NB11866001

NB09856001

NB11374001

NB10526001

NB08936001

NB08956001

829131P012

Product Affected

(Alias Part Numbers:

"7-1196474-1"

"ES2000-NO.1-C1-0-50MM")

NB11446001

NB11042001

NB10466001

NB08926001

NB0993-001

NB11536001

NB09914001

NB08994001

NB10946001

NB11706001

063725P029

(Alias Part Numbers:

"6-1190481-6"

"ES2000-NO.2-B9-0-95MM")

NB11456001

063725P017

(Alias Part Numbers:

"5-1190481-7"

"ES2000-NO.2-B9-0-40MM")

NB10892001

NB1077-001

NB11126001

NB10794001

829131P041

(Alias Part Numbers:

"9-1196474-8"

"ES2000-NO.1-A1-0-STK")

NB11192001

NB09906001

NB09446001

NB12146001

063725P046

(Alias Part Numbers:

"7-1190481-7"

"ES2000-NO.2-B9-0-100MM")

NB10226001

063725P011

Product Affected

(Alias Part Numbers:

"5-1190481-1"

"ES2000-NO.2-B9-0-50MM")

NB10448001

NB09562001

NB11666001

NB11436001

829131P034

(Alias Part Numbers:

"9-1196474-1"

"ES2000-NO.1-B5-0-50MM")

NB12352001

063725P028

(Alias Part Numbers:

"6-1190481-5"

"ES2000-NO.2-B9-0-25MM")

NB09486001

NB08972001

NB10984001

NB09196001

NB10056001

NB10322001

063725P035

(Alias Part Numbers:

"7-1190481-2"

"ES2000-NO.2-B9-0-70MM")

NB10554001

063725P022

(Alias Part Numbers:

"6-1190481-1"

"ES2000-NO.2-B9-0-STK"

"ES2000-2-4FOOT")

NB11612001

NB11546001

NB11986001

NB11586001

NB11306001

NB1035-001

NB11316001

NB11096001

Product Affected

NB12206001

NB11262001

NB11296001

499683-000

(Alias Part Numbers:

"4-1193735-4"

"ES2000-NO.2-B9-0-39MM")

NB0929-001

NB09272001

NB11794001

NB12312001

NB10784001

063725P030

(Alias Part Numbers:

"6-1190481-7"

"ES2000-NO.2-B9-0-80MM")

NB11286001

NB10656001

NB11014001

NB10802001

NB12184001

NB10956001

NB11184001

NB12166001

NB11526001

829131P079

(Alias Part Numbers:

"2-1196475-9"

"ES2000-NO.1-C1-0-15MM")

NB10536001

NB11382001

NB09396001

NB11496001

NB1134-001

NB11402001

NB10636001

NB12442001

NB11556001

NB09716001

NB12004001

Product Affected

NB10746001

NB10084001

NB11076001

NB09806001

NB10392001

NB09226001

NB10872001

NB09256001

NB11696001

NB10216001

NB11242001

(Alias Part Numbers:

"ATUM--40/13-0-STK")

063725P074

(Alias Part Numbers:

"1190482-4"

"ES2000-NO.2-B9-0-43MM")

NB08866001

NB11946001

NB12472001

NB10594001

NB09746001

NB10496001

NB09816001

NB11466001

NB10036001

NB10486001

NB09662001

NB11156001

063725P013

(Alias Part Numbers:

"5-1190481-3"

"ES2000-NO.2-B9-0-75MM")

NB12462001

NB09236001

NB11966001

NB11716001

NB11996001

NB10602001

NB09322001

Product Affected

NB10906001

NB09056001

(Alias Part Numbers:

"ATUM---12/4-0-100MM")

NB08964001

NB1058-001

NB10976001

NB12432001

NB09096001

NB09756001

NB12222001

NB09156001

NB08856001

NB11746001

NB09726001

NB10736001

NB09596001

NB12272001

NB09116001

NB08946001

NB12342001

NB09476001

NB12326001

NB10686001

NB11604001

NB11686001

NB09606001

NB09136001

NB09406001

NB11644001

NB12296001

NB09616001

NB11812001

NB09766001

NB10822001

NB08886001

829131P020

(Alias Part Numbers:

"7-1196474-8"

"ES2000-NO.1-C1-0-75MM")

Product Affected

NB10198001

NB08916001

NB11676001

NB11332001

NB09962001

NB09996001

NB12124001

NB10916001

NB10416001

NB09004001

NB12282001

NB10092001

829131P043

(Alias Part Numbers:

"1196475-1"

"ES2000-NO.1-C1-0-35MM")

NB10832001

NB1163-001

829131P076

(Alias Part Numbers:

"2-1196475-7"

"ES2000-NO.1-C1-0-305MM")

NB10456001

NB12106001

NB11364001

063725P036

(Alias Part Numbers:

"7-1190481-3"

"ES2000-NO.2-B9-0-90MM")

NB09866001

NB11032001

NB11976001

NB10236001

NB09416001

NB09786001

NB0951-001

NB10006001

NB10266001

NB09636001

829131P024

Product Affected

(Alias Part Numbers:

"8-1196474-1"

"ES2000-NO.1-C1-0-90MM")

NB10406001

NB09076001

NB12242001

NB09572001

NB09534001

NB0898-001

NB09826001

NB09738001

NB10754001

NB12306001

NB10716001

NB09146001

NB10856001

829131P039

(Alias Part Numbers:

"9-1196474-6"

"ES2000-NO.1-C1-0-20MM")

NB10066001

NB11488001

NB08906001

063725P034

(Alias Part Numbers:

"7-1190481-1"

"ES2000-NO.2-B9-0-35MM")

NB09108001

829131P019

(Alias Part Numbers:

"7-1196474-7"

"ES2000-NO.1-C1-0-27MM")

NB12012001

NB12096001

NB10862001

NB1010-001

NB09524001

NB10992001

063725P025

(Alias Part Numbers:

Product Affected

"6-1190481-3"

"ES2000-NO.2-B9-0-20MM")

NB09426001

NB09086001

(Alias Part Numbers:

"ATUM--12/4-0-175MM")

NB09436001

NB1177-001

NB10276001

NB12332001

NB09176001

NB09304001

NB1122-001

NB09022001

NB11802001

NB11832001

NB11426001

NB11726001

NB09696001

NB11324001

NB10726001

NB11412001

NB10842001

NB10372001

(Alias Part Numbers:

"ATUM--24/8-0-STK")

NB11576001

NB11276001

NB12196001

NB10364001

NB12212001

NB09494001

NB10812001

NB12062001

NB10076001

NB12052001

NB09796001

NB12392001

063725P016

(Alias Part Numbers:

Product Affected

"5-1190481-6"

"ES2000-NO.2-B9-0-60MM")

NB09046001

NB11596001

063725P049

(Alias Part Numbers:

"8-1190481-0"

"ES2000-NO.2-A1-0-STK")

NB08836001

NB10286001

NB09206001

NB12232001

NB09456001

063725P081

(Alias Part Numbers:

"1-1190482-0"

"ES2000-NO.2-A1-0-27MM")

829131P081

(Alias Part Numbers:

"3-1196475-0"

"ES2000-NO.1-C1-0-100MM")

NB09706001

NB11842001

NB10676001

NB11516001

NB09922001

NB12136001

NB09312001

(Alias Part Numbers:

"ATUM--12/4-0-STK")

NB11754001

829131P021

(Alias Part Numbers:

"7-1196474-9"

"ES2000-NO.1-C1-0-STK")

NB11146001

NB09846001

NB11762001

NB09686001

NB10176001

Product Affected

NB11852001

NB09626001

NB12382001

829131P052

(Alias Part Numbers:

"1196475-4"

"ES2000-NO.1-C1-0-63MM")

NB09552001

NB09466001

NB11886001

6001NB1093

NB10696001

NB09582001

NB11506001

NB10426001

NB09542001

(Alias Part Numbers:

"ATUM--16/4-0-STK")

063725P031

(Alias Part Numbers:

"6-1190481-8"

"ES2000-NO.2-B9-0-150MM")

NB09332001

NB10926001

NB10246001

NB09376001

NB12412001

829131P038

(Alias Part Numbers:

"9-1196474-5"

"ES2000-NO.1-C1-0-150MM")

NB09386001

NB10436001

NB09246001

(Alias Part Numbers:

"ATUM--12/4-0-80MM")

NB09876001

NB09186001

NB10762001

NB09032001

Product Affected

NB11088001

NB11234001

NB10612001

NB12172001

063725P018

(Alias Part Numbers:

"5-1190481-8"

"ES2000-NO.2-B9-0-30MM")

CR6142-000

(Alias Part Numbers:

"ES2000-NO.1-C1-0-70MM"

"1899833-7")

NB12372001

063725P021

(Alias Part Numbers:

"6-1190481-0"

"ES2000-NO.2-B9-0-27MM")

NB11896001

NB11652001

(Alias Part Numbers:

"ATUM--6/2-0-STK")

NB09654001

NB09676001

NB11876001

NB10162001

NB11918001

NB10206001

NB10296001

NB12156001

NB10966001

063725P012

(Alias Part Numbers:

"5-1190481-2"

"ES2000-NO.2-B9-0-65MM")

NB10132001

NB1100-001

NB11106001

NB09976001

NB09502001

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.