

27-Sep-2018 **PCN** #:P-18-016395

**Subject:** Shipping Point Change & China Tariff - NORTH AMERICA CUSTOMERS ONLY

Description of Change: Shipping location for parts attached will be changed to TE's HL20 warehouse in Hermosillo, Mexico. This will also lead to a price increase of 3%, because of additional logistics burden. Customers who wish to pick up parts in the US can pick them up at TE's cross dock operations at Nogales, AZ with a 8% tariff surcharge in 2018 and 20% surcharge in 2019. This notification includes affected parts that were shipped from TE in the last 12 months. To get a complete list of affected parts that is on a pricing agreement, please reach out to your TE Account Manager. TE Customer Service will work with you to setup a new Ship-to Account in Mexico if required, and to transition all EDI communications to the new warehouse. We request your support in these activities so that there is no delay/stoppage in shipments on the change date. ONLY FOR NORTH AMERICA CUSTOMERS(AMEND WITH PCN P-18-016264)

**Reason:** Product <u>improvement.As</u> part of Section 301 tariffs List 3, the United States Trade Representative implemented an additional duty of 10% on certain products of Chinese origin, imported into the US. This will then become 25% in 2019. Parts on this notification are affected by this tariff. TE is implementing an alternative logistics route to mitigate the effect of the tariff. TE will ship these parts via a bonded carrier into our Distribution Center in Hermosillo, MX, which will be the new pick-up location. TE will also implement a 3% price increase to cover the additional logistics burden. Customers who wish to pick up the parts in the US can pick them at TE's cross dock operations at Nogales, AZ with a 8% tariff surcharge in 2018 and 20% surcharge in 2019.

**Key Dates:** 

Contact By Date:22-Oct-2018 Implementation Date:22-Oct-2018

## **Product Affected**

- 316390-7
- 2309210-1
- 9-2247422-1
- 2137740-3
- 9-2247421-1
- 2321478-1
- 2137740-4
- 9-2247420-1
- 1939961-1
- 1939963-1
- 2-1437285-2
- (Alias Part Numbers:
- "3900113-2611")
- 1939961-2
- 3-644511-5
- 1823180-1
- 1565804-1
- 171425-1
- 9-2247419-1
- 2309211-1
- 2309212-1
- 1939963-2
- 112263-90
- (Alias Part Numbers:
- "ZPF00000000135911"
- "112263-90-AS")
- 2208656-4
- 2137740-1
- 114020-90
- (Alias Part Numbers:
- "ZPF00000000131782")
- 2137740-2
- 1939967-1
- 1939965-1
- 4-1437290-0
- (Alias Part Numbers:
- "3900113-3421")
- 4-1606228-8
- (Alias Part Numbers:
- "112263-90")

**Product Affected** 

2247596-1 5-1606228-1 (Alias Part Numbers: "114020-90") The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.