



11-Jan-2019

**PCN #:**P-19-016777

**Subject:**New Date Code

**Description of Change:** Dear Customer, we hereby inform you upfront about the new production Date Code on the front of the cover (the digit that indicated the shift was changed by 2 digits indicating the time of production).

**Reason:** Document clarification.Better traceability

**Key Dates:**

**Contact By Date:**19-Jun-2019

**Implementation Date:**19-Jun-2019

**Product Affected**

8-1393292-9

(Alias Part Numbers:  
"V23074A1002A402")

3-1904065-7

5-1419137-8

(Alias Part Numbers:  
"V23074A1002X 44")

4-1904107-3

9-1904107-9

4-1414979-7

3-1904107-7

8-1904105-9

6-1393292-3

(Alias Part Numbers:  
"V23074A2002A403")

2344846-1

8-1904105-8

## **Product Affected**

6-1414926-3

8-1414780-8

1-1414734-0

1-1393292-8

(Alias Part Numbers:

"V23074A1001X 9")

1393292-5

(Alias Part Numbers:

"V23074A1001A402")

3-1414997-0

3-1393292-8

(Alias Part Numbers:

"V23074A1002A403")

1-1415005-6

6-1419137-0

(Alias Part Numbers:

"V23074A1101X 51")

6-1393292-2

(Alias Part Numbers:

"V23074A2002A402")

4-1904124-4

7-1414994-9

1-1414742-0

9-1904126-4

6-1393292-4

(Alias Part Numbers:

"V23074A4001X 40")

1-1414731-0

2-1393292-7

(Alias Part Numbers:

"V23074A1001X 42\*B")

9-1393292-1

(Alias Part Numbers:

"V23074A1301X 31")

1-1904120-4

1-1904057-8

(Alias Part Numbers:

"V23074-A1801-X106")

6-1419137-1

(Alias Part Numbers:

**Product Affected**

"V23074A1401X 53")

9-1904105-7

3-1904124-9

9-1904105-4

8-1393292-4

(Alias Part Numbers:

"V23074A1001A403")

9-1904105-1

2-1904098-8

8-1414994-0

6-1419137-4

(Alias Part Numbers:

"V23074A2001A403")

2-1393292-9

(Alias Part Numbers:

"V23074A1001X 47")

4-1904124-2

3-1414977-5

2-1393292-6

(Alias Part Numbers:

"V23074A1001X 42")

9-1904105-0

6-1904080-5

8-1904080-0

2-1414967-9

6-1419137-2

(Alias Part Numbers:

"V23074A1501X 38")

7-1414994-7

3-1414941-4

3-1393292-5

(Alias Part Numbers:

"V23074A1001X016P")

1-1414972-4

4-1904107-4

7-1415010-5

(Alias Part Numbers:

"V23074-A1002-X097")

3-1393292-3

(Alias Part Numbers:

**Product Affected**

"V23074A1001X 52")

3-1393292-1

(Alias Part Numbers:

"V23074A1001X 49P")

5-1414998-7

1-1414735-0

1-1414358-0

1-1904059-8

(Alias Part Numbers:

"V23074-A2601-X108")

9-1904063-3

9-1904126-3

1-1414781-0

7-1414995-0

8-1414998-4

6-1904135-0

1-1414638-0

9-1904123-7

8-1904111-6

3-1414977-4

5-1904135-9

5-1393292-8

(Alias Part Numbers:

"V23074A2001A402")

1-1904057-9

(Alias Part Numbers:

"V23074-A1001-X107")

1-1414634-0

6-1414926-2

1-1414580-0

1-1414625-0

5-1904099-7

5-1415011-2

(Alias Part Numbers:

"V23074-A2302-X096")

1-1414717-0

1-1414165-0

6-1393292-7

(Alias Part Numbers:

"V23074A4001X 55")

## **Product Affected**

1-1414630-0

3-1904124-8

7-1904126-5

1-1414714-0

2-1393292-0

(Alias Part Numbers:

"V23074A1001X 10")

5-1904073-5

2-1414971-4

9-1904063-4

8-1904105-6

2-1414997-9

1-1414743-0

9-1904105-2

6-1419137-5

(Alias Part Numbers:

"V23074B1701X 20")

1-1414058-0

7-1414983-4

1-1414355-0

5-1904117-9

4-1904124-3

9-1904130-8

6-1414950-1

5-1904110-9

1-1904120-8

7-1414994-8

8-1904111-7

5-1393292-1

(Alias Part Numbers:

"V23074A1301X 43")

1-1414715-0

5-1393292-2

(Alias Part Numbers:

"V23074A1301X 43\*B")

2-1904123-1

2-1904123-2

1-1414306-0

9-1904105-3

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.