



06-Feb-2019

PCN #:E-19-001763

Subject:CPC Connectors

Description of Change: Change the material of the peripheral seal located on the mating end of these connectors from a nitrile rubber which contains the phthalate DEHP to a nitrile rubber which does not contain DEHP. The following parts do not contain a peripheral seal and although listed on this notice, they will only receive a revision level change. Revision level change only parts: 206036-1, 206036-2, 206036-3, 206036-7, 206036-8, 206043-1, 206043-3, 206043-7, 206061-1, 206061-3, 206151-1, 206151-2, 206153-1, 206306-1, 206306-2, 206306-5, 206306-7, 206430-1, 206430-2, 206613-1, 206613-3, 206705-1, 206705-2, 206838-1, 206838-2, 206934-1, 206934-5, 1-206934-1, 1-206934-3, 1-206934-4, 1-206934-8, 2-206934-7, 207486-1, 207486-2, 208224-1, 2-208224-1, 2-208224-2, 2-208224-9, 211398-1, 211398-2, 211398-4, 211401-1, 211401-2, 211401-4, 211401-5, 211401-7, 211401-8

Reason: Product Improvement. Parts containing DEHP do not comply with the EU 2015/863 RoHS directive also known as RoHS 2019 or RoHS 3 due to the presence of DEHP. The DEHP free parts are RoHS 3 compliant.

Key Dates:

Contact By Date:10-Jun-2019

Implementation Date:10-Jun-2019

Product Affected

208224-5

206430-1

206838-3

206151-4

207486-5

2-208224-3

Product Affected

206705-3

206151-3

206306-4

2-208224-2

206036-8

206306-3

206036-3

(Alias Part Numbers:

"A76356-000"

"AMPS-0-0206036-3")

796275-1

206404-1

796275-2

206838-2

211401-7

206838-4

211401-3

788159-2

1-206934-4

206043-1

206151-2

206430-4

211398-2

207486-2

211401-8

2-208224-1

1-206934-8

206934-5

206036-4

206043-5

2-208224-5

206036-2

206705-1

(Alias Part Numbers:

"683370-000"

"AMPS-0-0206705-1")

1-206934-3

206153-2

206404-2

206036-5

Product Affected

211401-1

206151-1

211398-4

788159-1

211401-2

206306-5

206151-8

206705-4

206306-1

207486-1

(Alias Part Numbers:

"402697510")

206153-1

(Alias Part Numbers:

"926370-000"

"LTRW-AMP-206153-1"

"0-0206153-1")

206613-5

2-206934-7

796095-2

206838-1

206061-3

211398-3

206061-2

206043-4

2-208224-9

206705-2

(Alias Part Numbers:

"195902-000"

"AMPS-0-0206705-2")

206613-3

206430-2

(Alias Part Numbers:

"5011473"

"CL0834-000"

"JOR-06588")

1-206934-1

1-208224-0

211398-1

206306-2

Product Affected

788154-2

206043-3

206036-1

(Alias Part Numbers:

"C21176-000"

"DUL-RECPT-SZ-17-16-CPC")

206430-3

206061-1

211401-4

206613-1

1-206934-7

208224-1

206934-9

206934-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.