



01-Mar-2019

PCN #:E-19-000491

Subject:PCF PCFL PCFN relay

Description of Change: PCF PCFL PCFN relay card component modification.

Reason: Product Improvement. TE will change the rib of card from current half-round to cambered of PCF PCFL PCFN relay as a assembly process improvement in the product line of TE plant(attached the comparison pictures). No relay function impact.

Key Dates:

Contact By Date:06-May-2019

Implementation Date:06-May-2019

Product Affected

1461477-7

(Alias Part Numbers:

"PCF-112D1M-2

000B")

1461193-7

(Alias Part Numbers:

"PCFN-109D2M

000")

1461514-1

(Alias Part Numbers:

"PCF-112D2M

000B")

1721159-6

(Alias Part Numbers:

"PCF-105D2M-A1")

Product Affected

1721155-4

(Alias Part Numbers:

"PCFN-112D2M

000X")

1461193-8

(Alias Part Numbers:

"PCFN-118D2M

000")

1721687-4

(Alias Part Numbers:

"PCF-112D2M

050")

5-1440002-8

(Alias Part Numbers:

"PCF-124D2M

000")

3-1419153-4

(Alias Part Numbers:

"PCF-112D2M

000")

2-1649000-3

(Alias Part Numbers:

"PCFL-112D2M

23000")

1721550-4

(Alias Part Numbers:

"PCFN-112D2M

001")

2071138-1

(Alias Part Numbers:

"PCF-124D2MF

00010")

1461477-4

(Alias Part Numbers:

"PCF-112D1M-2

000")

1721696-7

(Alias Part Numbers:

"PCFL-112D2MP-B

500")

Product Affected

7-1440004-2

(Alias Part Numbers:

"PCF-112D2M

200")

1721696-4

(Alias Part Numbers:

"PCFL-112D2MP-A

500")

2071141-1

(Alias Part Numbers:

"PCF-112D2M-B

01000")

1649000-4

(Alias Part Numbers:

"PCFL-124D2M

000")

2-1649000-0

(Alias Part Numbers:

"PCFL-110D2M

13000")

1649376-2

(Alias Part Numbers:

"PCF-112D1M-2A")

1649376-3

(Alias Part Numbers:

"PCF-112D1M-2C")

1649376-1

(Alias Part Numbers:

"PCF-112D1M-2B")

1461514-2

(Alias Part Numbers:

"PCF-112D2M

000BW")

1649376-4

(Alias Part Numbers:

"PCF-112D1M-2D")

1649717-1

(Alias Part Numbers:

"PCFL-110D2M

010")

Product Affected

1721550-1

(Alias Part Numbers:

"PCFN-105D2M

001")

4-1440827-0

2-1649000-2

1-1649000-3

(Alias Part Numbers:

"PCFL-110D2M

000")

1-1721696-1

(Alias Part Numbers:

"PCFL-112D2MFP-C

05000")

1461193-6

(Alias Part Numbers:

"PCFN-106D2M

000")

1721696-8

(Alias Part Numbers:

"PCFL-112D2MP-C

500")

2071376-1

1649321-4

1721159-1

(Alias Part Numbers:

"PCF-112D2M-B1")

3-1419153-5

(Alias Part Numbers:

"PCFN-112D2M

000")

1461193-9

(Alias Part Numbers:

"PCFN-124D2M

000")

1461193-5

(Alias Part Numbers:

"PCFN-148D2M

000")

1649000-3

Product Affected

(Alias Part Numbers:

"PCFL-112D2M

000")

2071401-1

1721542-5

(Alias Part Numbers:

"PCFN-118D2MF

000")

2-1649000-1

(Alias Part Numbers:

"PCFL-112D2M

13000")

1649321-5

(Alias Part Numbers:

"PCFN-124D1M-2

000")

1721696-9

(Alias Part Numbers:

"PCFL-112D2MFP-A

05000")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.