



20-Mar-2019

PCN #:P-19-017123

Subject:MCON 5P 1.2LL HSG ASSY

Description of Change: ECOC informed TE Suzhou to change the sealing from 1718810-1 to 2282255-1, the rib of inner HSG(2295772) should be cancelled to match the sealing change

Reason: Part status change.

Key Dates:

Contact By Date:21-Mar-2019

Implementation Date:21-Mar-2019

Product Affected

1-1718806-7

1-1718806-1

1-1670921-1

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.