

15-Apr-2019 **PCN** #:P-19-017222

Subject:GOLD PLATED METAL STRIP FOR MCP 2.8 SOCKET CONTACTS

Description of Change: Dear Customer, we hereby inform you about a new process equipment of a plating process for the component part number 704661-1.

Reason: Customer Request.To ensure the quality level as well as the supply also in future we would like to inform you with this PCN about new process equipment at our TE manufacturing location in Montcada (ES). This new process equipment will be used to perform the plating-process for parts on component level. The new process equipment will be technically equivalent to the existing ones using the same technology, tooling, plating bath and supplier. The process validation, capability analysis and release will be done TE internally. Therefore this PCN is for your notification only.

Key Dates:

Contact By Date: 06-May-2019

Implementation Date:06-May-2019

Product Affected

1-968851-2

1-968880-2

1-2141859-2

704661-1

1-968849-2

1-968855-2

1-968857-2

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary

from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.