

18-Apr-2019 **PCN** #:E-19-006031

Subject: Economy power connector plug housing

Description of Change: Product Improvement. Adding a second resin to accommodate market constraints. There are no performance changes, new parts have finished qualification test. Material certification and test report are available upon request to your local TE Connectivity Sales Engineer.

Reason: Manufacturing / Process Requirements. Product Improvement. Adding a second resin to accommodate market constraints. There are no performance changes, new parts have finished qualification test. Material certification and test report are available upon request to your local TE Connectivity Sales Engineer.

Key Dates:

Contact By Date:31-Oct-2019

Implementation Date:31-Oct-2019

Product Affected

1-1123722-5

2-1123722-4

4-1123722-3

3-1123722-7

1-1123722-0

1-1123722-1

3-1123722-6

1-1123722-7

1-1123722-8

3-1123722-3

5-1123823-1

6-1123722-9

1-1123722-6

Product Affected

- 4-1123722-5
- 2-1123823-1
- 3-1123722-2
- 1-1123722-3
- 5-1123722-7
- 4-1123823-1
- 1-1123722-4
- 1-1123823-1
- 5-1123722-9
- 5-1123722-6
- 1-1123722-2
- 6-1123722-4
- 3-1123823-1
- 1-1123722-9
- 5-1123722-5
- 5-1123722-3
- 3-1123722-9
- 2-1123722-3
- 6-1123722-5

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.