



# Product Change Notification

Current Date: 18-Apr-2019

## TE Connectivity

**Product Change Notification:** P-19-017220

**PCN Date:** 13-APR-19

**Customer:** TTI Inc(0000139702)

**Location:** WORLDWIDE

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

GOLD PLATED METAL STRIP FOR TAB 2.8 SOCKET CONTACTS

**Description of Changes**

Dear Customer, we hereby inform you about a new process equipment of a plating process for the component part number 705187-1.

**Reason for Changes:**

Customer Request.To ensure the quality level as well as the supply also in future we would like to inform you with this PCN about new process equipment at our TE manufacturing location in Montcada (ES). This new process equipment will be used to perform the plating-process for parts on component level. The new process equipment will be technically equivalent to the existing ones using the same technology, tooling, plating bath and supplier. The process validation, capability analysis and release will be done TE internally. Therefore this PCN is for your notification only.

**Estimated Dates:**

**Last Order Date** (Obsolete Parts Only):

**First Date To Ship** (Changed Parts Only):

06-MAY-2019

**Last Ship Date** (Obsolete Parts Only):

**Last Date for Mixed Shipments:** (Changed Parts Only):

No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-962841-3</a>	NO						
<a href="#">1-962842-3</a>	NO						
<a href="#">1-962915-3</a>	NO						
<a href="#">1-962916-3</a>	NO						

**Customer:** TTI Inc ( 3164508 )

**Location:** Fort Worth

**Agreement Number:** Agreement Unknown

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-962915-3</a>	NO						

**Customer:** TTI Inc ( 1281288 )

**Location:** Fort Worth

**Agreement Number:** TTI002

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-962915-3</a>	NO						

Customer: TTI Inc. ( 1305175 )

Location: Maisach-gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-962841-3</a>	NO		TYC1-962841-3				
<a href="#">1-962842-3</a>	NO		TYC1-962842-3				
<a href="#">1-962915-3</a>	NO		TYC1-962915-3				
<a href="#">1-962916-3</a>	NO						

Customer: TTI Inc ( 168830 )

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-962915-3</a>	NO						

Customer: TTI Inc. ( 3057778 )

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-962841-3</a>	NO		TYC1-962841-3				
<a href="#">1-962842-3</a>	NO		TYC1-962842-3				
<a href="#">1-962915-3</a>	NO		TYC1-962915-3				
<a href="#">1-962916-3</a>	NO						

