



12-Jun-2019

PCN #:P-19-017494

Subject:Manufacturing Location Change Appliances Tubing BSTS Products

Description of Change: Manufacturing location change. Following Part Numbers will be transferred from Menlo Park, USA to Trutnov, CZ. Different parts will move in different phases, consequently not all new part numbers will be immediately available at the end of the notification period.

Reason: Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a process which produces a finished TE-product.

Key Dates:

Contact By Date:02-Sep-2019

Implementation Date:02-Sep-2019

Product Affected

CB5009-000

CZ4092-000

(Alias Part Numbers:
"BSTS-15-CL-7.25IN")

CB5059-000

(Alias Part Numbers:
"8-1899832-9")

CB5066-000

(Alias Part Numbers:
"9-1899832-3")

Product Affected

CM6844-000

473538-001

(Alias Part Numbers:

"9-1200270-6"

"BSTS-17X4-RSU")

CB5069-000

(Alias Part Numbers:

"9-1899832-4")

CB5041-000

(Alias Part Numbers:

"8-1899832-3"

"BSTS-15X25")

CF8126-000

CF6051-000

CB5017-000

(Alias Part Numbers:

"3-1899832-1")

CB5003-000

(Alias Part Numbers:

"2-1899832-7")

CF6052-000

(Alias Part Numbers:

"BSTS-03X4FR")

CJ5163-000

(Alias Part Numbers:

"BSTS-07-2.5IN/FR/NM"

"BSTS-07-2.5IN/FR/NM")

CB5022-000

CB5038-000

(Alias Part Numbers:

"BSTS-13X4/NM"

"8-1899832-2")

CN5758-000

067168N002

(Alias Part Numbers:

"4-1190506-6")

CB5013-000

(Alias Part Numbers:

"2-1899832-9")

CL9352-000

Product Affected

(Alias Part Numbers:
"BSTS-17X25FR/WHT/NM")

CB5062-000

(Alias Part Numbers:
"9-1899832-1")

CB5024-000

(Alias Part Numbers:
"3-1195009-9")

CB5023-000

(Alias Part Numbers:
"3-1899832-2")

"BSTS-11X25")

CZ6522-000

(Alias Part Numbers:
"BSTS-11-CL-7.25IN")

CX1370-000

(Alias Part Numbers:
"BSTS-07X100FR")

311594-001

(Alias Part Numbers:
"1-1192358-1")

CB5021-000

942101-001

(Alias Part Numbers:
"3-1197294-1")

"BSTS-13X4FR")

CJ0189-000

CP3862-000

(Alias Part Numbers:
"BSTS-20X25/NM")

"3-1899833-9")

A02780-001

(Alias Part Numbers:
"5-1200273-3")

"BSTS-04X4-RSU")

CV6821-000

(Alias Part Numbers:
"BSTS-30X25/CL")

CL4192-000

(Alias Part Numbers:

Product Affected

"BSTS-13X25/CL/NM"

"5-1899833-6")

CB5018-000

CL5849-000

EG4273-000

(Alias Part Numbers:

"BSTS-11X4FR/WHT")

CJ5220-000

(Alias Part Numbers:

"BSTS-11X6IN"

"4-1899833-7")

CL9351-000

(Alias Part Numbers:

"BSTS-17X25FR/RED/NM"

"6-1899833-1")

CB5004-000

(Alias Part Numbers:

"BSTS-04X4"

"3-1899225-1")

CZ3940-000

(Alias Part Numbers:

"BSTS-35X25/FR/NM")

CB5033-000

(Alias Part Numbers:

"2-1196945-9")

CB5045-000

(Alias Part Numbers:

"8-1899832-6")

849184N002

(Alias Part Numbers:

"6-1196621-9")

832795-001

(Alias Part Numbers:

"1196502-4")

CM3869-000

(Alias Part Numbers:

"BSTS-11X25FR"

"6-1899833-5")

CB5026-000

(Alias Part Numbers:

Product Affected

"5-1899832-9")

CB5001-000

(Alias Part Numbers:

"2-1899832-6")

CB5064-000

(Alias Part Numbers:

"9-1899832-2")

CB5019-000

CZ3941-000

(Alias Part Numbers:

"BSTS-45X25/FR/NM")

CB5052-000

(Alias Part Numbers:

"6-1899211-8"

"BSTS-17X4")

CB5005-000

(Alias Part Numbers:

"BSTS-04X4FR")

CX1369-000

(Alias Part Numbers:

"BSTS-13X4FR/NM")

CF3962-000

CB5012-000

(Alias Part Numbers:

"2-1899832-8")

CB5060-000

CF6053-000

CB5072-000

(Alias Part Numbers:

"6-1899254-0")

CB5014-000

(Alias Part Numbers:

"3-1899832-0")

F00337-001

(Alias Part Numbers:

"3-1201269-3"

"BSTS-07X2.5IN/FR/NM")

CB5000-000

CP1444-000

(Alias Part Numbers:

Product Affected

"4-1899833-2")

312127N002

(Alias Part Numbers:

"7-1192361-4")

CB5071-000

(Alias Part Numbers:

"9-1899832-5")

CB5031-000

CJ3141-000

CB5011-000

D61513-001

(Alias Part Numbers:

"4-1200690-9")

CB5027-000

(Alias Part Numbers:

"6-1899832-0")

CB5067-000

(Alias Part Numbers:

"8-1899355-2")

CB5044-000

(Alias Part Numbers:

"8-1899832-5")

CU3939-000

(Alias Part Numbers:

"3-1190390-1")

CS6411-000

(Alias Part Numbers:

"BSTS-27X4/CL/NM")

CB5006-000

CN0029-000

CB5025-000

(Alias Part Numbers:

"5-1899832-8")

CJ6873-000

CB5061-000

(Alias Part Numbers:

"9-1899832-0")

CB5065-000

(Alias Part Numbers:

"BSTS-27X4"

Product Affected

"4-1899230-9")

CB5063-000

CB5068-000

266500-001

(Alias Part Numbers:

"1-1200272-9"

"BSTS-27X4-RSU")

CJ5694-000

(Alias Part Numbers:

"2-1899329-4"

"BSTS-03X25")

CB5032-000

(Alias Part Numbers:

"6-1899832-1")

CU9212-000

CB5037-000

(Alias Part Numbers:

"8-1899832-1")

CB5051-000

(Alias Part Numbers:

"BSTS-17X25"

"8-1899832-7")

CZ3939-000

(Alias Part Numbers:

"BSTS-04X25/FR/NM")

CB5053-000

(Alias Part Numbers:

"BSTS-17X4/CL"

"8-1899832-8")

421822-001

(Alias Part Numbers:

"5-1200271-6"

"BSTS-07X4-RSU")

CJ1417-000

(Alias Part Numbers:

"BSTS-11X25/NM"

"4-1899833-3")

CB5035-000

(Alias Part Numbers:

"BSTS-13X25FR/NM"

Product Affected

"6-1899832-3")

CB5020-000

903479-001

(Alias Part Numbers:

"3-1197021-3")

CB5015-000

(Alias Part Numbers:

"1899279-5"

"BSTS-07X4")

CS8624-000

(Alias Part Numbers:

"BSTS-15X4FR/NM"

"1899833-2")

CL3006-000

(Alias Part Numbers:

"8-1899356-1"

"BSTS-04X4/NM")

CB5010-000

CB5002-000

CB5036-000

(Alias Part Numbers:

"8-1899832-0")

CL9350-000

(Alias Part Numbers:

"BSTS-17X25FR/NM"

"6-1899833-0")

CB5034-000

(Alias Part Numbers:

"6-1899832-2"

"BSTS-13X25/NM")

CF6054-000

(Alias Part Numbers:

"3-1899593-5")

CB5007-000

CB5450-000

CB5070-000

(Alias Part Numbers:

"5-1899209-2")

CN2233-000

CB5042-000

Product Affected

(Alias Part Numbers:

"8-1899832-4")

F50671-001

(Alias Part Numbers:

"BSTS-45X4-RSU"

"5-1200273-1")

CL3005-000

(Alias Part Numbers:

"BSTS-11X25/FR/NM"

"5-1899833-5")

CB5028-000

CB5043-000

(Alias Part Numbers:

"BSTS-15X4"

"3-1899213-5")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.