



28-Jun-2019

PCN #:E-19-010156

Subject:Shipping location change from Tullahoma TN USA to Distribution Center at Greensboro NC USA for DT/DTM/DRC/DTF Products

Description of Change: The Industrial and Commercial Transportation business unit of TE Connectivity is making a change to shipping location for the part number(s) listed below. There is no change in manufacturing location or product. These PNs are TE proprietary designs, therefore considered catalog/general market product. All products you currently receive from our Tullahoma, TN (USA) location will be transitioned to the new Distribution Center at Greensboro, NC (USA).

Reason: Dear Customer, we hereby inform you of this change. The change is necessary to better serve our customers and as part of our continuous improvement efforts to provide extraordinary Customer Service.

Key Dates:

Contact By Date:02-Sep-2019

Implementation Date:02-Sep-2019

Product Affected

DTM1312PA12PBR008

(Alias Part Numbers:

"1899781-5"

"DTM13-12PA-12PB-R008")

AEC17-40PA

(Alias Part Numbers:

"ZPF000000000131267")

DT15-12PD-B016

DRC20-75P0102

HD10-9-96P-N005

(Alias Part Numbers:

Product Affected

"ZPF000000000130534")

DRC10-40P

(Alias Part Numbers:

"ZPF000000000131270")

DT15-12PA

DT04-2P-N006

DTF13-12PC

(Alias Part Numbers:

"ZPF000000000130560")

SRK13-MDB-32A-001

DRCP25-126PAA-G003

DTM1312PC12PDR008

(Alias Part Numbers:

"3-1899781-6"

"DTM13-12PC-12PD-R008")

DTF13-2PB

DTF13-6P-G003

(Alias Part Numbers:

"ZPF000000000130334")

DRCP25-86PBB-GC05

DRC22-50P05

AEC17-40PC

(Alias Part Numbers:

"ZPF000000000131269")

DRC13-40PB

(Alias Part Numbers:

"ZPF000000000131282")

DRC13-40PB-CG01

DRC20-60P05

DT15-12PC

DRC22-50P07

DTF13-2P

(Alias Part Numbers:

"ZPF000000000130128")

DT13-08PC

DRC22-50P04

DTM1312PA12PBGR01

(Alias Part Numbers:

"DTM13-12PA-12PB-GR01")

SRK15-MDE-32A-001

Product Affected

DRC23-40PB-N010

DT04-4P-RT01

DRC20-50P02

(Alias Part Numbers:

"ZPF000000000131352")

DT15-12PB-B028

DTP15-4P

DTF13-3P-1939

(Alias Part Numbers:

"ZPF000000000130195")

DTF13-12PA

(Alias Part Numbers:

"ZPF000000000130557")

DTF13-12PA-G003

(Alias Part Numbers:

"ZPF000000000130558")

DRC23-40PB-N012

DRC20-60P06

DRC10-24PA-A004

(Alias Part Numbers:

"ZPF000000000131084")

DT13-36PABC-R015

(Alias Part Numbers:

"5-1899792-7")

1034-006-0405

(Alias Part Numbers:

"1034-006-0405-B")

DTF13-12PD

(Alias Part Numbers:

"ZPF000000000130561")

247-520

DT15-08PA-G003

AEC17-40PD

DRC22-50P01

(Alias Part Numbers:

"ZPF000000000131361")

DT15-12PD

SRK13-MDA-32A-001

(Alias Part Numbers:

"5-1899842-7")

Product Affected

DT13-36PABC-GR02

0942318R02

DT13-12PB-B016

DRC23-40PD-N012

DRC23-64PAA

(Alias Part Numbers:

"ZPF000000000131389")

DT15-3P-R009

DRC23-40PA-N012

(Alias Part Numbers:

"ZPF000000000131312")

DT13-12PB

DTM15-12PA-G003

DT15-12PA-G003

DTM1312PA12PDR008

(Alias Part Numbers:

"DTM13-12PA-12PD-R008")

DTMF15-48P-B026

DRC22-50P02

DT15-12PC-G003

DTM15-12PB

(Alias Part Numbers:

"ZPF000000000130592")

DT13-6P-G003

DTF13-4P-G003

(Alias Part Numbers:

"ZPF000000000130262")

DTF15-12PD-G003

DTF15-12PB

(Alias Part Numbers:

"ZPF000000000130564")

DT15-08PA

DRC13-24PA

(Alias Part Numbers:

"ZPF000000000131097")

DT15-08PD

DTF13-4P

(Alias Part Numbers:

"ZPF000000000130261")

DT04-3P-P007

Product Affected

(Alias Part Numbers:

"5-1899776-8")

DT15-6P-G003

DTF13-12PB

(Alias Part Numbers:

"ZPF000000000130559")

DRC10-24PB-A004

(Alias Part Numbers:

"ZPF000000000131085")

DT13-4P

SRK15-MDC-32A-001

2297129-1

(Alias Part Numbers:

"DTP13-4P-E028")

DRC23-24PA

(Alias Part Numbers:

"ZPF000000000131123")

DT04-2P-RT21

DTM13-12PB

(Alias Part Numbers:

"ZPF000000000130586")

DTM13-12PB-R005

(Alias Part Numbers:

"ZPF000000000130587")

DT04-2P-RT25

DRCP25-86PCC-GC03

DTM13-12PD-R008

DTM13-12PD

(Alias Part Numbers:

"ZPF000000000130590")

DTF15-12PB-G003

SRK15-MDA-32A-001

DRC10-24PA

(Alias Part Numbers:

"ZPF000000000131083")

DTM1312PA12PCR008

(Alias Part Numbers:

"DTM13-12PA-12PC-R008")

DRC23-24PB

(Alias Part Numbers:

Product Affected

"ZPF000000000131124")

DT04-2P-RT26

DTM1312PC12PBR008

(Alias Part Numbers:

"DTM13-12PC-12PB-R008")

DT15-12PD-G003

DT04-2P-RT22

DT04-2P-RT01

DT13-12PD-B016

DTF15-12PC

(Alias Part Numbers:

"ZPF000000000130565")

DT15-4P-G003

DTM13-12PC-R008

DT13-24PAB-R015

DT13-12PD

DRC13-40PD

(Alias Part Numbers:

"ZPF000000000131286")

DT15-4P

DRC13-24PB

(Alias Part Numbers:

"ZPF000000000131100")

DRC20-50P05

(Alias Part Numbers:

"ZPF000000000131355")

DT13-08PB

DTM13-12PA-R008

(Alias Part Numbers:

"ZPF000000000139426")

DT15-08PC

SRK15-MDF-32A-001

DTM13-12PA-NP02

1034-005-0205

(Alias Part Numbers:

"1034-005-0205-B")

DRC13-40PA

(Alias Part Numbers:

"ZPF000000000131279")

DRC20-50P08

Product Affected

(Alias Part Numbers:
"ZPF000000000131358")

DT04-2P-RT24

DRC20-50P01

(Alias Part Numbers:
"ZPF000000000131351")

DT15-12PB

DTM1312PC12PDGR01

(Alias Part Numbers:
"DTM13-12PC-12PD-GR01")

DT15-12PA-B028

AEC17-40PB

(Alias Part Numbers:
"ZPF000000000131268")

DT13-12PB-G003

DT13-2P

DT13-20PAA-E004

46926-1

DRC23-40PC-N012

DTM13-12PC

(Alias Part Numbers:
"ZPF000000000130589")

DRC20-50P06

(Alias Part Numbers:
"ZPF000000000131356")

DTF13-6P

(Alias Part Numbers:
"ZPF000000000130333")

DT15-2P-A009

SRK15MDA32A001G003

DT13-6P

DRCP25-86PBB-GC03

SRK15-MDD-32A-001

DRC13-24PA-CG01

(Alias Part Numbers:
"ZPF000000000131098")

DT15-6P

DTM13-08PA-R004

(Alias Part Numbers:
"ZPF000000000130406")

Product Affected

DTM13-12PB-R008

(Alias Part Numbers:
"ZPF000000000130588")

DTM13-12PB-G003

DT13-12PA-B016

DTF13-3P

(Alias Part Numbers:
"ZPF000000000130194")

DT13-4P-G003

DT04-4P-RT03

DTM13-12PA

(Alias Part Numbers:
"ZPF000000000130584")

DT15-6P-GP01

DTM04-2P-P007

(Alias Part Numbers:
"ZPF000000000130138")

DRC20-50P09

(Alias Part Numbers:
"ZPF000000000131359")

DRC23-80P

(Alias Part Numbers:
"ZPF000000000131418")

DTP13-4P

DT04-2P-RT06

DT13-08PA

DT13-12PC-B016

DTF15-12PA-G003

(Alias Part Numbers:
"ZPF000000000130563")

DTP10-4P

(Alias Part Numbers:
"ZPF000000000130282")

DRC10-40P-A004

(Alias Part Numbers:
"ZPF000000000131271")

DT13-12PA-G003

DTM04-3P-R011

DT13-48PABCD-R015

(Alias Part Numbers:

Product Affected

"3-1899782-1")

DRC22-50P03

DRC13-40PA-CG01

DT15-2P-P010

DTMF15-48P

(Alias Part Numbers:

"ZPF000000000131348")

DT15-12PB-B016

DTM15-12PA

(Alias Part Numbers:

"ZPF000000000130591")

DTF13-12PB-G003

DTF15-12PA

(Alias Part Numbers:

"ZPF000000000130562")

DRCP25-86PAA-G003

(Alias Part Numbers:

"1-1899819-0")

DRCP25-86PCC-GC05

DT13-12PC

DRC20-50P04

(Alias Part Numbers:

"ZPF000000000131354")

DT13-12PA

DTM13-12PA-GR01

(Alias Part Numbers:

"ZPF000000000130585")

DTM15-12PC

(Alias Part Numbers:

"ZPF000000000130593")

DT04-2P-RT02

DRC13-40PC

(Alias Part Numbers:

"ZPF000000000131284")

DT15-12PB-G003

DTM13-12PA-R005

DRC20-60P07

SRK15-MDB-32A-001

DTM13-12PA-G003

DRC23-64PAA-N010

Product Affected

(Alias Part Numbers:
"ZPF000000000131390")

DTM15-12PD

(Alias Part Numbers:
"ZPF000000000130594")

DRCP25-86PAA-G005

DT15-08PB

DT13-12PA-R015

DTF15-12PD

(Alias Part Numbers:
"ZPF000000000130566")

DT15-2P

DT13-48PABCD-GR02

DT15-12PC-B016

DT13-08PB-G003

HD10-6-96P-N005

(Alias Part Numbers:
"ZPF000000000130380")

DRC20-50P07

(Alias Part Numbers:
"ZPF000000000131357")

2333113-1

(Alias Part Numbers:
"DTM13-12PA-R017")

DRC20-50P03

(Alias Part Numbers:
"ZPF000000000131353")

DT15-12PA-B016

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.