



12-Jul-2019

PCN #:E-19-010675

Subject:DEUTSCH DT, DTP Wedges and HDP Backshells Manufacturing Location Change

Description of Change: The Industrial and Commercial Transportation business unit of TE Connectivity is transferring the production of the part numbers listed below from TE Hemet/CA-USA to TE Tullahoma/TN-USA or TE externally approved supplier. Shipping point will change from Ontario, CA, USA to Greensboro, NC, USA. These PNs are TE proprietary designs, therefore considered catalog/general market product. Tools that manufacture parts within this PCN are identified as "swing tool" and TE reserves the right in future to move tool to a TE ICT Manufacturing location and/or a TE externally approved supplier as needed. In case of subsequent transfer of swing tool, PCN will be sent to notify but will have a zero day wait period. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or TE e-PPAP system. Submissions will not occur without request. If PPAP is requested, disposition response is required within 14 days of submit date or it will be considered approved.

Reason: This change is necessary for alignment of overall manufacturing capacity and footprint to better meet our Customer's needs. **IMPORTANT:** The change will not impact fit, form or function.

Key Dates:

Contact By Date:12-Sep-2019

Implementation Date:12-Sep-2019

Product Affected

W8S

(Alias Part Numbers:

"ZPF000000000131460"

"6-1899776-4")

WP-2S

Product Affected

(Alias Part Numbers:
"ZPF000000000131483")

2431-003-2405

W12S-P012

(Alias Part Numbers:
"ZPF000000000131464"

"W12S-P012-AS"

"W12S-P012-LD"

"W12S-P012-LS"

"W12S-P012-MS"

"\$\$W12S-P012"

"W12S-P012-E"

"W12S-P012-L"

"W12S-P012-M")

W2PD

(Alias Part Numbers:
"ZPF000000000131423")

W3S-1939-P012

(Alias Part Numbers:
"ZPF000000000131438"

"W3S-1939-P012-AS"

"W3S-1939-P012-MS"

"W3S-1939-P012-M"

"7-1899794-6")

W4SC-P012

(Alias Part Numbers:
"ZPF000000000131452")

W2SD-P012

(Alias Part Numbers:
"ZPF000000000131433")

W4SD

(Alias Part Numbers:
"ZPF000000000131453")

W4SD-P012

(Alias Part Numbers:
"ZPF000000000131454")

W12P

(Alias Part Numbers:
"ZPF000000000131462"

"W12P-AS"

Product Affected

"W12P-P004-M")

W3S

(Alias Part Numbers:

"W3S-AS")

W4SA-P012

(Alias Part Numbers:

"ZPF000000000131448")

W3P-P004

(Alias Part Numbers:

"W3P-P004-MS"

"W3P-P004-M")

W2S-P070-Y

WP-2P

(Alias Part Numbers:

"ZPF000000000131482"

"WP-2P-AS")

W2SD

(Alias Part Numbers:

"ZPF000000000131432")

W2S

(Alias Part Numbers:

"ZPF000000000131424")

W2SA

(Alias Part Numbers:

"ZPF000000000131426")

W4P-P004

W4SC

(Alias Part Numbers:

"ZPF000000000131451")

W6S2-P012

(Alias Part Numbers:

"ZPF000000000131458")

2428-008-2405

(Alias Part Numbers:

"ZPF000000000131576"

"2428-008-2405-AS"

"2428-008-2405-LD"

"2428-008-2405-MS"

"2428-008-2405-L"

"2428-008-2405-M")

Product Affected

W2P-P004

(Alias Part Numbers:

"W2P-P004-LD"

"W2P-P004-MS"

"W2P-P004-L"

"W2P-P004-M")

Y2428-024-24050000

(Alias Part Numbers:

"2428-024-2405")

W8P-P004

W2PB

(Alias Part Numbers:

"ZPF000000000131421")

W3P

(Alias Part Numbers:

"ZPF000000000131434"

"W3P-AS"

"W3P-LS"

"\$\$W3P"

"W3P-L"

"8202608764")

W4S-P012

(Alias Part Numbers:

"ZPF000000000131446"

"W4S-P012-LS"

"W4S-P012-MS"

"W4S-P012-L"

"W4S-P012-M")

W2S-P012

(Alias Part Numbers:

"ZPF000000000131425"

"W2S-P012-AS"

"W2S-P012-LD"

"W2S-P012-LS"

"W2S-P012-MS"

"\$\$W2S-P012"

"W2S-P012-E"

"W2S-P012-L"

"W2S-P012-M"

"820P-37547")

Product Affected

W3P-1939

(Alias Part Numbers:

"ZPF000000000131435")

WP-4S

(Alias Part Numbers:

"ZPF000000000131485"

"WP-4S-LD"

"WP-4S-LS"

"WP-4S-L")

W4S-ZZ

(Alias Part Numbers:

"W4S"

"ZPF000000000131445"

"W4S-AS"

"8202606748")

W2SB-P012

(Alias Part Numbers:

"ZPF000000000131429")

W2SB

(Alias Part Numbers:

"ZPF000000000131428")

WP-4P-P073

WP-2S-P082

W4PD

(Alias Part Numbers:

"ZPF000000000131444")

W2S-P070

(Alias Part Numbers:

"\$\$W2S-P070")

W2SC

(Alias Part Numbers:

"ZPF000000000131430")

W12S

(Alias Part Numbers:

"ZPF000000000131463"

"W12S-AS")

W2PC

(Alias Part Numbers:

"ZPF000000000131422")

WP-4P

Product Affected

(Alias Part Numbers:

"ZPF000000000131484")

W8S-P012

(Alias Part Numbers:

"ZPF000000000131461"

"W8S-P012-AS"

"W8S-P012-LD"

"W8S-P012-LS"

"W8S-P012-MS"

"W8S-P012-L"

"W8S-P012-M")

W8P-P073

W6P-P073

W2SC-P012

(Alias Part Numbers:

"ZPF000000000131431")

W8P

(Alias Part Numbers:

"ZPF000000000131459")

W3S-1939

(Alias Part Numbers:

"ZPF000000000131437")

W4PB

(Alias Part Numbers:

"ZPF000000000131442")

W2S-P070-R

W4SB-P012

(Alias Part Numbers:

"ZPF000000000131450")

W4PC

(Alias Part Numbers:

"ZPF000000000131443")

W3S-P012

(Alias Part Numbers:

"ZPF000000000131439"

"W3S-P012-AS"

"W3S-P012-LD"

"W3S-P012-LS"

"W3S-P012-MS"

"\$\$W3S-P012"

Product Affected

"W3S-P012-L"

"W3S-P012-M")

W2P

(Alias Part Numbers:

"ZPF000000000131419"

"W2P-AS"

"W2P-LD"

"W2P-LS"

"W2P-L"

"8202612042"

"43018-000")

W12P-P004

(Alias Part Numbers:

"W12P-P004-LS"

"W12P-P004-MS"

"W12P-P004-L")

W2SA-P012

(Alias Part Numbers:

"ZPF000000000131427")

W6S

(Alias Part Numbers:

"ZPF000000000131456"

"W6S-AS")

W4PA

(Alias Part Numbers:

"ZPF000000000131441")

W4P

(Alias Part Numbers:

"ZPF000000000131440"

"W4P-AS"

"820E-37523"

"820P-37764"

"4004200321"

"C20490")

W2S-P070-U

2428-004-2405

(Alias Part Numbers:

"ZPF000000000131575"

"2428-004-2405-AS"

"2428-004-2405-MS"

Product Affected

"2428-004-2405-M")

W4SA

(Alias Part Numbers:

"ZPF000000000131447")

W2PA

(Alias Part Numbers:

"ZPF000000000131420")

W6P

(Alias Part Numbers:

"ZPF000000000131455"

"W6P-AS"

"\$\$W6P")

W6P-P004

W4SB

(Alias Part Numbers:

"ZPF000000000131449")

W8S-P073

W6S-P012

(Alias Part Numbers:

"ZPF000000000131457"

"W6S-P012-LD"

"W6S-P012-LS"

"W6S-P012-MS"

"W6S-P012-L"

"W6S-P012-M")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.